



Asher

Section A - Accident Details

Registration Number	SHC4749L
Case Reference Number	TAX/12/18/2052
Registration Date	12/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	DORAY ANTONIO RAJA
Type of Accident	Head To Side
Accident Date and Time	11/12/2018 4:45 PM
Accident Reported Date and Time	12/12/2018 10:06 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	11/12/2018 5:13 PM
Replacement Vehicle issued?	No
Job Card Number	24099232
Special Instruction to ARC, if any	TOWED \$ 40 / AIG -LKK
Prepared Date and Time	12/12/2018 2:57 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Toyota

P/P \$10,108.86/- 6days.

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$450.00
Total Spray Cost	\$2,592.00	\$750.00
Total Spare Part Cost	\$20,006.28	\$8,628.86
Total Other Cost	\$1,596.00	\$280.00
TOTAL COST	\$25,208.28	\$10,108.86 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	6.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	13/12/2018 11:13 AM	13/12/2018 4:38 PM
Signature		
Remarks	SUP = 1 DAYS	P/P photo before paint. supplementary item pls send e-mail to : naz@lkkauto.com (91803151)

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1906-0289	Invoice Number	
Quotation Date	19.06.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$1,014.00	\$450.00
Total Labour	\$1,014.00	\$450.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$100.00
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY APRON PANEL RH	\$180.00	\$0.00
TO RESPRAY FRONT PILLAR RH	\$180.00	\$0.00
RESPRAY WHEEL CAP	\$180.00	\$50.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$2,592.00	\$750.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TOP UP A/C GAS	\$120.00	\$20.00
TOWING CHARGE	\$56.00	\$40.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$100.00
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$0.00
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	\$120.00	\$0.00
TO TOP UP A/C GAS	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,596.00	\$280.00



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/06/2019

User ID : PohSuan

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace	CUT
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	nee
		52115470 50	SUPPORT, FR BUMPER RH	1.00	\$76.90	25.00	\$57.68	Replace	Replace	CRA
		61013470 10	PILLAR, FRONT BODY, RH	0.00	\$339.40	0.00	\$0.00	Replace	Not Given	X hu
		60117470 20	COVER SUB-ASSY, FRONT PILLAR, UPR RH	1.00	\$96.90	25.00	\$72.68	Replace	Replace	mis
		53801470 80	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	25.00	\$699.83	Replace	Replace	BUC
		75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace	nee
		53875470 70	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Check	X
		53851470 61	PAD, FR WHEEL RH	0.00	\$57.70	0.00	\$0.00	Replace	Not Given	X hu
		53827470 50	PROTECTOR, FR FENDER RH	0.00	\$90.40	0.00	\$0.00	Replace	Check	X
		53701471 11	APRON SUB-ASSY, FRONT FENDER, RH	0.00	\$944.20	0.00	\$0.00	Replace	Check	X
		42602471 80	CAP SUB-ASSY, WHEEL	1.00	\$175.80	100.00	\$0.00	Replace	Repair	f
		42611-47450	WHEEL, DISC FRONT	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X hu
		67001471 52	PANEL SUB-ASSY, FRONT DOOR RH	0.00	\$1,249.60	0.00	\$0.00	Replace	Not Given	X hu
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	nee
			COOLANT	0.00	\$12.32	0.00	\$0.00	Replace	Not Given	X hu
		164A2370 12	TANK, RESERVE SEALED W/O CAP	0.00	\$127.00	0.00	\$0.00	Replace	Not Given	X hu
		81210470 20	LAMP ASSY, FOG, RH	1.00	\$910.20	10.00	\$819.18	Replace	Replace	scr
		51420470 30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Not Given	X hu
		53112472 40	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Not Given	X hu
		53213470 50	SUPPORT, RADIATOR UPPER RH	0.00	\$76.70	0.00	\$0.00	Replace	Check	X hu
		53202479 01	SUPPORT S/A RH	0.00	\$237.00	0.00	\$0.00	Replace	Check	X hu
		81145476 91	UNIT, HEADLAMP, RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	CRA
		81016476 90	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check	X hu
		53807470 20	SEAL SUB-ASSY, RH	0.00	\$50.20	0.00	\$0.00	Replace	Not Given	X hu
		85319471 70	WIPER WASHER INLET	0.00	\$55.40	0.00	\$0.00	Replace	Not Given	X hu
		85315471 60	WIPER WASHER JAR	1.00	\$183.60	25.00	\$137.70	Replace	Replace	DD
		85330-58010	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	0.00	\$245.00	0.00	\$0.00	Replace	Check	X hu
		90099330 80	HOSE, WINDSHIELD WASHER	0.00	\$14.00	0.00	\$0.00	Replace	Check	X hu
		8211147J 21	WIRE, ENGINE ROOM MAIN	0.00	\$6,138.00	0.00	\$0.00	Replace	Not Given	X hu
		53301471 10	HOOD SUB-ASSY	1.00	\$938.40	25.00	\$703.80	Replace	Replace	BT
		53410471 30	HINGE ASSY, HOOD, RH	0.00	\$57.00	0.00	\$0.00	Replace	Check	X hu
		53420471 30	HINGE ASSY, HOOD, LH	0.00	\$57.00	0.00	\$0.00	Replace	Not Given	X hu
		55753470 90	WIPER GARNISH SHIELD, COWL WATER, RH	0.00	\$18.90	0.00	\$0.00	Replace	Not Given	X hu
		52021471 10	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Check	X hu
		52611471 40	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Check	X hu
		52102470 20	EXTENSION SUB-ASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Check	X hu
		52102470 20	REINFORCEMENT FRONT LOWER	0.00	\$238.50	0.00	\$0.00	Replace	Check	X hu
		52618470 90	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Check	X hu

		52127479 07	COVER, FR BUMPER RH	1.00	\$28.10	100.00	\$0.00	Replace	Repair	R
Total					\$20,099.82		\$5,276.44			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		53213470 50	SUPPORT, RADIATOR UPPER RH	1.00	\$76.70	25.00	\$57.53	Replace	Replace
		53410471 30	HINGE ASSY, HOOD, RH	1.00	\$57.00	25.00	\$42.75	Replace	Replace
		52021471 10	REINFORCEMENT FRONT UPPER	1.00	\$691.10	25.00	\$518.33	Replace	Replace
		81185476 91	UNIT, HEADLAMP, LH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace
		88710471 60	TUBE & ACCESSORY	1.00	\$574.40	25.00	\$430.80	Replace	Replace
Total					3,958.10		3,352.42		

BT

DEF

BT

SLR

BT

$$\begin{array}{r}
 8628.86 \\
 + 450.00 \\
 + 1030.00 \\
 \hline
 10,108.86
 \end{array}$$