



Date of Accident : 13 December 2018

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Miss Lim Xuan Ting

Date : 14 December 2018

Estimate To Repair SJM9466T - Honda Jazz 1.3LA
Chassis No : JHMGE68509S216243

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	tailgate lid <i>3rd/500 781.30</i>	\$ 952.50
02	2 ps	tailgate lid damper @ \$125.00 <i>17</i>	\$ 250.00
03	1 pc	tailgate lid lock <i>2nd/500 148.50</i>	\$ 274.90
04	1 pc	tailgate lid lock striker <i>11</i>	\$ 24.70
05	1 pc	tailgate lid weatherstrip <i>2nd</i>	\$ 192.30
06	1 pc	tailgate lid Jazz badge <i>11</i>	\$ 65.00
07	1 pc	tailgate lid outer garnish <i>17</i>	\$ 290.40
08	1 pc	tailgate lid outer garnish with H badge <i>11</i>	\$ 255.00
09	1 pc	rear licence plate lamp <i>17</i>	\$ 55.20
10	2 ps	rear lamps @ \$317.40 <i>17</i>	\$ 634.80
11	1 pc	rear end panel <i>3rd/500 296.60</i>	\$ 451.50
12	1 pc	rear end panel inner trim <i>2nd/pe</i>	\$ 265.30
13	1 pc	rear bumper <i>2nd 466.01</i>	\$ 508.50
14	2 ps	rear bumper side retainers @ \$41.50 <i>2nd</i>	\$ 83.00
15	2 ps	rear bumper side holders @ \$48.70 <i>2nd</i>	\$ 97.40
16	1 pc	rear bumper end splashshield cover <i>17</i>	\$ 99.80
17	2 ps	rear bumper screws @ \$5.00 <i>17</i>	\$ 10.00
		Less 20 % <i>502</i>	\$ 4,510.30
			\$ 902.06
			\$ 3,608.24
		<u>SPECIAL NETT ITEMS</u>	
18	1 pc	rear licence plate <i>17</i>	\$ 50.00
19	1 set	rear bumper parking sensor <i>2nd</i>	\$ 450.00
			\$ 500.00
		<u>LABOUR & MISC. CHARGES</u>	
20	8 ps	rear bumper clips @ \$4.50	\$ 36.00
01		To reinstall of rear bumper parking sensor.	\$ 150.00
02		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 100.00
03		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 150.00
04		To check electrical lighting concerned.	\$ 60.00
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AXA Insured's Veh No : SLX6400X
Date of Accident : 13 December 2018

Miss Lim Xuan Ting

Date : 14 December 2018

Estimate To Repair SJM9466T - Honda Jazz 1.3LA
Chassis No : JHMGE68509S216243

S/No	Quantity	Description	Amount
06		LABOUR & MISC. CHARGES	
		Putty and spray painting of the affected portion.	\$ 850.00
			\$ 2,346.00
		Total	\$ 6,454.24

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-1198.20
S.N-200
labm-1820

3218.20

800