



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2010 MERCEDES E250 (SJP6556X)

Date of Loss 8 December 2018

Time of Loss 18.15

Loss Description SJP6556X (INSD) C/W JHE9383

Comment

Workshop Details

Total Rebate Amount 39050

Nett Loss Amount \$15,950.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion * 51



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SJP6556X

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

25/02/2011



Mileage

110111

Age of Vehicle

7

Driver Details

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2010	2010
Make	MERCEDES	MERCEDES BENZ
Model	E250	E250 CGI A

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	WONG SAI HOW	
Date of Birth	21 April 1961	dd/mm/y
Age	57	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Type		▼	Occupation	Unknown	
Type of Paint			Education Qualification	Other	▼
Chassis No	WDD2120472A367442	WDD2120472A3	Driving Experience	30	
Engine No	27186030171943	27186030171943	Driver License #		
Engine Capacity		1796	License Type		▼
Sum Insured	0	0	License Issue Date		dd/mm/y 
Market Value	0	55000	License Expiration Date		dd/mm/y 
			Address	BLK 244 YISHUN RING ROAD, #07-1133, 760244, Singapore	
			Address type	Residential	▼

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Married	
Identification #	S2669466C	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

18/12/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

245/40R18

Rear Tyre Size

245/40R18

Front left side

CONTINENTAL6mm

Rear left side

CONTINENTAL6mm

Front right side

CONTINENTAL6mm

Rear right side

CONTINENTAL6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			REAR BUMPER COVER (WCP) (10%)			Damaged	809.6				809.6	Reviewing	
		2	1			L/R BUMPER GUIDE (WCP) (10%)			Serviceable	0	0	0	0	0	Deny	
		3	1			R/R BUMPER GUIDE (WCP) (10%)			Bent	23.1				23.1	Reviewing	
		4	1			L/R BUMPER SUPPORT			Serviceable	0	0	0	0	0	Deny	
		5	1			R/R BUMPER SUPPORT			Serviceable	0	0	0	0	0	Deny	
		6	1			REAR BUMPER C-MEMBER (WCP) (10%)			Bent	429				429	Reviewing	
		7	10			RR BUMPER CLAMP KIT (WCP) (10%)			Necessary	3.08				30.8	Reviewing	
		8	1			L/R OUTER SENSOR			Serviceable	0	0	0	0	0	Deny	
		9	1			R/R OUTER SENSOR (WCP) (10%)			Shorted	129.8				129.8	Reviewing	
		10	1			L/R CTR PARKING SENS			Serviceable	0	0	0	0	0	Deny	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		11	1			R/R CTR PARKING SENS			Serviceable	0	0	0	0	0	Deny	
		12	1			L/R OUT SPACER RING			Serviceable	0	0	0	0	0	Deny	
		13	1			R/R OUT SPACER RING			Serviceable	0	0	0	0	0	Deny	
		14	1			L/R CTR SPACER RING			Serviceable	0	0	0	0	0	Deny	
		15	1			R/R CTR SPACER RING			Serviceable	0	0	0	0	0	Deny	
		16	1			RR BUMPER W/HARNESS			Serviceable	0	0	0	0	0	Deny	
		17	1			LOWER REAR PANELLING			Repair	0	0	0	0	0	Deny	
		18	1			BOOTLID / TAILGATE			Repair	0	0	0	0	0	Deny	
		19	1			BOOT / TAILGATE HANDLE			Serviceable	0	0	0	0	0	Deny	
		20	1			STAR EMBLEM			Serviceable	0	0	0	0	0	Deny	
		21	1			REAR BADGE			Serviceable	0	0	0	0	0	Deny	
		22	1			BADGE "CGI"			Serviceable	0	0	0	0	0	Deny	
		23	1			REAR SCREEN BOND KIT (NPA)			Serviceable	0	0	0	0	0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR / BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		24	3			REAR SCREEN SUPPORTS (NPA)			Serviceable	0	0	0	0	0	Deny	
		25	1			R/R OUTER LAMP (WCP) (10%)			Broken	407				407	Reviewing	
		26	1			R/R INNER LAMP			Serviceable	0	0	0	0	0	Deny	
		27	1			R/R WING			Repair	0	0	0	0	0	Deny	
		28	1			SPARE WHEEL WELL			Serviceable	0	0	0	0	0	Deny	
		29	1			ADHESIVE SEALANT (NPA)			Serviceable	0	0	0	0	0	Deny	
		30	1			R/R FLOOR PANEL (NPA)			Repair	0	0	0	0	0	Deny	
		31	1			R/R INNER PILLAR			Repair	0	0	0	0	0	Deny	
		32	1			INN REAR PANEL TRIM			Serviceable	0	0	0	0	0	Deny	
		33	1			R/R WHEEL			Serviceable	0	0	0	0	0	Deny	
		34	1			R/R BUMPER UNDER GAR			Serviceable	0	0	0	0	0	Deny	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		PANEL / MECHANICAL	1147.5	0	0	Reviewing		
		2		PAINTWORK	607.5	0	0	Reviewing		

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		3		VISUAL ALIGNMENT WORK	81	0	0	Reviewing		
		4		CORR PROT INTERNAL 12 WU	0	0	0	Deny		
		5		PAINT / MATERIAL COSTS	218.64	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE	
			1	DAYS OF REPAIR : 7 DAYS	Reviewing			
			2	R/R BUMPER LOWER BRACKET (WCP) (10%)	Reviewing	10.45	CRACKED (SUPPLEMENTARY)	
			3	R/R TAILLAMP LOWER BRACKET (WCP) (10%)	Reviewing	41.8	CRACKED (SUPPLEMENTARY)	
			4	R/R FENDER LOWER AIR VENT (WCP) (10%)	Reviewing	16.5	CRACKED	
			5	R/R LWR FLOOR COVER	Reviewing	28.6	CRACKED (SUPPLEMENTARY)	
			6	R/R TYRE (\$250.00) (60%) (LOCAL REPAIR)	Reviewing	150	PUNCTURED	
			7	WINDSCREEN SEALANT	Deny	0	NOT NECESSARY	

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$3,731.29			Claim Amount	\$3,731.29			

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$1,829.30	\$1,829.30
Labour	\$2,054.64	\$2,054.64
Miscellaneous	\$247.35	\$247.35
Excess	-\$400.00	-\$400.00

Submit for Review