

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

17-Dec-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1667 D

1 pc	Tailgate lower garnish <i>CRA</i>	\$	362.61
1 pc	Tailgate weatherstrip <i>neu</i>	\$	276.98
1 pc	Emblem I30 <i>neu</i>	\$	27.80
1 pc	Emblem CRDI <i>neu</i>	\$	29.40
1 pc	Emblem Hyundai <i>neu</i>	\$	29.40
2 pcs	Rear bumper n/s & o/s reflector @\$107.50 ?	\$	215.00
1 pc	Rear bumper <i>neu</i>	\$	811.11
1 pc	Rear bumper sponge ?	\$	79.20
1 pc	Rear bumper reinforcement ?	\$	815.64
1 pc	Rear bumper reinforcement centre ?	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20 <i>neu</i>	\$	104.40

\$ 2,830.74

Less 20%

\$ 566.15

\$ 2,264.59

S/NETT

1 set	Rear bumper clips <i>neu</i>	\$	48.00
1 set	Reverse sensor <i>neu</i>	\$	280.00 220
1 set	Tailgate stickers <i>neu</i>	\$	100.00
1 set	Tailgate lower garnish clips <i>neu</i>	\$	38.00
1 pc	Rear number plate <i>CRA</i>	\$	50.00 35

Sundry

Towing Fee

To dismantle and replace reverse sensor and test system

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, tailgate etc

To putty and spray painting on the rear bumper, tailgate lower garnish, tailgate, end panel

To apply rustproofing on the repaired and replaced panels

\$ 20 50.00 ? ~~receipt~~

\$ 50.00 ? receipt

\$ ~~80.00~~ 60

\$ ~~180.00~~ 80

\$ ~~900.00~~ 700

\$ ~~800.00~~ 700

\$ 120.00

Total

\$ 4,960.59