

18/02/19

CC 4 /AIG1802

LKK:
IDAC:

INS. CASE OWNER:

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE:



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :\$

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES/ NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

21/1/19
Amher

25/7/19

PM 8075A

CHK 11926

Pending for PR, CONFIRMING VERSION.

Pass file to submit WP. Informed ALG.
TP pass file to lawyers as liability
unclear.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: L15 \$5 2,600

(5 days) Reduction: 48 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability: %

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost: \$5

Loss of Rental (LOR): \$5

(x days)

Loss of Use (LOU): \$5

(S x days)

Loss of Income (LOI): \$5

(S x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐ [Tick only one]

GIA/LTA Search: \$5

Medical: \$5

Disbursement: \$5

(e.g. Tow/ Independent)

Legal Cost: \$5

Total: \$5

Global Sum \$5:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: WP

3) Survey fee: \$250

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: \$5

Name 1:

Payee 2: (Strike if N.A.) \$5

Name 2:

Payee 3: (Strike if N.A.) \$5

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18022666/T1eb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 18-12-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGK 1192G	Veh. Inspected	FU 8075A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	18/12/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/12/2018	Inspection Date	18/12/2018	
Survey held at	A.S. PHOON PTE LTD BLK 36 TOH GUAN ROAD EAST #01-35 SINGAPORE 608580			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



潘發展私人有限公司
A. S. PHOON PTE LTD
'cos no one else

6841 2360

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FU8075A YAMAHA RXZ 135 REPAIR ESTIMATE (18DEC2018)

ITEM	DESCRIPTION	AMOUNT (SGD)
1	FRONT WHEEL ASSY	\$280.00 ✓BT
2	FRONT WHEEL AXLE	\$25.00 ✓BT
3	FRONT WHEEL BEARING X2	\$40.00 ✓NEC
4	DUST COVER X2	\$16.00 ✓NEC
5	FRONT FENDER	\$68.00 ✓BRV
6	FRONT FORK ASSY R/H & L/H @\$320	\$640.00 ✓BT
7	STEM STEERING	\$145.00 ✓BT
8	CONE BEARING SET	\$65.00 ✓NEC
9	HEADLAMP ASSY	\$120.00 ✓CB
10	FRONT COWLING	\$110.00 ✓CUT
11	FRONT SIGNAL @\$48	\$96.00 ✓NNX
12	STAY . FRONT COWLING	\$80.00 ✓NNX
13	FRONT LICENCR PLATE	\$12.00 ✓CUT
14	WINDSCREEN	\$48.00 ✓CUT
15	METER ASSY	\$390.00 ✓NNX
16	STAY METER	\$48.00 ✓NNX
17	BALABCR	\$50.00 ✓CUT
18	HANDLEBAR	\$170.00 ✓BT
19	CLUTCH LEVER	\$18.00 ✓CUT
20	SIDE MIRROR	\$50.00 ✓CUT
21	GEAR PEDAL	\$68.00 ✓BT
22	SIDE STAND	\$35.00 ✓BT
23	FRONT FOOTREST LH	\$48.00 ✓CUT
24	FOOTREST BRACKET L/H	\$85.00 ✓NNX
25	FUEL TANK	\$390.00 ✓NNX
26	SIDE COVER LH	\$85.00 ✓CB
27	REAR TOP BOX	\$320.00 ✓CUT \$380
28	TOP BOX BRACKET	\$120.00 ✓NNX
29	REAR LICENCE PLATE	\$28.00 ✓BT
30	TAIL COVER	\$20.00 ✓CB
31	REAR FOOTREST L/H	\$28.00 ✓NNX
32	WORKMANSHIP	\$350.00 ✓



潘發展私人有限公司

A. S. PHOON PTE LTD

'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FU8075A YAMAHA RXZ 135 REPAIR ESTIMATE (18DEC2018)

ITEM	DESCRIPTION	AMOUNT (SGD)
33	TRANSPORTATION TP-IDAC-BIKESHOP @\$50	\$100.00 ✓
34	BODY CHASSIS REPAIR	\$350.00 300
35	TRANSPORTATION X2 @ \$50	\$100.00 80
36	SPRAY PAINTING	\$450.00 200.00
TOTAL		\$5,048.00

L/S → \$2,600.00

05 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Fu 8075A

R77

Front wheel assy bt ~~photo~~
Front wheel axle bt
Bearing x2 m

Rust cover x2
Front fender
Front fork assy R & L?

Stem steering?
cone bearing set?

Headlamp on

Front cowling out

Stay, front cowling?

Front license plate out
windscreen out

Balance out
Handlebar bt
Clutch lever out
Side mirror out

Gen pedal bt

Side stand bt

Front footrest LH out
" " bracket LH?

Fuel tank R7.

Side cover LH m

Rea top box 280
— bracket?

Rea license plate bt

Tail cover on
250
Workmanship 350

Transportation TP-Idee-shop
@50 \$100 ft
Body chassis repair → 350
200

Transportation 2 way to
Repair chassis 80
@50 \$150

Tamplin 97495449

lump sum

Resing after repair

05 days

transfer @ 1000 auto con.

18/12/18 @ 1715



Fu 8075A

R77

Front wheel assy ~~bt~~ ~~photo~~
Front wheel axle ~~bt~~
Bearing x2 ~~bt~~

Rust cover x2
Front fender
Front fork assy R & L?

Stem steering?
cone bearing set?

Headlamp on

Front cowling out

Stay, front cowling?

Front licence plate out
windscreen out

Balance out
Handlebar ~~bt~~
Clutch lever out
Side mirror out

Gen pedal ~~bt~~
Side stand ~~bt~~

Front footrest LH out
" " bracket LH?

Fuel tank RY

Side cover LH on

Rear top box ^{GRV} ~~wt~~ 280
— bracket?

Rear licence plate ~~bt~~

Tail cover on 250

Workmanship 350

Transportation TP-Idae-shop

Body chassis rep ^{@50 \$100} 350
200

Transportation 2 way to

Repair chassis 80
@50 \$150

Tamfil 97495429

Limf 5m

Resurvey after repair

05 days

tamfil@lkkauto.com

18/12/18 & 17/15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- Pre repair inspection request - FU8075A VS SGK1192G (OI) DOA: 06/12/2018

From: Azlan, Syazairdina
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Hor, Yinrul, Chan, Yoke Shi, Kaur, Baljit
Sent: Monday, 17 December, 2018 4:51:36 PM
Attachments:  tmo6508.ctf

Hi,

Please refer to the enclosed request from Tan Chin Hoe & Co.

Claim no : 5773944679SG003
Case Owner : CHEE HENG LOH

If you have any queries/concerns, please let us know.
Kindly assist to assign Mohamad Taufikh as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

17.12.2018 @ 5:18pm
Mr. Kee whin

From: sheena@tanchinhoe.com.sg [mailto:sheena@tanchinhoe.com.sg]

Sent: Monday, December 17, 2018 4:15 PM

To: Azlan, Syazairdina

Cc: 'kee kee'

Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGK1192G AND FU8075A ON 06/12/2018

WITHOUT PREJUDICE

Dear Sirs

- i. We refer to your email of even date.
- ii. Our client's workshop agrees to Mr Mohamad Taufikh from LKK Auto Consultants Pte Ltd to carry out the survey but reserve their position on whether to agree to Mr Mohamad Taufikh being the SJE at the appropriate time.

Sheena Ng, Paralegal
TAN CHIN HOE & CO
24 Raffles Place
#24-01 Clifford Centre
Singapore 048621
Tel: 65382687
Fax: 65380287
Email: sheena@tanchinhoe.com.sg

This email is subject to legal privilege. If you are not the intended recipient, please delete this email and all its attachments from your computer immediately.

----- Forwarded Message -----

From: "Azlan, Syazairdina" <Syazairdina.Azlan@aig.com>

Date: Dec 17, 2018 10:17 AM

Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGK1192G AND FU8075A ON 06/12/2018

To: Tan Chin Hoe & Co <info@tanchinhoe.com.sg>

Cc: "Fong, Andy-SY" <Andy.SY.Fong@aig.com>, "Chin, Lee-Ying" <Lee-Ying.Chin@aig.com>, "Abu Kassim, Noor Mariesa" <NoorMariesa.AbuKassim@aig.com>, "Md Ishak, Mohd Imran" <Imran.Ishak@aig.com>, "Lim, Sheng Yang" <ShengYang.Lim@aig.com>, "Mithoosingh, Aashweenjeetkaur" <Aashweenjeetkaur.Mithoosingh@aig.com>, "Hor, Yinrul" <Yinrul.Hor@aig.com>, "Chan, Yoke Shi" <yokeshi.chan@aig.com>, "Kaur, Baljit" <Baljit.Kaur@aig.com>



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือสารที่ผ่านการเข้ารหัสเพื่อความปลอดภัยของข้อมูล กรุณาเปิดไฟล์แนบก่อน

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-12-24 10:17 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairdina.Azlan@aig.com

To: info@tandinhoe.com.sg

Cc: Andy-SY.Fong@aig.com, Lee-

Ying Chin@aig.com, NoorMarisa.AbuKassim@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Yinnul.Hor@aig.com, yokeshi.chan@aig.com, Bal

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGK1192G AND FU8075A, ON 06/12/2018

Date: Mon, 17 Dec 2018 02:17:20 +0000

Without Prejudice

Your Reference : RT/473/2018/sm

Our Reference : 5773944679SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Chin, Ann

Sent: Monday, December 17, 2018 10:04 AM

To: PRDSG.FNOL

Cc: Chan, Yoke Shi; Abu Kassim, Noor Marisa; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina; Md Ishak, Mohd Imran; Tan, Lily (AIG); Zhou, Aiping; Ho, Choon-Poh; Quek, Joyceline-CH

Subject: 05#SGK1192G#002,002#DEFAULT

TAN CHIN HOE & CO
ADVOCATES & SOLICITORS
GST No. & UEN: 53131160X

24 Raffles Place
#24-01 Clifford Centre
Singapore 048621

Tel: 6538 2687
Facsimile: 6538 0287
Email: info@tanchinhoe.com.sg

Your Ref: RT/473/2018/sn

Our Ref:
13 December 2018

INJURY CLAIM

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
Singapore 079120

FAX NO: 68357416

PROPERTY DAMAGE CLAIM

Attn: Claims Department

Dear Sirs

ACCIDENT INVOLVING FU8075A AND SGK1192G ON 6 DECEMBER 2018

1. We act for Mr Muhammad Nazrul Bin Mohd Noor who was involved in an accident caused solely by the negligence of your insured, the driver of SGK1192G. Our client was injured as a result of the accident.
2. We will revert with our client's quantification shortly.
3. In the meantime, our client's motorcycle is at the premises of A S Phoon Pte Ltd at Blk 36 Toh Guan Road East #01-35 Singapore 608580. Please contact Mr Kee at 65150770 for an appointment to survey the motorcycle within 2 days, failing which A S Phoon Pte Ltd will proceed to carry out the repairs.
4. We also enclose a copy of our client's traffic police report for your attention.
5. Please let us have a copy of your insured driver's accident statement/traffic police report, if any.

Yours faithfully



cc 1. client

2. Allswell Leasing & Limousine Pte Ltd
100 Jalan Sultan
#02-41 Sultan Plaza
Singapore 199001
3. A S Phoon Pte Ltd
Fax No: 65150779
Attention: Mr Kee

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Dec 2018 Edit Reg		17 Dec 2018 00:00 Edit Adj Rpt	S\$2,600.00 Edit Estimates	S\$2,600.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	ALLSWELL LEASING & LIMOUSINE PTE LTD, Co. Reg. No.: 201432541Z		
Main Claimant:	RADUAN, ID: S7330770H		
Vehicle Reg. No.:	FU8075A	Date of Loss:	06/12/2018 00:00 - :59 [199 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5773944679SG	Policy/Cover Note No.:	0999994369 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	SGK1192G	Policy No. (Claimant):	MSD/VMT/18-377510-CA
		Excess:	
Repairer:	A.S. Phoon Pte Ltd (Toh Guan) Blk 36 Toh Guan Road, East Enterprise Hub #01-35, 608580 Jurong East - Tel: 6515 0770		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tee, Chee-Wah] Chee-Wah.Tee@aig.com		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 28/12/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (19/12/2018): Request to upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***FU8075A (5773944679SG)**
[SGK1192G]
TP
RADUAN
Dec 6 2018 12:00AM
[ALLSWELL LEASING & LIMOUSINE PTE LTD]
A.S. Phoon Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/08/19 09:01	General View	 Load JPG	☒
2	02/08/19 09:01	General View	 Load JPG	☒
3	02/08/19 09:01	General View	 Load JPG	☒
4	02/08/19 09:01	General View	 Load JPG	☒
5	02/08/19 09:01	General View	 Load JPG	☒
6	02/08/19 09:01	General View	 Load JPG	☒
7	02/08/19 09:01	General View	 Load JPG	☒
8	02/08/19 09:01	General View	 Load JPG	☒
9	02/08/19 09:01	General View	 Load JPG	☒
10	02/08/19 09:01	General View	 Load JPG	☒
11	02/08/19 09:01	General View	 Load JPG	☒
12	02/08/19 09:01	General View	 Load JPG	☒
13	02/08/19 09:01	General View	 Load JPG	☒
14	02/08/19 09:01	General View	 Load JPG	☒
15	02/08/19 09:01	General View	 Load JPG	☒
16	02/08/19 09:01	General View	 Load JPG	☒
17	02/08/19 09:01	General View	 Load JPG	☒
18	02/08/19 09:01	General View	 Load JPG	☒
19	02/08/19 09:01	General View	 Load JPG	☒
20	02/08/19 09:01	General View	 Load JPG	☒
21	02/08/19 09:01	General View	 Load JPG	☒
22	02/08/19 09:01	General View	 Load JPG	☒
23	02/08/19 09:01	General View	 Load JPG	☒
24	02/08/19 09:01	General View	 Load JPG	☒
25	02/08/19 09:01	General View	 Load JPG	☒
26	02/08/19 09:01	General View	 Load JPG	☒
27	02/08/19 09:01	General View	 Load JPG	☒
28	02/08/19 09:01	General View	 Load JPG	☒
29	02/08/19 09:01	General View	 Load JPG	☒
30	02/08/19 09:01	General View	 Load JPG	☒
31	02/08/19 09:01	General View	 Load JPG	☒
32	02/08/19 09:01	General View	 Load JPG	☒
33	02/08/19 09:01	General View	 Load JPG	☒
34	02/08/19 09:01	General View	 Load JPG	☒
35	02/08/19 09:01	General View	 Load JPG	☒

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	02/08/19 09:01	General View	 Load JPG	✓
37	02/08/19 09:01	General View	 Load JPG	✓
38	02/08/19 09:01	General View	 Load JPG	✓
39	02/08/19 09:01	General View	 Load JPG	✓
40	02/08/19 09:01	General View	 Load JPG	✓
41	02/08/19 09:01	General View	 Load JPG	✓
42	02/08/19 09:01	General View	 Load JPG	✓
43	02/08/19 09:01	General View	 Load JPG	✓
44	02/08/19 09:01	General View	 Load JPG	✓
45	02/08/19 09:01	General View	 Load JPG	✓
46	02/08/19 09:01	General View	 Load JPG	✓
47	02/08/19 09:01	General View	 Load JPG	✓
48	02/08/19 09:01	General View	 Load JPG	✓
49	02/08/19 09:01	General View	 Load JPG	✓
50	02/08/19 09:01	General View	 Load JPG	✓
51	02/08/19 09:01	General View	 Load JPG	✓
52	02/08/19 09:01	General View	 Load JPG	✓
53	02/08/19 09:01	General View	 Load JPG	✓
54	02/08/19 09:01	General View	 Load JPG	✓
55	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
56	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
57	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
58	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
59	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
60	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
61	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
62	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
63	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
64	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
65	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
66	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
67	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
68	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
69	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
70	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
71	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
72	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
73	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
74	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
75	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
76	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
77	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
78	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
79	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
80	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
81	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
82	02/08/19 09:02	Reinspection Photo	 Load JPG	✓
83	02/08/19 09:02	Reinspection Photo	 Load JPG	✓

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	☒
			Thumbnail	Print

Documentation

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1 per page ▼	☒
1	18/12/18 15:09	EMAIL FROM AIG DD 17122018	Thumbnail	Print
2	18/12/18 15:09	NOTICE & POLICE REPORT	1 Load PDF	
3	20/12/18 09:27	TP ESTIMATE- MARKED	1 Load PDF	
4	07/01/19 10:06	TP GIA REPORT	1 Load PDF	
5	02/08/19 15:01	EMAIL	1 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	1 Load PDF	
1	19/12/18 11:58	OI GIA REPORT	Thumbnail	Print
			1 Load PDF	

Documents Checklist**DOCUMENTS CHECKLIST**

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18022666/T1KB3S2

Date: 02/08/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994369
Claimant Vehicle No :	FU8075A	Insured Vehicle No :	SGK1192G
Date of Loss:	06/12/2018	Nature of Claim:	TP
		Claim No:	5773944679SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FU8075A	Engine No:	3BS264234
Make & Model:	YAMAHA RXZ, 133cc (M)	Chassis No:	ZMC264234
Reg. Date:	17/04/2002 (Man. Year: 2002)	Odometer:	28228 km
Colour:	Blue		
Engine Capacity:	133 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	80/80-18	Rear Tyre Size:	3.00-18
Front Left Side:	FKR 5 mm	Rear Left Side:	Metzeler 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,698.00	2,421.00	1,277.00	34.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	930.00	420.00	31.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,048.00	3,351.00	1,697.00	33.62
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	5,048.00	2,600.00	2,448.00	48.49
+ GST 7.00/7.00% (S\$)	353.36	182.00	171.36	48.49
Nett Amount (S\$)	5,401.36	2,782.00	2,619.36	48.49

INSPECTION

Date of Assignment:	17/12/2018	
Date Inspected:	18/12/2018	Inspected At: A.S. Phoon Pte Ltd (Toh Guan) Blk 36 Toh Guan Road, East Enterprise Hub #01-35 Singapore 608580
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=773690&extid=290594&CFID=56931797&C... 1/4

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WHEEL ASSY			
2	1		*FRONT WHEEL AXLE	Bent	280.00 F	*280.00 F
3	2		*FRONT WHEEL BEARING	Bent	25.00 F	*25.00 F
4	2		*DUST COVER	Necessary	40.00 F	*40.00 F
5	1		*FRONT FENDER	Necessary	16.00 F	*16.00 F
6	2		*FRONT FORK ASSY R/H & L/H	Broken	68.00 F	*68.00 F
7	1		*STEM STEERING	Bent	640.00 F	*640.00 F
8	1		*SET CONE BEARING	Bent	145.00 F	*145.00 F
9	1		*HEADLAMP ASSY	Necessary	65.00 F	*65.00 F
10	1		*FRONT COWLING	Chipped	120.00 F	*120.00 F
11	2		*FRONT SIGNAL	Cut	110.00 F	*110.00 F
12	1		*STAY, FRONT COWLING	Not Necessary	96.00 F	*- F
13	1		*FRONT LICENCE PLATE	Not Necessary	80.00 F	*- F
14	1		*WINDSCREEN	Cut	12.00 F	*12.00 F
15	1		*METER ASSY	Cut	48.00 F	*48.00 F
16	1		*STAY METER	Not Necessary	390.00 F	*- F
17	1		*BALANCER	Not Necessary	48.00 F	*- F
18	1		*HANDLEBAR	Cut	50.00 F	*50.00 F
19	1		*CLUTCH LEVER	Bent	170.00 F	*170.00 F
20	1		*SIDE MIRROR	Cut	18.00 F	*18.00 F
21	1		*GEAR PEDAL	Cut	50.00 F	*50.00 F
22	1		*SIDE STAND	Bent	68.00 F	*68.00 F
23	1		*FRONT FOOTREST LH	Bent	35.00 F	*35.00 F
24	1		*FOOTREST BRACKET L/H	Cut	48.00 F	*48.00 F
25	1		*FUEL TANK	Not Necessary	85.00 F	*- F
26	1		*SIDE COVER LH	Not Necessary	390.00 F	*- F
27	1		*REAR TOP BOX	Cracked	85.00 F	*85.00 F
28	1		*TOP BOX BRACKET	Cut	320.00 F	*280.00 F
29	1		*REAR LICENCE PLATE	Not Necessary	120.00 F	*- F
30	1		*TAIL COVER	Bent	28.00 F	*28.00 F
31	1		*REAR FOOTREST L/H	Cracked	20.00 F	*20.00 F
				Not Necessary	28.00 F	*- F

F=Franchise part.

Total Parts (S\$)	3,698.00	2,421.00
-------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WORKMANSHIP.	New	350.00	350.00
2	TRANSPORTATION TP-IDAC-BIKESHOP.	New	100.00	100.00
3	BODY CHASSIS REPAIR.	New	350.00	200.00
4	TRANSPORTATION.	New	100.00	80.00
5	SPRAY PAINTING.	New	450.00	200.00
Gross Labour Cost (S\$)			1,350.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >