

Fu 8075A

RX7

Front wheel assy ~~bt~~ ~~photo~~
Front wheel axle ~~bt~~
Bearing x2 ~~in~~

Rust cover x2
Front fender
Front fork assy ~~R&L~~?

Stem steering?
cone bearing set?

Headlamp ~~on~~

Front cowling ~~out~~

Stay, front cowling?

Front license plate ~~out~~
windscreen ~~out~~

Balance ~~out~~
Handlebar ~~bt~~
Clutch lever ~~out~~
Side mirror ~~out~~

Gen pedal ~~bt~~
Side stand ~~bt~~

Front footrest LH ~~out~~
" " bracket LH?

Fuel tank ~~RX~~

Side cover LH ~~on~~

^{GIVI} ~~out~~
Rear top box 280
— bracket?

Rear license plate ~~bt~~

Tail cover ~~on~~
250

Workmanship 350

Transportation TP-Idae-shop

@50 \$100 ~~ft~~
Body chassis repair → 350
200

Transportation 2 way to

Repair chassis 80
@50 \$150

Tanaka 97495749

Wangsun

Resurvey after repair

05 days

tanaka@kanto.com

18/12/18 @ 1715

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: