

TP INSURER:

India International Insurance Pte Ltd (HQ)

Comfort Transportation Pte Ltd

Singapore

Claimant Insurer:

NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:

THIRD PARTY

Ref. No: Date of Loss: TP020122018

Policy No:

Vehicle Reg. No.:

SBT433E

Driveable?

16/12/2018

Party At Fault:

UNKNOWN

Driver (TP):

TAN TAK WEI, PHILIP

HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD

Vehicle Reg. Date:

23/05/2017

ke/Model: Vehicle Colour:

4DR (A)

RED

0 KM

Engine No:

G4FGHU691774

Chassis No:

KMHD841CMHU462637

Odometer:

Paint Type:

List Item Discount:

25.00 %

Total Loss?

NO

Est. Duration of Repair (day)

ON 16.12.2018 AT ABOUT 1535HRS, I WAS TRAVELLING STRAIGHT IN MY VEHICLE (A: SBT433E) ALONG 3RD LANE OF CTE TOWARDS EXIT 2. OUT OF A SUDDEN, A

VEHICLE (B: SHA2271X) WHICH WAS TRAVELLING ON MY RIGHT SIDE OF THE LANE, SWERVED ABRUPTLY INTO MY LANE. I TRIED TO REACT AND SWAYED AWAY TO THE LEFT WHERE THE EXIT TO CLEMENCEAU AVENUE AND ALSO SOUND MY HORN BUT VEHICLE B FAILED TO KEEP BACK AND HIT ONTO THE RIGHT FRONT PORTION ON

Description of Accident/Loss

MY VEHICLE VIGOROUSLY. THE DRIVER OF VEHICLE B DID NOT STOP, BUT HE CONTINUED HIS JOURNEY. I CHASED AFTER HIS VEHICLE AND EVENTUALLY, I SAW HIM PUT UP HAZARD LIGHT TO STOP AT THE TUNNEL EXIT. VEHICLE A (SBT433E): 1 FEMALE PASSENGER ON BOARD, VEHICLE B (SHA2271X): 2 PASSENGERS ON

BOARD.

Present Location:

TAN LIM MOTOR PTE LTD (DEFU)

| | LKK Auto Consultants hence | notify | |
|------------------------------|---|-------------------|-------------------|
| COST OF CLAIMS | the Repairer of the following: • To resurvey before/after spray pair | ating | Amount |
| Parts Miscellaneous Items | To display damaged part(s) during resurvey Parti prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and | | 2,253.55 10.00 |
| Labour Paintwork Labour | | | 840.00 900.00 |
| Towing | is subject to final approval from ins | urance Company | 0.00 |
| | Acknowledged by Repairer | Gross Total (S\$) | 4,003.55 |
| | Signature: | + GST 7.00% (S\$) | 280.25 |
| | Date: | Nett Amount (S\$) | 4,283.80 |

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 17 Dec 2018)

Parts:

HYUNDAI ELANTRA 1.6 ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour:

(Price-denominated Standard List) Repairer's

Print Code: Tan Lim Motor Pte Ltd/SBT433E/17/12/2018 12:39

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF

ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

| No. | Qty Part No. | Particulars | %Disc | %Depr | Amount |
|-----|-----------------------------|---------------------------------------|---------|-------|-------------|
| 1 | 1 | *front bumper Deep cu? | 25.00 | 0.00 | *443.00 FL |
| 2 | 1 | *o/s front bumper side retainer | 25.00 | 0.00 | *34.00 FL |
| 3 | 1 | *o/s front fender D/Led | 25.00 | 0.00 | *966.80 FL |
| 4 | 1 | *o/s front fender inner cowling | 25.00 | 0.00 | |
| 5 | 6 | *front fender inner cowling clips ACC | 25.00 | 0.00 | *21.00 FL |
| 6 | 1 | *o/s side mirror 9 read | 25.00 | 0.00 | *638.60 FL |
| 7 | 1 | *o/s side mirror cover | 25.00 | 0.00 | *80.00 FL X |
| 8 | 1 | *o/s front wheel rim (47 4505.N | 0 | 0.00 | *550.00 FS |
| D' | anchise part. S=SpcNett. L= | ListItemDisc. | | | 2.821.40 |
| | | Sub Total (S | | | |
| | | - List Item Discount on L Items (S | \$) | | 567.85 |
| | | Total Parts (S | (\$) | | 2,253.55 |

Tan Lim Motor Pte Ltd/SBT433E/17/12/2018 12:39. Not valid without Reference section. Generated using Merimen e-Claims IEAS

2103:4

No Qty Particulars

Amount

Miscellaneous Items

OD/TP Case (Insurer) 1

10.00 ner

Sub Total (S\$)

10.00

| | | - |
|--------|---------|--------|
| Ectima | toe on | Labour |
| | 125 011 | Labour |

| No | Particulars | Lab.Type | | Amount |
|------------------|---|----------|-----|--------|
| Paintwork Labour | | | | 000.00 |
| 1 | Putty and spray painting of the affected portion. | New | 000 | 900.00 |
| Lab | our Items | | | V |
| 2 | To transfer of tyre, rim and on wheel balancing. | New | 11 | 50.00 |
| 3 | To check steering geometry and computer wheel alignment. | New | | 60.00 |
| 4 | To check electrical lighting concerned. | New | , . | 30.00 |
| 5 | Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. | New | 400 | 700.00 |

Gross Labour Cost (S\$)

1,740.00

Tan Lim Motor Pte Ltd/SBT433E/17/12/2018 12:39. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1080

51 Defu Lane 10 Singapore 539216 Tel: 6858 5151 (24 hours) Fax: 6858 0877 email@tlmotor.com.sg www.tlmotor.com.sg

Co. Reg. No.: 199503965M GST Reg. No.: M2-8922054-2

P- 1577:55 S.N- 460 Jahr-1090 3127:53