

INSD001

INS. CASE OWNER:

CC 4 / III 1802

LKK

IDAC

Surveyor:

Kenneth

DOI:

ASSIGNMENT

27/11/18

Date / Time:

18/11/18

Registered in Merimen:

17/11/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 8AT4B

Name of Insured:

Lip

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A.:

16/12/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: Wan Hui Kim

Driver Tel No.:

(V/L (YES) / NO)

Claim No.:

MUTIGW51V

Policy No.:

MLO00015

Make / Model:

HUMMER

Place of Accident:

HONGKONG WISERS

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

sup 5802R

INSRS:
WSP:
Tel:
Liability:
RMKS:Mini
YangINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

24/11/18

sup 5802R

SHC 8AT4B-X

UT 8/11/18 File pass to Typist Mandate

22/11/18 FILE PASS TO ISP TO CLOSE

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

1 days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

(\$5)

\$5 1605.00

Loss of Rental (LOR):

(\$5)

\$5 513.60

(4 days) x \$120

Loss of Use (LOU):

\$5

(5 x days)

Loss of Income (LOI):

\$5

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost

\$5

Total:

\$5

2118.60

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

2118.60

Name 1:

Pau Yang Motor Pte Ltd

Payee 2 (Strike if N.A.):

\$5

Name 2:

Payee 3 (Strike if N.A.):

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:


24/11/19

Kenneth

ASSIGNMENT

Veh No: SIP 5803R Yr Regn: 06, 17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Wagon
 Make: Toyota cc 1986
 Colour: M.P. White AC: Insured / Std / NI / NA
 Sp. Reading: 30893 TRadio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 85460 0100878
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/65R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front
 R/Bal. 7 mm Rear
 L/Bal. 7 mm
 D.O.A. 16/12/18 D.O.I. 27/12/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Acc
 The U/C / Chassis frame / Body Structure affected due to collision.

From _____ Date: _____
 Estimated Cost: _____
 OD C WS / TP RES / OD RES / EVA / INV / MV
 To Report Vehicle No: _____
 All Workshop m/s 1711 Yang
 of _____
 Insured: _____
 Policy No: _____
 Closing: _____
 Surplus: _____ Excess: _____
 (Check Record)
 Make: _____



(For condition)
 Remarks: Veh had commenced its
 at the time of inspection.
 Bal. of Assets Value: _____
 IDAC Report: _____ Consistent? : Yes or No
 GVA: _____ Consistent? : Yes or No
 Est. value: 03 days Res.: Yes or No
 Lump Sum: 20 % 3 Val.: Yes or No
 CA: REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date: _____ Action / Instruction
28/12 File note to Carhouse
2/5 - \$1500 (Red \$3837.45 / 72%)

Date/Time: _____
☐ : Prelim. Report
☐ : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 \$ - RS. \$ _____
 Photos _____
 Others _____
 TOTAL _____

Report Form: _____
 Lump Sum: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18022673/pb3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 18-12-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8974B	Veh. Inspected	SLP 5803R	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	18/12/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	16/12/2018	Inspection Date		
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Kp

20/12/18
(Thursday)
after 12am

辉 陽 汽 車 有 限 公 司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

16/12/2018

Owner: SIM HONG HOON

ESTIMATE TO REPAIR TOYOTA HARRIER 2.0 - SLP5803R

1pc	rear bumper	R	\$ 1,718.40	X
1pc	rear bumper LH side retainer 1	L	\$ 132.25	X
1pc	rear bumper LH side retainer 2	L	\$ 131.25	X
1pc	rear LH absorber	SL	\$ 529.50	X
1pc	rear LH knuckle arm	R	\$ 430.20	X
1pc	rear LH knuckle bearing	R	\$ 229.50	X
1pc	rear LH top arm	L	\$ 385.50	X
			<u>\$ 3,556.60</u>	
	less 25%		<u>\$ 889.15</u>	
			<u>\$ 2,667.45</u>	

1pc rear LH sport rim P11 R s.nett \$ 680.00 ✓

remove & refit rear undercarriage	\$ 380.00	100%
wiring	\$ 60.00	100%
spray painting	\$ 800.00	240%
labour charges	\$ 750.00	150%
Total	<u>\$ 5,337.45</u>	

Not Authorised
61 Pay 81500L
Recovery After Paid

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



辉 陽 汽 車 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

21/12/18
(Thursday)
after 10am

16/12/2018

Owner: SIM HONG HOON

ESTIMATE TO REPAIR TOYOTA HARRIER 2.0 - SLP5803R

1pc	rear bumper	R	\$ 1,718.40	X
1pc	rear bumper LH side retainer 1	L	\$ 132.25	<
1pc	rear bumper LH side retainer 2	L	\$ 131.25	X
1pc	rear LH absorber		\$ 529.50	?
1pc	rear LH knuckle arm		\$ 430.20	?
1pc	rear LH knuckle bearing		\$ 229.50	?
1pc	rear LH top arm		\$ 385.50	?
			\$ 3,556.60	
less 25%			\$ 889.15	
			\$ 2,667.45	

1pc rear LH sport rim P/R N/s.nett \$ 680.00 ✓

remove & refit rear undercarriage	\$ 380.00	?
wiring	\$ 60.00	1d
spray painting	\$ 800.00	240d
labour charges	\$ 750.00	15d
Total		
	\$ 5,337.45	

Not authorized
U/Sy 8?
Assembly After Paint
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature



Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	18 Dec 2018 15:35	Cim Veh Model Changed	(205317) TOYOTA HARRIER 2.0 Elegance (A).	[A] Lau Shu Pei
2	18 Dec 2018 15:35	Cim Created	Reg No: SLP5803R, Acct Date: 2018/12/16, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ), Workshop: Hui Yang Motor Pte Ltd (HQ)	[A] Lau Shu Pei
3	18 Dec 2018 15:35	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	18 Dec 2018 15:35	Adj Next Rpt Changed	Next Rpt:Final Rpt, Due Date:2018/12/28	[A] Lau Shu Pei
5	18 Dec 2018 15:35	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] Lau Shu Pei
6	18 Dec 2018 15:36	Label Added	(30651):Vehicle Not In,(30653):Direct Settlement.	[A] Lau Shu Pei
7	18 Dec 2018 15:36	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Lau Shu Pei
8	24 Dec 2018 09:54	Cim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
9	24 Dec 2018 09:54	Cim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
10	28 Dec 2018 11:27	Label Removed	(30651):Vehicle Not In.	[A] Lau Shu Pei
11	02 Jan 2019 11:30	Adj Mandate Request	Cur,Req:0.00:PODS Liability: 100% Remarks: Insured driver turned out from minor road and collided with third party who was on main road.	[A] CHEW HSIAO TONG
12	02 Jan 2019 14:15	Adj Next Rpt Changed	Next Rpt:Final Rpt, Due Date:2018/12/28, Mandate Remarks: Agreed to do direct settlement. Please revert with your quantum advice	[I] Sundari Nagarajan
13	02 Jan 2019 14:15	Adj Mandate Set	Approved:0.00:Agreed to do direct settlement. Please revert with your quantum advice	[I] Sundari Nagarajan

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
No billing items							

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Wednesday, 2 January 2019 7:22 PM
To: 'hui_yang_motor@hotmail.com'
Subject: Your ref: SLP 5803R *Our Ref: CC4/III18022673/Kpb3 [ACCIDENT INVOLVING SHC 8974B(III) & SLP 5803R ON 16/12/2018]

Your ref: **SLP 5803R**
Our Ref: CC4/III18022673/Kpb3

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING SHC 8974B(III) & SLP 5803R ON 16/12/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLP5803R (MCT18120512)
[SHC8974B]**

TP

SIM HONG HOON MRS CHEUNG KAI HO
Dec 16 2018 6:00PM
[COMFORT TRANSPORTATION PTE LTD]
Hui Yang Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on **29/04/2019 11:19 AM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2118.60) - SLP5803R - Claim Handler: Pooi Chin Han Daniel

Approved:2118.60:

DOCUMENTS SUMMARY

There are no documents.

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	18 Dec 2018 15:35	Cim Veh Model Changed	(205317) TOYOTA HARRIER 2.0 Elegance (A),	[A] Lau Shu Pei
2	18 Dec 2018 15:35	Cim Created	Reg No: SLP5803R. Acct Date: 2018/12/16. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ). Workshop: Hui Yang Motor Pte Ltd (HQ)	[A] Lau Shu Pei
3	18 Dec 2018 15:35	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	18 Dec 2018 15:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/12/28	[A] Lau Shu Pei
5	18 Dec 2018 15:35	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	18 Dec 2018 15:36	Label Added	(30651):Vehicle Not In,(30653):Direct Settlement.	[A] Lau Shu Pei
7	18 Dec 2018 15:36	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Lau Shu Pei
8	24 Dec 2018 09:54	Cim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
9	24 Dec 2018 09:54	Cim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
10	28 Dec 2018 11:27	Label Removed	(30651):Vehicle Not In.	[A] Lau Shu Pei
11	02 Jan 2019 11:30	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remarks: Insured driver turned out from minor road and collided with third party who was on main road.	[A] CHEW HSIAO TONG
12	02 Jan 2019 14:15	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/12/28. Mandate Remarks: Agreed to do direct settlement. Please revert with your quantum advice	[I] Sundari Nagarajan
13	02 Jan 2019 14:15	Adj Mandate Set	Approved:0.00:Agreed to do direct settlement. Please revert with your quantum advice	[I] Sundari Nagarajan
14	17 Jan 2019 13:20	Adj Rpt Initiated		[A] Lau Shu Pei
15	17 Jan 2019 13:20	Cim Dtl Modified	JPJ Reg. Date: -> 2000/01/01.	[A] Lau Shu Pei
16	17 Jan 2019 13:20	Cim Details Notified		[A] Lau Shu Pei
17	09 Apr 2019 08:46	Cim Dtl Modified	JPJ Reg. Date: 2000/01/01 -> 2017/06/09.	[A] JOANNE LEE KHANG MIN
18	25 Apr 2019 17:53	Adj Mandate Request	Cur.Req:2118.60:PODS Liability: 100% Quantum: (a)CORw/GST: \$1,605.00 + (b)LOR (4days x \$120.00): \$513.60 = Total: \$2,118.60 Vehicle Model: Toyota Harrier 2.0 (1986cc) 3 recommendation repair days + 1Sunday = 4days For your approval please.	[A] CHAN JIA LE

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2032501	17/01/2019 13:20	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLP5803R	SHC8974B	10.70

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

Date: 04/04/2019

India International Insurance Pte Ltd

Motor Claims Department

64 Cecil Street

#04-00 IOB Building

Singapore 049711

**RE: ACCIDENT INVOLVING SLP5803R & SHC8974B ON 16/12/2018
ALONG CLEMENTI AVE 3 NEAR BLK 443**

SETTLEMENT OF OUR CLAIM FOR SLP5803R

Lump Sum repair cost as recommended by surveyor (TP0553)	\$ 1,605.00
4 days Loss of Rental @ \$128.00 per day	\$ 513.60
Total	<u>\$ 2,118.60</u>

**The above claim applies only to vehicle damage and expressly exclude all personal injuries and other consequential loss.*

Please let us have your reply soonest possible, thank you.

Best Regards,

Marco Neo

HUI YANG MOTOR PTE LTD

DID: 64515752

Fax: 64514658

email: hui_yang_motor@hotmail.com

AUTHORIZATION LETTER

TO WHOM IT MAY CONCERN

I/We, Sims Hong Hean hereby declare and agree to use the address of **Hui Yang Motor Pte Ltd**, that is at Blk 176 Sin Ming Drive, #04-02 Sin Ming Autocare Singapore 575721 in all my/our correspondences with any party in connection with my/our claim arising from an accident involving my/our motor vehicle registration number SLP 5803R and other vehicles registration number SHC 897+B along Along Clementi Ave 3 near BIK #43 on 16/12/18

I/We, further grant authority to Messrs **Hui Yang Motor Pte Ltd** or any of their representatives to open all my/our letters and to negotiate my/our claim on my/our behalf.

I/We wish to inform you that you could issue the cheque payment in favour of my/our repairer Messrs **Hui Yang Motor Pte Ltd**.



Signature of registered owner and Company's stamp

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: TP / MCT18120512
Claimant Ref: SLP 5803R

We/I, Hui Yang Motor Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 1,605.00 (repair cost), S\$ 513.60 (loss of ~~use~~ rental), S\$ - (search fee), vehicle no. SLP 5803R that was damaged pursuant to the accident which occurred on 16/12/2018 (date) at Clementi Ave 3 Near Blk 443 (location) involving vehicle no. SHC 8974B (insured vehicle). This is pursuant to the inspection conducted on 27/12/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Sim Hong Hoon Mrs Cheung Kai Ho ("the third party claimant") of vehicle no. SLP 5803R to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLP 5803R (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 2,118.60 to Hui Yang Motor Pte Ltd.

Dated this 14 day of May 20 19

CLAIMANT:

Signature:


Name:

NRIC:

Address:

Nationality:

Occupation:


Signed by "the workshop" (with chop)

Name: Hui Yang Motor Pte Ltd
NRIC: 20162943811
Address: 176 Sin Ming Drive
#04-02, 5(575721)

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:


Signed by appointed Surveyor
Name: LKK Auto Consultants Pte Ltd
NRIC: _____
Address: 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

HUI YANG MOTOR PTE LTD

Bill To:

India International Insurance Pte Ltd
Motor Claims Department
64 Cecil Street
#04-00 IOB Building
Singapore 049711

TAX INVOICE

TP Claim Invoice No: TP0553
Bill Date: 04/04/2019

	Description	Amount
	Date of Accident : 16/12/2018 Owner : SIM HONG HOON MRS CHUNG KAI HO Vehicle No : <u>SLP5803R</u> Make & Model : <u>TOYOTA HARRIER 2.0A</u>	
	<u>Lump Sum repair cost as recommended by surveyor</u>	\$ 1,500.00
	Sub-Total :	\$ 1,500.00
	Add 7% GST :	\$ 105.00
	Total Amount SGD :	\$ 1,605.00

Reg No.:201629438M

GST No:201629438M

HUI YANG MOTOR PTE LTD



Authorised Signature

Hui Yang Motor Pte Ltd

Sin Ming Autocare Blk 176 Sin Ming Drive

#04-02 Singapore 575721

Email: hui_yang_motor@hotmail.com

H/P: 98625891 Office: 64515752 Fax : 64514658

ACE FLEET MANAGEMENT PTE LTD

176 Sin Ming Drive #04-14 S(575721)

Sin Ming Autocare

Tax Invoice

Company Registration Nos.: 201710914N

GST Registration Nos.: 201710914N

Email.: acefleetmanagement@gmail.com

To : Ng Gek Kee

Car Plate : SJX9983J

Model : BMW 320i

Invoice Nos : 2018/1804

Invoice date : 31/12/2018

SLP5807R

Payment statement for 27/12/18 - 31/12/18

Description	Unit Price (incl. GST)	Amount (incl. GST)
No of Days	4	
Rental per days	\$120.00	
Total rental		\$480.00
<u>Remarks:</u>		
Sub Total		\$480.00
7% GST		\$33.60
Grand Total		\$513.60

Payment term :

- 1) 1 working day from date of invoice/payment slip
- 2) A late payment fee of 3 % of the amount due is applicable for any delay in payment
- 3) Please sent/whatapps a copy of the transaction slip via email/whatsapp when the transfer is made



ACE FLEET MANAGEMENT PTE LTD

237 ALEXANDRA ROAD #02-03 THE ALEXCIER SINGAPORE(159929)

RENTAL AGREEMENT


Kindly fill up all of the details below

CAR MODEL: Bmw 320i

CARPLATE: SJX9983J

HIRER'S NAME: Ng Gek Klee	
NRIC/PASSPORT NO.: S1598215B	D.O.B: 13/04/1953
NEXT OF KINS: -	TEL: -
ADDRESS: 480 Segar Rd #15-378 S670480	
CONTACT NO.: 88218811	
RENTAL DEPOSIT: -	
DATE OF COMMENCE: 27/12/18 10am - (End 31/12/18 10am)	
EMAIL: -	
RENTAL PER DAY: \$120/-	
BANK/ ACCOUNT NO.: *All Rental Payments to be make latest by every Monday . Thank you.	
CONTRACT VAILDITY: 04 days	
1)INSURANCE 1 ST PARTY EXCESS \$2500 2)INSURANCE 3 RD PARTY EXCESS \$2500 3)INSURANCE EXCESS FOR OVERSEA WILL BE DOUBLED 4)INSURANCE EXCESS FOR DRIVING LICENCE LESS THEN 2 YEAR AND BELOW 22 YEAR OLD WILL BE DOUBLED 5)WINDSCREEN EXCESS \$200	

Left Side



Right Side



REMARKS:

Back



Front



Top



D=DENT B=SCRATCHES C=CHIPS R=RUST M=MISSING

Hirer's Signature

GENERAL DEFINITIONS

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jan 2019 Edit Reg		18 Dec 2018 00:00 Edit Adj Rpt	\$51,500.00 Edit Estimates	\$51,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	SIM HONG HOON MRS CHEUNG KAI HO, ID: S8603195G								
Vehicle Reg. No.:	SLP5803R	Date of Loss:	16/12/2018 18:00 - :59 (18 Months and 7 Days From LTA Reg Date (Man Yr))						
Claim Type:	TP / MCT18120512	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SHC8974B	Policy No. (Claimant):	5091786047-01						
		Excess:							
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pool Chin Han Daniel]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 28/12/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (29/04/2019): Alert - Adj Mandate Approved (\$52118.60) - SLP5803R - Claim Handler: Pool Chin H... - III_SG (02/01/2019): Alert - Adj Mandate Approved (\$50.00) - SLP5803R - Claim Handler: Pool Chin Han ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP5803R (MCT18120512)
[SHC8974B]
TP
SIM HONG HOON MRS CHEUNG KAI HO
Dec 16 2018 6:00PM
[COMFORT TRANSPORTATION PTE LTD]
Hui Yang Motor Pte Ltd

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

View [View in Browser](#)

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	02/01/19 11:28	General View	 Load JPG	☒	
2	02/01/19 11:28	General View	 Load JPG	☒	
3	02/01/19 11:28	General View	 Load JPG	☒	
4	02/01/19 11:28	General View	 Load JPG	☒	
5	02/01/19 11:28	General View	 Load JPG	☒	
6	02/01/19 11:28	General View	 Load JPG	☒	
7	02/01/19 11:28	General View	 Load JPG	☒	
8	02/01/19 11:28	General View	 Load JPG	☒	
9	02/01/19 11:28	General View	 Load JPG	☒	
10	02/01/19 11:28	General View	 Load JPG	☒	
11	02/01/19 11:28	Odometer Reading	 Load JPG	☒	
12	02/01/19 11:28	General View	 Load JPG	☒	
13	02/01/19 11:28	Chassis Number	 Load JPG	☒	

Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	18/12/18 15:36	EMAIL FROM III DD 18122018	 Load PDF		
2	18/12/18 15:36	TP ESTIMATE	 Load PDF		
3	18/12/18 15:36	TP GIA REPORT	 Load PDF		
4	31/12/18 09:15	TP ESTIMATE- MARKED	 Load PDF		
5	09/04/19 08:50	WORKSHOP INVOICE	 Load PDF		
6	09/04/19 08:50	RENTAL RECEIPT	 Load PDF		
7	09/04/19 08:50	LOD	 Load PDF		
8	31/05/19 08:50	DISCHARGE VOUCHER	 Load PDF		
9	31/05/19 08:50	AUTHORISATION TO ACT FORM	 Load PDF		

No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	19/12/18 09:02	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18022673/KPB3Q2

Date: 31/05/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle
No : SLP5803R

Insured Vehicle No : SHC8974B

Date of Loss: 16/12/2018

Nature of Claim:

TP

Claim No: MCT18120512

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP5803R

Make & Model: TOYOTA HARRIER, 2.0 Elegance (A)

Engine No: 3ZRB976659

Reg. Date: 09/06/2017 (Man. Year: 2017)

Chassis No: ZSU600100874

Colour: Metallic Pearl White

Odometer: 30893 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65 R17

Rear Tyre Size:

225/65 R17

Front Left Side: Michelin 7 mm

Rear Left Side:

Michelin 8 mm

Front Right Side: Michelin 7 mm

Rear Right Side:

Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,347.45	1,174.77	2,172.68	64.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,990.00	700.00	1,290.00	64.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,337.45	1,874.77	3,462.68	64.88
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	5,337.45	1,500.00	3,837.45	71.90
+ GST 7.00/7.00% (S\$)	373.62	105.00	268.62	71.90
Nett Amount (S\$)	5,711.07	1,605.00	4,106.07	71.90
+ Car Rental (4.0 x S\$120.00/day + 7.00% GST) (S\$)		513.60		
Nett Liability (S\$)		2,118.60		

INSPECTION

Date of Assignment: 18/12/2018

Date Inspected: 27/12/2018 Inspected At:

Hui Yang Motor Pte Ltd (HQ)
176 Sin Ming Drive #04-02, Sin Ming
AutoCare
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Apr 2019)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP5803R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,718.40 FL	*- FL
2	1		*REAR BUMPER LH SIDE RETAINER 1	Serviceable	132.25 FL	*- FL
3	1		*REAR BUMPER LH SIDE RETAINER 2	Serviceable	131.25 FL	*- FL
4	1		*REAR LH ABSORBER	Serviceable	529.50 FL	*- FL
5	1		*REAR LH KNUCKLE ARM	Bent	430.20 FL	*430.20 FL
6	1		*REAR LH KNUCKLE BEARING	Necessary	229.50 FL	*229.50 FL
7	1		*REAR LH TOP ARM	Serviceable	385.50 FL	*- FL
8	1		*REAR LH SPORT RIM	Dented	680.00 FS	*680.00 FS
					Sub Total (S\$)	4,236.60
					- List Item Discount on L Items 25.00/25.00% (S\$)	889.15
					Total Parts (S\$)	3,347.45
						1,174.77

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIT REAR UNDERCARRIAGE	New	380.00	100.00
2	WIRING	New	60.00	10.00
3	SPRAY PAINTING	New	800.00	440.00
4	LABOUR CHARGES	New	750.00	150.00
Gross Labour Cost (\$\$)			1,990.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >