

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

21/12/18
(Thursday)
after 10am

16/12/2018

Owner: SIM HONG HOON

ESTIMATE TO REPAIR TOYOTA HARRIER 2.0 - SLP5803R

1pc	rear bumper	R	\$ 1,718.40	X
1pc	rear bumper LH side retainer 1	h	\$ 132.25	X
1pc	rear bumper LH side retainer 2	h	\$ 131.25	X
1pc	rear LH absorber		\$ 529.50	?
1pc	rear LH knuckle arm		\$ 430.20	?
1pc	rear LH knuckle bearing		\$ 229.50	?
1pc	rear LH top arm		\$ 385.50	?

\$ 3,556.60

less 25%

\$ 889.15

\$ 2,667.45

1pc rear LH sport rim P11 No s.nett \$ 680.00 ✓

remove & refit rear undercarriage

\$ 380.00 ?

wiring

\$ 60.00 1d

spray painting

\$ 800.00 24d

labour charges

\$ 750.00 15d

Total

\$ 5,337.45

Not authorized
U/S 8?
Resurvey After Paint

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

