

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

16/12/2018

Owner: SIM HONG HOON

ESTIMATE TO REPAIR TOYOTA HARRIER 2.0 - SLP5803R

1pc	rear bumper	\$ 1,718.40
1pc	rear bumper LH side retainer 1	\$ 132.25
1pc	rear bumper LH side retainer 2	\$ 131.25
1pc	rear LH absorber	\$ 529.50
1pc	rear LH knuckle arm	\$ 430.20
1pc	rear LH knuckle bearing	\$ 229.50
1pc	rear LH top arm	\$ 385.50
		\$ 3,556.60
less 25%		\$ 889.15
		\$ 2,667.45

1pc	rear LH sport rim	s.nett \$ 680.00
-----	-------------------	------------------

remove & refit rear undercarriage	\$ 380.00
wiring	\$ 60.00
spray painting	\$ 800.00
labour charges	\$ 750.00
Total	
	\$ 5,337.45

