

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompso Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: NGO SAU WEI SHAWN

Date: 21 Dec 2018

Preliminary Advice

Insured Vehicle No	: SKJ1859A		
TP Vehicle No	: SLX3709B	Accident Date	: 15/12/2018
Make	: LAND ROVER FREELANDER 2	Assignment Date	: 18/12/2018
Date of Inspection	: 20/12/2018	Est. Duration of Repair	: 3.00
Inspection At	: MOTORICARZ GARAGE (HQ) 53 UBI AVENUE 1, #01-19 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,050.70
Revised Amount	:S\$	7,807.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,807.20

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The above survey was conducted on a 'Without Prejudice' basis.