

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 9150R

DATE 17/12/2018 14:58

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille ✓			\$ 1,110.10
	Radiator Grille H Emblem ✓			\$ 39.50
	Front Bumper Cover <i>x ppr</i>			\$ 1,052.20
	Front Bumper Bracket Top (LH/RH) <i>x</i>	\$	22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) <i>x</i>	\$	24.60	\$ 49.20
	SUB TOTAL			\$ 2,295.80
	LESS 20%			\$ 459.16
	DISCOUNTED TOTAL			\$ 1,836.64
	Labour Charge			
	Panel Beating			\$ 400.00 ²⁰⁰
	Spray Painting Charge			\$ 300.00 ²⁰⁰
	TOTAL LABOUR			\$ 700.00
	ESTIMATE TOTAL			\$ 2,536.64
<p><i>Kalin 11/11/14</i></p> <p><i>17/12/18 1530h</i></p> <p><i>26/1</i></p> <p><i>P18</i></p> <p><i>Alfa Repair plot</i></p> <div style="border: 1px solid black; padding: 5px; margin-top: 10px;"> <p>KK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				