

SS. REC. BY:

REF:

CS / FC18022683 / Kltbn2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

WS Eileen Lee

of

FC1

Date/Time:

18/12/2018 230pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 6090P

Insured:

SHC 7248X

at Workshop m/s

Premier

Tel:

6544 6676

of

23 Chungi South Ave 2 # 03-02

Policy No:

Claim No:

D18008888MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi'

H.O.D. Endorsement:

Date/Time:

18/12/2018

237pm

Person Contacted:

Garry

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

SHC 6090P - CC3 / MSG 17001108 / Hltbn2

DUA: 13012017

SHC 7248X - NA / INC18006105 / K4

DUA: 03042018

20/12@ 11:21am - Rensed preli advise via email

Surveyor: Kalvin

REF: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OO/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 6090P Yr Regn: 30 24, 24
Type: M.Car / M.Cycle / Bus / Van / Lorry / T~~o~~il / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1682Colour: Silver A/C: Insued / Std / NI / NASp. Reading: 59 223 T/Radio: Insued / Std / NI / NA

Eng/No: _____

C/No: KNA6M44ME5464252Gen. Cond: Good / 6ir / Poor / BurntSteering: Inorder / 6ir / Jammed / Leaked / Burnt orBrake: Inorder / 6ir / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD 6ir orTyre Size: F: 205/65R16R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 7 Rear 7R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 16/12/8 D.O.I. 19/12/8Survey held at Premier

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

o/s Pen

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/12/8 Chkd up \$1050 / 2 B's. (Red: 89440; 45%) FCI

4s.

RECEIVED 28 DEC 2018

Date/Time, File Pass to? ☐ : Prel. Report1) 28/12 Typist ☒ : Final Report

Date/Time, File Return to?

2) _____

Report Format: TPLump Sum / I.B.I. (\$) 10501-Days Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____) \$ + RS \$ _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

Survey Fee:	100
Transportation:	50
	50
	29
TOTAL	229

MOTOR SURVEY ASSIGNMENT

Date	17-12-2018	Our Ref No. D18008888MFSH
Accident Date	16-12-2018	Claim Type. Third Party
Insured Vehicle	SHC7248X	Third Party Vehicle. SHC6090P
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	GOH WEE DEK	
Contact No.	65446676/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 20 December 2018 11:29 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D1800888MFSH/1
Attachments: PRELI ADVISED SHC 6090P.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHC 6090P**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 18 December 2018 2:39 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D1800888MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 18 December, 2018 2:30 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D1800888MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008888MFSH

Date: 20/12/2018

Our Ref: CS/FCI18022683/K1tb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6090P

Please be informed that we had conducted the inspection of the abovementioned vehicle
19/12/2018 at the premises of M/s Premier have the following to report: -

Workshop Estimate Amount	: S\$ <u>1,944.40</u>
Revised Estimate Amount	: S\$ <u>1,304.40</u>
"Check" Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the o/s rear
portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kalvin
Automotive Assessor

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	30 Jul 2014 / 08:46:02	Receipt No.:	AACCK001-AX239-140730-000001
Asset Type:	Vehicle	Transaction Amount:	\$65,685.00
Asset ID:	SHC6090P	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140730084602990951		

Vehicle No.:	SHC6090P
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	30 Jul 2014
Original Registration Date:	30 Jul 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5464252
Engine No.:	D4FDDH307918
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$19,776.00
Minimum PARF Benefit:	\$7,365.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	30 Jul 2014 08:46:02
COE No.:	2014073001001353K
COE Expiry Date:	29 Jul 2022
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$53,269.00
Lifespan Expiry Date:	29 Jul 2022
Owner ID Type:	Company

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

17-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6090 P

1 pc	Wheel cover <i>— hand</i>	\$	116.00
	Less 10%	\$	11.60
		\$	104.40

S/NETT

1 set	Rear o/s fender sticker <i>— m</i>	\$	60.00
1 set	o/s door sticker <i>— m</i>	\$	100.00

Sundry *new* \$ ~~50.00~~ *20*

To check wheel alignment \$ ~~80.00~~ *X 1.1*

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear bumper, rear o/s fender, rear o/s door, o/s rocker panel garnish \$ ~~600.00~~ *300*

To putty and spray painting on rear bumper, rear o/s fender, rear o/s door, o/s rocker panel garnish \$ ~~800.00~~ *720*

To apply rustproofing on the repaired and replaced panels. \$ ~~150.00~~ *X 1.1*

\$ 1,944.40

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.


Ka/lin Uay

19/12/18 13:10 hr.

2 Pgs

4/s

After Repair p/ls





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18022683/K1tbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 31-12-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7248X	Veh. Inspected	SHC 6090P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008888MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	18/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414ME5464252	Colour	SILVER	
Odometer	392273	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	ACHILLES	7 mm	
L/H Front Tyre	205/65 R16	ACHILLES	7 mm	
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/12/2018	Inspection Date	19/12/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6090P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	WHEEL COVER	GRAZED	116.00	116.00
	LESS 10% DISCOUNT		-11.60	-11.60
			104.40	104.40
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR O/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SET O/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			210.00	180.00
	<u>LABOUR</u>			
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE REAR BUMPER,REAR O/S FENDER,REAR O/S DOOR,O/S ROCKER PANEL GARNISH.		600.00	300.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER,REAR O/S FENDER,REAR O/S DOOR,O/S ROCKER PANEL GARNISH.		800.00	720.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	150.00	-
			1,630.00	1,020.00
	GRAND TOTAL		1,944.40	1,304.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,050.00

Report Ref No. CS/FC18022683/K1tbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.