

ASS. REC. BY:

REF: CS/AT(180)22693 / Asbn2

Special Instruction:

Supervisor: Muriman

Adrian

**ASSIGNMENT (Office)**

From (Person):

Syazgirdina

of

ALL

Date/Time:

15/12/2018 11:39am

Estimated Cost:

Bill to:

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No:

SMC 3905A

Insured:

SKX 4387B

at Workshop m/s

ACE AutoLution

Tel:

6844 1184

of

13 1/2 km Bukit Raju #03-29

Policy No:

Claim No:

858434003267011

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

15.12.2018

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

15/12/2018 11:50am

Person Contacted:

Anna

Vehicle

IN/OUT

Date/Time

Action/Instruction (  ) Estimate

SMC 3905A - X

SKX 4387B - NA / AT(180)22551 / r3

DOA: 15/12/2018

Q1000000

REF:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SMC3905A Yr Regn: 2018 / June  
 Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or

Make: Honda Shuttle c.c. 1496  
 Colour: Red A/C: Insured / Std / NI / NA  
 Sp. Reading: 12155 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 C/No: GK81201117

Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60 R15  
 R: 185/60 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.I. <u>18/12/18</u>

Survey held at ACE Autodetection  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Date / Time	Action / Instruction
-------------	----------------------

18/02/19	<u>TP ALG.</u> Confirmed HS \$ 7,500/- @ 7 days with Adrian. ( \$ 7,326.88 Red - 49% )
----------	--

RECEIVED 18 FEB 2019

Date/Time, File Pass to?

1) 18/02/19  
TP

Date/Time, File Return to?

2) \_\_\_\_\_

: Preli. Report  
 : Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS: SI

Photos

Others

TOTAL

Add Fee:  : Site Insp (\$ )

: Interview (\$ )

: Tech. Invs (\$ )

: Weekend (\$ )

Report Format :

Lump Sum / I.B.I: (\$ 7,500/- HS )

250

10

260

- Pre repair inspection request - SMC3905A VS SKX4387B (OI) DOA 15/12/2018

From: Azlan, Syazairdina  
To: admin-a@lkkauto.com, assignments@lkkauto.com  
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; Kaur, Baljit  
Sent: Tuesday, 18 December, 2018 11:39:58 AM  
Attachments: 20181217180520077.pdf

Hi,

Please refer to the enclosed request from **Chia S Arul LLC**.

Claim no : 8584340032SG011  
Case Owner : CHEE HENG LOH

If you have any queries/concerns, please let us know.  
Kindly assist to assign **Adrian Ling** as *Single Joint Expert* as requested.

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II  
SG Claims Operations | AIG Shared Services

**From:** Weng Kit [mailto:wengkit@chiaarul.com]  
**Sent:** Tuesday, December 18, 2018 11:32 AM  
**To:** Azlan, Syazairdina  
**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; Kaur, Baljit; 'Jerone'  
**Subject:** RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKX4387B AND SMC3905A ON 15/12/2018

Dear Sirs,

We refer to your email below.

We write to confirm that our client would like to nominate **Mr. Adrian Ling from LKK Auto Consultants Pte Ltd** as the *Single Joint Expert* for the above matter.

Please let us have your confirmation on the same.

Best Regards,

**Weng Kit (Mr.)**  
Paralegal  
M/s Chia S Arul LLC  
151 Chin Swee Road  
#03-09 Manhattan House  
Singapore 169876  
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and/or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

**From:** Azlan, Syazairdina [mailto:Syazairdina.Azlan@aig.com]  
**Sent:** Tuesday, December 18, 2018 11:12 AM  
**To:** Weng Kit  
**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; Kaur, Baljit; 'Jerone'  
**Subject:** RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKX4387B AND SMC3905A ON 15/12/2018

📧📧

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสขึ้นเพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-12-25 11:12 +08 to read your message.  
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its contents are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

**IMPORTANT NOTICE**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**From:** Syazairina Azlan@aig.com  
**To:** wengkit@chiaarul.com  
**Cc:** Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, NoorMariessa.AbuKassim@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Yinrul.Hor@aig.com, yokeshi.chen@aig.com, Bai  
**Subject:** AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKX4387B AND SMC3905A ON 15/12/2018  
**Date:** Tue, 18 Dec 2018 02:46:08 +0000  
Without Prejudice

Your Reference : SMC 3905A (wk)  
Our Reference : SKX4387B

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan  
AIG  
Express Claims Adjuster II  
SG Claims Operations | AIG Shared Services

**From:** AIG SGP, Claims-Survey  
**Sent:** Tuesday, December 18, 2018 9:08 AM  
**To:** Azlan, Syazairina  
**Subject:** FW: Our Ref: SMC 3905A (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SMC 3905A & SKX 4387B ALONG PIE ON 15 DECEMBER 2018

**From:** Weng Kit [mailto:wengkit@chiaarul.com]  
**Sent:** Monday, December 17, 2018 6:06 PM  
**To:** AIG SGP, Claims-Survey  
**Cc:** 'Jerone'  
**Subject:** Our Ref: SMC 3905A (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SMC 3905A & SKX 4387B ALONG PIE ON 15 DECEMBER 2018

Dear Sirs,

We refer to the above matter.

Attached is a copy of our pre-repair survey notice dated 17 December 2018 for your attention.

Best Regards,

**Weng Kit (Mr.)**  
Paralegal  
M/s Chia S Arul LLC  
151 Chin Swee Road  
#03-09 Manhattan House  
Singapore 169876  
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and/or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

**CHIA S ARUL LLC**  
ADVOCATES & SOLICITORS  
UEN 201330709H

A R U L C H E L V A N S

Our Ref : SMC 3905A (wk)

Your Ref : To be advised

17 December 2018

AIG Asla Pacific Insurance Pte Ltd

BY EMAIL ONLY

Dear Sirs,

RE: PROPERTY DAMAGE CLAIM  
CLAIMANT : KASSIM B KAMIS  
ACCIDENT INVOLVING SMC 3905A & SKX 4387B ALONG PIE ON 15  
DECEMBER 2018  
PRE-REPAIR SURVEY NOTICE

1. We act for Kassim B Kamis, the owner of motor vehicle no. SMC 3905A which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. SKX 4387B or damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

Workshop	Ace Autolution
Address	13 Kaki Bukit Road 4 #03 - 29 Bartley Biz Centre Singapore 417807
Contact Person	Ms. Anna (6844 1184)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

**MR ARULCHELVAN S**  
cc: Client (By Email)

151 CHIN SWEE ROAD • #03-09  
MANHATTAN HOUSE • SINGAPORE 169876  
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)  
EMAIL : info@chiasrul.com

M/s Chia S Arul LLC  
Page 2

Our Ref : SMC 3905A (wk)

Your Ref : To be advised

PRE-REPAIR SURVEY (1)  
WORKSHOP:

SURVEYOR:

---

Name:  
Date/Time:

---

Name of Surveyor:  
Contact Number:  
Date/Time:

---

PRE-REPAIR SURVEY (2)  
WORKSHOP:

SURVEYOR:

---

Name:  
Date/Time:

---

Name of Surveyor:  
Contact Number:  
Date/Time:

---

POST-REPAIR SURVEY  
WORKSHOP:

SURVEYOR:

---

Name:  
Date/Time:

---

Name of Surveyor:  
Contact Number:  
Date/Time:

**Enquire Vehicle & Owner Information ( Vehicle No. SKX4387B As At 15 Dec 2018 / 14:00:00 )**

## Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident  
Law Firm Case No.: SMC3905A

## Current Owner Details

Owner ID Type: Company  
Owner ID: 201533046C  
Owner Name: TWINCAR LEASING PTE LTD  
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes  
Registered Block/House No.: 2  
Registered Street Name: KAKI BUKIT AVENUE 2  
Registered Unit No.: # 01 - 17  
Registered Building Name: KAKI BUKIT AUTOHUB  
Registered Postal Code: 417921

## Current Vehicle Details

Vehicle No.: SKX4387B  
Make Description/Model: TOYOTA / COROLLA ALTIS CLASSIC 1.6 CVT  
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.



ACE AUTOLUTION PTE LTD  
 13 Kaki Bukit Road 4 Bartley Biz Centre #03-29  
 Singapore 417807  
 Tel:6702 4282 Fax:6702 4202

GK8120117  
 TRIG Shirley

Vehicle No. SMC3905A HONDA SHUTTLE

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ADJUSTMENT
<b>PARTS (LIST ITEMS)</b>				
1	TAILGATE <i>Distorted</i>		1193.00	✓
1	TAILGATE HANDLE COVER <i>Deland</i>		55.00	✓
2	TAILGATE DAMPER @\$298.00 <i>new</i>		596.00	+ ✓
2	TAILGATE RUBBER STOPPER @\$6.00 <i>new</i>		12.00	+ ✓
1	TAILGATE "SHUTTLE" EMBLEM <i>new</i>		98.00	✓
1	TAILGATE EDGE WEATHERSHIP <i>lit</i>		184.00	✓
1	TAILGATE CHROME <i>white</i>		198.00	✓
1	TAILGATE TRIM BOARD <i>white</i>		345.00	✓
1	TAILGATE INNER GARNISH <i>new</i>		215.00	+ ✓
1	TAILGATE HONDA LOGO <i>new</i>		110.00	38 ✓
1	TAILGATE LOCK <i>Deland</i>		410.00	181 ✓
1	TAILGATE LOCK SWITCH <i>new</i>	80776	198.00	+ ✓
1	TAILGATE SPOILER <i>new</i>		310.00	+ ✓
1	REAR WINDSCREEN MOULDING <i>new</i>	6462.08	172.00	✓
2	REAR TAILLAMP LH & RH @530.00 <i>lit</i>		1060.00	✓
2	REAR TAILGATE LAMP LH & RH @410.00 <i>lit</i>		820.00	✓
1	REAR BUMPER <i>Deland</i>		1150.60	✓
2	REAR BUMPER SPONGE LH & RH @105.00 <i>Deland</i>		210.00	✓
1	REAR BUMPER TOWING COVER <i>Deland</i>		75.00	✓
2	REAR BUMPER REFLECTOR LH & RH @148.00 <i>new</i>		296.00	+ ✓
2	REAR BUMPER SIDE RETAINER LH & RH @130.00 <i>new</i>		260.00	68 ✓
1	END PANEL <i>Distorted</i>		610.00	✓
1	END PANEL TOP GARNISH <i>Deland</i>		261.00	✓
1	SPARE TYRE BOX <i>Repair</i>		1980.00	+ ✓
2	REAR FENDER INNER COVER LH & RH @ 335.00 <i>Deland</i>		670.00	✓
1	SMART SENSOR <i>Deland</i>		250.00	65 ✓
1	EXHAUSE PIPE <i>new</i>		980.00	✓
<i>Tools Tray " 325 "</i> <i>Spare Tyre Pond " Deland "</i> <i>Top Cover " 299 "</i>			12358.60	
less 20%			2471.72	20%
			9886.88	
<b>SPECIAL NETT ITEMS</b>				
1 SET	REVERSE SENSOR <i>Deland</i>		280.00	20 ✓
1	REAR END SEALANT <i>new</i>		100.00	60 ✓
1	REAR END PANEL TOP GARNISH CLIPS <i>new</i>		80.00	10 ✓
1 SET	TAILGATE INNER TRIM CLIPS <i>new</i>		60.00	30 ✓
1	REAR WINDSCREEN SEALANTS <i>new</i>		100.00	60 ✓
1 SET	REAR BUMPER CLIPS <i>new</i>		80.00	30 ✓
1	REVERSE CAMERA <i>new</i>		480.00	✓
Total Parts			11066.88	



**ACE AUTOLUTION PTE LTD**  
 13 Kaki Bukit Road 4 Bartley Biz Centre #03-29  
 Singapore 417807  
 Tel:6702 4282 Fax:6702 4202

Vehicle No. SMC3905A HONDA SHUTTLE

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT
	<b>LABOUR</b>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	<del>1600.00</del> 1200	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	<del>1200.00</del> 1000	
3	To remove and refix wiring at damaged areas	<del>200.00</del> 30	
4	To perform anti rust treatment on affected areas	<del>240.00</del> 60	
5	To remove & refix / replace rear trims, garnish and fitting so as to facilitate repairs as rear compartment	<del>250.00</del> 80	
6	To remove and replace reverse sensors and check for proper functions	<del>120.00</del> 50	2540
7	To remove and refix rear tailgate windscreen	<del>150.00</del> 120	
	Labour Total :	3760.00	
	<b>TOTAL (PARTS &amp; LABOUR):</b>	<del>14826.88</del>	

15614.08

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Adrian King - total 9392.08  
 4/s 19/12/18 4/s: 7.5k.  
 07 rmp (7.5k)

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18022693/ASBN2

Date: 18/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994387  
 Claimant Vehicle No : SMC3905A Insured Vehicle No : SKX4387B  
 Date of Loss: 15/12/2018 Nature of Claim: TP Claim No: 8584340032SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMC3905A Engine No: L15B5461324  
 Make & Model: HONDA SHUTTLE, 1.5 (A) Chassis No: GK81201117  
 Reg. Date: 29/06/2018 (Man. Year: 2018) Odometer: 12155 km  
 Colour: Red  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,854.08	6,852.08	5,002.00	42.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	2,540.00	1,220.00	32.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,614.08</b>	<b>9,392.08</b>	<b>6,222.00</b>	<b>39.85</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>15,614.08</b>	<b>7,500.00</b>	<b>8,114.08</b>	<b>51.97</b>

INSPECTION

Date of Assignment: 18/12/2018  
 Date Inspected: 18/12/2018 Inspected At: Ace Autolution Pte Ltd (KAKI BUKIT)  
 13 Kaki Bukit Road 4, #03-29/30 Bartley  
 Biz Centre  
 Singapore 417807  
 Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Distorted	1,193.00 FL	*1,193.00 FL
2	1		*TAILGATE HANDLE COVER	Deformed	55.00 FL	*55.00 FL
3	2		*TAILGATE DAMPER	Not Necessary	596.00 FL	*- FL
4	2		*TAILGATE RUBBER STOPPER	Not Necessary	12.00 FL	*- FL
5	1		*TAILGATE SHUTTLE EMBLEM	Necessary	98.00 FL	*98.00 FL
6	1		*TAILGATE EDGE WEATHERSTRIP	Cut	184.00 FL	*184.00 FL
7	1		*TAILGATE CHROME	Cracked	198.00 FL	*198.00 FL
8	1		*TAILGATE TRIM BOARD	Cracked	345.00 FL	*345.00 FL
9	1		*TAILGATE INNER GARNISH	Not Necessary	215.00 FL	*- FL
10	1		*TAILGATE HANDA LOGO	Necessary	110.00 FL	*38.00 FL
11	1		*TAILGATE LOCK	Damaged	410.00 FL	*181.00 FL
12	1		*TAILGATE LOCK SWITCH	Not Necessary	198.00 FL	*- FL
13	1		*TAILGATE SPOILER	Not Necessary	310.00 FL	*- FL
14	1		*REAR WINDSCREEN MOULDING	Necessary	172.00 FL	*172.00 FL
15	2		*REAR TAILLAMP LH & RH	Cut	1,060.00 FL	*1,060.00 FL
16	2		*REAR TAILGATE LAMP LH & RH	Cut	820.00 FL	*820.00 FL
17	1		*REAR BUMPER	Deformed	1,150.60 FL	*1,150.60 FL
18	2		*REAR BUMPER SPONGE LH & RH	Deformed	210.00 FL	*210.00 FL
19	1		*REAR BUMPER TOWING COVER	Deformed	75.00 FL	*75.00 FL
20	2		*REAR BUMPER REFLECTOR LH & RH	Not Necessary	296.00 FL	*- FL
21	2		*REAR BUMPER SIDE RETAINER LH & RH	Necessary	260.00 FL	*68.00 FL
22	1		*END PANEL	Distorted	610.00 FL	*610.00 FL
23	1		*END PANEL TOP GARNISH	Deformed	261.00 FL	*261.00 FL
24	1		*SPARE TYRE BOX	Repair	1,980.00 FL	*- FL
25	2		*REAR FENDER INNER COVER LH & RH	Deformed	670.00 FL	*670.00 FL
26	1		*SMART SENSOR	Damaged	250.00 FL	*65.00 FL
27	1		*EXHAUST PIPE	Not Necessary	980.00 FL	*- FL
28	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
29	1		*REAR END SEALANT	Necessary	100.00 FS	*60.00 FS
30	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*10.00 FS
31	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
32	1		*REAR WINDSCREEN SEALANTS	Necessary	100.00 FS	*60.00 FS
33	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
34	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
35	1		*TOOLS TRAY	Deformed	325.00 FL	*325.00 FL
36	1		*SPARE TYRE PANEL TOP COVER	Deformed	299.00 FL	*299.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,522.60</b>	<b>8,467.60</b>
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,668.52	1,615.52
<b>Total Parts (\$\$)</b>	<b>11,854.08</b>	<b>6,852.08</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,600.00	1,200.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	1,000.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	200.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	240.00	60.00
5	TO REMOVE & REFIX/REPLACE REAR TRIMS,GARNISH AND FITTING SO AS TO FACILITATE REPAIRS AS REAR COMPARTMENT	New	250.00	80.00
6	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTIONS	New	120.00	50.00
7	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN	New	150.00	120.00
<b>Gross Labour Cost (S\$)</b>			<b>3,760.00</b>	<b>2,540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >