## CITY CAB PTE LTD **REPAIR ESTIMATE\***

VEHICLE NO: SHC 7123Y

MAKE

PE.

DATE 17/12/2018 15:19

Qty	Parts Description/ Labour	Type	Unit Price	1	Amount
	Rear Bumper			\$	553.00
	Rear Bumper Reinforcement ?			\$	428.40
	Rear Bumper Reinforcement Bracket (LH/RH).		\$ 80.30	\$	160.60
	Rear Bumper Clip 10 pcs			\$	22.00
	Rear Bumper Bracket		\$ 35.60	\$	71.20
	Rear Bumper Sponge ?			\$	103.50
	Rear Bumper Under Cover			S	228.00
	icai Bumper Onder Cover			"	220.00
	SUB TOTAL			\$	1,566.70
	LESS 20%			\$	313.34
	DISCOUNTED TOTAL			\$	1,253.36
	DISCOUNTED TOTAL			9	1,233.30
	Door Dummon Bukhon Mot			0	50.00
	Rear Bumper Rubber Mat			\$	135.70
	Rear Bumper Reverse Sensor			\$	133.70
				6	105 70
				\$	185.70
	Labour Channe				
	Labour Charge				200
	Panel Beating			\$	400.00
	Spray Painting Charge			\$	300.00
	Wiring Charge			\$	30.00
	Remove/Refix Reverse Sensor			\$	80,00
	TOTAL LABOUR			\$	810.00
	ESTIMATE TOTAL			\$	2,249.06
	1 1 1				
	Kalui Willy				
	Kali 1004 18/0/3 1348h 2 Gr	112	V Auto Consultanto honos	polifi	
	1/ 18/0/8 17/1/		Auto Consultants hence Repairer of the following:		,
	10/0/1/452	e.10	resurvey before/after spray pair	ting	
		• To	display damaged part(s) during arts prices are subject to confirm		/ey
	24.		arts prices are subject to commit and party survey is on a "With mil		dice" basis
	PIP	• N	dillegal modification(s) is allowed		
	Refore Paint pht.	• S	upplementary item(s) must be re subject to final approval from ins	uranc	ed and e Company
	Refore fairly photo				
	1		nowledged by Repairer		
		Sig	rature:		
		Da		-	

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.