

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : AXA INSURANCE SINGAPORE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTKB/TP/1811/013
Policy No:	0081822896-13	Date of Loss:	16/11/2018
Vehicle Reg. No.:	FD7P	Driveable?	yes
Driver Age:		Third Party Vehicle No.:	SCH282A
Any Injuries?	no	Contact No:	
Insured/Claimant:	ONG PENG YEOW	Driver:	ONG PENG HWEE

Make/Model:	Harley Davidson, XL883C	Vehicle Reg. Date:	24/11/2018
Vehicle Colour:	BLACK	Engine Number:	BPLS019944
Chassis No:	1HD1BPL18SY019944	Odometer:	0
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	16,979.30
Miscellaneous Items	0.00
Labour	800.00
Paintwork Labour	500.00
Towing	0.00

Gross Total(S\$):	18,279.30
GST 7.00%(S\$):	1,279.55
Nett Amount(S\$):	19,558.85

This claim is handled by: Shaun Toh L M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorized

LKK

Take photo After repair

18/11/18

Sty.

Tel: 62563581

[Signature]

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	HANDLE BAR <i>Bel</i>	0.00	380.00	+10.00	418.00
2	1	GAS TANK <i>100</i>	0.00	1,300.00	+10.00	1,430.00
3	2	SIDE MIRROR <i>320</i>	0.00	280.00	+15.00	322.00
4	1	HEADLIGHT <i>100/Bel</i>	0.00	430.00	+10.00	473.00
5	1	DASH PANEL <i>che</i>	0.00	280.00	+10.00	308.00
6	1	SPEEDOMETER <i>320</i>	0.00	530.00	+10.00	583.00
7	2	FRONT SIGNAL <i>320</i>	0.00	440.00	+10.00	484.00
8	1	DERBY COVER <i>?</i>	0.00	120.00	+10.00	132.00
9	1	GEAR SHIFTER PAD <i>320</i>	0.00	70.00	+10.00	77.00
10	1	REAR SIGNAL <i>115 320</i>	0.00	110.00	+10.00	121.00
11	1	FRONT FORK ASSEMBLY <i>?</i>	0.00	7,609.00	+10.00	8,369.90
12	2	RISER BOLT <i>?</i>	0.00	602.00	+10.00	662.20
13	2	RISER <i>?</i>	0.00	1,132.00	+10.00	1,245.20
14	1	FRONT BRAKE MASTER CYLINDER <i>147</i>	0.00	365.00	+10.00	401.50
15	1	CLUTCH LEVER HOUSING <i>147</i>	0.00	85.00	+10.00	93.50
16	1	CLUTCH LEVER <i>502</i>	0.00	90.00	+10.00	99.00
17	1 <i>pin</i>	NUMBER PLATE <i>che 145.00</i>	0.00	20.00	+10.00	22.00
18	2	DECALS <i>new</i>	0.00	800.00	+10.00	880.00
19	2	EMBLEM <i>new</i>	0.00	300.00	+10.00	330.00
20	2	FOOT PEG <i>out of 125 1004</i>	0.00	480.00	+10.00	528.00

Total Parts (\$\$) 16,979.30**Estimates of Miscellaneous Items**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
Sub Total (\$\$)						<u>0.00</u>

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	800.00	800.00	0.00	800.00

Gross Labour Cost (\$\$) 800.00**Estimates On Paint Work Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	500.00	500.00	0.00	500.00

Gross Labour Cost (\$\$) 500.00

< END OF ESTIMATES >