

15/5/2018

INS. CASE OWNER:

CC 4 / AXA1802

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

3,200.00

(6 days) Reduction:

78

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

18

Repair Cost:

SS

3,424.00

Loss of Rental (LOR):

SS

-

(days)

Loss of Use (LOU):

SS

500.00

x 9

days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GLA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

3,966.00

Global Sum SS:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

3,966.00

Name 1:

VERHOOGEN KOB PRS LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4300.00

COPY SENT

7/2/2018

Tanji

REF:

AXIA

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLG 9687 E 2016 Oct.

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Grom

C.C

1496

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

166258

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GM 41104604

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Roadster

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

18/12/18

Survey held at

Vannagar

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Wp \$ 3,200.00
CRAB \$ 11,760.24 (78%)

Date/Time. File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS. \$

) Photos

) Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18022707/T1hb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 18-12-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKG 7109H	Veh. Inspected	SLG 9687E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/12/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	14/12/2018	Inspection Date	18/12/2018
Survey held at	VERMOGEN ACE PTE LTD 1 BUKIT BATOK CRESCENT #04-54/55 WCEGA PLAZA SINGAPORE 658064		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



SLG9687E

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 14/12/2018

Vehicle Reg. No. : SLG9687E
Vehicle Reg. Date: 19-Oct-2016
Make / Model : HONDA GRACE 1.5 DX HY
Engine No. : LEB5255753
Chassis No. : GM41104604

COST OF CLAIMS

Parts Cost / List Items : \$ 10,712.80
Plus/Less 20% \$ 2,142.56
Total Cost / List : \$ 8,570.24
Special Nett Items : \$ 1,160.00
Total Parts Amount : \$ 9,730.24
Total Labour Amount : \$ 5,230.00
Gross Total : \$ 14,960.24
GST % : 7% \$ 1,047.22
Nett Amount : \$ 16,007.46

Surveyor Name and Company :

Tan Jiah 97495449
Date of survey : 18/12/18 1145
Part by Part / Lump Sum : 6 days
Resurvey Before Paint / After Paint After Paint
Authorize/Not Authorize/Without Prejudice Without Prejudice
Email : sup@lkkauto.com
Fax No : _____
HP No : _____

This claim is handled by : MINOKO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLG9687E**
 Vehicle Reg. Date: **19/10/2016**
 Make / Model : **HONDA GRACE 1.5 DX HYBRID CVT ABS D/A**
 Engine No. : **LEB5255753**
 Chassis No. : **GM41104604**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	LH front door	ht ✓	\$ 900.00		
2	1	LH front door sticker	ht ✓	\$ 50.00		
3	2	LH front door hinges	Rp	\$ 120.00		
4	1	LH front door lock	X	\$ 350.00		
5	1	LH front door checker	X	\$ 50.00		
6	2	LH front door weatherstrip front	ht ✓	\$ 45.00		
7	1	LH front door weatherstrip lower	X	\$ 50.00		
8	1	LH front door weatherstrip rear	X	\$ 80.00		
9	1	LH front door weatherstrip top	X	\$ 60.00		
10	1	LH front door trim board	X	\$ 800.00		
11	1	LH front door trim board clips	X	\$ 50.00		
12	1	LHF door outer handle side cover	X	\$ 125.00		
13	1	LHF door outer handle	X	\$ 75.00		
14	1	LHF door glass outer moulding	X	\$ 150.00		
15	1	LHF power window regulator with motor	X	\$ 320.00		
16	1	LH rear door	ht ✓	\$ 900.00		
17	1set	LH rear door sticker	ht ✓	\$ 50.00		
18	2	LH rear door hinges	Rp	\$ 120.00		
19	1	LH rear door checker	Rp	\$ 50.00		
20	1	LH rear door weatherstrip front	ht ✓	\$ 50.00		
21	1	LH rear door weatherstrip lower	X	\$ 50.00		
22	1	LH rear door weatherstrip rear	X	\$ 40.00		
23	1	LH rear door trim board	X	\$ 800.00		
24	1	LH rear door trim board clips	X	\$ 50.00		
25	1	LH rear door outer handle side cover	X	\$ 125.00		
26	1	LHR door outer handle	X	\$ 75.00		
27	1	LHR door glass outer moulding	X	\$ 120.00		
28	1	LHR power window regulator with motor	X	\$ 320.00		
29	1	Rear bumper	Rp	\$ 550.00		
30	1	Rear bumper clip - set	X	\$ 50.00		
31	1	Rear bumper retainer LH	X	\$ 39.00		
32	1	Tail lamp LH	X	\$ 420.00		
33	1	Tail lamp clip LH	X	\$ 20.00		
34	1	Rocker panel LH	Rp	\$ 970.00		
35	1	Front pillar LH	X	\$ 650.00		
36	1	Rear fender LH	Rp	\$ 1,350.00		
37	1	Rear fender sealant	X		\$ 80.00	
38	1	Rocker panel sealant	X		\$ 80.00	
39	1	Rear rim cover LH	ht ✓		\$ 250.00	
40	1	REAR RIM RH	X		\$ 450.00	

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLG9687E**
Vehicle Reg. Date: **19/10/2016**
Make / Model : **HONDA GRACE 1.5 DX HYBRID CVT ABS D/A**
Engine No. : **LEB5255753**
Chassis No. : **GM41104604**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	REAR TYRE RH	x		\$ 300.00	
42	1	REAR SHOCK ABSORBER RH	x	\$225.00		
43	1	REAR SHOCK ABSORBER TOP MOUNTING RH	x	\$40.20		
44	1	REAR SHOCK ABSORBER STOPPER RH	x	\$27.60		
45	1	REAR WHEEL HUB RH with bearing RH	<	\$197.50		
46	1	REAR WINDSCREEN GLASS MOULDING	x	\$ 198.50		
47	0	0				
48	0	0				
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLG9687E**
Vehicle Reg. Date: **19/10/2016**
Make / Model : **HONDA GRACE 1.5 DX HYBRID CVT ABS D/A**
Engine No. : **LEB5255753**
Chassis No. : **GM41104604**

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT
1	To starighten and panel beating. To cut/weld panels. To remove/refit damaged parts. FRT DOOR LH, CENTER PILLAR LH, RR DOOR LH, ROCKER PANEL LH, RR FENDER LH, RR BUMPER.	\$ 1,800.00
2	To putty, respray painting and polish affected areas. FRT DOOR LH, CENTER PILLAR LH, RR DOOR LH, ROCKER PANEL LH, RR FENDER LH, RR BUMPER.	\$ 1,800.00
3	To remove and refit interior trims and upholstery	\$ 180.00
4	To check and rectify wiring after disconnect and connect.	\$ 120.00
5	To rust proof affected areas.	\$ 180.00
6	To conduct computer wheel alignment	\$ 180.00
7	To remove and transfer front door components LHS	\$ 180.00
8	To remove and transfer rear door components LHS	\$ 180.00
9	To remove & refit undercarriage to assist work load.	\$ 280.00
10	To do tyre balancing	\$ 150.00
11	To remove & refit rear windscreen glass	\$ 180.00

14960.24



Service Request Details

Claim

S8M016Q9

Reference

None 

Loss Date

14 December 2018

Request Date

17 December 2018

Due Date

24 December 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

17.12.2018 @ 136pm

Pila veh in.

Tunfileh.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLG9687E

Make

TPVD HONDA

Service Address

...

Primary Contact/Insured

MUNA LIM BT ABDULLAH
348 EAST COAST ROAD, 428966, Singapore
94575551
MUNALIM@GMAIL.COM

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

New Message

Catherine Chong (LKK Auto)

From: pila@vermogen-group.com
Sent: Monday, 17 December, 2018 10:52 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: 'Minoko Chan'; 'Tejano Exequiel Dawal'; 'Baldoz Juan Paulo Bongon'; 'Edmond Lim'; 'Yira Rahman'; 'Glorioso Eric Paul Patambang'; 'Luis Tan'; 'ace'
Subject: Accident involving SLG9687E & SKG7109H (Your Insured) on 14/12/2018 - PLEASE ARRANGE TP SURVEY
Attachments: SLG9687E.PDF
Categories: Pragati

Dear officer in-charge,

Refer to above attachment kindly arrange our client's vehicle for pre-repair survey at **Vermogen Ace Pte Ltd** here at **6 Benoi Sector**.

VEHICLE IN WORKSHOP

Beside, we would like to check for the liability on this matter.

Kindly check & revert to us as soon as possible.

Thanks & regards,

Pila

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6358 3031

Fax: 6694 4929



Pls proceed DS with quantum s proposed

Type

 Question

Message

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKG 7109H (Insd veh)	Model:	HONDA GRACE
	SLG 9687E (TP veh)		
Date of Accident:	14/12/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	16,007.46
Final Repair Cost	:	\$	3,424.00
Loss of Use	:	\$	540.00
Rental (if any)	:	\$	9 days at \$60.00 per day
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	3,966.00

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____		
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	VERMOGEN ACE PTE LTD	:	\$ 3,966.00

NUR SHAQILAH BTE ABDOL
WAHAB

24/05/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18022707/T1hb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 24-05-2019



ATTN: PETER WANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKG 7109H	Veh. Inspected	SLG 9687E
Policy No.	VA1/GA023708	Coverage (\$)	0.00
Claim No.	S8M016Q9	Excess (\$)	0.00
Assign From	PETER WANG	Assign Date	18/12/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA GRACE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	GM41104604	Colour	SILVER
Odometer	166258	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60R15	ROADSTONE	6 mm
L/H Front Tyre	185/60R15	ROADSTONE	6 mm
R/H Rear Tyre	185/60R15	ROADSTONE	6 mm
L/H Rear Tyre	185/60R15	ROADSTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/12/2018	Inspection Date	18/12/2018
Survey held at	VERMOGEN ACE PTE LTD 1 BUKIT BATOK CRESCENT #04-54/55 WCEGA PLAZA SINGAPORE 658064		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 9687E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LH FRONT DOOR (CONSISTENT)	BENT	900.00	900.00
1	LH FRONT DOOR STICKER (CONSISTENT)	NECESSARY	50.00	50.00
2	LH FRONT DOOR HINGES (CONSISTENT)	TO REPAIR SEE LABOUR	120.00	-
1	LH FRONT DOOR LOCK (CONSISTENT)	NOT NECESSARY	350.00	-
1	LH FRONT DOOR CHECKER (CONSISTENT)	NOT NECESSARY	50.00	-
2	LH FRONT DOOR WEATHERSTRIP FRONT (CONSISTENT)	NECESSARY	45.00	45.00
1	LH FRONT DOOR WEATHERSTRIP LOWER (CONSISTENT)	NOT NECESSARY	50.00	-
1	LH FRONT DOOR WEATHERSTRIP REAR (CONSISTENT)	NOT NECESSARY	80.00	-
1	LH FRONT DOOR WEATHERSTRIP TOP (CONSISTENT)	NOT NECESSARY	60.00	-
1	LH FRONT DOOR TRIM BOARD (CONSISTENT)	NOT NECESSARY	800.00	-
1	LH FRONT DOOR TRIM BOARD CLIPS (CONSISTENT)	NOT NECESSARY	50.00	-
1	LHF DOOR OUTER HANDLE SIDE COVER (CONSISTENT)	NOT NECESSARY	125.00	-
1	LHF DOOR OUTER HANDLE (CONSISTENT)	NOT NECESSARY	75.00	-
1	LHF DOOR GLASS OUTER MOULDING (CONSISTENT)	NOT NECESSARY	150.00	-
1	LHF POWER WINDOW REGULATOR WITH MOTOR (CONSISTENT)	NOT NECESSARY	320.00	-
1	LH REAR DOOR (CONSISTENT)	BENT	900.00	900.00
1	SET LH REAR DOOR STICKER (CONSISTENT)	NECESSARY	50.00	50.00
2	LH REAR DOOR HINGES (CONSISTENT)	TO REPAIR SEE LABOUR	120.00	-
1	LH REAR DOOR CHECKER (CONSISTENT)	TO REPAIR SEE LABOUR	50.00	-
1	LH REAR DOOR WEATHERSTRIP FRONT (CONSISTENT)	NECESSARY	50.00	50.00
1	LH REAR DOOR WEATHERSTRIP LOWER (CONSISTENT)	NOT NECESSARY	50.00	-
1	LH REAR DOOR WEATHERSTRIP REAR (CONSISTENT)	NOT NECESSARY	40.00	-
1	LH REAR DOOR TRIM BOARD (CONSISTENT)	NOT NECESSARY	800.00	-
1	LH REAR DOOR TRIM BOARD CLIPS (CONSISTENT)	NOT NECESSARY	50.00	-
1	LH REAR DOOR OUTER HANDLE SIDE COVER (CONSISTENT)	NOT NECESSARY	125.00	-
1	LHR DOOR OUTER HANDLE (CONSISTENT)	NOT NECESSARY	75.00	-

Report Ref No. CC4/ASM18022707/T1hb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LHR DOOR GLASS OUTER MOULDING (CONSISTENT)	NOT NECESSARY	120.00	-
1	LHR POWER WINDOW REGULATOR WITH MOTOR (CONSISTENT)	NOT NECESSARY	320.00	-
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	550.00	-
1	SET REAR BUMPER CLIP (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR BUMPER RETAINER LH (CONSISTENT)	NOT NECESSARY	39.00	-
1	TAIL LAMP LH (CONSISTENT)	NOT NECESSARY	420.00	-
1	TAIL LAMP CLIP LH (CONSISTENT)	NOT NECESSARY	20.00	-
1	ROCKER PANEL LH (CONSISTENT)	TO REPAIR SEE LABOUR	970.00	-
1	FRONT PILLAR LH (CONSISTENT)	NOT NECESSARY	650.00	-
1	REAR FENDER LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,350.00	-
1	REAR SHOCK ABSORBER (CONSISTENT)	NOT NECESSARY	225.00	-
1	REAR SHOCK ABSORBER TOP MOUNTING RH (CONSISTENT)	NOT NECESSARY	40.20	-
1	REAR SHOCK ABSORBER STOPPER RH (CONSISTENT)	NOT NECESSARY	27.60	-
1	REAR WHEEL HUB RH WITH BEARING RH (CONSISTENT)	NOT NECESSARY	197.50	-
1	REAR WINDSCREEN GLASS MOULDING (CONSISTENT)	NOT NECESSARY	198.50	-
	LESS 20% DISCOUNT		-2,142.56	-399.00
			8,570.24	1,596.00
	SPECIAL NETT ITEMS			
1	REAR FENDER SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	ROCKER PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR RIM COVER LH (SN) (CONSISTENT)	CUT	250.00	250.00
1	REAR RIM RH (SN) (CONSISTENT)	NOT NECESSARY	450.00	-
1	REAR TYRE RH (SN) (CONSISTENT)	NOT NECESSARY	300.00	-
			1,160.00	250.00

Report Ref No. CC4/ASM18022707/T1hb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO STRAIGHTEN AND PANEL BEATING. TO CUT / WELD PANELS. TO REMOVE / REFIT DAMAGED PARTS. FRT DOOR LH, CENTER PILLAR LH, RR DOOR LH, ROCKER PANEL LH, RR FENDER LH, RR BUMPER. INCLUSIVE OF THE REPAIR OF LH FRONT DOOR HINGES, LH REAR DOOR HINGES, LH REAR DOOR CHECKER, REAR BUMPER, ROCKER PANEL LH AND REAR FENDER LH.		1,800.00	900.00
	TO PUTTY, RESPRAY PAINTING AND POLISH AFFECTED AREAS. FRT DOOR LH, CENTER PILLAR LH, RR DOOR LH, ROCKER PANEL LH, RR FENDER LH, RR BUMPER.		1,800.00	900.00
	TO REMOVE AND REFIT INTERIOR TRIMS AND UPHOLSTERY.		180.00	40.00
	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT.		120.00	30.00
	TO RUST PROOF AFFECTED AREAS.		180.00	50.00
	TO CONDUCT COMPUTER WHEEL ALIGNMENT.		180.00	60.00
	TO REMOVE AND TRANSFER FRONT DOOR COMPONENTS LHS.		180.00	60.00
	TO REMOVE AND TRANSFER REAR DOOR COMPONENTS LHS.		180.00	60.00
	TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD.	NOT NECESSARY	280.00	-
	TO DO TYRE BALANCING.		150.00	30.00
	TO REMOVE & REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
			5,230.00	2,130.00
	GRAND TOTAL		14,960.24	3,976.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,200.00

Report Ref No. CC4/ASM18022707/T1hb3s2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.