



SLG9687E

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 14/12/2018

Vehicle Reg. No. : SLG9687E
Vehicle Reg. Date: 19-Oct-2016
Make / Model : HONDA GRACE 1.5 DX HY
Engine No. : LEB5255753
Chassis No. : GM41104604

COST OF CLAIMS

Parts Cost / List Items : \$ 10,712.80
Plus/Less 20% \$ 2,142.56
Total Cost / List : \$ 8,570.24
Special Nett Items : \$ 1,160.00
Total Parts Amount : \$ 9,730.24
Total Labour Amount : \$ 5,230.00
Gross Total : \$ 14,960.24
GST % : 7% \$ 1,047.22
Nett Amount : \$ 16,007.46

Surveyor Name and Company :

Tan Jia 97495449
Date of survey : 18/12/18 1145
Part by Part / Lump Sum : 6 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : sup@kklauto.com
Fax No :
HP No :

This claim is handled by : MINOKO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLG9687E**
 Vehicle Reg. Date: **19/10/2016**
 Make / Model : **HONDA GRACE 1.5 DX HYBRID CVT ABS D/A**
 Engine No. : **LEB5255753**
 Chassis No. : **GM41104604**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	LH front door	ht	\$ 900.00		
2	1	LH front door sticker	ne	\$ 50.00		
3	2	LH front door hinges	Rp	\$ 120.00		
4	1	LH front door lock	X	\$ 350.00		
5	1	LH front door checker	X	\$ 50.00		
6	2	LH front door weatherstip front	na	\$ 45.00		
7	1	LH front door weatherstip lower	X	\$ 50.00		
8	1	LH front door weatherstip rear	X	\$ 80.00		
9	1	LH front door weatherstip top	X	\$ 60.00		
10	1	LH front door trim board	X	\$ 800.00		
11	1	LH front door trim board clips	X	\$ 50.00		
12	1	LHF door outer handle side cover	X	\$ 125.00		
13	1	LHF door outer handle	X	\$ 75.00		
14	1	LHF door glass outer moulding	X	\$ 150.00		
15	1	LHF power window regulator with motor	X	\$ 320.00		
16	1	LH rear door	ht	\$ 900.00		
17	1set	LH rear door sticker	ne	\$ 50.00		
18	2	LH rear door hinges	Rp	\$ 120.00		
19	1	LH rear door checker	Rp	\$ 50.00		
20	1	LH rear door weatherstip front	ne	\$ 50.00		
21	1	LH rear door weatherstip lower	X	\$ 50.00		
22	1	LH rear door weatherstip rear	X	\$ 40.00		
23	1	LH rear door trim board	X	\$ 800.00		
24	1	LH rear door trim board clips	X	\$ 50.00		
25	1	LH rear door outer handle side cover	X	\$ 125.00		
26	1	LHR door outer handle	X	\$ 75.00		
27	1	LHR door glass outer moulding	X	\$ 120.00		
28	1	LHR power window regulator with motor	X	\$ 320.00		
29	1	Rear bumper	Rp	\$ 550.00		
30	1	Rear bumper clip - set	X	\$ 50.00		
31	1	Rear bumper retainer LH	X	\$ 39.00		
32	1	Tail lamp LH	X	\$ 420.00		
33	1	Tail lamp clip LH	X	\$ 20.00		
34	1	Rocker panel LH	Rp	\$ 970.00		
35	1	Front pillar LH	X	\$ 650.00		
36	1	Rear fender LH	Rp	\$ 1,350.00		
37	1	Rear fender sealant	X		\$ 80.00	
38	1	Rocker panel sealant	X		\$ 80.00	
39	1	Rear rim cover LH	wt		\$ 250.00	
40	1	REAR RIM RH	X		\$ 450.00	

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLG9687E**
Vehicle Reg. Date: **19/10/2016**
Make / Model : **HONDA GRACE 1.5 DX HYBRID CVT ABS D/A**
Engine No. : **LEB5255753**
Chassis No. : **GM41104604**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	REAR TYRE RH	✕		\$ 300.00	
42	1	REAR SHOCK ABSORBER RH	✕	\$225.00		
43	1	REAR SHOCK ABSORBER TOP MOUNTING RH	✕	\$40.20		
44	1	REAR SHOCK ABSORBER STOPPER RH	✕	\$27.60		
45	1	REAR WHEEL HUB RH with bearing RH	✕	\$197.50		
46	1	REAR WINDSCREEN GLASS MOULDING	✕	\$ 198.50		
47	0	0				
48	0	0				
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLG9687E**
Vehicle Reg. Date: **19/10/2016**
Make / Model : **HONDA GRACE 1.5 DX HYBRID CVT ABS D/A**
Engine No. : **LEB5255753**
Chassis No. : **GM41104604**

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT
1	To starighten and panel beating. To cut/weld panels. To remove/refit damaged parts. FRT DOOR LH, CENTER PILLAR LH, RR DOOR LH, ROCKER PANEL LH, RR FENDER LH, RR BUMPER.	\$ 1,800.00
2	To putty, respray painting and polish affected areas. FRT DOOR LH, CENTER PILLAR LH, RR DOOR LH, ROCKER PANEL LH, RR FENDER LH, RR BUMPER.	\$ 1,800.00
3	To remove and refit interior trims and upholstery	\$ 180.00
4	To check and rectify wiring after disconnect and connect.	\$ 120.00
5	To rust proof affected areas.	\$ 180.00
6	To conduct computer wheel alignment	\$ 180.00
7	To remove and transfer front door components LHS	\$ 180.00
8	To remove and transfer rear door components LHS	\$ 180.00
9	To remove & refit undercarriage to assist work load.	\$ 280.00
10	To do tyre balancing	\$ 150.00
11	To remove & refit rear windscreen glass	\$ 180.00

900

900

40.

30

50.

60.

60

60.

X

30.

X