

ASS. REC. BY:

REF:

CS/AWA18022709 (Jvber)

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Hazel Chuq

of

AWA

Date/Time:

18.12.2018 4.19pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 638H

Insured:

WD 1732X

at Workshop m/s

Carz Auto

Tel:

9073 6692.

of

No. 61 Woodlands Ind Park SQ #04-04

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11.12.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS wp:

19.12.2018 @ morning

H.O.D. Endorsement:

Date/Time:

18/12/2018 4.55pm

Person Contacted:

Allan

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLB 638H - X
	WD 1732X - X

REF: Hwa Jix

REF: AWA

ASSIGNMENT

From: Date: 19/12/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 81B 638H

at Workshop n/s

of No. 61 woodlands Ind. park Eq #

Insured: 04-04

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLB 638H

Yr Regn: 11 Jan 2013

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes CLS350 C.C 3498

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 103791 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2183592A049636

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/35 R19

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 11/12/18 D.O.I. 19/12/18

Survey held at: Carz Auto

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/12/18 Confirmed L/S \$6050/- 4days repair. (Red 16,517.00, 739)

RECEIVED 28 DEC 2018

28/12/2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 28/12 - typist

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others

TOTAL

Report Format :

TP

Lump Sum / I.B.I. (\$

6050/-

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

350

350

Catherine Chong (LKK Auto)

From: Chua, Hazel <Hazel.Chua@awac.com>
Sent: Tuesday, 18 December, 2018 4:19 PM
To: assignments@lkkauto.com
Cc: sur@lkkauto.com
Subject: New matter - Public Liability Claim - Accident between WD1732X and SLB638H on 11/12/2018 ; Insured: Satoyu Trading Pte Ltd; Policy no: C044692/001
Attachments: GIA REPORT SLB638H.pdf; PRI SLB638H.pdf; 2376_001.pdf; IMG-20181211-WA0042.jpg; IMG-20181211-WA0043.jpg; IMG-20181211-WA0044.jpg; IMG-20181211-WA0041.jpg; IMG-20181211-WA0045.jpg

Dear Sir/Madam

Our insured is the forklift WD1732X which collided into Third Party Vehicle SLB638H whilst reversing.

Attached are the accident report, the driving license of our Insured's employee and the photos of the Third Party Vehicle. The vehicle is a Mercedes Benz CLS350-3.5(A) car model. The Third Party vehicle is presently in Carz Auto Services Pte Ltd's workshop. The contact person is Mr Allan Goh and he is contactable at 9023 6692.

Please make the necessary arrangement and commence work at your end for the above matter. Please kindly conduct your survey by today if possible.

Upon completion of your survey, please kindly keep me informed of your findings.

Please kindly acknowledge this email upon receipt. Thank you.

Best Regards

Hazel Chua
Claims Analyst
Allied World Assurance Company, Ltd
60 Anson Road #08-01 (8th Floor) Singapore 079914
T: +65 6423 0531
F: +65 6423 0798
E: Hazel.Chua@awac.com
W: www.awac.com

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	2394M
Vehicle Details	
Vehicle No.:	SLB638H
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CLS 350 A
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	27695230163751
Chassis No.:	WDD2183592A049636
Maximum Power Output:	225.0 kW (301 bhp)
Open Market Value:	\$83,525.00
Original Registration Date:	11 Jan 2013
First Registration Date:	11 Jan 2013
Transfer Count:	1
Actual ARF Paid:	\$83,525.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jan 2023
PARF Rebate Amount:	\$58,467.00
Intended COE Rebate Details	
COE Expiry Date:	10 Jan 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$93,990.00
COE Rebate Amount:	\$37,726.00
Total Rebate Amount:	\$96,193.00

The information contained herein is correct as at 20 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/12/2018 15:45
Date Of Accident	11/12/2018 14:30
Exact Location Of Accident	OPS CAR PARK PASIR PANJANG WHOLESALE CENTRE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB638H
Insured/Policyholder	
Name Of Registered Owner	HPS VEG TRADING
o Reg No	53052394M
Email Address	HPSVEGTRADING@SINGNET.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-98455357

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	CLS350-3.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3042011800

Cover Note Number

Driver

Name of Driver	LEE KHIAM HOCK
NRIC No	S1162473A
Date Of Birth	31/08/1955
Occupation	OUTDOOR
Date Of Driving Pass	01/02/1974
Driving Experience	44 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98455357
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 21, WHOLESALE CENTRE, #01-142, SINGAPORE 110021
 Postcode
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLIDED INTO PARKED VEHICLE
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident


ON 11/12/2018 AT ABOUT 1430 HRS. MY VEHICLE A (SLB638H) WAS PARKED AT THE OPEN CAR PARK AT BLK 21, PASIR PANJANG WHOLESALE CENTRE. WHEN I WAS ABOUT TO TURN OUT OF THE CARPARK LOT. SUDDENLY VEHICLE B (WD1732X) TRAVELLING AGAINST THE TRAFFIC WHICH IS SUPPOSED TO BE ONE WAY TRAFFIC AND OFFENDED THE LAW, COLLIDED TO THE FRONT PORTION OF MY VEHICLE CAUSING THE DAMAGE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number WD1732X
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver TOE WIN
 NRIC/Passport Number G6066223T
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)



Open Space Car Park
BLK 21 Pasir Panjang Wholesale Centre

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to circumstances

<input type="checkbox"/> Claim own policy <input type="checkbox"/> Claim third party <input checked="" type="checkbox"/> Claim OD <u>TP</u> at other workshop <u>Carz Auto</u> <input type="checkbox"/> For record purpose
Policy No. <u>DMPCSN 3042011800</u> Insurer <u>Cina</u> Veh. No. <u>SLB638H</u>

DECLARATION

/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

3. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM)

#04-04 Singapore 757047

Tel: 65 6493 1924

Fax: 65 6493 1928

VEHICLE REPAIR ESTIMATE

Insurance Company: ALLIED WORLD INSURANCE

Address: NO 60, ANSON ROAD, #08-01, MAPLETREE ANSON, S(079914)

Telephone: 65 6220 1188

Fax:

Email: Motorsurvey@awac.com

Make/ Model : MERCEDES-BENZ

Date: 14/12/2018

Chassis No : WDD2183592A049636

Vehicle No: SLB 638 H

Date/Time of Accident : 11/12/2018 14:30

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	FRONT BUMPER DD	1	\$1180 3,100.80	10%	\$1062 2,790.72
2	FRONT BUMPER CENTER LOWER GRILLE NN	1	\$ 388.90	10%	\$ 350.01
3	FRONT BUMPER SIDE BRACKET (RH) CRA	1	\$ 60 246.80	10%	\$ 54 222.42
4	FRONT BUMPER REINFORCEMENT NN	1	\$ 628.70	10%	\$ 565.83
5	FRONT BUMPER SPONGE (FRONT) CUT	1	\$ 158.90	10%	\$ 143.01
6	FRONT BUMPER SPONGE (REAR) CUT	1	\$ 163.20	10%	\$ 146.88
7	FRONT BUMPER INNER FRAME CENTER NN	1	\$ 2,825.70	10%	\$ 2,543.13
8	FRONT BUMPER SIDE FRAME RH NN	1	\$ 234.10	10%	\$ 210.69
9	FRONT BUMPER PARKING SENSOR RH CRA	1	\$ 200 410.20	10%	\$ 180 369.18
10	FRONT BUMPER TOW COVER RH NN	1	\$ 89.10	10%	\$ 80.19
11	FRONT BUMPER LED LAMP RH CRA	1	\$ 410 641.30	10%	\$ 369 577.17
12	FRONT BUMPER LED LAMP GARNISH RH CRA	1	\$ 102 366.70	10%	\$ 92 330.03
13	FRONT BUMPER CENTER TOP BRACKET CRA	2	\$ 180 456.80	10%	\$ 162 411.12
14	FRONT BUMPER NOZZLE RH NN	1	\$ 330.60	10%	\$ 297.54
15	FRONT BUMPER NOZZLE COVER RH CRA	1	\$ 63 120.80	10%	\$ 56 108.72
16	FRONT BUMPER TOP EMBLEM NEL	1	\$ 120.90	10%	\$ 108.81
17	FRONT BUMPER REINFORCEMENT BRACKET RH NN	1	\$ 340.60	10%	\$ 306.54
18	FRONT HEAD LAMP (RH) CRA	1	\$2800 6,635.80	10%	\$2520 5,972.22
19	FRONT HEAD LAMP TOP PANEL RH DEF	1	\$ 180 334.20	10%	\$ 162 300.78
20	FRONT HEAD LAMP SIDE BRACKET RH DD	1	\$ 65.40	10%	\$ 58.86
21	FRONT HEAD LAMP LOWER BRACKET RH NN	1	\$ 100.00	10%	\$ 90.00
22	FRONT RADIATOR GRILLE BASE DEF	1	\$ 480.60	10%	\$ 432.54
23	FRONT RADIATOR GRILLE LOGO NN	1	\$ 320.10	10%	\$ 288.09
24	FRONT RADIATOR GRILLE CHROME OUTER DEF	1	\$ 340.20	10%	\$ 306.18
25	FRONT RADIATOR GRILLE CHROME CENTER CRA	2	\$ 320.20	10%	\$ 288.18
26	FRONT SUPPORT PANEL TOP CRA	1	\$ 265.20	10%	\$ 238.68
27	FRONT SUPPORT PANEL TOP GARNISH NN	1	\$ 385.60	10%	\$ 347.04
28	FRONT ENGINE UNDER COVER NN	1	\$ 485.70	10%	\$ 437.13
29	FRONT FENDER SPLASHIELD RH NN	1	\$ 350.70	10%	\$ 315.63

SPECIAL ITEMS	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT RADIATOR GRILLE CLIP <i>NEC</i>	1 SET	\$ 40.00	\$ 30 40.00
2	FRONT NUMBER PLATE WITH CASING <i>DEF</i>	1 SET	\$ 50.00	\$ 40 50.00
3	FRONT ENGINE UNDER COVER CLIPS <i>NN</i>	1 SET	\$ 40.00	\$ 40.00
4	FRONT SUPPORT PANEL TOP GARNISH CLIP <i>NN</i>	1 SET	\$ 40.00	\$ 40.00
5	FRONT FENDER SPLASHIELD CLIP <i>NN</i>	1 SET	\$ 40.00	\$ 40.00
Total Special Items Cost				\$ 18,847.02

Labour Works/ Panel Beating Related Works

Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS	\$ 600 1,400.00

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 200 1,000.00

Others Cost (Accident Repair Related Expenses)

Job Scope	Quotation
TO REMOVE/ REPLACE AIRCON CONDENSOR, VACUUM, TOP UP AIRCON GAS	\$ 120 120.00
TO REMOVE/ REFIT WIRING CHECKS	\$ 30 100.00
TO TUFFCOAT AFFECTED AREAS	\$ 40 200.00
TO REMOVE/ REPLACE PARKING SENSORS AND DISTANCE SETTLING	\$ 30 150.00
TO REAPPLY NANO COATING TO AFFECTED AREAS	\$ 120 400.00
TO CHECK AND RESET ENGINE CHECK LIGHT AND DECODE SYSTEM	\$ 100 350.00
Total Others Cost	\$ 1,320.00
GRAND TOTAL	\$ 22,567.02

NET- \$6050/-

Hwee Jie
19/12/18

[Signature]
20/12/18

c/s 4days

[Signature]



[Signature]

CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Jeslyn Chua
Job Title: Account Assistant
Direct Contact: 65 8322 7418
Email: jeslyn@carzauto.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA18022709/Jvbe2

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 03-01-2019



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	WD 1732X	Veh. Inspected	SLB 638H
Policy No.	C044692/001	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	HAZEL CHUA	Assign Date	18/12/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CLS 350 A	c.c	3498
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WDD2183592A049636	Colour	BLACK
Odometer	103791	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/35 R19	YOKOHAMA	6 mm
L/H Front Tyre	255/35 R19	YOKOHAMA	6 mm
R/H Rear Tyre	255/35 R19	YOKOHAMA	6 mm
L/H Rear Tyre	255/35 R19	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/12/2018	Inspection Date	19/12/2018
Survey held at	CARZ AUTO - 61 WOODLANDS IND PARK E9 #04-04		
Repairer	-		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 638H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DENTED	3,100.80	1,180.00
1	FRONT BUMPER CENTER LOWER GRILLE	NOT NECESSARY	388.90	-
2	FRONT BUMPER SIDE BRACKET	O/S CRACKED	246.80	60.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	628.70	-
1	FRONT BUMPER SPONGE (FRONT)	CUT	158.90	158.90
1	FRONT BUMPER SPONGE (REAR)	CUT	163.20	163.20
1	FRONT BUMPER INNER FRAME CENTER	NOT NECESSARY	2,825.70	-
1	FRONT BUMPER SIDE FRAME RH	NOT NECESSARY	234.10	-
2	FRONT BUMPER PARKING SENSOR RH	CRACKED-1 PC ONLY	410.20	200.00
1	FRONT BUMPER TOW COVER RH	NOT NECESSARY	89.10	-
1	FRONT BUMPER LED LAMP RH	CRACKED	641.30	410.00
1	FRONT BUMPER LED LAMP GARNISH RH	CRACKED	366.70	102.00
2	FRONT BUMPER CENTER TOP BRACKET	CRACKED	456.80	180.00
1	FRONT BUMPER NOZZLE RH	NOT NECESSARY	330.60	-
1	FRONT BUMPER NOZZLE COVER RH	CRACKED	120.80	63.00
1	FRONT BUMPER TOP EMBLEM	NECESSARY	120.90	120.90
1	FRONT BUMPER REINFORCEMENT BRACKET RH	NOT NECESSARY	340.60	-
2	FRONT HEAD LAMP	O/S CRACKED	6,635.80	2,800.00
1	FRONT HEAD LAMP TOP PANEL RH	DEFORMED	334.20	180.00
1	FRONT HEAD LAMP SIDE BRACKET RH	DENTED	65.40	65.40
1	FRONT HEAD LAMP LOWER BRACKET RH	NOT NECESSARY	100.00	-
1	FRONT RADIATOR GRILLE BASE	DEFORMED	480.60	480.60
1	FRONT RADIATOR GRILLE LOGO	NOT NECESSARY	320.10	-
1	FRONT RADIATOR GRILLE CHROME OUTER	DEFORMED	340.20	340.20
2	FRONT RADIATOR GRILLE CHROME CENTER	CRACKED	320.20	320.20
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	385.60	-
1	FRONT ENGINE UNDER COVER	NOT NECESSARY	485.70	-
1	FRONT FENDER SPLASHIELD RH	NOT NECESSARY	350.70	-
1	FRONT SUPPORT PANEL TOP	CRACKED	265.20	265.20

Report Ref No. CS/AWA18022709/Jvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-2,070.78	-708.96
			18,637.02	6,380.64
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT RADIATOR GRILLE CLIP (SN)	NECESSARY	40.00	30.00
1	SET FRONT NUMBER PLATE WITH CASING (SN)	DEFORMED	50.00	40.00
1	SET FRONT ENGINE UNDER COVER CLIP (SN)	NOT NECESSARY	40.00	-
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	40.00	-
1	SET FRONT FENDER SPLASHIELD CLIP (SN)	NOT NECESSARY	40.00	-
			210.00	70.00
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS.		1,400.00	600.00
	TO RESPRAY AFFECTED AREAS.		1,000.00	200.00
	TO REMOVE / REPLACE AIRCON CONDENSOR, VACUUM, TOP UP AIRCON GAS.	NOT NECESSARY	120.00	-
	TO REMOVE / REFIT WIRING CHECKS.		100.00	30.00
	TO TUFFCOAT AFFECTED AREAS.		200.00	40.00
	TO REMOVE / REPLACE PARKING SENSORS AND DISTANCE SETTLING.		150.00	30.00
	TO REAPPLY NANO COATING TO AFFECTED AREAS.		400.00	120.00
	TO CHECK AND RESET ENGINE CHECK LIGHT AND DECODE SYSTEM.		350.00	100.00
			3,720.00	1,120.00
	GRAND TOTAL		22,567.02	7,570.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,050.00

Report Ref No. CS/AWA18022709/Jvbe2

ONG HWEE JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.