

Original

INS. CASE OWNER

CC/LPC1802

LKE

IDAC

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost: (w/hst)

SS 2088.64

Loss of Rental (LOR):

SS 334.75

(5 days) x \$66.95

Loss of Use (LOU):

SS -

(5 x days)

Loss of Income (LOI):

SS 250.00

(50 x 5 days)

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

GIA/LTA Search

SS 7.49

Medical:

SS -

Disbursement:

SS -

(e.g. Tow / Independent)

Legal Cost

SS -

Total:

SS 2680.88

Global Sum SS: 2680.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 2680.00

Name 1:

Regulus Engineering & Trading Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Taylor

REF:

LPC

ASSIGNMENT

SLJ7H89Z

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 100 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ7H89Z Yr Regn: 2016 Dec.
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3.

C.S. 1496

Colour: Blue A/C Insured / Std / NI / NA

Sp. Reading: 126277 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM 65N.22HSH0132506

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16
R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Triangle

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 14/12/18

Survey held at: Pegasus Insurance

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P - 1952.00 (Red ~~6071.60~~ / 76%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) \$ + RS. 50

2) Photos

3) Others

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18022717/T1fb3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 18-12-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 3095G	Veh. Inspected	SLJ 7189Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	18/12/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/12/2018	Inspection Date	18/12/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564313

Your ref: To Be Advised
Our ref: CC4/LPC18022717/T1fb3

Date: 19.12.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLJ7189Z

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18.12.2018 at the premises of M/s Pegasus Engineering & Trading Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	8,023.60
Revised Estimate Amount	: S\$	1,952.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800
Officer in Charge : YVONNE WONG YIN CHENG Tel : Email :

Customer :
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn : Tel : Fax No. :

Quotation No. : QO18/12-1252	Quotation Date : 15/12/2018	Terms : 30 DAYS
Vehicle No. : SLJ7189Z	Chassis No. : JM6BN22A8H0132506	Third Party Insurer : LONPAC
Model : MAZDA 3	Date of Accident : 15/12/2018	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1	1,075.0000	de 1,075.00
2	REAR BUMPER SIDE RETAINERS	2	45.0000	nm x 90.00
3	REAR BUMPER CLIPS	10	4.0000	nm 40.00
4	REAR BUMPER TOW COVER	2	25.0000	x 50.00
5	REAR BUMPER REFLECTORS	2	55.0000	x 110.00
6	REAR REINFORCEMENT	1	545.0000	x 545.00
7	REAR BUMPER SIDE HOLDERS	2	50.0000	x 100.00
8	REAR BUMPER SIDE HOLDER RIVETS	2	5.0000	x 10.00
9	REAR BUMPER CENTER BRACKET	1	150.0000	x 150.00
10	BOOT LID COVER	1	965.0000	nm 965.00
11	BOOT LID LOCK	1	155.0000	x 155.00
12	BOOT LID LOCK SWITCH	1	135.0000	x 135.00
13	BOOT LID WEATHERSTRIP	1	135.0000	x 135.00
14	BOOT LID KEYLESS SENSOR	1	80.0000	x 80.00
15	BOOT LID INNER TRIM BOARD	1	285.0000	nm x 285.00
16	BOOT LID INNER TRIM BOARD CLIPS	10	5.0000	y 50.00
17	REAR END PANEL	1	722.0000	x 722.00
18	REAR END PANEL TOP GARNISH	1	195.0000	x 195.00
19	REAR END PANEL TOP GARNISH CLIPS	10	5.0000	y 50.00
20	LESS 20% (ITEM 1 TO ITEM 19)	1	-988.4000	-988.40
21	REVERSE SENSOR	1	280.0000	200 280.00 nm
22	TO REMOVE & REPLACED REAR REVERSE SENSOR	1	120.0000	30 120.00

C/F 0.00



Quotation

From :	
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800	
Officer in Charge : YVONNE WONG YIN CHENG	
Tel :	
Email :	

Customer :
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn: :
Tel :
Fax No. :

Quotation No. : QO18/12-1252	Quotation Date : 15/12/2018	Terms : 30 DAYS
Vehicle No. : SLJ7189Z	Chassis No. : JM6BN22A8H0132506	Third Party Insurer : LONPAC
Model : MAZDA 3	Date of Accident : 15/12/2018	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
23	TO REMOVE & REARRANGE REAR ELECTRICAL WIRING WHERE NECESSARY	1	120.0000	30. 120.00
24	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS	1	150.0000	un x 150.00
25	TO PANEL BEATING, KNOCKING & STRAIGHTEN NECESSARY PORTION, REMOVE & RENEWAL OF PARTS ADJUST & REALIGN TO THE SAME.	1	1,800.0000	300 400 1,800.00
26	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREA.	1	1,600.0000	300 400 1,600.00

Center:

Taughlin 97495744
- WP
18/12/18 @ 1040.
Resurvey before paint
of #elays
sure William to work

Sub Total	8,023.60
GST(7.00%)	561.65
Total (SGD)	8,585.25

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800
Officer in Charge : YVONNE WONG YIN CHENG
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn :
Tel :
Fax No. :

Quotation No. : QO18/12-1252	Quotation Date : 15/12/2018	Terms : 30 DAYS
Vehicle No. : SLJ7189Z	Chassis No. : JM6BN22A8H0132508	Third Party Insurer : LONPAC
Model : MAZDA 3		Date of Accident : 15/12/2018
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1	1,075.0000	de 1,075.00
2	REAR BUMPER SIDE RETAINERS	2	45.0000	X 90.00
3	REAR BUMPER CLIPS	10	4.0000	ne 40.00
4	REAR BUMPER TOW COVER	2	25.0000	X 50.00
5	REAR BUMPER REFLECTORS	2	55.0000	X 110.00
6	REAR REINFORCEMENT	1	545.0000	X 545.00
7	REAR BUMPER SIDE HOLDERS	2	50.0000	X 100.00
8	REAR BUMPER SIDE HOLDER RIVETS	2	5.0000	X 10.00
9	REAR BUMPER CENTER BRACKET	1	150.0000	X 150.00
10	BOOT LID COVER	1	965.0000	R 965.00
11	BOOT LID LOCK	1	155.0000	X 155.00
12	BOOT LID LOCK SWITCH	1	135.0000	X 135.00
13	BOOT LID WEATHERSTRIP	1	135.0000	X 135.00
14	BOOT LID KEYLESS SENSOR	1	80.0000	X 80.00
15	BOOT LID INNER TRIM BOARD	1	285.0000	X 285.00
16	BOOT LID INNER TRIM BOARD CLIPS	10	5.0000	X 50.00
17	REAR END PANEL	1	722.0000	X 722.00
18	REAR END PANEL TOP GARNISH	1	195.0000	X 195.00
19	REAR END PANEL TOP GARNISH CLIPS	10	5.0000	X 50.00
20	LESS 20% (ITEM 1 TO ITEM 19)	1	-988.4000	-988.40
21	REVERSE SENSOR	1	280.0000	200 280.00
22	TO REMOVE & REPLACED REAR REVERSE SENSOR	1	120.0000	30 120.00

C/F 0.00

Page 1 of 2



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer In Charge : YVONNE WONG YIN CHENG Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
--	---

Quotation No. : QO18/12-1252	Quotation Date : 15/12/2018	Terms : 30 DAYS
Vehicle No. : SLJ7189Z	Chassis No. : JM6BN22A8H0132508	Third Party Insurer : LONPAC
Model : MAZDA 3	Date of Accident : 15/12/2018	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
23	TO REMOVE & REARRANGE REAR ELECTRICAL WIRING WHERE NECESSARY	1	120.0000	30. 120.00
24	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS	1	150.0000	X 150.00
25	TO PANEL BEATING, KNOCKING & STRAIGHTEN NECESSARY PORTION, REMOVE & RENEWAL OF PARTS ADJUST & REALIGN TO THE SAME.	1	1,800.0000	200 400 1,800.00
26	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREA.	1	1,800.0000	200 400 1,800.00

860

P - # 892.00
 B - # 200.00
 C - # 860.00

 T - # 1952.00 P/P

Taufik 97495744
 WP
 18/12/18 @ 1040.
 Remun before paint
 o/peboys
 sure/blanko.com

Sub Total	8,023.60
GST(7.00%)	561.65
Total (SGD)	8,585.25

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 17 December 2018 2:01 PM
To: Admin-D (LKKAuto)
Cc: MT_Claim_SG; Pegasus Engineering
Subject: FW: ACCIDENT INVOLVING SLJ7189Z & YOUR INSURED: GBE3095G DOA: 15/12/2018 - ARRANGE SURVEY

206pro 17/12/2018
penoroyenne
vehicle in

Dear Catherine,

Kindly proceed accordingly.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Pegasus Engineering [mailto:ar_claims@pegasusengrg.com.sg]

Sent: Monday, 17 December, 2018 1:57 PM

To: GERALD POH WEE BIN

Subject: Re: ACCIDENT INVOLVING SLJ7189Z & YOUR INSURED: GBE3095G DOA: 15/12/2018 - ARRANGE SURVEY

Hi Gerald

We like to appoint LKK Mohamad Taufikh to survey our vehicle.

Thank You

Best Regards,

Yvonne Wong

Pegasus Engineering & Trading Pte Ltd

74 Kian Teck Road S628800

Office: 65137748

Fax: 62513161

On Mon, Dec 17, 2018 at 1:45 PM GERALD POH WEE BIN <geraldpoh@lonpac.com> wrote:

WITHOUT PREJUDICE

Our Ref : 18/18/18/VC05/021228

Dear Yvonne,

As spoken, please see attached and revert to us.

We are unable to agree on a direct settlement yet as our insured has yet to lodge a report.

In the meantime, please furnish us with a copy of your client's GIA report.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Pegasus Engineering [mailto:ar_claims@pegasusengrg.com.sg]

Sent: Monday, 17 December, 2018 1:06 PM

To: GERALD POH WEE BIN

Subject: ACCIDENT INVOLVING SLJ7189Z & YOUR INSURED: GBE3095G DOA: 15/12/2018 - ARRANGE SURVEY

Your Ref: GBE3095G

Our Ref: SLJ7189Z

DOA: 15/12/2018

Without Prejudice

Dear All,

We refer to the above matter.

Pursuant to paragraph 2.3 of Pre-Action Protocol for NIMA Cases, please let us have a **list of 10 motor surveyors** for our selection and please let us know within **2 working days** whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

In the event that you request for post repair inspection pursuant to paragraph 4.1 under the NIMA Protocol, you must compensate our client for the loss of use of his/her vehicle for the day that the inspection is conducted.

In addition, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

Vehicle will be ground at our premises. Please arrange to survey our client's vehicle at 74 Kian Teck Road S628800.

Thank You

Best Regards,

Yvonne Wong

Pegasus Engineering & Trading Pte Ltd

74 Kian Teck Road S628800

Office: 65137748

Fax: 62513161


Shu Pei (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 2 January 2019 1:35 PM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; Admin A; Poh Kin (LKKAUTO)
Subject: RE: ACCIDENT INVOLVING SLJ7189Z & YOUR INSURED: GBE3095G DOA: 15/12/2018 - Our Ref: 18/18/18/VC05/021228
Attachments: GBE3095G 151218.PDF

Dear Shu Pei

Attached is our Insured's GIA report for your handling.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706




From: ONG LI LI
Sent: Thursday, 20 December, 2018 11:07 AM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; Admin A; Poh Kin (LKKAUTO)
Subject: RE: ACCIDENT INVOLVING SLJ7189Z & YOUR INSURED: GBE3095G DOA: 15/12/2018 - Our Ref: 18/18/18/VC05/021228

Dear Shu Pei

Our Insured has not reported the accident to us yet.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Thursday, 20 December, 2018 8:55 AM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; Admin A; Poh Kin (LKKAUTO)
Subject: RE: ACCIDENT INVOLVING SLJ7189Z & YOUR INSURED: GBE3095G DOA: 15/12/2018 - ARRANGE SURVEY

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SLJ 7189Z at M/s Pegasus Engineering & Trading Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Our case handler in-charge is Poh Kin and he can be contacted at DID: 6841-2132.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 17 December 2018 2:21 PM

To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: RE: ACCIDENT INVOLVING SLJ7189Z & YOUR INSURED: GBE3095G DOA: 15/12/2018 - ARRANGE SURVEY

Dear Mr Gerald,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]

Sent: Monday, 17 December, 2018 2:01 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>; Pegasus Engineering <car_claims@pegasusengrg.com.sg>

Subject: FW: ACCIDENT INVOLVING SLJ7189Z & YOUR INSURED: GBE3095G DOA: 15/12/2018 - ARRANGE SURVEY


Dear Catherine,

Kindly proceed accordingly.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Pegasus Engineering [mailto:ar_claims@pegasusengrg.com.sg]

Sent: Monday, 17 December, 2018 1:57 PM

To: GERALD POH WEE BIN

Subject: Re: ACCIDENT INVOLVING SLJ7189Z & YOUR INSURED: GBE3095G DOA: 15/12/2018 - ARRANGE SURVEY

Hi Gerald

We like to appoint LKK Mohamad Taufikh to survey our vehicle.

Thank You

Best Regards,

Yvonne Wong
Pegasus Engineering & Trading Pte Ltd
74 Kian Teck Road S628800
Office: 65137748
Fax: 62513161

On Mon, Dec 17, 2018 at 1:45 PM GERALD POH WEE BIN <geraldpoh@lonpac.com> wrote:

WITHOUT PREJUDICE

Our Ref : 18/18/18/VC05/021228

Dear Yvonne,

As spoken, please see attached and revert to us.

We are unable to agree on a direct settlement yet as our insured has yet to lodge a report.

In the meantime, please furnish us with a copy of your client's GIA report.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Pegasus Engineering [mailto:ar_claims@pegasusengrsg.com.sg]

Sent: Monday, 17 December, 2018 1:06 PM

To: GERALD POH WEE BIN

Subject: ACCIDENT INVOLVING SLJ7189Z & YOUR INSURED: GBE3095G DOA: 15/12/2018 - ARRANGE SURVEY

Your Ref: GBE3095G

Our Ref: SLJ7189Z

DOA: 15/12/2018

Without Prejudice

Dear All,

We refer to the above matter.

Pursuant to paragraph 2.3 of Pre-Action Protocol for NIMA Cases, please let us have **a list of 10 motor surveyors** for our selection and please let us know within **2 working days** whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

In the event that you request for post repair inspection pursuant to paragraph 4.1 under the NIMA Protocol, you must compensate our client for the loss of use of his/her vehicle for the day that the inspection is conducted.

In addition, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

Vehicle will be ground at our premises. Please arrange to survey our client's vehicle at 74 Kian Teck Road S628800.

Thank You

Best Regards,

Yvonne Wong

Pegasus Engineering & Trading Pte Ltd

74 Kian Teck Road S628800

Office: 65137748

Fax: 62513161



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18022717/T1da3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Date : 21-02-2020	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 3095G	Veh. Inspected	SLJ 7189Z	
Policy No.	Z18VC05000949	Coverage (\$)	0.00	
Claim No.	18/18/18/VC05/021228	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	17/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6BN22A8H0132506	Colour	BLUE	
Odometer	126277	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	TRIANGLE	6 mm	
L/H Front Tyre	205/60 R16	TRIANGLE	6 mm	
R/H Rear Tyre	205/60 R16	TRIANGLE	6 mm	
L/H Rear Tyre	205/60 R16	TRIANGLE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/12/2018	Inspection Date	18/12/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 7189Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,075.00	1,075.00
2	REAR BUMPER SIDE RETAINERS @\$45.00	NOT NECESSARY	90.00	-
10	REAR BUMPER CLIPS @\$4.00	NECESSARY	40.00	40.00
2	REAR BUMPER TOW COVER @\$25.00	NOT NECESSARY	50.00	-
2	REAR BUMPER REFLECTORS @\$55.00	NOT NECESSARY	110.00	-
1	REAR REINFORCEMENT	NOT NECESSARY	545.00	-
2	REAR BUMPER SIDE HOLDERS @\$50.00	NOT NECESSARY	100.00	-
2	REAR BUMPER SIDE HOLDER RIVETS @\$5.00	NOT NECESSARY	10.00	-
1	REAR BUMPER CENTER BRACKET	NOT NECESSARY	150.00	-
1	BOOT LID COVER	TO REPAIR SEE LABOUR	965.00	-
1	BOOT LID LOCK	NOT NECESSARY	155.00	-
1	BOOT LID LOCK SWITCH	NOT NECESSARY	135.00	-
1	BOOT LID WEATHERSTRIP	NOT NECESSARY	135.00	-
1	BOOT LID KEYLESS SENSOR	NOT NECESSARY	80.00	-
1	BOOT LID INNER TRIM BOARD	NOT NECESSARY	285.00	-
10	BOOT LID INNER TRIM BOARD CLIPS @\$5.00	NOT NECESSARY	50.00	-
1	REAR END PANEL	NOT NECESSARY	722.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	195.00	-
10	REAR END PANEL TOP GARNISH CLIPS @\$5.00	NOT NECESSARY	50.00	-
	LESS 20% DISCOUNT		-988.40	-223.00
			3,953.60	892.00
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	NOT WORKING	280.00	200.00
			280.00	200.00
LABOUR				
	TO REMOVE & REPLACED REAR REVERSE SENSOR .		120.00	30.00
	TO REMOVE & REARRANGE REAR ELECTRICAL WIRING WHERE NECESSARY.		120.00	30.00
	TO APPLY RUSTPROOFING/TUFFCOATING TREATMENT TO REPLACED PARTS.	NOT NECESSARY	150.00	-

Report Ref No. CC4/LPC18022717/T1da3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BOOT LID COVER .		1,800.00	400.00
	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREA.		1,600.00	400.00
			3,790.00	860.00
GRAND TOTAL			8,023.60	1,952.00
RECOMMENDED COST OF REPAIRS				1,952.00

Report Ref No. CC4/LPC18022717/T1da3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES - This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.