



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877	Cust No/Name /Mr Lim Tze Seng (lin Zicheng) Reg No/Reg Date SLH9134D / 23/11/2016 Date In/Mileage 12/12/2018/ 0 Chassis No KNAHU815VG7164401 Engine No D4FDGH113219 Make/Model KIA/CARENS 1.7 A D SX SUNROOF GP8 Colour/Trim K7N / WK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
F0000034	Credit	17/12/2018/ 08:34	DS	218 / MarsLer	15280				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
M	SUNDRY								50.00 ✓
	FRONT NUMBER PLATE WITH CASING <i>3ent</i>								250.00 ✓
S	MIPNT88088								80.00 <i>60</i>
	DIAGNOSTIC/SCANNING ✓								
S	MIPNT88088								200.00 <i>100</i>
	TO CHECK LIGHTNING & WIRING ON FRONT ACCIDENT AFFECTED AREAS ✓								
S	MIPNT88088								2400.00 <i>600</i>
	TO APPLY SEALANT KIT ON THE NEW BODY KIT ✓								
S	MIPNT88088								840
	TO REPLACE FRONT BUMPER, REINFORCEMENT, ETC. <input type="checkbox"/>								1260.00
	STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS								
S	MIPNT98088								
	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS								
M	KS 86511 A4 010	COVER - FRONT BUMPER	<i>255</i>		1.00	695.00	0.00	695.00 ✓	
P	KS 86520 A4 000	ABSORBER - FRONT BUMPER	<i>300</i>		1.00	78.00	0.00	78.00 ✓	
P	KS 86530 A4 000	RAIL ASSY- FRONT BUMPER	<i>300</i>		1.00	389.00	0.00	389.00 ✓	
P	KS 06032 50 037A	FASTENER- BUMPER	<i>300</i>		15.00	2.00	0.00	30.00 ✓	
M	KS 86320 A4 000	EMBLEM - KIA	<i>76</i>		1.00	76.00	0.00	76.00 ✓	
M	KS 86561 A4 000	MESH - FRONT BUMPER	<i>183</i>		1.00	183.00	0.00	183.00 ✓	
M	KS 95720 A4 001K 7N	ULTRASONIC SENSOR AS	<i>162</i>		1.00	162.00	0.00	162.00 ✓	
M	KS 86583 A4 000	HOLDER PARKING ASSIS	<i>17</i>		1.00	17.00	0.00	17.00 ✓	
M	KS 86581 A4 000	HOLDER PARKING ASSIS	<i>17</i>		1.00	17.00	0.00	17.00 ✓	
M	KS 86582 A4 000	HOLDER PARKING ASSIS	<i>17</i>		1.00	17.00	0.00	17.00 ✓	
M	KS 86584 A4 000	HOLDER PARKING ASSIS	<i>17</i>		1.00	17.00	0.00	17.00 ✓	
M	SUK91010104	CARENS BODYKIT ASSY	<i>1688</i>		1.00	1688.00	0.00	1688.00 ✓	
M	KS 86350 A4 010	GRILLE ASSY - RADIAT	<i>295</i>		1.00	295.00	0.00	295.00 ✓	
M	KS 86514 A4 000	BRACKET - FRONT BUMP	<i>12</i>		1.00	12.00	0.00	12.00 ✓	
M	KS 86513 A4 000	BRACKET - FRONT BUMP	<i>12</i>		1.00	12.00	0.00	12.00 ✓	
Z	NOTES								
	ACCIDENT ON 12/12/2018 ALONG SMITH ST BMKAM MSCP								
	OWNER CLAIMING THIRD PARTY								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877	Cust No/Name /Mr Lim Tze Seng (lin Zicheng) Reg No/Reg Date SLH9134D / 23/11/2016 Date In/Mileage 12/12/2018/ 0 Chassis No KNAHU815VG7164401 Engine No D4FDGH113219 Make/Model KIA/CARENS 1.7 A D SX SUNROOF GP8 Colour/Trim K7N / WK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0030034	Credit	17/12/2018/ 08:34	DS	218 / MarsLer	15280

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

REQUIRED REPLACEMENT CAR
TP # SHA7867U TP INS: MS FIRST CAPITAL

Estimate

- Repaired by the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Adrian Lij
20/12/18
0329p

Confirm & accepted by

Parts	3,688.00
Labour	0.00
Standard Menu	0.00
Specialist Job	4,190.00
Others(Lub,etc)	0.00
Sundry	50.00
Total(w/o GST)	7,928.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.