



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AXA Insured's Veh No : SKR8330U
Date of Accident : 12 December 2018

Mr Koh Hong Beng

Date : 19 December 2018

Estimate To Repair SBZ7766S - Opel Astra ST 1.0 AT
Chassis No : W0LBE8EAXH8065704

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	rear bumper	\$ 1,380.65
02	1 pc	rear bumper absorber foam	\$ 290.00
03	2 pc	rear bumper side retainer @ \$110.00	\$ 220.00
04	8 pc	rear bumper clips @ \$9.00	\$ 72.00
05	1 pc	rear bumper reinforcement	\$ 558.00
			\$ 2,520.65
Less 10 % <i>Suz</i>			\$ 252.07
			\$ 2,268.59
<u>SPECIAL NETT ITEMS</u>			
06	1 pc	reverse sensor	\$ 300.00
			\$ 300.00
<u>LABOUR & MISC. CHARGES</u>			
01		To reinstall of rear bumper parking sensor.	\$ 80.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 300.00
03		Putty and spray painting of the affected portion.	\$ 300.00
			\$ 680.00
Total			\$ 3,248.59

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

P-1452.65
S02
P-726.32
1452.65
1176.32