

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/LHI/089/2018
DATE : 07-DEC-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :
MOTOR CLAIM DEPT

OWNER'S NAME : QUAH AH BENG
ADDRESS : BLK 787 CHOA CHU KANG NORTH 6
#10-206
S(682787)
TELEPHONE NO : 96699592

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800130294
VEHICLE NO : SMF3570R
MODEL CODE : GT7BKVL
MODEL/YEAR : XV 2.0I-S EYESIGHT AWD CVT
ENGINE NO : FB20YE77057
CHASSIS NO : JF1GT7KL5JG047593
MILEAGE : 1 KM
DATE IN : 07/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : JEFF TEH TENG CHUEN
ACCIDENT DATE : 07/12/2018

Print Date : 29/07/2019
Print Time : 11:30:20

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMF3570R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ANTI	TO CONDUCT ANTI-RUST PROTECTION FOR REAR UNDERCARRIAGE WITH ANTI RUST COATING	550.00	290.00
2	REVERSE2	TO SUPPLY AND INSTALL 2-POINT REVERSE SENSOR	400.00	300.00
3	UNDERPANEL	TO CONDUCT PANEL PROTECTION FOR REAR UNDERCARRIAGE	500.00	250.00
4	ZZ/001	TO REPAIR AND REPLACE REAR BUMPER, TAILGATE, REAR BUMPER BEAM, REAR END PANEL AND SPARE TYRE WELL	3360.00	1000.00
5	ZZ/002	TO RESPRAY REAR BUMPER, TAILGATE, REAR BUMPER BEAM , REAR END PANEL, REAR BOTH SIDE FENDER AND SPARE	3960.00	625.00
6	ZZ/003	TYRE WELL		
7	ZZ/004	REMOVE AND REFIX EXHAUST FOR FACILITATE REPAIR AND CHECKING	500.00	250.00
8	ZZ/005	TRANSFER TAILGATE MECHANISM	350.00	180.00
9	ZZ/006	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	350.00	180.00
10	ZZ/007	REMOVE & INSTALL REAR WINDSCREEN	350.00	240.00
11	ZZ/008	TO SUPPLY AND INSTALL REAR WINDSCREEN TINT FILM	300.00	145.00
12	ZZ/009	SUNDRIES	150.00	20.00
13	ZZ/011	TO RESPRAY REAR END PANEL (SUPP)	200.00	200.00
14	ZZ/10	TO REPAIR REAR END PANEL (SUPP)	250.00	250.00
TOTAL LABOUR CHARGES			11220.00	3930.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMF3570R

S/NO PARTS DESCRIPTION			DAMAGED PARTS & PRICES				REMARKS
			PARTS NUMBER	NETT	LIST	S/NETT	
1	CUSHION EXH RH/LH	*2	(4) 44066AE001			21.60	X
2	MUFFLER ASSY W20		44300FL000			576.00	OK
3	BUMPER FACE R XV		57704FL250			401.10	OK
4	BRKT SD R XV RH		57707FL400			12.10	OK
5	BRKT SD R XV LH		57707FL410			12.10	OK
6	BRKT CORNER R 5D RH		57707FL460			21.60	X
7	BRKT CORNER R 5D LH		57707FL470			21.60	X
8	BRKT LWR R	*2 (SUPP)	57707FL510			50.40	OK
9	BEAM COMPL R EU		57711FL0419P			202.90	OK
10	COVER HOOK R XV		57731FL570NN			6.50	OK
11	PANEL COMPL R GAT		60809FL0009P			940.00	OK
12	GLASS ASSY R G		63019FL030			1062.00	OK
13	DAM RUBBER		65245FL000			18.00	OK
14	LETTER MK R		93079FL100			90.00	OK
15	LETTER MK R XV		93079FL140			36.00	OK
16	EYE SIGHT EMBLEM (TCS)		LPH010ES-EMB			43.20	OK
SUB TOTAL				0.00	0.00	43.20	3407.10
LESS DISCOUNT (S/LIST-30 %)				0.00	0.00	0.00	1022.13
GRAND TOTAL				0.00	0.00	43.20	2384.97
OVERALL TOTAL				2428.17			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.,
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SMF3570R

NETT ITEM	0.00
LESS 20 %	0.00
NETT AMOUNT	0.00

LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00

SPECIAL NETT AMOUNT	43.20
---------------------	-------

S/LIST ITEM	3407.10
LESS 30 %	-1022.13
S/LIST AMOUNT	2384.97

TOTAL LABOUR CHARGES	3930.00
TOTAL SPARE PARTS CHARGES	2428.17

TOTAL CHARGES	6358.17
ADD 7 % GST	445.07

GRAND TOTAL	6803.24
-------------	---------
