

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/LHI/089/2018
DATE : 07-DEC-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :
MOTOR CLAIM DEPT

OWNER'S NAME : QUAH AH BENG
ADDRESS : BLK 787 CHOA CHU KANG NORTH 6
#10-206
S(682787)
TELEPHONE NO : 96699592

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800130294
VEHICLE NO : SMF3570R
MODEL CODE : GT78KVL
MODEL/YEAR : XV 2.0I-S EYESIGHT AWD CVT
ENGINE NO : FB20YE77057
CHASSIS NO : JF1GT7KL5JG047593
MILEAGE : 1 KM
DATE IN : 07/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : JEFF TEH TENG CHUEN
ACCIDENT DATE : 07/12/2018

Print Date : 07/12/2018
Print Time : 20:10:08

Tanjah 97445749
'wp'
19/12/18 2115
Resurvey before paint
sur@lkkauto.com.
27 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
15 LENG KEE ROAD
SINGAPORE 159897

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMF3570R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ANTI	TO CONDUCT ANTI-RUST PROTECTION FOR REAR UNDERCARRIAGE WITH ANTI RUST COATING	550.00	250, 290
2	REVERSE2	TO SUPPLY AND INSTALL 2-POINT REVERSE SENSOR	400.00	300 nw ✓
3	UNDERPANEL	TO CONDUCT PANEL PROTECTION FOR REAR UNDERCARRIAGE	500.00	250.
4	ZZ/001	TO REPAIR AND REPLACE REAR BUMPER, TAILGATE, REAR BUMPER BEAM, REAR END PANEL AND SPARE TYRE WELL	3360.00	230, 1000.
5	ZZ/002	TO RESPRAY REAR BUMPER, TAILGATE, REAR BUMPER BEAM, REAR END PANEL, REAR BOTH SIDE FENDER AND SPARE	3960.00	200, 625.
6	ZZ/003	TYRE WELL		
7	ZZ/004	REMOVE AND REFIX EXHAUST FOR FACILITATE REPAIR AND CHECKING	500.00	250.
8	ZZ/005	TRANSFER TAILGATE MECHANISM	350.00	180.
9	ZZ/006	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	350.00	180.
10	ZZ/007	REMOVE & INSTALL REAR WINDSCREEN	350.00	240.
11	ZZ/008	TO SUPPLY AND INSTALL REAR WINDSCREEN TINT FILM	300.00	145.
12	ZZ/009	SUNDRIES	150.00	20.
TOTAL LABOUR CHARGES			10770.00	

TO RESPRAY REAR END PANEL (SUPP) \$200

TO REPAIR REAR END PANEL (SUPP) \$250

MOTQRIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMF3570R

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	CUSHION EXH RH/LH *2	(4) 44066AE001				21.60 ?X nn
2	MUFFLER ASSY W20	44300FL000				576.00 bb
3	BUMPER FACE R XV	57704FL250				401.10 cr
4	BRKT SD R XV RH	57707FL400				12.10 ne
5	BRKT SD R XV LH	57707FL410				12.10 ne
6	BRKT CORNER R 5D RH	57707FL460				21.60 ?X nn
7	BRKT CORNER R 5D LH	57707FL470				21.60 ?X nn
8	BRKT LWR R *2	57707FL510				50.40 ?✓ nec
9	BEAM COMPL R EU	57711FL0419P				202.90 bt
10	COVER HOOK R XV	57731FL570NN				6.50 mis
11	PANEL COMPL R GAT	60809FL0009P				940.00 bb
12	GLASS ASSY R G	63019FL030				1062.00 ne
13	DAM RUBBER	65245FL000				18.00 ne
14	LETTER MK R	93079FL100				90.00 ne
15	LETTER MK R XV	93079FL140				36.00 ne
16	EYE SIGHT EMBLEM (TCS)	LPH010ES-EMB			43.20	ne
SUB TOTAL			0.00	0.00	43.20	3471.90
LESS DISCOUNT (S/LIST-30 %)			0.00	0.00	0.00	1041.57
GRAND TOTAL			0.00	0.00	43.20	2430.33
OVERALL TOTAL			2473.53			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMF3570R

TOTAL LABOUR CHARGES	10770.00
TOTAL SPARE PARTS CHARGES	2473.53

GRAND TOTAL	13243.53 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.