

ASS. REC. BY:

REF:

CS/FCI18022745/R19d301

Special Instruction:

Surveyor:

aus

Rasul

ASSIGNMENT (Office)

From (Person):

Serene Ler

of

FCI

Date/Time: 10:09am @ 19/12/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 6032T

Insured:

SHA 7669A

at Workshop m/s

Kah Motor

Tel:

9072 1769

of

255 Alexandra Road

Policy No:

Claim No:

D18008847MPSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 11/12/18

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

21.12.2018 @ morning

I.O.D. Endorsement:

Date/Time: 10:17am @ 19/12/18

Person Contacted:

Mr. Ng

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMD 6032T-X
	SHA 7669A- NS/INC/6002820/H/vbn2 DOA: 9/2/2016
14/12/18 @ 3:08pm	revised to Serene Ler by email.
15/11/19 @ 11:17am	confirmed with Sin Hui final fig \$6107.72, 6 days. Cred \$8513.86, 58%.

Signature

REF: FCI

8510F

ASSIGNMENT

From: Date: 21/12/18

Estimated Cost:

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMD 6032 T
at Workshop m/s: Kah Motor
of: 255 Alexandra Road

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh: Moming
Ng Sin Hui

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lrp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMD 6032 T Yt Regn: 2018 / 429

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jazz 1.3 CVT C.C. 1318

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 002185 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHM4K3850JX226745

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Order / Jammed / Leaked / Burnt or

Brake: ☒ Order / Jammed / Leaked / Burnt or

Modl: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 175/65R15

R:

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 11/12/18 D.O.I. 21/12/18

Survey held at Kah Motor

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear o/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 15 JAN 2019

Signature
21/12/19

Date/Time, File Pass to?

☐ : Preli. Report

1) 15/1 11/12/18

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 6107.22

4x15
170 + 60
50
50
27
357

MOTOR SURVEY ASSIGNMENT

Date	13-12-2018	Our Ref No. D18008847MFSH
Accident Date	11-12-2018	Claim Type. Third Party
Insured Vehicle	SHA7669A	Third Party Vehicle. SMD6032T
Survey Location	255 ALEXANDRA ROAD	
Contact Person.	NG SIN HAI	
Contact No.	64715419/ 90721769	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO. SDN. BHD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 15 January 2019 11:17 AM
To: 'Ng Sin Hai'; Rasul (LKKAUTO); SUR
Subject: RE: Submission Pre-Invoice for vehicle SMD6032T

Dear Sin Hai,

WITHOUT PREJUDICE

Confirm final fig \$6,107.72 before GST and 6 repair days.

Kindly send the relevant documents to First Capital Insurance.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>
Sent: Monday, 14 January 2019 8:00 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FW: Submission Pre-Invoice for vehicle SMD6032T

Dear Rasul,

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle .

Cost of repair : \$6,535.27 (before GST)

No of working days : 06 days. (LOU)

We will proceed for closing after 1 week of submission to you.

Kindly contact me if there is any discrepancy.

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 24 December 2018 3:08 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008847MFSH/1
Attachments: CSFCI18022745R1qd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SMD 6032T.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 19 December 2018 10:20 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008847MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 19 December 2018 10:09 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008847MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008847MFSH

Date: 24 December 2018

Our Ref: CS/FC118022745/R1qd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SMD 6032T .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/12/2018 at the premises of M/s KAH MOTOR . and have the following to report:-

Workshop Estimate Amount	: S\$ 14,621.58 .
Revised Estimate Amount	: S\$ 6,107.72 .
"Check" Items Amount	: S\$ 665.86 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the rear o/s portion.



Yours faithfully

Rasul
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/12/2018 19:42
Date Of Accident	11/12/2018 21:30
Exact Location Of Accident	ALONG SLIP ROAD OF ANG MO KIO AVE 6 AND AVE 1.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD6032T
Insured/Policyholder	
Name Of Registered Owner	SIA CHONG HOCK
NRIC No	S2548510F
Email Address	SCH1955K@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96274248
Alternative Phone No	OFFICE-96274248

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ 1.3 CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10864741
Cover Note Number	

Driver

Name of Driver	SIA CHONG HOCK
NRIC No	S2548510F
Date Of Birth	01/09/1955
Occupation	INDOOR
Date Of Driving Pass	01/02/1985
Driving Experience	33 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96274248
Fax Number	
Contact Number	OFFICE-96274248
Email Address	SCH1955K@GMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : CHAN LAI WAH GENDER: : FEMALE
Passenger 2	NAME: : SHERILYN SIA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	BISHAN N.P.C.
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 11/12/2018 at about 2130hrs, I was driving along Ang Mo Kio Ave 6 on the left most lane of a 3 lane road. Then I took the slip road on the left. At the slip road, I had to stop due to the oncoming vehicle coming from Ang Mo Kio Ave 1. All of a sudden, I felt an impact from the rear portion of my vehicle. The rear bumper on my car sustained dents, cracks and there was a misalignment. We both exchanged particulars and contact numbers. No one was injured.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA7669A
Vehicle Make/Model/Colour	HYUNDAI/I40 1.7L CRDI AT ABS AIRBAG 4DR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SAFRIY BIN JAMIL
NRIC/Passport Number	S7909045Z
Contact Number	97899527

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured my vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER

Johnny


Voo Cheon Yee

Witnessed by Reporting Centre
Personnel

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Sketch Plan



NOTICE OF REPORTING

Annex D

NOTICE OF REPORTING

This is to confirm that Sin Chong Hock, NRIC/FIN: S2548510F, 58 Pemimpin Place S576055 HP: 96274248 has reported to the Police a non-injury traffic accident which occurred near Ang Mo Kio Ave 6 towards Ang Mo Kio Ave 1 on the slip road on 11/12/2018 at about 2130hrs involving the following vehicles:

V1) SMD6032T (Complainant's vehicle)

V2) SHA7669A (Other party's vehicle) - Safriy Bin Jamil, S7909045Z, HP 97899527

On 11/12/2018 at about 2130hrs, I was driving along Ang Mo Kio Ave 6 on the left most lane of a 3 lane road. Then I took the slip road on the left. At the slip road, I had to stop due to the oncoming vehicles coming from Ang Mo Kio Ave 1. All of a sudden, I felt an impact from the rear. I alighted from the vehicle and noticed that a taxi (V2) had collided into the rear portion of my vehicle. The rear bumper on my car sustained dents, cracks and there was a misalignment.

We both exchanged particulars and contact numbers. No one was injured.

If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.


Rank/Name of Issuing Officer: SGT (3) Nur Marissa


Date: 12/12/2018 Time: 0859hrs

S/D Ref: eSD-61

Police Post/Unit: Bishan NPC

Original - to be issued to informant
Duplicate - to be submitted to Traffic Police


BISHAN NPC
30 BISHAN STREET 21
SINGAPORE 570117
TEL: 1800 372 2222


NRIC: S2548510F

ACCIDENT STATEMENT (2000 characters)

On 11/12/2018 at about 2130hrs, I was driving along Ang Mo Kio Ave 6 on the left most lane of a 3 lane road. Then I took the slip road on the left. At the slip road, I had to stop due to the oncoming vehicle coming from Ang Mo Kio Ave 1. All of a sudden, I felt an impact from the rear portion of my vehicle. The rear bumper on my car sustained dents, cracks and there was a misalignment. We both exchanged particulars and contact numbers. No one was injured.


Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
JOHNNY VOO CHEON YEE

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

12 December 2018 at 1:04 PM

Date/Time:

12 December 2018 at 1:04 PM



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SMD6032T
Chassis No : JHMGK3850JX226745
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : SIA CHONG HOCK
Ins Policy No. :
Date of Accident : 11/12/2018

Document No. : SQT18005406 Page 1
Date : 18. Dec 2018
Customer No. : WZF002
Svc Advisor :
Engine No : L13B11031094
Date | Time : 18. Dec 2018 10:39:00 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>3XNN</i>	1	320.00		320.00 <i>X</i>	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>Xnn</i>	1	45.00		45.00	3.15	48.15
33500-T5A-J02	TAILLIGHT ASSY,R. <i>3XNN</i>	1	223.90	25	167.92 <i>X</i>	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL <i>X3NN</i>	1	223.90	25	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSY,R.LID <i>X3NN</i>	1	81.70	25	61.27	4.29	65.56
34155-T5A-J01	LIGHT ASSY,L.LID <i>X</i>	1	81.70	25	61.27	4.29	65.56
34270-T5A-J01	LIGHT ASSY,HIGH MOUNT STOP <i>Xnn</i>	1	79.80	25	59.85	4.19	64.04
68100-TAR-U10ZZ	TAILGATE COMP <i>PA-3XNN</i>	1	730.60	25	547.95 <i>✓</i>	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE <i>3XNN</i>	1	92.30	25	69.22 <i>X</i>	4.85	74.07
74801-T5S-K01	LOCK ASSY,TAILGATE <i>X3NN</i>	1	78.90	25	59.17	4.14	63.31
74810-S6A-003	HANDLETAILGATE <i>X3NN</i>	1	60.40	25	45.30	3.17	48.47
75722-T5L-T01	EMBLEMRR. <i>nn-3XNN</i>	1	10.90	25	8.17 <i>✓</i>	0.57	8.74
74890-T5A-A11	GARN ASSY,RR LICE <i>X3NN</i>	1	105.50	25	79.12	5.54	84.66
34100-S60-013	LIGHT ASSY,LICENCE <i>X3NN</i>	2	34.10	25	51.15	3.58	54.73
04715-T5A-J50ZZ	FACE,RR.BUMPER <i>DE-3XNN</i>	1	492.70	25	369.52 <i>✓</i>	25.87	395.39
71502-T5A-J60	COVER,R.RR.BUMPER <i>X3NN</i>	1	20.70	25	15.52	1.09	16.61
71503-T5A-J50	COVER,RR.EXPI FIN <i>X3NN</i>	1	9.30	25	6.97	0.49	7.46
71505-T5A-J50	GARNISH,RR.BUMPER <i>3XNN</i>	1	38.30	25	28.72 <i>X</i>	2.01	30.73
71507-T5A-J60	COVER,L.RR.BUMPER <i>XNN</i>	1	20.70	25	15.52	1.09	16.61
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE <i>nn-3XNN</i>	1	16.90	25	12.67 <i>✓</i>	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE <i>nn-3XNN</i>	1	16.90	25	12.67 <i>✓</i>	0.89	13.56



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Registration No : SMD6032T

Chassis No : JHMGK3850JX226745

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : SIA CHONG HOCK

Ins Policy No. :

Date of Accident : 11/12/2018

Document No. : SQT18005406 Page 2

Date : 18. Dec 2018

Customer No. : WZF002

Svc Advisor :

Engine No : L13B11031094

Date | Time : 18. Dec 2018 10:39:00 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
91505-TM8-003	CLIP,BUMPER <i>new</i>	7	2.30	25	12.07	0.84	12.91
66100-TAR-T00ZZ	PANEL COMPRR. <i>repair</i>	1	320.40	25	240.30	16.82	257.12
04655-TAS-300ZZ	PANEL SET,RR.FLOOR <i>X R</i>	1	683.30	25	512.47	35.87	548.34
84640-T5A-003ZA	LINING ASSYRR.PANEL <i>X NN</i>	1	60.80	25	45.60	3.19	48.79
72841-SH3-315	OILSHEET <i>X NN</i>	3	40.70	25	91.57	6.41	97.98
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>new</i>	2	60.00		120.00	8.40	128.40
Sum Item					<u>3251.58</u>	<u>227.62</u>	<u>3,479.20</u>
BOSUN	SUNDRIES	1	100.00 <i>30</i>		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00 <i>? X NN</i>		80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00 <i>X NN</i>		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00 <i>X NN</i>		560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00 <i>280</i>		560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00		100.00	7.00	107.00
BKRP02M	CUT OFF & RENEW RR PANEL.	1	4500.00 <i>1680</i>		4500.00	315.00	4815.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00 <i>1350</i>		3000.00	210.00	3210.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	450.00 <i>X NN</i>		450.00	31.50	481.50
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	380.00 <i>X NN</i>		380.00	26.60	406.60
Sum Labor					<u>11370.00</u>	<u>795.90</u>	<u>12,165.90</u>

Printed on 18/12/2018 10:43:25 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SMD6032T
Chassis No : JHMGK3850JX226745
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : SIA CHONG HOCK
Ins Policy No. :
Date of Accident : 11/12/2018

Document No. : SQT18005406 Page 3
Date : 18. Dec 2018
Customer No. : WZF002
Svc Advisor :
Engine No : L13B11031094
Date | Time : 18. Dec 2018 10:39:00 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By	Rasul - Hp 90010068						
Date & Time	21/12/18 @ 12:10						
Excess							
Status							
Signature							
Total Amount					14,621.58	1,023.52	15,645.10
Total (Inclusive of GST)							<u>15,645.10</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 18/12/2018 10:43:25 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMGK3850JX226745
License No: SMD6032T
Mileage: 2100
Engine No: L13B11031094

Document No: SVO18076286
Printed By: SHNG
Order Date: 21. December 2018
Order Time: 12:21:35 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:SIA CHONG HOCK OWNER INSURER:AVIVA ACC DATE:11/12/2018 SURVEYED BY:RASUL DATE:21/12/2018 REF NO: TP INSURER:MS FIRST CAPITAL TP VEH:SHA7669A						
68100-T5A-U10ZZ	TAIL GATE COMP	1	730.60	25	547.95	38.36	586.31
75722-T5L-T01	EMBLEMRR.	1	10.90	25	8.17	0.57	8.74
04715-T5A-J50ZZ	FACE,RR.BUMPER	1	492.70	25	369.52	25.87	395.39
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
	SUM PARTS:				1,107.72	77.55	1,185.27
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10
BA02R	0669 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BOJSE	1610 SEALANT FOR TAILGATE	1	80.00		80.00	5.60	85.60
BML02I	0701 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00		180.00	12.60	192.60
BMI02D	0669 REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	560.00		560.00	39.20	599.20
BKTG02R	0669 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	280.00		280.00	19.60	299.60
BG02D	1757 REMOVE & INSTALL RR. WINDSCREEN. (N)	1	560.00		560.00	39.20	599.20
BODAMKIT	0701 WINDSCREEN DAM KIT.	1	100.00		100.00	7.00	107.00
BKRP02M	0669 CUT OFF & RENEW RR PANEL. RR FLOOR PAN & RENEW DAMAGE PARTS.	1	1,680.00		1,680.00	117.60	1,797.60
BP06R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	1,350.00		1,350.00	94.50	1,444.50



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMGK3850JX226745
License No: SMD6032T
Mileage: 2100
Engine No: L13B11031094

Document No: SVO18076286
Printed By: SHNG
Order Date: 21. December 2018
Order Time: 12:21:35 PM
Service Advisor: NG SIN HAI

REAR PORTION

SUM LABOUR:	5,000.00	350.00	5,350.00
TOTAL SGD	6,107.72	427.55	6,535.27

Total Payable (SGD) 6,535.27

GST Amount is calculated from individual line(s)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18022745/R1qd3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 16-01-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7669A	Veh. Inspected	SMD 6032T
Policy No.		Coverage (\$)	0.00
Claim No.	D18008847MFSH	Excess (\$)	0.00
Assign From	SERENE LER	Assign Date	19/12/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ 1.3 CVT	c.c	1318
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JHMGK3850JX226745	Colour	GREY
Odometer	2185	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R15	DUNLOP	6 mm
L/H Front Tyre	175/65 R15	DUNLOP	6 mm
R/H Rear Tyre	175/65 R15	DUNLOP	6 mm
L/H Rear Tyre	175/65 R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/12/2018	Inspection Date	21/12/2018
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 6032T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
4	ACT RR.SENSOR (SN)	NOT NECESSARY	320.00	-
1	NUMBER PLATE WITH CASING - L (SN)	NOT NECESSARY	45.00	-
1	TAILLIGHT ASSY,R. (SN)	NOT NECESSARY	167.92	-
1	TAILLIGHT ASSYL (SN)	NOT NECESSARY	167.92	-
1	LIGHT ASSYR.LID (SN)	NOT NECESSARY	61.27	-
1	LIGHT ASSYL.LID (SN)	NOT NECESSARY	61.27	-
1	LIGHT ASSYHIGH MOUNT STOP (SN)	NOT NECESSARY	59.85	-
1	TAILGATE COMP (SN)	BENT	547.95	547.95
1	WEATHERSTRIPTAILGATE (SN)	NOT NECESSARY	69.22	-
1	LOCK ASSY, TAILGATE (SN)	NOT NECESSARY	59.17	-
1	HANDLETAILGATE (SN)	NOT NECESSARY	45.30	-
1	EMBLEMRR. (SN)	NECESSARY	8.17	8.17
1	GARN ASSY, RR LICE (SN)	NOT NECESSARY	79.12	-
2	LIGHT ASSYLICENCE (SN)	NOT NECESSARY	51.15	-
1	FACE,RR.BUMPER (SN)	DEFORMED	369.52	369.52
1	COVER,R.RR.BUMPER (SN)	NOT NECESSARY	15.52	-
1	COVER,RR.EXPI FIN (SN)	NOT NECESSARY	6.97	-
1	GARNISH,RR.BUMPER (SN)	NOT NECESSARY	28.72	-
1	COVER,L.RR.BUMPER (SN)	NOT NECESSARY	15.52	-
1	SPACER,R.RR.BUMPER SIDE (SN)	NECESSARY	12.67	12.67
1	SPACER,L.RR.BUMPER SIDE (SN)	NECESSARY	12.67	12.67
7	CLIP, BUMPER (SN)	NECESSARY	12.07	12.07
1	PANEL COMPRR. (SN)	TO REPAIR SEE LABOUR	240.30	-
1	PANEL SET, RR.FLOOR (SN)	TO REPAIR SEE LABOUR	512.47	-
1	LINING ASSYRR.PANEL (SN)	NOT NECESSARY	45.60	-
3	OILSHEET (SN)	NOT NECESSARY	91.57	-
1	RUBBER CWINDSHIELD DAMPER (SN)	NECESSARY	8.55	8.55
2	RUBBERWINDSHIELD DAMPER (SN)	NECESSARY	9.75	9.75
1	DAMPERSTD 5X5 (SN)	NECESSARY	6.37	6.37

Report Ref No. CS/FCI18022745/R1qd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	WINDSCREEN SEALANT (SN)	NECESSARY	120.00	120.00
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
			3,351.58	1,137.72
	LABOUR			
	REMOVE & RENEW REVERSE SENSORS - 4PCS.		180.00	180.00
	SEALANT FOR REAR END PANEL.	NOT NECESSARY	80.00	-
	SEALANT FOR TAILGATE.		80.00	80.00
	SEALANT FOR REAR FLOOR PANEL.	NOT NECESSARY	80.00	-
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		180.00	180.00
	REMOVE & INSTALL FUEL TANK FUEL PIPES.	NOT NECESSARY	560.00	-
	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK.		560.00	560.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &		560.00	280.00
	REMOVE & INSTALL RR.WINDSCREEN.		560.00	560.00
	WINDSCREEN DAM KIT.		100.00	100.00
	CUT OFF & RENEW RR PANEL. INCLUSIVE OF THE REPAIR OF PANEL COMPRR. AND PANEL SET, RR.FLOOR.		4,500.00	1,680.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)		3,000.00	1,350.00
	REMOVE & RENEW RR FLOOR INSULATOR.	NOT NECESSARY	450.00	-
	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA.	NOT NECESSARY	380.00	-
			11,270.00	4,970.00
	GRAND TOTAL		14,621.58	6,107.72
	RECOMMENDED COST OF REPAIRS			6,107.72

Report Ref No. CS/FC18022745/R1qd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.