

DING AUTOMOTIVE PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

27/12/2018 16:41

JOB-NO: 50111240

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE

64739522

SINGAPORE 575717 0

VEHICLE DETAILS

LICENSE NO: SHA9261D

TRANS: AUTO

CHASSIS: KMHC851CVKU107267

MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 D

ENGINE: G4LEJU080154

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	MARK UP	MARKUP PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,500.00	0.00	1,500.00		Y	800
2 RESPRAY FRONT BUMPER	1.00	230.00	0.00	230.00		Y	200
3 RESPRAY REAR BUMPER	1.00	230.00	0.00	230.00		Y	200
4 RESPRAY REAR BUMPER GARNISH	1.00	230.00	0.00	230.00		Y	100
5 RESPRAY REAR FENDER RHS	1.00	230.00	0.00	230.00		Y	200
6 TOWING SERVICE	1.00	160.00	0.00	160.00		Y	150
7 REMOVE & REFIT SPARE TYRE & CAR PET & SIDE TRIM	1.00	120.00	0.00	120.00		Y	40
TOTAL:		2,700.00	0.00	2,700.00			

MATERIALS

1 REAR BUMPER	1.00	0.00	0.00	0.00		Y	car
2 REAR BUMPER FOG LAMP ASSY	1.00	0.00	0.00	0.00		Y	x
3 REAR BUMPER LOWER CENTER MOULDING	1.00	0.00	0.00	0.00		Y	?
4 REAR BUMPER RETAINER LH	1.00	0.00	0.00	0.00		Y	new
5 REAR BUMPER RETAINER RH	1.00	0.00	0.00	0.00		Y	new
6 REAR BUMPER CENTER GARNISH	1.00	0.00	0.00	0.00		Y	new
7 REAR TOWING CAP	1.00	0.00	0.00	0.00		Y	x
8 REAR BUMPER REFLECTOR LH	1.00	0.00	0.00	0.00		Y	new
9 REAR BUMPER REFLECTOR RH	1.00	0.00	0.00	0.00		Y	new
10 REAR BUMPER LOWER COVER	1.00	0.00	0.00	0.00		Y	x
11 REAR BUMPER SIDE COVER LH	1.00	0.00	0.00	0.00		Y	del
12 REAR BUMPER SIDE COVER RH	1.00	0.00	0.00	0.00		Y	?
13 REAR REVERSE SENSOR SET IONIQ	1.00	0.00	0.00	0.00		Y	?
14 REAR SMARTKEY ANTENNA	1.00	0.00	0.00	0.00		Y	x
15 REAR BUMPER REINFORCEMENT	1.00	0.00	0.00	0.00		Y	?
16 REAR BUMPER REINFORCEMENT BRACKET RH	1.00	0.00	0.00	0.00		Y	?
17 REAR BUMPER REINFORCEMENT BRACKET LH	1.00	0.00	0.00	0.00		Y	?
18 REAR BUMPER REINFORCEMENT LOWER BRACKET X3	1.00	0.00	0.00	0.00		Y	?
19 REAR END PANEL	1.00	0.00	0.00	0.00		Y	x
20 REAR FENDER RHS	1.00	0.00	0.00	0.00		Y	RY
21 REAR BUMPER CLIP SET	1.00	0.00	0.00	0.00		Y	new
22 REAR CENTER GARNISH CLIP & SCREW	1.00	0.00	0.00	0.00		Y	new
23 FRONT WHEEL CAP LHS	1.00	0.00	0.00	0.00		Y	new
24 FRONT WHEEL CAP RHS	1.00	0.00	0.00	0.00		Y	?

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	MARK UP	MARKUP PRICE	IND	SUR.DISP	REV PRICE
25 REAR WHEEL CAP LHS	1.00	0.00	0.00	0.00		Y	<u>at</u>
TOTAL:		0.00	0.00	0.00			

TOTAL PARTS & LABOUR :

2,700.00 0.00 2,700.00

EXCESS/LOADING:\$ 0.00

No. Of Day: 6

RE-SURVEY: BEFORE/AFTER PAINTING

PART BY: PART OR LUMP SUM: \$

DATE OF SURVEY: 27 / 12 / 18SURVEYED BY: TamperCONTACT NO: 92495799

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: