VIDA.

ANN REC. BY:	REF CS3 MSG 18015777/NV6-3 Set LANGUERON
WHINN)	Chhia Nyuk Pui of MS16 Detertime 18132018
To Inspect Ve at Workshop	Bill to:  S/TP RES/OD RES/EVA/INV/MY/CS  Chicle No: GBF 4989R Insured: SKK 1115H  Tel: 6747 2755
Policy No	2 Kaki Bld Ave 2 # 02-25 327487632SMP Claim No: 568202
Som Insored Make of Veh	D.O.A. 21\08 2018
CA / REV Date/Time C	REP. / REV 24 HRS (4)  1:36am @ 29/8/18 Person Contiscted Connie Vehicle DON'T  Action/Instruction (X) Estimate DON'T Findit  GBF 4984R - NA FCT 1808373/24 DOA: 21/08/18
	SICK 1115H - NA   FC[ 180 15373/24 DOA: 21 08/18  After repair: 5/9/2018
41/19	Submit LS \$ 5100 (Red 4300, 4690), 6 days / maron 12
	RECEIVED 0 4 JAN 2019 27/12/2018

Dorl.

Naz

	MSIG SSIGNMENT
A	
From: Date:	Veh No: GBF 4989 R Yr Regn: 28 NOV1 2016 Typr M. Cov 7 M. Cycle / Bus / Van J. Corry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: NIJAN NV 200 _ c.c   461
at Workshop m/s	Colour SILVER AC: Casural Isid NIII
of	Sp.Reading 33, 975 T/Radio Cravil/std/NI/1
Insured:	Eng/No:
Policy No.	CINO: VSKYBAM20Z0131466
Claims No.	Gen. Cond: Good / Poor / Burnt
Sum insured: Excess:	Steering in IXAV   Jammed   Leaked   Burnt or
(Client's Record)	Brake: ( Jan / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 175/70 R14 C
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY ) FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal, or Market Value;	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. F P/Bal
GIA / PR Seen: Consistent? : Yes or No	L/Bal, F mm L/Bal F
Est. Repairs: 6 days Res.: Yes or No	004 01/0/10
Lum Sum: % 3 Val.: Yes or No	11971
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / ROV POIS I NIS I UIC I Rooftop or
Vehicle: IN / OUT	Ols This Tole T Roottop or
Date: Person Contacted:  Date / Time   Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision
Action? instruction	
Range 5000/2 - 6000	MS/G P/P
	meante
	7 100
	TOUM Sholens
	- W
	7/0/18
Date/Time, File Pass to? : Prell. Report Da	ys Of Repair:
1) : Final Report Res	survey No. of Trip:   Survey Fee:   120
_	Transportation;
Add Fee:	: Site Insp (\$ )s+Rssi
Report Format : PRS -	:Interview (\$ ) Photos
Lump Sum / I.B.I: (\$	: Tech. Invs (\$ ), Others 10
	:Weekend (\$
	TOTAL 136

## Catherine Chong (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Tuesday, 18 December, 2018 4:35 PM

To:

'Chhia Nyuk Pui'; assignments

Cc:

SUR

Subject:

FW: Your ref: JEQ/180684/0818/HS A (zl) Our ref: 568202 (OI: SKK1115H)

Dear Nyuk Pui,

Thank you for your email.

Dear assignment team,

Kindly assist.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chhia Nyuk Pui [mailto:NyukPui Chhia@sg.msig-asia.com]

Sent: Tuesday, 18 December 2018 2:31 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com> Subject: FW: Your ref:JEQ/180684/0818/HS A (zl) Our ref: 568202 (OI: SKK1115H)

Dear Sir/Madam

Our ref: 568202

Please do paper survey. Have sent back in Merimen.

Thanks

Chhia Nyuk Pui

Senior Executive, Claims Services Direct line +65 6594 2521 | Direct fax +65 6643 1349 | nyukpui\_chhia@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on @MSIG\_SG

A member of MS&AD INSURANCE GROUP

From: Chhia Nyuk Pui

Sent: Monday, 17 December, 2018 5:33 PM

To: claims@juseq.com.sg

Subject: RE: Your ref:JEQ/180684/0818/HS A (zl) Our ref: 568202 (OI: SKK1115H)

Dear Kevin

Thanks for your email

We will review and come back to you.

Regards,

Chhia Nyuk Pui

Senior Executive, Claims Services

Direct line +65 6594 2521 | Direct fax +65 6643 1349 | nyukpui\_chhia@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on ■ @MSIG\_SG

A member of MS&AD INSURANCE GROUP

From: claims@juseq.com.sg [mailto:claims@juseq.com.sg]

Sent: Friday, 14 December, 2018 1:16 PM

To: Chhia Nyuk Pui <Nyuk Pui Chhia@sg.msig-asia.com>

Subject: RE: Your ref:JEQ/180684/0818/HS A (zl) Our ref: 568202 (OI: SKK1115H)

Importance: High

#### WITHOUT PREJUDICE SAVE AS TO COSTS

Dear Sir / Madam

Your Ref: 568202

Our Ref: JEQ/180684/0818 (HSA)

Thanks for your email below.

We have mandate to counter-propose the following: -

1.	Damages	
	a. Costs of repair	\$ 7,800.00
	b. Loss of use	\$ 800.00
2.	Disbursements	
	a. LTA / GIA	\$ 36.49
	b. Survey report	\$ 963.00
3.	Costs + GST	\$ 695.50
	TOTAL	\$ 10,294.99

Please let us hear from you on an urgent basis.

TAKE NOTICE that we have given you 10 clear days' notice on 14.12.2018.

\*\*\* Kindly take note of our new email address. Thank you.

Regards

Kevin Foo On behalf of Mr. Michael Yap JusEquity Law Corporation

From: Chhia Nyuk Pui [mailto:NyukPui\_Chhia@sg.msig-asia.com]

Sent: Friday, December 14, 2018 11:11 AM

To: JUSEQ < juseq@singnet.com.sg>

Subject: Your ref:JEQ/180684/0818/HS A (zl) Our ref: 568202 (OI: SKK1115H)

Dear Sir/Madam

Without Prejudice Save as to Costs

For amicable settlement sake, we are prepared to offer: \$5000 repair cost (in lieu of physical re-inspection) \$500 loss of use (5 days recommended by our surveyor LKK x 100/day) \$450 survey fee \$7.49 LTA \$29 Report fee \$500 Costs & Incidentals Total \$6486.49

Please advise acceptance.

Regards,

Please note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data for the purpose of assessing your claim. This may include disclosing and sharing your personal data with our service providers and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore, for the proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws (collectively, "the Purpose"). We may also need to disclose or share your personal data with service providers who are sited outside Singapore for the Purpose.

Chhia Nyuk Pui Senior Executive, Claims Services Direct line +65 6594 2521 | Direct fax +65 6643 1349 | nyukpui\_chhia@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on ■ @MSIG\_SG

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	st Submitted Adj Assigned Adj		t	Adj Submitted	Ins Auth	ed Status		
23 Aug 2018 Main			28 Aug 2018		o ates	5\$0.00			Pending for Survey Report Cancel Case	
	Main		Reference		Claim D	Petails	Doc	cuments	Show All	
CLAIM S	UBFOLDER DE	TAILS						[Created by in	surer]	
Insured:			ANA DASS S/O BA		AN NAI	R, ID: S1618463	B, Tel: +65	596609207, En	nail:	
Main Clair	mant:	ROB	INSON CAR RENT	AL PTE LTD,	Co. R	eg. No.: 20041404	1W			
Vehicle Reg. No.:		GBI	GBF4989R			Loss:		21/08/2018 19:00 - :59 [20 Months and 24 Days From LTA Reg Date (Man Yr)]		
Claim Type:		TP.	TP / 568202			Cover Note No.:		B27487632SMP (Comprehensive) Coverage: 30/03/2018 - 29/03/2019		
Vehicle R	eg. No. (Insured)	: SKK	1115H		Policy No. (Claimant):					
				Excess:				S\$1,000.00		
Repairer:			H S Automotive Services (Kaki Bukit) BLK 2 KAKI BUKIT, AVENUE 2, # 01-15, KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 67472755							
Handling	Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 [Handled by Chhia Nyuk Pui - 6594 2521]							
Adjuster:			LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Handled by Muhammad Nazrii Bin Abdullah] [Final Rpt due 20/12/2018]							
Driver/Custodian (Insured): MOHANA DASS S/O BA				AKRISHNAN	NAIR (5	4 / Male), NRIC:	S1618463B,	Tel: +659660	9207	
Adj Asg. Remarks: SURVEY DISAGREE ON SJE - ASSIG					LKK LIA	BILITY: 100% CO	NTACT: MR A	ALEX 6538 1368	UNIT NO: #02-25	
ASSOCI	ATED MAIL REG	CEIVED					٧	/iew All   Co	mpose Case Mail	
· MSIG_	SG (18/12/2018)	: Report Send	Back Alerts - GBF4	4989R (TP)						
E										
(100)	SOCIATED TASE	KS				View All   Searc	ch Tasks	Create New Ta	sk Complete	
Due D	ate Priority	Type Tas	Group Subje	ct Handl	ler -	Assigned By	Complete	d On Crea	ted On Done?	



# JusEquity Law Corporation

# ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS

171 Chin Swee Road #02-06, CES Centre, Singapore 169877
Telephone (65) 6536 9339, (65) 6253 1812, (65) 6397 2008, (65) 6533 2327
Fax: (65) 6253 0120 (Conveyancing), (65) 6536 5368 (Litigation)
Email: juseq@singnet.com.sg website: www.juseq.com.sg

. ↑ 1 8 OCT 2018

REG/CS/PAY/FA

Our Ref:

JEQ/180684/0818/ HS A (zl)

Your Ref:

SKK1115H 508202

16 October 2018

WITHOUT PREJUDICE

MSIG INSURANCE SINGAPORE PTE LTD

4 Shenton Way #21 – 01 SGX Centre 2 Singapore 068807 BY HAND

MOHANA DASS S/O BALAKRISHNAN NAIR

30 Teban Gardens Road #11 - 205 Singapore 600030 BY CERTIFICATE OF POSTING

Dear Sirs

PROPERTY DAMAGE CLAIM ARISING FROM ACCIDENT INVOLVING VEHICLES GBF4989R & SKK1115H AT WEST COAST HIGHWAY ON 21.08.2018

We act for ROBINSON CAR RENTAL PTE LTD, the owner of motor vehicle no. GBF4989R, in his claim for damages as a result of the above accident.

We are instructed that on the 21 August 2018, the driver of your insured motor vehicle no. SKK1115H so negligently drove, managed and controlled the said motor vehicle that he caused or permitted the same to collide into our client's vehicle.

The said collision was solely caused by the negligence of the driver of your insured motor vehicle no. SKK1115H.

As a result of the said collision, our client has suffered loss and damage which are set out hereunder as follows: -

A Damages

a. Cost of repairs

b. Loss of use (10 days @ 120.00 per day)

\$ 9,400.00

1,200.00

(1) UDOAC (2) ML1 0 Z

#### CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

16/10/181 Janya

В	Disbursements a. Search Fees / LTA / GIA (at this stage) b. Automobile Inspection Report	\$ 36.49 963.00
С	Cost with GST (at this stage)	\$ 1,070.00
		12660-40

We enclose herewith copies of the following documents in support of our client's claim: - 10750

- a) GIA report lodged by the driver of our client's vehicle;
- b) GIA search and document invoice for SKK1115H;
- Our letter dated 28 August 2018 to 3<sup>rd</sup> party and his insurers;
- d) LTA search result for SKK1115H;
- e) Repair invoice from HS Automotive Services;
- f) Automobile Inspection Report & Invoice from PAR Automotive Consultancy;
- g) Forty-eight (48) pages colour / non colour photographs depicting the damage to our client's motor vehicle.


We had on 28 August 2018 notified you / your insurer of the accident, and a pre-repair survey of our client's vehicle was carried out.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all enclosed documents to your insurer.

Please note that you as insurers / owner should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured(s) / you without further notice to you.

Please also note that if you have a counterclaim against our clients arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully



#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	23/08/2018 19:13
Date Of Accident	21/08/2018 19:45
Exact Location Of Accident	ALONG WEST COAST HWY
Country/State of Loss	SINGAPORE
AND THE RESIDENCE OF THE PROPERTY OF THE PERSON OF THE PER	Construction and a Land Language and the Construction of the Const

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number GBF4989R

sured/Policyholder

Name Of Registered Owner ROBINSON CAR RENTAL PTE LTD

Co Reg No 200414041W
Email Address NOEMAIL

Mobile Phone No

Alternative Phone No OFFICE-89999999

Vehicle Particulars

Manufacturer NISSAN

Model NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

surance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy YES

Policy Number D-18090225MFCV/12

Cover Note Number

Driver

Name of Driver PEH HAN YONG (BAI HANRONG)

 NRIC No
 S9041203E

 Date Of Birth
 28/10/1990

 Occupation
 OUTDOOR

 Date Of Driving Pass
 16/05/2014

Driving Experience 4 YEARS AND 3 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96708751

Fax Number

Contact Number OFFICE-96708751

EMail Address NOEMAIL

BLK 518 WEST COAST ROAD Address #04-577 120518 Postcode Was driver an employee of the Insured's Company NO If No, Relationship of the Driver with the Insured OTHER - HIRER Vehicle Registration Number of Driver's Own Vehicle Insurance Company of Driver's Own Vehicle General Information of the Accident Type Of Accident COLLISION - HEAD TO REAR CLEAR Weather Conditions DRY Road Surface Other Information Was any foreign vehicle involved in this accident? NO 2 Number of vehicles involved in the accident NO Was any body injured in the Accident? Vas any injured conveyed to hospital by ambulance? YES Was any other material or property damaged? I have been approached by unknown person(s) NO soliciting/offering accident claims assistance. 1 Number of Passengers (Including Driver) **Details of Police Action** Was the accident reported to the police? NO If Yes, Please state which Police Station NO Was notice of intended Prosecution given? If Yes, against whom? Circumstances of Accident REFER TO STATEMENT. Attachment(s) Are accident photos available for attachment? YES Vas there any video captured by Car Camera? NO Was there any audio recorded? NO DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKK1115H

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

MOHANA DASS NAIR Name of Driver

NRIC/Passport Number S1618463B Contact Number 96609207

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Accident Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- " I was a significant correctly the details of the one and deat to appear with the " or old in a
- The later that is completed by the Policyholder and/or the Authorized Driver
- is the may be access to the an truthful and accurate as possible. An existing of the existing of the contract of the contract of the public terms as the contract of the contract of the public terms as the contract of the contract of the public terms as the contract of t
- 3 The lines and acceptable and this form by insurance companies to not an arm segment points to de the part in the first acceptable of colors.
- day take expecting may be referred to the Police for investigation.

The request will be furmanced by the insurers of the GIA Record Managements entering the process of the insurers of the establishment of the insurers of the establishment of the

be the abover of this report to the insulant, you kereby cursent to the althour got this report at the centre and for this experience and the transfer made weak to be above and resident.

: Content under the Personal Data Protection Act (PDPA)

and artist of a trick air figur, agrees and a convent that

- If without we workshop and the General insulative Association of Sergapoints GIA. This start personal of the personal data/personal information set put of this florm, and give street on vitral information and dealing of the set of the personal data/personal information is an electric three dealing of the set of the se
  - brokeszité transiesz análor dealog with my claims including the sattlement of the cay recursives lives is so musical across relating to the plants.
  - incestigating the accordant and the my claims.
  - asserted and around decising with the enthictions or respecting to any enquiries of the re-
  - and on the maximum emboding the development contributed for statements, in page of your contributed and on the development data about the techniques of the contributed and one to the contributed by the contributed and one to the contributed by the contributed and one to the contributed by the contribute
  - et composite with applicable law in administering, brokessing, handling antifer her rejection of a control and control.

    Purposes in
- At a minute of a traver inputed ephicosist insulated in this assigned who take implicate to take the more traver in the
  contest, we discover wild to process the timeseas information to open the minute travers in the contest at the
  - my fer you'd intermediate implicance my my being as you at the magness singler of a restrict or as some or a restrict or open to relate the transfer of the a reservation from the arms of the arms of
- mercanical integration will also be collected able used to complete the highest feet the posture or of the integration and management in persent and 48 to take plans.
- the control of the control of the state of t
  - to an character and fact are other than parties that associate evaluating the structure control and to the light spiritual entering and programment appropriate experiences, required the true programment and programment appropriate experiences.
  - in the completing with requirements upday and regulations light to require or sec-

CONTROL CO

The management of the section of the sec

Track of the second sec

SKETCHPLAN	1	1 1	
	han Kus Kan	Na Km	A. GOFUGSAR B: Skeinsh
DESCRIBE CIACUMSTANCES C		NT NT	and the state of t
A copyright of the copy			
	of the state of th		
DECLARATION  Ale cations for torsions properties	Quint sing	24	Accounting townsend was not of the state of

#### Accident Sketch Plan

ON STATED DATE AND TIME, I WAS TRAVELLING ALONG LANE 1 WEST COAST HWY. VEHICLE INFRONT OF ME BRAKE HIS VEHICLE. I BRAKE MY VEHICLE ACCORDINGLY. SUDDENLY I FELT AN IMPACT OF MY VEHICLE, I ALIGHT FROM MY VEHICLE AND REALIZE THAT VEHICLE B HIT ONTO MY VEHICLE REAR PORTION.

1



# GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

## TAX INVOICE

Our Ref No:

GR-18-133075

Date of Request:

29/08/2018

Your Ref No:

180684-HSA

JusEquity Law Corporation No. 171 Chin Swee Road, #02-06 CES Centre Singapore 169877

Dear Sir/Madam,

ur Search Criteria:

Date of Accident:

21/08/2018

Place of Accident:

WEST COAST HIGHWAY

Client Vehicle No:

GBF4989R

DESCRIPTION	AMOUNT (S\$)		
E-File Search Fee (Public)	14.02		
GST Amount	0.98		
Total Amount Due (GST Inclusive)	15.00		

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

GIRO [] Cash [] Cheque



### GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

#### TAX INVOICE

Our Ref No:

GR-18-133082

Date of Request:

29/08/2018

Your Ref No:

180684-HSA

JusEquity Law Corporation No. 171 Chin Swee Road, #02-06 CES Centre Singapore 169877

Dear Sir/Madam,

e of Accident:

21/08/2018

Vehicle No:

**GBF4989R** 

Place of Accident:

ALONG WEST COAST HWY

Involving Vehicle No: SKK1115H

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SKK1115H	ALONG WEST COAST HWY	14.0	0 1	13.08
GST Amount	0.92			
Total Amount Due	(GST Inclusive)	Hill (1997) (1997) (1997)		14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque



# JusEquity Law Corporation

# ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS

171 Chin Swee Road #02-05, CES Centre, Singapore 169877
Telephone (65) 6536 9339, (65) 6253 1812, (65) 6397 2008, (65) 6533 2327
Fax: (65) 6253 0120 (Conveyancing), (65) 6536 5368 (Litigation)
Email: juseq@singnet.com.sg

Our Ref.

JEQ /180684/0818/ HS A (zl)

Your Ref:

SKK1115H

28 August 2018

MOHANA DASS S/O BALAKRISHNAN NAIR

By Post Only

30 Teban Gardens Road #11 - 205

Singapore 600030

MSIG INSURANCE SINGAPORE PTE LTD

By Fax: 6225 7402 Only

Singapore

Dear Sir

ACCIDENT INVOLVING GBF4989R & SKK1115H ON 21.08.2018

We act for the owner of vehicle no. GBF4989R.

We hereby notify you of a road traffic accident on 21 August 2018 at about 1945 hrs, at West Coast Highway involving our client's vehicle and vehicle registration no. SKK1115H driven by you / your insured at the material time. A copy of our client's report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully



#### CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

# Enquire Vehicle & Owner Information (Vehicle No. SKK1115H As At 21 Aug 2018 / 19:45:00)

Law Firm Search Details

Search Reason:

Insurance claim in relation to traffic accident

Law Firm Case No.:

**HSA** 

Current Owner Details

Owner ID Type:

Singapore NRIC

Owner ID:

S1618463B

Owner Name:

MOHANA DASS S/O BALAKRISHNAN NAIR

Registered Address Type: HDB/HUDC

Registered Block/House

30

No.:

Registered Street Name: TEBAN GARDENS ROAD

Registered Unit No.:

#11-205

Registered Building Name: -

Registered Postal Code: 600030

Current Vehicle Details

Vehicle No.:

SKK1115H

Make Description/Model: B.M.W. / Z4 SDRIVE20I D/AB 2WD 2DR GAS/D NAV

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

# H S AUTOMOTIVE SERVICES

# BLOCK 2 KAKI BUKIT AVE 2 #02-25 KAKI BUKIT AUTOHUB SINGAPORE 417921 TEL: 6538 1368 FAX: 6538 1367

4th October 2018

#### SIANG HOCK HOLDING PTE LTD

21 Jalan Masjid Singapore 418946

#### FINAL REPAIR BILL FOR "NISSAN NV 200" NO. GBF4989R

Final Repair Costs (Lump Sum Basis) as recommended by the Assessor: -

#### PAR AUTOMOTIVE CONSULTANCY

\$ 9,400.00

Singapore Dollars: Nine Thousand & Four Hundred Only



# R Automotive Consultancy

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel: 645 31173, Fax: 645 36131.

Regn. No: 52986974L

Report No: 0633-18-HSA

24 September 2018

Siang Hock Holding Pte Ltd 21 Jalan Masjid Singapore 418946

INVOICE No.

0633-18-HSA

Vehicle No.

GBF4989R

S/NO.

SERVICES RENDERED

Amount due

1

Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post

repair inspection).

\$963.00

Total amount payable

\$963.00

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy

# PAR Automotive Consultancy

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel: 645 31173, Fax: 645 36131.

Report No: 0633-18-HSA

24 September 2018

## ACCIDENT VEHICLE SURVEY REPORT

Siang Hock Holding Pte Ltd 21 Jalan Masjid Singapore 418946

#### VEHICLE INFORMATION:

Vehicle Reg No .:

GBF4989R

Odometer:

33975km

Make & Model:

Nissan NV 200

Colour:

Silver

Chassis number:

VSKYBAM20Z0131466

Date of accident:

21/08/2018

Year of Regn.:

28/11/2016

Date inspected:

28/08/2018

Repairer at:

Date inspected (After Repair):

H S Automotive Services

05/09/2018

Blk 2 Kaki Bukit Ave 2 #02-25

Kaki Bukit Auto Hub Singapore 417921

#### STATIC CHECKS, where applicable:

Steering:

serviceable

Footbrake:

serviceable

Handbrake:

serviceable

Paintwork:

Good

General condition:

Good

#### TIRE CONDITION:

LH / Make

RH / Make

Size

Front:

4mm/Eco Saver

175/70R14

5mm/Goodyear

Rear:

5mm/Goodyear

5mm/Goodyear

175/70R14

#### POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.

Please see details as described in the Annex for parts and labour.

#### REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

# PAR Automotive Consultancy Parts and I

# Parts and Labour Assessment

Report No: 0633-18-HSA

Vehicle No: GBF4989R

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Tailgate door LH	1	buckled	1,281.10	1,281.10 Buc
Tailgate door logo "Nissan" LH	1	necessary	66.40	66.40 / nec
Tailgate door chrome emblem"NV200" LH	1	necessary	125.10	125.10 ml
Tailgate door third brake lamp LH	1	reuse	457.70	0.00 X 3VC
Tailgate number plate lamp LH	1	fractured	73.50	73.50 XNN
Tailgate door outer garnish LH	1	fractured	336.00	336.00
Tailgate door wiper blade LH	1	reuse	27.20	2√2× 00.0
Tailgate door wiper motor LH	1	shorted	240.10	240.10 & NN
Tailgate door upper lock mechanism LH	1	bent	109.90	109.90 NN
Tailgate door lower lock striker LH	1	bent	98.50	98.50
Tailgate door lower lock mechanism LH	1	bent	109.90	109.90 \$7
Tailgate door upper lock striker LH	1	bent	98.50	98.50 X- Nr
Tailgate door outer handle LH	1	distorted	336.00	336.00 × ~/
Tailgate door hinge LH	2	bent	234.20	234.20 XSX
Tailgate door hinge cover LH	2	warped	191.00	191.00 KNY
Tailgate inner trim board LH	1	fractured	226.60	226.60 (CR)
Tailgate door inner handle LH	1	reuse	74.60	0.00 X SU(
Tailgate door window glass LH	1	reuse	920.70	0.00 x SVL
Tailgate door RH	1	buckled	960.90	960.90 Buc
Tailgate door chrome emblem "DCI" RH	1	necessary	56.20	56.20 NEC
Tailgate door weatherstrip RH	1	deformed	96.40	96.40 - 37
Tailgate door hinge RH	1	bent	234.20	234.20 TNN
Tailgate door hinge cover RH	1	warped	191.00	191.00 入りん
Tailgate door upper lock mechanism RH	1	bent	109.90	109.90 TUN
Tailgate door lower lock striker RH	1	bent	98.50	98.50 > 50(
Tailgate door lower lock mechanism RH	1	bent	109.90	109.90 51
Tailgate door upper lock striker RH	1	bent	98.50	98.50 X NN
Tailgate inner trim board RH	1	fractured	74.60	74.60 BT
Tailgate door window glass RH	1	reuse	697.50	0.00 XCVC
Rear tail lamp RH/LH	2	fractured	517.40	517.40 NN
Tailgate weatherstrip	1	deformed	83.90	83.90 PEF
Rear end panel	1	buckled	246.20	246.20 Buc
Rear end panel top garnish	1	warped	85.00	85.00 OFF
Rear bumper	1	squashed	624.80	624.80 DEF
Rear bumper side retainer RH/LH	2	nessary	70.40	70.40 × 50c
Rear bumper reflector lamp RH/LH	2	fractured	133.20	133.20 / 500

4,147

# - PAR Automotive Consultancy

							V
Rear bumper sponge			1	deformed		133.80	133.80 DEF
Rear bumper air ventilate	or RH/LH		2	warped		158.20	158.20 X NN 47.20 X SVC
Rear bumper spare tyre i	rack		1	bent		47.20	47.20 - SUC
Rear bumper spare tyre i	rack lever		1	bent		240.10	240.10 \ 500
Rear exhaust pipe			1	bent		552.00	552.00 / SUL
Rear exhaust pipe top mo	ounting		1	distorted		37.20	37.20 X 5
Rear inner panel RH/LH			2	repair		894.00	0.00 X R
Rear tail lamp inner pane	RH/LH		2	repair	133.80	554.40	0.00 X R
			Sta	ibtotal before	discount	12,112.40	8,486.30 4,280
	Percentage discount	0%	and	10%	-	0.00	848.63 3852.7
				St	ub-total 1	12,112.40	7,637.67
Tailgate door reverse can	nera LH		1	shorted		550.00	550.00 Tinh
Tailgate inner trim board	clip LH - set		1	necessary		57.00	30 57.00 NE
Tailgate inner trim board	clip RH - set		1	necessary		57.00	30 57.00 - NEC
Rear bumper clip - set			1	necessary		49.00	35 49.00 ME
Rear bumper reverse sens	sor RH/LH		2	shorted		350.00	200300.00 / seR
Rear door sealant RH/LH	I		2	necessary		200.00	00 160.00 NE.
Rear number plate			1		_	60.00	40.00 × NN
			Su	btotal before	discount	1,323.00	1,213.00 395
	Percentage discount	0%	and	0%	_	0.00	0.00
				Su	ib-total 2	1,323.00	1,213.00
				Par	rts-total _	13,435.40	8,850.67
LABOUR 1. To straighten and panel fender RH/LH and rear frend panel. To remove and	ame members. To cut and	-				2,300.00	1,250.00
2. To putty, re-spray pain	ting and polish affected a	reas.				2,200.00	1,320.00
3. To check and rectify w	W-971					150.00	60.00 30
4. To remove and refit rea	r exhaust pipe.					300.00	120.00 × NN
5. To remove and refit tail	lgate windscreen glass.					380.00	200.00 120
				Labo	our total	5,330.00	2,950.00 2,150
				Parts & Lab	our total_	18,765.40	11,800.67 6,397,7

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is : and the recommended number of working days for the repairs is :

8 6 \$

th. 400 00

B J Loi (I Eng. MIMI, AIRTE)

Automotive Appraiser

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case 1	Notified	Est Submitted	Adj Assigned	Adi Rpt	I Ac	i Submitted	Ins Auth'ed	Status		
	23 Aug 2018	28 Aug		\$\$5,10	0.00 S	5,100.00 View Rpt	Ins Autrea	Pending for Report Cancel Case	1	
M	lain	R	eference		laim Details		Documents		Show All	
CLAIM SUE	FOLDER DE	TAILS				[Created I	by insurer]			
Insured:	MOHANA	DASS S/O BALA	KRISHNAN NAIR,	ID: S161	8463B, Tel:	+6596609207	, Email: MNAIRE	AS@GMAIL.CO	М	
Main Claimant:	ROBINSO	N CAR RENTAL	PTE LTD, Co. Reg	. No.: 2004	14041W					
/ehicle Reg. No.:	GBF498	9R			Date of Loss		3 19:00 - :59 and <b>24</b> Days Fro	m LTA Reg Date	(Man Yr)]	
Claim Type:	<b>TP</b> / 568	202			Policy/Cover Note No.:		SMP (Comprehens 30/03/2018 - 29/0			
Vehicle Reg. No. (Insured):	SKK1115H				Policy No. (Claimant):					
					Excess:	S\$1,000.00				
Repairer:	H S Autor 67472755	notive Services	(Kaki Bukit) BLK 2	KAKI BUKI	T, AVENUE 2,	# 01-15, KAK	I BUKIT AUTOHUE	3, 417921 Kaki	Bukit - Tel:	
Handling Insurer:	MSIG Ins	urance (Singapo	ore) Pte. Ltd. (HQ)	- Tel: +65	6827 7888	. [Handled by	Chhia Nyuk Pui	6594 2521]		
Adjuster:	20/12/20		Ltd (HQ) - Tel: 62	56-3561	[Handled by	Muhammad	Nazril Bin Abdull	lah] [Final	Rpt due	
Driver/Custo dian (Insured):		DASS S/O BALAKR	ISHNAN NAIR (54 /	Male), N	RIC: S161846	3B, Tel: +6	596609207			
Adj Asg. Remarks:	SURVEY D	ISAGREE ON SJE	- ASSIGN LKK LIABI	LITY: 100%	CONTACT:	AR ALEX 6538	1368 UNIT NO: #	02-25		
ASSOCIAT	ED MAIL RE	CEIVED					Viev	v All Compo	se Case Mail	
• MSIG_SG	(18/12/2018	): Report Send	Back Alerts - GBF4	1989R (TP	)					
ALL ASSO	CIATED TAS	iks⊟				View All S	earch Tasks C	reate New Task	Complete	
Due Date	Priority	Type Task	Group Subject	t Hand	ler Assi	ned By	Completed On	Created C	n Done	

Page 1 of 2

#### Claim Documents

\*GBF4989R (568202)

[SKK1115H]

TP

ROBINSON CAR RENTAL PTE LTD

Aug 21 2018 7:00PM

[MOHANA DASS S/O BALAKRISHNAN NAIR]

H S Automotive Services

Ass	essment Reports		1 per p	1 per page 🔻	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	28/08/18 13:44	Accident Statement From:OD - Reg. No: SKK1115H, Claimant: MOHANA DASS S/O BALAKRISHNAN NAIR	0	Load HTM	
Pho	otos/Images		3 per p	age 🔻	<b>V</b>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	No.	Thumbnail	Print
1	29/08/18 18:26	General View	0	Load JPG	~
2	29/08/18 18:26	General View	0	Load JPG	<b>✓</b>
3	29/08/18 18:26	General View	0	Load JPG	~
4	29/08/18 18:26	General View	0	Load JPG	4
5	29/08/18 18:26	General View	0	Load JPG	V
6	29/08/18 18:26	General View	0	Load JPG	V
7	29/08/18 18:26	General View	0	Load JPG	V
8	29/08/18 18:26	General View	0	Load JPG	~
9	29/08/18 18:26	General View	0	Load JPG	~
10	29/08/18 18:26	General View	0	Load JPG	~
11	29/08/18 18:26	General View	0	Load JPG	V
12	29/08/18 18:26	General View	0	Load JPG	V
13	29/08/18 18:26	General View	0	Load JPG	~
14	29/08/18 18:26	General View	0	Load JPG	<b>V</b>
15	29/08/18 18:26	General View	0	Load JPG	~
16	29/08/18 18:26	General View	0	Load JPG	V
17	29/08/18 18:26	General View	0	Load JPG	V
18	29/08/18 18:26	General View	0	Load JPG	V
19	29/08/18 18:26	General View	0	Load JPG	~
20	29/08/18 18:26	General View	0	Load JPG	V
21	08/10/18 10:02	Photo After Spray	0	Load JPG	V
22	08/10/18 10:02	Photo After Spray	0	Load JPG	V
23	08/10/18 10:02	Photo After Spray	0	Load JPG	V
24	08/10/18 10:02	Photo After Spray	0	Load JPG	V
25	08/10/18 10:02	Photo After Spray	0	Load JPG	V
26	08/10/18 10:02	Photo After Spray	0	Load JPG	V
20	00/10/10 10:02	Thota Alkai Spidy			
Doc	cumentation		1 per j	page 💟	~
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	28/08/18 13:44	TP GBF4989R GIA Report From: OD - Reg, No: SKK1115H, Claimant: MOHANA DASS S/O BALAKRISHNAN NAIR	0	Load PDF	
2	28/08/18 13:47	PRI - JUSEQUITY LAW CORPORATION	0	Load PDF	
3	28/08/18 15:17	SURVEY DISAGREE ON SJE - ASSIGN LKK	0	Load PDF	
4	18/10/18 16:10	LOD & SUPPORTING DOCUMENTS	0	Load PDF	

Ass	Assessment Reports		1 per page		<b>∀</b>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
6	18/10/18 16:10	SURVEY PHOTOS PART 1	0	Load PDF	
7	18/10/18 16:10	SURVEY PHOTOS PART 2	0	Load PDF	
8	18/10/18 16:10	SURVEY PHOTOS PART 3	0	Load PDF	
9	18/10/18 16:10	SURVEY PHOTOS PART 4	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/01/19 13:43	Colour Photo	0	Load PDF	
2	04/01/19 13:43	PRS Invoice	0	Load PDF	

## **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

#### LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/MSG18015777/NVBE2-1

Date:

04/01/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

B27487632SMP

Claimant Vehicle

**GBF4989R** 

Insured Vehicle No:

SKK1115H

No: Date of Loss:

21/08/2018

Nature of Claim:

TP

Claim No: 568202

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

**GBF4989R** 

Make & Model:

NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR

Engine No:

K9KC400D055941

Reg. Date:

(A)

28/11/2016 (Man. Year: 2016)

Chassis No: Odometer:

VSKYBAM20Z0131466

Colour: Engine Capacity: Silver

1461 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

33975 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size:

175/70 R14C

Rear Tyre Size:

175/70 R14C

Front Left Side:

Goodyear 5 mm

Rear Left Side:

Goodyear 5 mm

Front Right Side:

Goodyear 5 mm

Rear Right Side:

Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,435.40	4,247.72	9,187.68	68.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,330.00	2,150.00	3,180.00	59.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,765.40	6,397.72	12,367.68	65.91
Approved Total (Overridden) (S\$)		5,100.00		
Nett Amount (S\$)	18,765.40	5,100.00	13,665.40	72.82

INSPECTION

Date of Assignment:

28/08/2018

Date Inspected:

29/08/2018 Inspected At:

H S Automotive Services (Kaki Bukit)

BLK 2 KAKI BUKIT, AVENUE 2, # 01-15,

KAKI BUKIT AUTOHUB Singapore 417921

Estimated Period of Repair:

6.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 04 Jan 2019)

Parts: N/A NISSAN NV200 1.5 D MT ABS AIRBAG 2WD 6DR (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBF4989R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE DOOR LH	Buckled	1,281.10 F	*1,281.10 FL
2	1		*TAILGATE DOOR LOGO NISSAN LH	Necessary	66.40 F	*66.40 FL
3	1		*TAILGATE DOOR CHROME EMBLEM NV200 LH	Necessary	125.10 F	*125.10 FL
4	1		*TAILGATE DOOR THIRD BRAKE LAMP LH	Serviceable	457.70 F	*- FL
5	1		*TAILGATE NUMBER PLATE LAMP LH	Not Necessary	73.50 F	*- FL
6	1		*TAILGATE DOOR OUTER GARNISH LH	Not Necessary	336.00 F	*- FL
7	1		*TAILGATE DOOR WIPER BLADE LH	Serviceable	27.20 F	*- FL
8	1		*TAILGATE DOOR WIPER MOTOR LH	Not Necessary	240.10 F	*- FL
9	1		*TAILGATE DOOR UPPER LOCK MECHANISM LH	Not Necessary	109.90 F	*- FL
10	1		*TAILGATE DOOR LOWER LOCK STRIKER LH	Serviceable	98.50 F	*- FL
11	1		*TAILGATE DOOR LOWER LOCK MECHANISM LH	Bent	109.90 F	*109.90 FL
12	1		*TAILGATE DOOR UPPER LOCK STRIKER LH	Not Necessary	98.50 F	*- FL
13	1		*TAILGATE DOOR OUTER HANDLE LH	Not Necessary	336.00 F	*- FL
14	2		*TAILGATE DOOR HINGE LH	Serviceable	234.20 F	*- FL
15	2		*TAILGATE DOOR HINGE COVER LH	Not Necessary	191.00 F	*- FL
16	1		*TAILGATE INNER TRIM BOARD LH	Cracked	226.60 F	*226.60 FL
17	1		*TAILGATE DOOR INNER HANDLE LH	Serviceable	74.60 F	*- FL
18	1		*TAILGATE DOOR WINDOW GLASS LH	Serviceable	920.70 F	*- FL
19	1		*TAILGATE DOOR RH	Buckled	960.90 F	*960.90 FL
20	1		*TAILGATE DOOR CHROME EMBLEM DCI RH	Necessary	56.20 F	*56.20 FL
21	1		*TAILGATE DOOR WEATHERSTRIP RH	Bent	96.40 F	*96.40 FL
22	1		*TAILGATE DOOR HINGE RH	Not Necessary	234.20 F	*- FL
23	1		*TAILGATE DOOR HINGE COVER RH	Not Necessary	191.00 F	*- FL
24	1		*TAILGATE DOOR UPPER LOCK MECHANISM RH	Not Necessary	109.90 F	*- FL
25	1		*TAILGATE DOOR LOWER LOCK STRIKER RH	Serviceable	98.50 F	*- FL
26	1		*TAILGATE DOOR LOWER LOCK MECHANISM RH	Bent	109.90 F	*109.90 FL
27	1		*TAILGATE DOOR UPPER LOCK STRIKER RH	Not Necessary	98.50 F	*-FL
28	1		*TAILGATE INNER TRIM BOARD RH	Bent	74.60 F	*74.60 FL
29	1		*TAILGATE DOOR WINDOW GLASS RH	Serviceable	697.50 F	*- FL
30	2		*REAR TAIL LAMP RH / LH	Not Necessary	517.40 F	*- FL
31	1		*TAILGATE WEATHERSTRIP	Deformed	83.90 F	*83.90 FL
32	1		*REAR END PANEL	Buckled	246.20 F	*246.20 FL
33	1		*REAR END PANEL TOP GARNISH	Deformed	85.00 F	*85.00 FL
34	1		*REAR BUMPER	Deformed	624.80 F	*624.80 FL
35	2		*REAR BUMPER SIDE RETAINER RH / LH	Serviceable	70.40 F	*- FL
36	2		*REAR BUMPER REFLECTOR LAMP RH / LH	Serviceable	133.20 F	*- FL
37	1		*REAR BUMPER SPONGE	Deformed	133.80 F	*133.80 FL
38	2		*REAR BUMPER AIR VENTILATOR RH / LH	Not Necessary	158.20 F	*- FL
39	1		*REAR BUMPER SPARE TYRE RACK	Serviceable	47.20 F	*- FL

Report was unsubmitted during this print-out.

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*REAR BUMPER SPARE TYRE RACK LEVER	Serviceable	240.10 F	*- FL
1		*REAR EXHAUST PIPE	Serviceable	552.00 F	*- FL
1		*REAR EXHAUST PIPE TOP MOUNTING	Serviceable	37.20 F	*-FL
2		*REAR INNER PANEL RH / LH	Repair	894.00 F	*-FL
2		*REAR TAIL LAMP INNER PANEL RH / LH	Repair	554.40 F	*-FL
1		*TAILGATE DOOR REVERSE CAMERA LH	Not Necessary	550.00 FS	*- FS
1		*SET TAILGATE INNER TRIM BOARD CLIP LH	Necessary	57.00 FS	*30.00 FS
1		*SET TAILGATE INNER TRIM BOARD CLIP RH	Necessary	57.00 FS	*30.00 FS
1		*SET REAR BUMPER CLIP	Necessary	49.00 FS	*35.00 FS
2		*REAR BUMPER REVERSE SENSOR RH / LH	Scratched	350.00 FS	*200.00 FS
2		*REAR DOOR SEALANT RH / LH	Necessary	200.00 FS	*100.00 FS
1		*REAR NUMBER PLATE	Not Necessary	60.00 FS	*- FS
nchise	part. S=Spc	Nett. L=ListItemDisc.			
			Sub Total (S\$)	13,435.40	4,675.80
		- List Item Discount on L Items (	0.00/10.00% (S\$)	0.00	428.08
			Total Parts (S\$)	13,435,40	4,247.72
	1 1 1 2 2 1 1 1 1 2 2 1	1 1 1 2 2 1 1 1 1 2 2 1	*REAR EXHAUST PIPE  *REAR EXHAUST PIPE TOP MOUNTING  *REAR INNER PANEL RH / LH  *REAR TAIL LAMP INNER PANEL RH / LH  *TAILGATE DOOR REVERSE CAMERA LH  *SET TAILGATE INNER TRIM BOARD CLIP LH  *SET TAILGATE INNER TRIM BOARD CLIP RH  *SET REAR BUMPER CLIP  *REAR BUMPER REVERSE SENSOR RH / LH  *REAR DOOR SEALANT RH / LH  *REAR NUMBER PLATE  **Inchise part. S=SpcNett. L=ListItemDisc.	1 *REAR BUMPER SPARE TYRE RACK LEVER Serviceable 1 *REAR EXHAUST PIPE Serviceable 1 *REAR EXHAUST PIPE TOP MOUNTING Serviceable 2 *REAR INNER PANEL RH / LH Repair 2 *REAR TAIL LAMP INNER PANEL RH / LH Repair 1 *TAILGATE DOOR REVERSE CAMERA LH Not Necessary 1 *SET TAILGATE INNER TRIM BOARD CLIP LH Necessary 1 *SET TAILGATE INNER TRIM BOARD CLIP RH Necessary 1 *SET REAR BUMPER CLIP Necessary 2 *REAR BUMPER REVERSE SENSOR RH / LH Scratched 2 *REAR DOOR SEALANT RH / LH Necessary 1 *REAR NUMBER PLATE Not Necessary 2 *REAR BUMPER REVERSE SENSOR RH / LH Scratched 3 *REAR NUMBER PLATE Not Necessary 4 *REAR NUMBER PLATE Not Necessary 5 *Canada Not Necessary 6 *Canada Not Necessary 7 *Canada Not Necessary 8 *Canada Not Necessary 9 *Canada Not Necessary 1 *REAR NUMBER PLATE Not Necessary 1 *Canada	1         *REAR BUMPER SPARE TYRE RACK LEVER         Serviceable         240.10 F           1         *REAR EXHAUST PIPE         Serviceable         552.00 F           1         *REAR EXHAUST PIPE TOP MOUNTING         Serviceable         37.20 F           2         *REAR INNER PANEL RH / LH         Repair         894.00 F           2         *REAR TAIL LAMP INNER PANEL RH / LH         Repair         554.40 F           1         *TAILGATE DOOR REVERSE CAMERA LH         Not Necessary         550.00 FS           1         *SET TAILGATE INNER TRIM BOARD CLIP LH         Necessary         57.00 FS           1         *SET REAR BUMPER CLIP         Necessary         57.00 FS           2         *REAR BUMPER REVERSE SENSOR RH / LH         Scratched         350.00 FS           2         *REAR DOOR SEALANT RH / LH         Necessary         200.00 FS           1         *REAR NUMBER PLATE         Not Necessary         60.00 FS           nchise part. S=SpcNett. L=ListItemDisc.         Sub Total (S\$)         13,435.40

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO STRAIGHTEN AND PANEL BEATING REAR BOOT FLOOR PANEL, REAR FENDER RH / LH AND REAR FRAME MEMBERS. TO CUT AND WELD REAR END PANEL. TO REMOVE AND REFIT ABOVE PARTS	New	2,300.00	1,000.00
2	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS	New	2,200.00	1,000.00
3	TO CHECK AND RECTIFY WIRING SYSTEM	New	150.00	30.00
4	TO REMOVE AND REFIT REAR EXHAUST PIPE	New	300.00	0.00
5	TO REMOVE AND REFIT TAILGATE WINDSCREEN GLASS	New	380.00	120.00
	Gross Labou	ır Cost (S\$)	5,330.00	2,150.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >