

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JFISJSK65JG112353

QUEK MUI YEE JERIN
129 JALAN PELIKAT
S 537616

TOP ALG.
Vic

Date :26.12.2018
Vehicle no :SME 997 T
Make/Model :SUBARU FORESTER
Accident date :16.12.2018

No	DESCRIPTION	Qty	Amount (\$\$)
<u>Nett Items</u>			
1	Rear tailgate top garnish <i>Not new</i>	1	\$ 742.5 ✓
2	Rear windscreen rubber <i>New</i>	1	\$ 105.80 ✓
3	Rear tailgate <i>Dated</i>	1	\$ 127.2 ✓
4	Rear tailgate centre emblem <i>Not new</i>	1	\$ 87.2 ✓
5	Rear tailgate SUBARU emblem	1	\$ 71.3 ✓
6	Rear tailgate SUMMETRICAL emblem <i>New</i>	1	\$ 71.3 ✓
7	Rear tailgate AWD emblem	1	\$ 71.3 ✓
8	Rear tailgate FORESTER emblem	1	\$ 53.3 ✓
9	Rear tailgate upper lock <i>changed</i>	1	\$ 216.7 ✓
10	Rear tailgate lower lock <i>Not new</i>	1	\$ 20.9 ✓
11	Rear tailgate hinges @ \$41.80 <i>Not new</i>	2	\$ 83.6 ✓
12	Rear tailgate shock absorber @ \$138.60 <i>New</i>	2	\$ 277.2 ✓
13	Rear tailgate inner side rubber @ \$64.90 <i>New</i>	2	\$ 129.8 ✓
14	Rear tailgate inner board <i>cracked</i>	1	\$ 278.40 ✓
15	Rear tailgate weather strip <i>lit</i>	1	\$ 118.8 ✓
16	Rear bumper <i>Defend</i>	1	\$ 690 ✓
17	Rear bumper side holder @ \$15.80 <i>New</i>	2	\$ 31.6 ✓
18	Rear bumper top FORESTER garnish <i>lit</i>	1	\$ 302.5 ✓
19	Rear bumper reflector @ \$22.60 <i>Not new</i>	2	\$ 45.2 ✓
20	Rear bumper reinforcement <i>Best</i>	1	\$ 316.8 ✓
21	Rear bumper bracket	1	\$
22	Rear bumper clips (1set) <i>New</i>	1	\$ 50.30 ✓
23	Rear end panel <i>Repair</i>	1	\$ 316.8 ✓
24	Rear end panel inner top garnish <i>Defend</i>	1	\$ 108.20 ✓
25	Rear lamp @ \$1018.20 <i>Not new</i>	2	\$ 2036.4 ✓
			20%
			\$ 7052.9
Less 10% Disc			\$ 705.29
Total			\$ 6347.61

3738

2990.40

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

QUEK MUI YEE JERIN
129 JALAN PELIKAT
S 537616

Date :26.12.2018
Vehicle no :SME 997 T
Make/Model :SUBARU FORESTER
Accident date :16.12.2018

No	Description	Qty	Amount (S\$)
Special Nett Items			
1	Rear bumper reverse sensor <i>Damaged</i>	1	\$ 380 <i>200</i>
2	Rear tailgate camera <i>HE NEW</i>	1	\$ 800 <i>X</i>
		Total	\$ 1180

Labour cost

- 1 To supply rear windscreen sealant
- 2 To supply rear end panel inner sealant
- 3 Remove & reinstall boot lid inner garnish
- 4 Remove & reinstall rear windscreen
- 5 Remove & reinstall reverse sensor
- 6 Remove, replace & repair consistent to the accident
- 7 Respray painting
- 8 Tuff kote

\$ 50	✓
\$ 200	X
\$ 200 <i>80</i>	
\$ 200 <i>120</i>	
\$ 150 <i>50</i>	
\$ 1800 <i>750</i>	
\$ 1500 <i>750</i>	
\$ 150	X
Total	\$ 4250

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Grand Total \$ 11777.61

total: 4990.40

h/s HK.

04 Days.

HK