



Mercedes-Benz

Cycle & Carriage Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

ESTIMATE FOR SFG3J

Lux Limo SG Pte. Ltd.  
  
19 Kim Keat Road  
#04-01/02 Fu Tsu Building  
Singapore 328804  
Attn: Mr Bernard Foo  
Mobile: 93212243

Vehicle & Document Information

WIP No 29471  
Reg No/Reg Date SFG3J / 11/05/2018  
Date In/Mileage / 100  
Chassis No WDD2130892A388223  
Engine No 17798060045572  
Make/Model MB/ 63 S 4MATIC SEDAN (W213)  
Colour/Trim 020 056 Des.Magno N/ 045 571 Exclusive A

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	18/12/2018/ 18:18	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : CN890284 // 17.12.18 DRIVE IN/EXCESS : 18.12.18 // TP CAR NO.: SKF3636J=AXA DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				1200.00
A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR.NETT LHF DR,LHR DR				3360.00
A BPILAB DISASSEMBLE AND REPLACE ON LHF DR, LHR DR, LEFT RUNNING BOARD				4500.00
A BPIRES RESPRAY ON LHF DR, LHR DR,LEFT RUNNING BOARD				480.00
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				
M LH DRIVER'S DOOR	1.00	1954.96	00.00	1954.96
M LH DR REINFORCEMENT	1.00	12.30	00.00	12.30
M LHF DOOR WEATHERSTRIP	1.00	280.72	00.00	280.72
M LHF DR INSULATION	1.00	32.68	00.00	32.68
M LHF DOOR LOCK	1.00	667.17	00.00	667.17
M LHF DR WINDOW RUN	1.00	141.23	00.00	141.23
M LHF DR PANELING WINDOW FRAME	1.00	86.62	00.00	86.62
M LEFT REAR DOOR	1.00	2175.70	00.00	2175.70
M LH RR DR DEFLECTOR STRIP	1.00	28.74	00.00	28.74
M LH RR DR COVER STRIP	1.00	34.30	00.00	34.30
M LHR DR INSULATION	1.00	32.68	00.00	32.68
M LHR DOOR WEATHERSTRIP	1.00	280.72	00.00	280.72
M LH RR DR BOTTOM HINGE	1.00	201.06	00.00	201.06
M LH RR COVER STRIP	1.00	28.01	00.00	28.01
M LHR DR FIXED WINDOW	1.00	140.37	00.00	140.37
M LHR DR WINDOW RUN	1.00	174.87	00.00	174.87
M LHR DR PANELING WINDOW FRAME	1.00	82.04	00.00	82.04

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

**ESTIMATE FOR SFG3J**

Lux Limo SG Pte. Ltd.  
  
19 Kim Keat Road  
#04-01/02 Fu Tsu Building  
Singapore 328804  
Attn: Mr Bernard Foo  
Mobile: 93212243

Vehicle & Document Information

WIP No **29471**  
Reg No/Reg Date **SFG3J / 11/05/2018**  
Date In/Mileage **/ 100**  
Chassis No **WDD2130892A388223**  
Engine No **17798060045572**  
Make/Model **MB/ 63 S 4MATIC SEDAN (W213)**  
Colour/Trim **020 056 Des.Magno N/ 045 571 Exclusive A**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	18/12/2018/ 18:18	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LEFT TRIM STRIP	1.00	720.32	00.00	720.32
M TRIM, LONGITUDINAL MEMBER	1.00	740.47	00.00	740.47
M LEFT RUNNING BOARD STRIP	1.00	1678.73	00.00	1678.73

THIS IS NOT AN OFFICIAL TAX INVOICE  
ESTIMATE

Confirmed & accepted by

	<b>Nett</b>	<b>19,033.69</b>
<b>7% GST on</b>	<b>19033.69</b>	<b>1332.36</b>
	<b>Total Payable</b>	<b>20,366.05</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg