

15/02/2010

INS. CASE OWNER:

CC 4, AXA1802

LKK:  
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II : \$S

D.O.A.:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO )

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$S

94501-

( 6 days)

Reduction:

#17,757.40%

6.5

Email

Call

FINAL SETTLEMENT

Date/Time:

9/9/10-30

Confirm with:

And Motorsports

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

\$S

94500.00

Loss of Rental (LOR):

\$S

480.00

( 4 days)

x \$120

Loss of Use (LOU):

\$S

-

(S

x days)

Loss of Income (LOI):

\$S

-

(S

x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$S

7.45

Medical:

\$S

-

Disbursement:

\$S

-

(e.g. Tow/ Independent)

Legal Cost

\$S

-

Total:

\$S

9437.45

Global Sum \$S:

FINAL PAYMENT

Date/Time:

9/9/10-30

Confirm with:

And Motorsports

Email

Call

Payee 1:

\$S

9437.45

Name 1:

Asia Motorsports Solution Pte Ltd

Payee 2: (Strike if N.A.)

\$S

-

Name 2:

-

Payee 3: (Strike if N.A.)

\$S

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$3501-

(38/11/13) wef

ASS. REC. BY: Marcus

REF:

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lum Sum:

70

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21A 65770 Rep 15  
 31/12/2018 - Received repair estimate thru email.  
 9/1/2019 6.05pm - Fax marked estimate to repairer.  
 16/1/2019 4.00pm - Fax again amended marked estimate to repairer.  
 16/1/2019 9.15pm - Confirm with repairer CUR LS \$9,450 with 6 days repair day. (Red = \$17,757.40 / 65.1.)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

\$ + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	8335K
<b>Vehicle Details</b>	
Vehicle No.:	SLA1309G
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS NX200T EXECUTIVE
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	8ARW228415
Chassis No.:	JTJBARBZX02067101
Maximum Power Output:	175.0 kW (234 bhp)
Open Market Value:	\$41,966.00
Original Registration Date:	25 Feb 2016
First Registration Date:	25 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$50,753.00 <i>28 376</i>
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Feb 2026
PARF Rebate Amount:	\$38,064.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	24 Feb 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$44,001.00
COE Rebate Amount:	\$27,716.00
<b>Total Rebate Amount:</b>	<b>\$65,780.00</b>

The information contained herein is correct as at 20 Dec 2018

OK

Wide selection of Inchcape Certified Pre-owned LEXUS & TOYOTA

**Christmas Sale**

Free Tyre & Service Credits up to \$3,000

Interest Rate 2.28%

Extended Warranty 1yr

**Post an Advertisement**  
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

2017 Mercedes-Benz C180 Avantgarde at \$143,800



Very Low Mileage, Almost New Condition, Serviced And Warranty By C&C. Speedo Motoring StarAd

Think One Automobile

**NEW & USED COMMERCIAL VEHICLES**

Browse by Category ▾

7 vehicles

lexus nx

Sort by Date Posted ▾

20 results/page

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	lexus nx		Any	Any	2016	Any	Any	Any	Available
	Lexus NX Turbo NX200t	Luxury	\$145,800	\$15,440 /yr	15-Jul-2016	1,998 cc	31,520 km	SUV	Available
<p>\$15K Down Payment! 2.18% Interest Rate! 1 Owner! Fully Maintained By Borneo Motor! Agent Unit With 5 Years Unlimited Mileage Warranty! High Trade In And In House Financing Available! View Today!</p> <p>Posted: 18-Dec-2018 Tags: 2016 Lexus NX, 2016 lexus nx, Lexus NX, lexus nx, Lexus, NX, nx, Used Lexus</p>									
	Lexus NX Turbo NX200t	Executive	\$140,800	\$14,740 /yr	19-Oct-2016	1,998 cc	37,600 km	SUV	Available
<p>New Carplate No. Low Mileage. Only 1 Owner. 5 Years/Unlimited Warranty By LEXUS. 3 Years Free Servicing Package. Additional \$500 Discount On Insurance Premium When You Trade In A Car. 90% Loan Availab...</p> <p>Performance Carz Pte Ltd</p> <p>Posted: 10-Dec-2018 Tags: 2016 Lexus NX, 2016 lexus nx, Lexus NX, lexus nx, Lexus, NX, nx, Used Lexus</p>									
	Lexus NX Turbo NX200t	Executive	\$143,800	\$15,530 /yr	04-Aug-2016	1,998 cc	35,000 km	SUV	Available
<p>One Very Careful Owner, Accident Free, Low Down Payment &amp; Very Well Maintained. 5 Years Warranty With Agent, Very Neat Interior, Powerful &amp; Smooth Transmission. Spacious Interior &amp; Well Decorated Features...</p> <p>Posted: 24-Nov-2018 Tags: 2016 Lexus NX, 2016 lexus nx, Lexus NX, lexus nx, Lexus, NX, nx, Used Lexus</p>									
	Lexus NX Turbo NX200t	Luxury	\$145,000	\$15,460 /yr	22-Jun-2016	1,998 cc	44,000 km	SUV	Available
<p>NX 200T Luxury Ed With Panoramic Sunroof And 360 Cam. Agent Warranty Till June 2021. Free Servicing - June 2019. Added Mods Of &gt;\$10K Included. Front/Rear Camera, Forged Rims. Schedule A Test Drive Tod...</p> <p>Carro</p> <p>Posted: 07-Nov-2018 Tags: 2016 Lexus NX, 2016 lexus nx, Lexus NX, lexus nx, Lexus, NX, nx, Used Lexus</p>									

CONSIGNMENT



### Glamping under the stars with Lexus

Lexus showcased its range of SUVs, including the new Lexus RX350L, and their abilities to enjoy the outdoors with all your creature comforts.

Read this article



Lexus NX Turbo NX200t	Luxury	\$143,000	\$14,770 /yr	09-Sep-2016	1,998 cc	52,000 km	SUV	Available
<p>Interest Rate From 1.98%. 1 Owner, 5 Years Warranty With Unlimited Mileage And 3 Years Free Servicing By Borneo Motors, Brand New Condition, Great Saving From New. Flexible Loan At Low Interest Rate A...</p> <p>Motor Universe Credit Pte Ltd</p> <p>Posted: 29-Oct-2018 Tags: 2016 Lexus NX, 2016 lexus nx, Lexus NX, lexus nx, Lexus, NX, nx, Used Lexus</p>								



Lexus NX Turbo NX200t	F Sport	\$162,000	\$17,250 /yr	14-Sep-2016	1,998 cc	47,000 km	SUV	Available
<p>One Owner Agent Unit! A Black Mafia With Its Aggressive Energetic Looks. This Beast Is A Powerful AWD That Performs And Handles Well. The Black Exterior! With F Sport's Exclusive Red Leather Seats Not ...</p> <p>ad: 25-Oct-2018 Tags: 2016 Lexus NX, 2016 lexus nx, Lexus NX, lexus nx, Lexus, NX, nx, Used Lexus</p>								

CONSIGNMENT

Compare

Attn = Edison  
Fax = 67465110

Estimate Repair For Vehicle SLA 1309 G (Lexus NX200t)

from = Simon

Item Description Parts	Qty	Price list
1 Rear bumper	1	\$828 2,083.10 DIS
2 Rear bumper side retainer L/R @ \$103.70 92.50	2	\$185 207.40 DIS
3 Rear bumper bracket L/R @ \$71.50 55	2	\$55 143.00
4 Rear bumper reinforcement	1	\$599 822.80 DD
5 Rear reinforcement mount bracket L/R @ \$258.40 180	2	\$180 516.80
6 Rear bumper lower diffuser	1	\$598 848.70 CUT
7 Rear bumper under cover	1	\$470.60 XNN
8 Rear bumper reflector L/R @ \$208.20	2	\$76 416.40
9 Rear tail gate	1	\$1290 2,978.80 BUC
10 Rear tail gate lock	1	\$598.90 BT
11 Rear tail gate weather-strip	1	\$299 312.30 DIS
12 Rear tail gate glass moulding L/R @ \$84.30	2	\$168.60 NEC
13 Rear tail gate glass lower moulding	1	\$304.50 NEC
14 Rear tail gate finish panel	1	\$585 1,552.40 CRA
15 Rear end panel	1	\$628 1,644.50 BUC
16 Rear end panel top garnish	1	\$398 658.50 CRA
17 Rear exhaust tail pipe extension @ \$296.50	2	\$296.50 593.00
18 Rear bumper clips	1	\$52.60 NEC
19 Rear pressure air vent L/R @ \$164.90	2	\$329.80 XNN
20 Rear wheel arch moulding L/R @ \$425.70 261	2	\$261 851.40
21 Rear end panel top garnish chrome plate	2	\$318 488.00 NEC
22 Rear tail gate emblem	1	\$89.40
23 Rear tail gate "Lexus" emblem	1	\$74.70
24 Rear tail gate "NT200T" emblem	1	\$95.80
25 Rear tail gate opener switch	1	\$298.80 XNN
26 Rear tail gate autogate switch	1	\$324.00 XNN
27 Rear tail lamp L/R @ 920.60 689	2	\$1,378 1,841.20 CRA
28 Rear tail gate lamp L/R @ \$828.80 710	2	\$770 1,657.60
29 Rear tail gate license lamp @ \$99.40	2	\$198.80 XNN
30 Rear tail gate view camera	1	\$859.00 XNN
31 Rear bumper reverse sensor retainer @ \$32.00	4	\$64 128.00 NEC
32 Rear bumper reverse sensor @ \$287.00	4	\$514 1,148.00 Short
<b>Parts Total :</b>		<b>\$ 22,757.40</b>

Less 1070

**LABOUR CHARGES & MISC**

33	Check wiring, lighting, auto gate, wiper motor & centre locking system	\$	80.00	30
34	Remove damaged parts, knock out dents, straighten, panel beating, remove & reinstall necessary fittings to facilitate repairs.	\$	1,800.00	800
35	Spray painting all affected areas.	\$	1,400.00	800
36	To transfer rear tail gate mechanism & components.	\$	80.00	60
37	To remove & reinstall rear tail gate glass to assist repair.	\$	120.00	
38	To supply rear windscreen glass sealant.	\$	50.00	
39	Anti-rust proofing on affected panel.	\$	120.00	80
40	To reinstall rear bumper reverse sensor & view camera and check for proper function.	\$	250.00	90
41	To straighten and re-align exhaust system to position.	\$	200.00	70
42	To carry out diagnostic checks, erase fault codes & reset.	\$	350.00	120
<b>Labour Total :</b>		<b>\$</b>	<b>4,450.00</b>	

**Sub Total :** \$ 27,207.40

Lump Sum Repair Adjustment  
Estimated Time required for Repairs

\$21,750 \$9,450  
8 days 6 days





## Service Request Details

Claim

S8M0172E

Reference

None

Loss Date

16 December 2018

Request Date

19 December 2018

Due Date

27 December 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

19.12.2018 @ 25am  
Mr. Luo veh in  
mess:

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SLA1309G

Make

TPVD

Service Address

---

...

Primary Contact/Insured

---

AAP MARKETING PTE LTD  
32 JALAN SELASEH, 808448, Singapore

Claim Handler

---

NG Stacey  
6568804351  
stacey.ng@axa.com.sg

Additional Instructions  
NON REPORTED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

**Catherine Chong (LKK Auto)**

---

**From:** Asia Motorsports Solution Pte Ltd <asiamotorsports@hotmail.com>  
**Sent:** Tuesday, 18 December, 2018 2:26 PM  
**To:** customer.service@axa.com.sg; SG AXA Insurance SM AXA SGP - Motor Survey  
**Subject:** NOTICE OF ACCIDENT: ACCIDENT INVOLVING SLA 1309 G & GBD 1502 S ON 16 DECEMBER 2018

**Categories:** Pragati

**Your Ref:**  
**Our Ref:** SLA 1309 G

18 December 2018

AXA Insurance Pte Ltd  
8 Shenton Way  
#27-01  
AXA Tower  
Singapore 068811

**PROPERTY CLAIM  
(WITHOUT PREJUDICE  
TO: Any Personal Injury  
Claims)**

Attn: Claims  
Department

Dear Sir/Mdm,

**NOTICE OF ACCIDENT: ACCIDENT INVOLVING SLA 1309 G & GBD 1502 S ON 16 DECEMBER 2018**

We are instructed to notify you of a road traffic accident on **16 December 2018** at about **8.30 pm** at **Junction of Jln Kelulut & Yio Chu Kang Road** involving our client's vehicle registration number **SLA 1309 G** and vehicle registration number **GBD 1502 S** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice and your proposed list of 10 recommended motor surveyors for our appointment.

Kindly note that if we do not hear from you by **20 December 2018 (Thursday), 1430H**, we will be forwarding our **proposed list of 10 motor surveyors** for your appointment, in accordance to the new regulations.

Thank you and we hope to hear from you soonest.

Regards,  
Asia Motorsports Solution Pte Ltd  
6745 3811  
6746 5110 (fax)  
asiamotorsports@hotmail.com




**AAP MARKETING PTE LTD**  
32 Jalan Selasih  
Singapore 800448  
Tel: 6383 7277

2/9/2019

To whom maybe concern,

I hereby confirmed that MR XIAO XIAO YANG /PERMIT NUMBER:0 74792634 was authorized to drive our company van -number GBD1502S ,on 16/12/2018

ONG ENG SHENG



Director

AAP MARKETING PTE LTD



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 09/06/2019

### Survey Details:

Date of loss	16-Dec-18
Date of appointment	19-Dec-18
Date of survey	19-Dec-18
Location of survey	ASIA MOTORSPORTS SOLUTION PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SLA 1309G
Make and Model	LEXUS NX 200T
Date of registration	25/2/2016
Excess	
Market Value	\$130,000
Parf Rebate	\$65,780
Nett Loss	\$64,220

### Repair details:

Initial Estimate	\$ 27,207.40
------------------	--------------

### Proposed/Revised repair cost:

Parts	\$ 9,514.71
Check items (estimate)	\$ -
Labour	\$ 2,220.00
<b>Total</b>	<b>\$ 11,734.71</b>
<b>Lump Sum(if applicable)</b>	<b>\$ 9,450.00</b>

Number of days for repair	6
---------------------------	---



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

--

**Mandate:**

Liability(TP)		100%	
Proposed repair cost	\$	9,450.00	
Loss of use	\$	-	
Loss of rental	\$	720.00	4days x \$180
Loss of income		-	
LTA search fees	\$	7.45	
Others		-	
Proposed Total	\$	10,177.45	\$ -



## <MANDATE IA> - S8M0172E {ACCIDENT INVOLVING GBD 1502S (OI) & SLA 1309G (TP) ON 16/12/2018}

Type

🔗 Question

Message

LIABILITY:100% BOLA S27 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$10,177.45 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED INTO SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CECILIA

Reply



## ASIA MOTORSPORTS SOLUTION PTE LTD

Specialise in sales of new & reconditioned bikes

Co. Reg. No: 200507766N

No. 568, Geylang Road Singapore 389514 Tel: +65 6745 3811 Fax: +65 6746 5110 Website: [www.asiamotorsports.com.sg](http://www.asiamotorsports.com.sg)

FATIMAH MOHSIN THE WEDDING GALLERY  
PTE LTD

INVOICE NO: 2017/C111

DATE: 21/01/2019

VEHICLE NO: SLA 1309 G

ENGINE CAPACITY : 1998 CC

ENGINE NO : 8ARW228415

MAKE : TOYOTA

CHASSIS NO : JTJBARBZX02067101

MODEL : LEXUS NX200T  
EXECUTIVE

YEAR : 2016

---

DESCRIPTION	AMOUNT
-------------	--------

---

Total lump sum repair including supply of parts and labour

Adjusted total lump sum repair costs

S\$9,450.00

**Total amount payable**

**S\$9,450.00**



---

Asia Motorsports Solution Pte Ltd



**Re:<MANDATE IA> - S8M0172E {ACCIDENT INVOLVING  
GBD 1502S (OI) & SLA 1309G (TP) ON 16/12/2018}**

Type

Question

Message

pls proceed

Reply



## Poh Kin (LKKAUTO)

---

**From:** Asia Motorsports Solution Pte Ltd <asiamotorsports@hotmail.com>  
**Sent:** Friday, 22 February 2019 2:10 PM  
**To:** Poh Kin (LKKAUTO)  
**Subject:** ACCIDENT INVOLVING SLA 1309 G & GBD 1502 S ON 16 DECEMBER 2018 - CALL FOR DIRECT SETTLEMENT  
**Attachments:** SLA1309G\_estimate\_finalization.pdf; SLA1309G\_invoice.pdf; SLA1309G\_report.pdf; SLA1309G\_rental\_invoice.pdf; GBD1502S\_ins\_search.pdf

**Your Ref:**  
**Our Ref :** SLA 1309 G

22 February 2019

AXA Insurance Singapore Pte Ltd  
8 Shenton Way  
#27-01  
AXA Tower  
Singapore 068811

**PROPERTY CLAIM  
(WITHOUT PREJUDICE  
TO: Any Personal Injury  
Claims)**

LKK Auto Consultants Pte Ltd  
Blk 51, Paya Ubi Industrial Park,  
Ubi Avenue 1,  
#02-25  
Singapore 408933

Attn: Claims Department

Dear Sir/Mdm,

**ACCIDENT INVOLVING SLA 1309 G & GBD 1502 S ON 16 DECEMBER 2018 - CALL FOR DIRECT SETTLEMENT**

Kindly find attached the finalized report for SLA 1309 G, as proposed by our Single Joint Expert, **SIMON HO**. We are pleased to inform that we are agreeable to the amount proposed.

As such, we are writing to your kind office to call for a direct settlement, in relation to the accident involving SLA 1309 G & GBD 1502 S on 16 December 2018. We will like to know if your company is prepared to settle for the amount as stated below:

Cost of Repair (amount as proposed by SJE)	: \$9,450.00
Cost of Rental	:\$ 880.00
LTA Search	: \$ 7.45
<b>Total:</b>	<b>: \$10,337.45</b>

We seek your kindest assistance in letting us know whether your kind office is agreeable to the above within the next 7 days and we look forward to you forwarding us the DV (without prejudice to any personal injury claims), if required, so that we can expedite on its return for an amicable settlement to the matter.

We have also attached a copy of our company's invoice for SLA 1309 G, the Singapore Accident Statement of SLA 1309 G, rental invoice and LTA Search, for your easy reference.

Thank you and we hope to hear from you soonest.

Regards,  
Asia Motorsports Solution Pte Ltd  
568 Geylang Road

Singapore 389514

6745 3811

6746 5110 (fax)

[asiamotorsports@hotmail.com](mailto:asiamotorsports@hotmail.com)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18022762/Ugb3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN: STACEY NG

Date : 02-10-2019



Code : ASM

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 1502S	Veh. Inspected	SLA 1309G
Policy No.	P1628469	Coverage (\$)	0.00
Claim No.	S8M0172E	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	19/12/2018

## 2. Vehicle Particulars & Condition

Make & Model	TOYOTA LEXUS NX200T (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTJBARBZX02067101	Colour	BLACK
Odometer	109367	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/60 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/60 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/60 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/60 R18	BRIDGESTONE	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	16/12/2018	Inspection Date	19/12/2018
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 568 GEYLANG ROAD SINGAPORE 389514		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 1309G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER (CONSISTENT)	DISTORTED	2,083.10	828.00
2	REAR BUMPER SIDE RETAINER L/R @ \$103.70 (CONSISTENT)	DISTORTED	207.40	185.00
2	REAR BUMPER BRACKET L/R @ \$71.50 (CONSISTENT)	N/S DENTED / O/S NOT NECESSARY	143.00	55.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	DENTED	822.80	599.00
2	REAR REINFORCEMENT MOUNT BRACKET L/R @ \$258.40 (CONSISTENT)	N/S DENTED / O/S NOT NECESSARY	516.80	180.00
1	REAR BUMPER LOWER DIFFUSER (CONSISTENT)	CUT	848.70	598.00
1	REAR BUMPER UNDER COVER (CONSISTENT)	NOT NECESSARY	470.60	-
2	REAR BUMPER REFLECTOR L/R @ \$208.20 (CONSISTENT)	N/S CRACKED / O/S NOT NECESSARY	416.40	76.00
1	REAR TAIL GATE (CONSISTENT)	BUCKLED	2,978.80	1,290.00
1	REAR TAIL GATE LOCK (CONSISTENT)	BENT	598.90	598.90
1	REAR TAIL GATE WEATHER-STRIP (CONSISTENT)	DISTORTED	312.30	299.00
2	REAR TAIL GATE GLASS MOULDING L/R @ \$84.30 (CONSISTENT) }	NECESSARY	168.60	278.00
1	REAR TAIL GATE GLASS LOWER MOULDING (CONSISTENT) }	NECESSARY	304.50	-
1	REAR TAIL GATE FINISH PANEL (CONSISTENT)	CRACKED	1,552.40	585.00
1	REAR END PANEL (CONSISTENT)	BUCKLED	1,644.50	628.00
1	REAR END PANEL TOP GARNISH (CONSISTENT)	CRACKED	658.50	398.00
2	REAR EXHAUST TAIL PIPE EXTENSION @ \$296.50 (CONSISTENT)	N/S CUT / O/S NOT NECESSARY	593.00	296.50
1	REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	52.60	52.60
2	REAR PRESSURE AIR VENT L/R @ \$164.90 (CONSISTENT)	NOT NECESSARY	329.80	-
2	REAR WHEEL ARCH MOULDING L/R @ \$425.70 (CONSISTENT)	N/S CRACKED / O/S NOT NECESSARY	851.40	261.00
2	REAR END PANEL TOP GARNISH CHROME PLATE (CONSISTENT)	NECESSARY	488.00	318.00
1	REAR TAIL GATE EMBLEM (CONSISTENT)	NECESSARY	89.40	89.40
1	REAR TAIL GATE "LEXUS" EMBLEM (CONSISTENT)	NECESSARY	74.70	74.70
1	REAR TAIL GATE "NT200T" EMBLEM (CONSISTENT)	NECESSARY	95.80	95.80

Report Ref No. CC4/ASM18022762/Ugb3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAIL GATE OPENER SWITCH (CONSISTENT)	NOT NECESSARY	298.80	-
1	REAR TAIL GATE AUTOGATE SWITCH (CONSISTENT)	NOT NECESSARY	324.00	-
2	REAR TAIL LAMP L/R @ \$920.60 (CONSISTENT)	CRACKED	1,841.20	1,378.00
2	REAR TAIL GATE LAMP L/R @ \$828.80 (CONSISTENT)	N/S CRACKED / O/S NOT NECESSARY	1,657.60	770.00
2	REAR TAIL GATE LICENCE LAMP @ \$99.40 (CONSISTENT)	NOT NECESSARY	198.80	-
1	REAR TAIL GATE VIEW CAMERA (CONSISTENT)	NOT NECESSARY	859.00	-
4	REAR BUMPER REVERSE SENSOR RETAINER @ \$32.00 (CONSISTENT)	NECESSARY 2PCS ONLY	128.00	64.00
4	REAR BUMPER REVERSE SENSOR @ \$287.00 (CONSISTENT)	SHORTED 2PCS ONLY	1,148.00	574.00
	LESS 10% DISCOUNT		-	-1,057.19
			22,757.40	9,514.71
	<b>LABOUR</b>			
	CHECK WIRING, LIGHTING, AUTO GATE, WIPER MOTOR & CENTRE LOCKING SYSTEM.		80.00	30.00
	REMOVE DAMAGED PARTS, KNOCK OUT DENTS, STRAIGHTEN, PANEL BEATING, REMOVE & REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS.		1,800.00	800.00
	SPRAY PAINTING ALL AFFECTED AREAS.		1,400.00	800.00
	TO TRANSFER REAR TAIL GATE MECHANISM & COMPONENTS.		80.00	60.00
	TO REMOVE & REINSTALL REAR TAIL GATE GLASS TO ASSIST REPAIR.		120.00	120.00
	TO SUPPLY WINDSCREEN GLASS SEALANT.		50.00	50.00
	ANTI-RUST PROOFING ON AFFECTED PANEL.		120.00	80.00
	TO REINSTALL REAR BUMPER REVERSE SENSOR & VIEW CAMERA AND CHECK FOR PROPER FUNCTION.		250.00	90.00
	TO STRAIGHTEN AND RE-ALIGN EXHAUST SYSTEM TO POSITION.		200.00	70.00
	TO CARRY OUT DIAGNOSTIC CHECKS, ERASE FAULT CODES & RESET.		350.00	120.00
			4,450.00	2,220.00
	<b>GRAND TOTAL</b>		<b>27,207.40</b>	<b>11,734.71</b>

Report Ref No. CC4/ASM18022762/Ugb3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,450.00
---	--	--	----------

Report Ref No. CC4/ASM18022762/Ugb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.