

SYNOPSIS

REF: ALH

ASSIGNMENT

From: _____ Date: 19.12.2018
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GBG 2343L
 at Workshop m/s: Abwin Service
 of: 8 Kaki Bukit Ave 4 #07-48
 Insured: _____
 Policy No: S/K 73020E
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

after 2pm

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: 4 Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

5646M
 Vehicle: IN / OUT

Veh No: GBG 2343L Yr Regn: 6 17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or (M)
 Make: Toyota Dyna C.C. 2982
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 52206 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KDY2318026112
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195 R15 :
 R: 145 R13 Yokohama
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 mm Rear 6/6 mm
 R/Bal. 6 mm R/Bal. 6/6 mm
 L/Bal. 6 mm L/Bal. 6/6 mm
 D.O.A. 7/12/18 D.O.I. 19/12/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 26078

PIP \$2847.30 (Red of NW/406)

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18022765/Upb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 19-12-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKZ 3020E	Veh. Inspected	GBG 2343L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	19/12/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	17/12/2018	Inspection Date	19/12/2018
Survey held at	ABWIN SERVICE PTE LTD No. 8 KAKI BUKIT AVENUE 4 #07-48 PREMIER@KAKI BUKIT GATE 2 SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

Date : 18/12/2018
TP Vehicle No. : SKZ-3020-E
To : AIG ASIA PACIFIC INSURANCE PTE LTD
Attn : Motor Claim Department

IVAN TEO
ABWIN SERVICE PTE LTD
DID: 67139416
Fax: 67139415
HP: 86680608

Owner : SING SOON HUAT PLASTIC TRADING ENTERPRISE
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5092717644-01
Vehicle No. : GBG-2343-L
Make & Model : TOYOTA DYNA 150 3.0 DIESEL Y (M)

Accident Date: 18/12/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	TAIL LAMP ASSY RH	Cu7 \$236.40	✓
	Sub Total	\$236.40	
	Discount 25% on Parts	(\$59.10)	
		\$177.30	

Special Nett

1	CUSTOMISED REAR DOOR RH	20/12 \$2,200.00	1200
1	CUSTOMISED STEP BRACKET	5/12 \$550.00	✓
1	CUSTOMISED END PANEL GARNISH	2 \$800.00	X
	Sub Total	\$3,550.00	

Labour & Misc

LABOUR TO FACILITATE REPAIR	\$800.00	700
TO SPRAY PAINT ON AFFECTED AREAS	\$300.00	220
TO RUST PROOF AFFECTED AREA	11 \$100.00	X
Sub Total	\$1,200.00	

not Authorized
19/12/18
to be photo After repair
4 day.

Sub Total	\$4,927.30	2847.30
GST 7%	\$344.91	
Total	\$5,272.21	

End user / Insured party must notify
insurer immediately of the following:

- The surveyor must be notified of any painting
- The surveyor must be notified of any repair
- The surveyor must be notified of any replacement
- The surveyor must be notified of any "Without Prejudice" basis
- The surveyor must be notified of any other
- The surveyor must be notified of any other
- The surveyor must be notified of any other

Acknowledged by Repairer
Signature:
Date:

Date : 03/01/2019
 TP Vehicle No. : SKZ-3020-E
 To : AIG ASIA PACIFIC INSURANCE PTE LTD
 Attn : Motor Claim Department

IVAN TEO
 ABWIN SERVICE PTE LTD
 DID: 67139416
 Fax: 67139415
 HP: 86680608

Owner : SING SOON HUAT PLASTIC TRADING ENTERPRISE
 NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Certificate No. : 5092717644-01
 Vehicle No. : GBG-2343-L
 Make & Model : TOYOTA DYNA 150 3.0 DIESEL Y (M)

Accident Date: 18/12/2018

FINAL REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
List Item			
1	TAIL LAMP ASSY RH	\$236.40	\$236.40
	Sub Total	\$236.40	\$236.40
	Discount 25% on Parts	(\$59.10)	(\$59.10)
		\$177.30	\$177.30
Special Nett			
1	CUSTOMISED REAR DOOR RH	\$2,200.00	\$1,200.00
1	CUSTOMISED STEP BRACKET	\$550.00	\$550.00
1	CUSTOMISED END PANEL GARNISH	\$800.00	-
	Sub Total	\$3,550.00	\$1,750.00
Labour & Misc			
	LABOUR TO FACILIATE REPAIR	\$800.00	\$700.00
	TO SPRAY PAINT ON AFFECTED AREAS	\$300.00	\$220.00
	TO RUST PROOF AFFECTED AREA	\$100.00	-
	Sub Total	\$1,200.00	\$920.00
	Sub Total	\$4,927.30	\$2,847.30
	GST 7%	\$344.91	\$199.31
	Total	\$5,272.21	\$3,046.61

ABWIN 論燿

IVAN TEO
ABWIN SERVICE PTE LTD
DID: 67139416
Fax: 67139415
HP: 86680608

Accident Date: 18/12/2018

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

1	TAIL LAMP ASSY RH	C47	\$236.40
	Sub Total		\$236.40
	Discount 25% on Parts		(\$59.10)
			\$177.30

1	CUSTOMISED REAR DOOR RH	50/100	\$2,200.00
1	CUSTOMISED STEP BRACKET	50/100	\$550.00
1	CUSTOMISED END PANEL GARNISH	2	\$800.00
Sub Total			\$3,550.00

LABOUR TO FACILITATE REPAIR	\$800.00
TO SPRAY PAINT ON AFFECTED AREAS	\$300.00
TO RUST PROOF AFFECTED AREA	\$100.00
Sub Total	\$1,200.00

Sub Total	\$4,927.30
GST 7%	\$344.91
Total	\$5,272.21

not adhered
near
19/12/18
the photo. After repair
4 day.

Hsiao Tong (LKKAUTO)

From: Ivan Teo <ivanteo@abwin.com.sg>
Sent: Saturday, 5 January 2019 8:58 AM
To: Hsiao Tong (LKKAUTO)
Subject: LOD GBG2343L AGAINST AIG SKZ3020E DOA 17/12/2018
Attachments: LOD-GBG2343L.pdf

Dear Hsiao Tong,

Please find the attached LOD for your necessary action.

Kindly let us have the offer soonest.

Thank you.

Best Regards,

ABWIN 諭輝

Abwin Service Pte Ltd
No. 8 Kaki Bukit Avenue 4
#07-48 Premier@Kaki Bukit Gate 2
Singapore 415875

Ivan Teo

Motor Claim Executive

DID +65 6713 9416 / 86680608

T +65 6713 9400 | F +65 6713 9415

[Website](#) | [Facebook](#) | [LinkedIn](#)

Looking to start a new business soon? Find out how we can provide you with a complete vehicle ownership solution and much more!

Click [here](#) to view our listing >>



From: Marcus Chua (LKKAUTO) [mailto:MarcusChua@lkkauto.com]
Sent: Friday, 4 January, 2019 8:39 AM
To: Ivan Teo <ivanteo@abwin.com.sg>
Subject: RE: FINALISE GBG2343L AGAINST AIG SKZ3020E DOA 17/12/2018

Hi Ivan,

Confirmed COR \$2847.30 and please send LOD to Hsiao Tong.

Regards

From: Ivan Teo [mailto:ivanteo@abwin.com.sg]
Sent: Thursday, 3 January, 2019 9:25 AM
To: Marcus Chua (LKKAUTO)
Subject: FINALISE GBG2343L AGAINST AIG SKZ3020E DOA 17/12/2018

Dear Marcus,

Kindly assist to finalise cost of repair **\$2,847.30 4days**

Thank you.

Best Regards,

ABWIN 論
北軍

Abwin Service Pte Ltd
No. 8 Kaki Bukit Avenue 4
#07-48 Premier@Kaki Bukit Gate 2
Singapore 415875

Ivan Teo

Motor Claim Executive

DID +65 6713 9416 / 86680608

T +65 6713 9400 | F +65 6713 9415

[Website](#) | [Facebook](#) | [LinkedIn](#)

Looking to start a new business soon? Find out how we can provide you with a complete vehicle ownership solution and much more!

Click [here](#) to view our listing >>



From: Admin-D (LKKAUTO) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 18 December, 2018 2:30 PM
To: Ivan Teo <ivanteo@abwin.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: ARRANGE FOR SURVEY GBG2343L AGAINST AIG SKZ3020E DOA 17/12/2018

Dear Ivan,

Noted with thanks.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ivan Teo [<mailto:ivanteo@abwin.com.sg>]
Sent: Tuesday, 18 December, 2018 2:27 PM
To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Subject: ARRANGE FOR SURVEY GBG2343L AGAINST AIG SKZ3020E DOA 17/12/2018

Dear Catherine,

Kindly arrange for 3rd party survey against AIG on 19/12/2018 after 2PM
Surveyor : Marcus or Adrian
My client : GBG2343L
AIG insured : SKZ3020E
DOA : 17/12/2018

Thank you.

Best Regards,

ABWIN 論輝
Abwin Service Pte Ltd
No. 8 Kaki Bukit Avenue 4
#07-48 Premier@Kaki Bukit Gate 2
Singapore 415875

Ivan Teo
Motor Claim Executive
DID +65 6713 9416 / 86680608
T +65 6713 9400 | F +65 6713 9415
[Website](#) | [Facebook](#) | [LinkedIn](#)

Looking to start a new business soon? Find out how we can provide you with a complete vehicle ownership solution and much more!

Click [here](#) to view our listing >>



Your Ref:
Our Ref: AC18120011

05/01/2019

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Department

Dear Sirs,

ACCIDENT ON 18/12/2018 INVOLVING GBG-2343-L & SKZ-3020-E PIE GOING TOWARDS TPE SLIP ROAD

We are authorised repair workshop for the owner of vehicle, GBG-2343-L, which was involved in the captioned accident with your insured's vehicle. The vehicle owner has requested and authorised us to assist him/her in presenting his claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured, SKZ-3020-E, we are submitting these claims for your consideration on behalf of the owner/driver/claimant.

1. Cost of Repair	\$3,046.61	✓
2. 0 days Car Rental x \$0.00	-	
3. Loss of Use (4 x \$80.00)	\$320.00	✓
4. Survey Fees	-	
5. LTA Fees	-	
6. TP/GIA Fees	\$2.00	✓
7. Medical Fees	-	
8. Others	-	
(E&OE)		\$3,368.61

We enclose the following documents to support the claims:-

- | | | | |
|--|---|---|--|
| <input checked="" type="checkbox"/> Repair/Excess Bill | <input type="checkbox"/> GIA/Police Report(s) | <input checked="" type="checkbox"/> Power of Attorney | <input type="checkbox"/> Medical Bill |
| <input type="checkbox"/> Surveyor Report | <input checked="" type="checkbox"/> GIA/TP Search | <input type="checkbox"/> Car Rental Bill | <input type="checkbox"/> Witness Statement |
| <input type="checkbox"/> Coloured Photographs | <input type="checkbox"/> Insurance Certificate | <input type="checkbox"/> Others: _____ | |

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/driver/claimant.

Yours faithfully,
ABWIN SERVICE PTE LTD

ABWIN

ABWIN SERVICE PTE LTD
8 Kaki Bukit Avenue 4 #07-48
Premier @ Kaki Bukit Gate 2
Singapore 415875
Tel: 67139400 Fax: 65 67139415

IVAN TEO

Claims Department

E-mail: ivanteo@abwin.com.sg

DID: 67139416



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18022765/Upb3

31 JAN 2019

CHOW KAI WEN
13 PASIR RIS GROVE
#10-12
SINGAPORE 518141

Dear Sir/Madam,

**ACCIDENT INVOLVING SKZ 3020E & GBG 2343L ALONG/AT PIE TURNING
INTO TPE ON 17/12/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from GBG 2343L against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
Email: chewht@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

Date: 18/12/2018

From: SING SOON HUAT PLASTIC TRADING ENTERPRISE (Name of Policyholder)

My Vehicle No.: GBG2343L Other Vehicles: SKZ3020E

Accident Date: 17/12/2018 Location: PIE GOING TOWARDS TPE SLIP ROAD

LETTER OF AUTHORISATION

To: AIG ASIA PACIFIC INSURANCE PTE LTD (Third Party and/or Third Party Insurer)

I have authorized ABWIN SERVICE PTE LTD to proceed with the repairs to my accident damaged vehicle and to proceed with 3rd Party Insurance Claims against Third Party and / or its Insurer on my behalf for property damages, costs, and expenses, including loss of use, loss of rental, medical fees and legal costs.

To have absolute discretion to agree to any settlement of compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).

As ABWIN SERVICE PTE LTD will be handling the entire 3rd Party Claims, which includes signing / submission of all relevant documents and negotiation of my claims on my behalf, kindly forward and make payable all proceeds of my claims to ABWIN SERVICE PTE LTD.

I confirm that the payment of any negotiated settlement with and accepted by ABWIN SERVICE PTE LTD will serve as an effectual discharge of my claims against the Third Party and / or its Insurer for the damage caused.

I further confirmed and accept that:

- i) I will indemnify & keep Abwin Service Pte Ltd indemnified in connection with or arising from the claim and under no circumstances that will hold Abwin Service Pte Ltd liable for any losses or damages of whatever nature arising from or in connection with the claim;
- ii) Abwin Service Pte Ltd does not guarantee and never represented that the Insurer & or Third Party will fully indemnify me for the damage and/or the repair costs and that I shall continue to be liable to Abwin Service for the whole repair costs.

SING SOON HUAT PLASTIC TRADING ENTERPRISE

Policyholder's Signature / Company's Stamp (if applicable)

Name: SING SOON HUAT PLASTIC TRADING ENTERPRISE

NRIC No./ROC No.: 52965646M

Designation:

Witness's Signature

Name:

NRIC No.:

ABWIN
ABWIN SERVICE PTE LTD
8 Kaki Bukit Avenue 4 #07-48
Premier @ Kaki Bukit Gate 2
Singapore 415875
Tel: 67139400 Fax: 65 67139415

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **ABWIN SERVICE PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$3,046.61** (Repair Cost), **S\$320.00** (Loss of Use/Rental), **S\$2.00** (Disbursement) for vehicle no. **GBG 2343L** that was damaged pursuant to the accident which occurred on **17/12/2018** (date) along **PIE GOING TOWARDS TPE SLIP ROAD** (location) involving vehicle no/s **SKZ 3020E**. This is pursuant to the inspection conducted on **19/12/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **SING SOON HUAT PLASTIC TRADING ENTERPRISE** (the third party claimant") of vehicle no. **GBG 2343L** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **GBG 2343L** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 9th (day) of Feb (month) 2019 (year)



uks

Signed by appointed surveyor

ABWIN

ABWIN SERVICE PTE LTD
8 Kaki Bukit Avenue 4 #07-48
Premier @ Kaki Bukit Gate 2
Singapore 415875
Tel: 67139400 Fax: 65 67139415

Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only.
All personal injuries and damages arising therefrom are excluded
from the ambit and application of this document"

TAX INVOICE

INV19010005

To: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Date: 05/01/2019
Vehicle No.: GBG-2343-L
Make: TOYOTA
Model: DYNA 150 3.0 DIESEL Y (M)

Attention:**Date of Accident:** 17/12/2018

S/N	DESCRIPTION	QTY	AMOUNT (S\$)
1	BEING CLAIM FOR VEHICLE NO. GBG-2343-L ACCIDENT ON 17/12/2018 AS FOLLOWS :-		
2	REPAIR COSTS	1.000	\$2,847.30

SUB TOTAL \$2,847.30
7% GST \$199.31
TOTAL \$3,046.61

Remarks:

ABWINABWIN SERVICE PTE LTD
8 Kaki Bukit Avenue 4 #07-48
Premier @ Kaki Bukit Gate 2
Singapore 415875
Tel: 67139400 Fax: 65 67139415

Payment by cheque should be crossed and made payable to **ABWIN SERVICE PTE LTD.**

For ABWIN SERVICE PTE LTD

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-194823
Date of Request: 18/12/2018

Your Ref No: Online Purchase

Abwin Service Pte Ltd
No. 8 Kaki Bukit Avenue 4
#07-48 Premier@Kaki Bukit Gate 2
Singapore 415875

Dear Sir/Madam,

Enquiry Date 18/12/2018
Enquiry By Ivan Teo
TP Vehicle No. SKZ3020E
Accident Date 17/12/2018

DESCRIPTION	AMOUNT (\$S)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-194823

Date of Request: 18/12/2018

Your Ref No: Online Purchase

Abwin Service Pte Ltd
No. 8 Kaki Bukit Avenue 4
#07-48 Premier@Kaki Bukit Gate 2
Singapore 415875

Dear Sir/Madam,

Enquiry Date 18/12/2018
Enquiry By Ivan Teo
TP Vehicle No. SKZ3020E
Accident Date 17/12/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKZ3020E	AIG Asia Pacific Insurance Pte. Ltd.	19/01/2018-18/01/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

Fastlane

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2018 Edit Reg		19 Dec 2018 00:00 Edit Adj Rpt	\$52,847.30 Edit Estimates	\$52,847.30 View Rpt		Pending for Survey Report Cancel Case

<https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=d...> 20/2/2019

Claim Documents

***GBG2343L (7923410889SG)**
[SKZ3020E]

TP

SING SOON HUAT PLASTIC TRADING ENTERPRISE

Dec 17 2018 12:00AM

[CHOW KAI WEN]

Abwin Service Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	Use Viewer
Video						1 per page	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)			Thumbnail	Print	
1	30/01/19 17:14	Video - Accident From:OD - Reg. No: SKZ3020E, Claimant: CHOW KAI WEN			Load MP4		
2	30/01/19 17:14	Video - Accident From:OD - Reg. No: SKZ3020E, Claimant: CHOW KAI WEN			Load MP4		
Letters/Correspondences						1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown			Edit		
Assessment Reports						1 per page	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)			Thumbnail	Print	
1	30/01/19 17:14	Accident Statement From:OD - Reg. No: SKZ3020E, Claimant: CHOW KAI WEN			Load HTM		
Photos/Images						3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	19/12/18 17:53	Chassis Number			Load JPG		
2	19/12/18 17:53	Odometer Reading			Load JPG		
3	19/12/18 17:53	General View			Load JPG		
4	19/12/18 17:53	General View			Load JPG		
5	19/12/18 17:53	General View			Load JPG		
6	19/12/18 17:53	General View			Load JPG		
7	19/12/18 17:53	General View			Load JPG		
8	19/12/18 17:53	General View			Load JPG		
9	19/12/18 17:53	General View			Load JPG		
10	19/12/18 17:53	General View			Load JPG		
11	19/12/18 17:53	General View			Load JPG		
12	19/12/18 17:53	General View			Load JPG		
13	19/12/18 17:53	General View			Load JPG		
14	19/12/18 17:53	General View			Load JPG		
15	19/12/18 17:53	General View			Load JPG		
16	19/12/18 17:53	General View			Load JPG		
17	19/12/18 17:53	General View			Load JPG		
18	19/12/18 17:53	General View			Load JPG		
19	19/12/18 17:53	General View			Load JPG		
20	19/12/18 17:53	General View			Load JPG		
21	19/12/18 17:53	General View			Load JPG		
22	19/12/18 17:53	General View			Load JPG		
23	19/12/18 17:53	General View			Load JPG		
24	19/12/18 17:53	General View			Load JPG		
25	19/12/18 17:53	General View			Load JPG		
26	19/12/18 17:53	General View			Load JPG		
27	19/12/18 17:53	General View			Load JPG		
28	19/12/18 17:53	General View			Load JPG		
29	19/12/18 17:53	General View			Load JPG		
30	19/12/18 17:53	General View			Load JPG		

				<input checked="" type="checkbox"/>
31	19/12/18 17:53	General View		Load JPG <input checked="" type="checkbox"/>
32	19/12/18 17:53	General View		Load JPG <input checked="" type="checkbox"/>
33	19/12/18 17:53	General View		Load JPG <input checked="" type="checkbox"/>
34	19/12/18 17:53	General View		Load JPG <input checked="" type="checkbox"/>
35	19/12/18 17:53	General View		Load JPG <input checked="" type="checkbox"/>
36	19/12/18 17:53	General View		Load JPG <input checked="" type="checkbox"/>
37	19/12/18 17:53	General View		Load JPG <input checked="" type="checkbox"/>
38	19/12/18 17:53	General View		Load JPG <input checked="" type="checkbox"/>
39	07/02/19 15:50	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
40	07/02/19 15:50	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
41	07/02/19 15:50	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
42	07/02/19 15:50	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
43	07/02/19 15:50	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
44	07/02/19 15:50	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation				
			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/12/18 18:55	TP ESTIMATE- MARKED	Load PDF	
2	20/12/18 18:55	TP GIA REPORT	Load PDF	
3	20/02/19 10:46	WORKSHOP INVOICE	Load PDF	
4	20/02/19 10:46	AUTHORISATION TO ACT FORM	Load PDF	
5	20/02/19 10:46	Release Voucher	Load PDF	
6	20/02/19 10:46	GIA SEARCH	Load PDF	
7	20/02/19 10:46	LETTER TO OI	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	20/12/18 08:37	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKZ3020E (Insd veh)	Model:	TOYOTA DYNA 3.0 D (M)
	GBG2343L (TP veh)		
Date of Accident:	17/12/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	5,272.21
Final Repair Cost	:	\$	3,046.61
Loss of Use	:	\$	320.00
			4.00days at \$80.00 per day
Rental (if any)	:	\$	0.00
			days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,368.61

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Abwin Service Pte Ltd	:	\$ 3,368.61
2)		:	\$
3)		:	\$

HUEY YON

20 Feb
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18022765/UPB3N2
Date: 20/02/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100447913
Claimant Vehicle No :	GBG2343L	Insured Vehicle No :	SKZ3020E
Date of Loss:	17/12/2018	Nature of Claim:	TP
		Claim No:	7923410889SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG2343L	Engine No:	1KD2636758
Make & Model:	TOYOTA DYNA, 3.0 D (M)	Chassis No:	KDY2318026112
Reg. Date:	29/06/2017 (Man. Year: 2016)	Odometer:	52206 km
Colour:	Blue		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	145 R13 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Yokohama 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,727.30	1,927.30	1,800.00	48.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	920.00	280.00	23.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,927.30	2,847.30	2,080.00	42.21
+ GST 7.00/7.00% (S\$)	344.91	199.31	145.60	42.21
Nett Amount (S\$)	5,272.21	3,046.61	2,225.60	42.21
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,368.61		

INSPECTION

Date of Assignment:	19/12/2018	
Date Inspected:	19/12/2018 Inspected At:	Abwin Service Pte Ltd (HQ) No. 8 Kaki Bukit Avenue 4, #07-48 Premier@Kaki Bukit Gate 2 Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP ASSY RH	Cut	236.40 FL	*236.40 FL
2	1		*CUSTOMISED REAR DOOR RH	Dented / Bent	2,200.00 FS	*1,200.00 FS
3	1		*CUSTOMISED STEP BRACKET	Bent	550.00 FS	*550.00 FS
4	1		*CUSTOMISED END PANEL GARNISH	Repair	800.00 FS	*- FS
				Sub Total (S\$)	3,786.40	1,986.40
				- List Item Discount on L Items 25.00/25.00% (S\$)	59.10	59.10
				Total Parts (S\$)	3,727.30	1,927.30

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO FACILITATE REPAIR	New	800.00	700.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	300.00	220.00
3	TO RUST PROOF AFFECTED AREA	New	100.00	0.00
Gross Labour Cost (S\$)			1,200.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >