

# FIRST AUTOWORKS

## Repair Estimate

Date : 15/12/2018

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SMA 3787J  
CHASSIS NO.: W0V7H9ED4J4143234  
ENGINE NO.: 10XVA10916074

TP ALG.  
Vic

Reference: SMA 3787J  
Make: Opel  
Crossland

Name of insured : Amour Ventures  
Date of accident.: 15/12/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

### Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BUMPER UPPER	2,400.00 *
2	1	FRT BUMPER CLIP SET	60.00 *
3	1	RHF FOG LAMP COVER	250.00 *
4	1	RHF H/LAMP	4,300.00 *
5	1	FRT TOP GRILLE	590.00 ✓
Parts Total:			\$7,600.00
Less 10%:			\$760.00
Total :			\$6,840.00

### Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	2200.00 65+
2	Carry out spray painting on accident affected area. ( Frt Bumper)	1500.00 *
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	80.00 *
4	To conduct 4 wheel alignment	180.00 *
5	To conduct H/Light alignment	120.00 *
Labour Total :		\$4,080.00

Total : \$10,920.00  
Gst (7%) : \$764.40  
GRAND TOTAL: \$11,684.40

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully,

Service Advisor  
Ronnie Tan  
DID: 6844 1985 Fax: 6844 5185

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian S  
P/P 19/12/18  
04 Day

Total: 1181

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

## 1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 ( South Wing) Singapore 415933 Tel: 68441985 Fax: 68445185

### TAX INVOICE

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way  
#07-16, Singapore 079120

GST Ref. No: M2-0111811-5

Vehicle No: SMA 3787J  
Chasis No : W0V7H9ED4J4143234  
Engine No: 10XVA10916074

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT SGD
-------------	---------------

#### Parts

<u>No.</u>	<u>Qty.</u>	<u>Description</u>	<u>Price (SGD)</u>
1	1	FRT TOP GRILLE	590.00

Total: 590.00  
Less 10%: 59.00  
Parts Total : 531.00


#### Labour

<u>No.</u>	<u>Description</u>	<u>Price (SGD)</u>
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair	650.00

Labour Total : 650.00

Sub Total : 1181.00  
GST (7%) 82.67  
**Grand Total: 1263.67**

Yours Faithfully,

  
Ronnie Tan  
Service Advisor  
Tel: 68441985 Fax: 68445185

#### E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1 ST AUTOWORKS PTE LTD".  
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.