

ASS. REC. BY:

REF:

CS/CT18022772/T1+d302

Special Instruction:

Surveyor:

Meimen

Taufik

ASSIGNMENT (Office)

From (Person):

Chung Bun An

of

CT1

Date/Time:

19/12/18 @ 3:05pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 8391T

Insured:

SGU 8871G

at Workshop m/s

Weemes Automotive

Tel:

6378 2680

of

28 Leng Kee Rd

Policy No:

DMPCSN3098841700

Claim No:

SNM18D05850C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/12/2018

CA / REV / REP. / REV 24 HRS 'up

20/12/18 @ 11am

H.O.D. Endorsement:

Date/Time:

3:48pm @ 19/12/18

Person Contacted:

patricia

Vehicle IN/OUT

OUT

Date/Time	Action/Instruction (✓) Estimate
	SLK 8391T-X
	SGU 8871G-X
	Vehicle not sent in for repair.
	Submit preli advise.

Insp: 45 Leng Kee Rd.

Surveillance Taffin

REF:

CTI

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Patricia

Veh No: SLK 839 IT Yr Regn: 2017 Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Jaguar XE C.C. 1999

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 56764 T/Radio: Insured / Std / NI / NA

Eng/No:

C.No: SA 57 B4AN 7 MC P00318

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225 / 45 R18

R: - -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 20/12/18

Survey held at Weames Long Hill

Des. of Damages: Frt / Rear / P/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 10 JAN 2019

Date/Time, File Pass to?

1) 18/11 Typist

Date/Time, File Return to?

2)

☒ : Preli. Report

☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: -

Survey Fee:

Transportation:

) \$ + RS, SI

) Photos

) Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : TP

Lump Sum / I.B.I. (\$

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Dec 2018		19 Dec 2018 15:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:		[Created by insurer]	
Main Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD		
Vehicle Reg. No.:	SLK8391T	Date of Loss:	14/12/2018 00:00 - :59
Claim Type:	TP / SNM18D05850C02	Policy/Cover Note No.:	DMPCSN3098841700
Vehicle Reg. No. (Insured):	SGU8871G	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Wearnes Automotive Pte Ltd (Leng Kee) 28 Leng Kee Road, 159105 Leng Kee - Tel: 63782680		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/12/2018]		
Adj Asg. Remarks:	EST \$17,288.10, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS ☐

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/12/2018 19:50
Date Of Accident	14/12/2018 12:55
Exact Location Of Accident	STEVENS ROAD TOWARDS WHITLEY ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK8391T
Insured/Policyholder	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-84999689

Vehicle Particulars

Manufacturer	JAGUAR
Model	XE-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	SOCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	-
Cover Note Number	

Driver

Name of Driver	PACHECO MARK ANGELO MANACSA
NRIC No	S9774248J
Date Of Birth	29/03/1997
Occupation	INDOOR
Date Of Driving Pass	13/12/2017
Driving Experience	1 YEAR AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84999689
Fax Number	

Address	BLK 453 CHOA CHU KANG AVENUE 4 #16-123
Postcode	680453
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer attachments.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGU8871G
Vehicle Make/Model/Colour	MERCEDES
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JAYSAANGEEVEN S/O MORGAN
NRIC/Passport Number	S8132726B
Contact Number	83835088
Address	BLK 39 CAMBRIDGE ROAD #02-129
Postcode	210039
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing w ith my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as w ell as on the external cover of envelopes/mail packages); and/or

(v) complying w ith applicable law in administering, processing, handling and/or dealing w ith my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

AR


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date
& Time

Kueh

Witnessed by Reporting Centre Personnel

Sketch Plan



Dunearn rd

Describe Circumstance of the Accident

On 14/12/18 at about 1255hrs, at ~~81~~ Duneath Rd → STEVENS RD JUNCTION, I was on the outermost lane, ~~going~~ which can go straight or right, I was signalling and turning right. Mr Jay was on the right of my lane which was right turn only. As I was turning right, he continued to go straight, went out of his lane and his front-left head ~~car~~ hit my right side passenger door. By the time I saw him close to me, it was too late.


IMPORTANT NOTE

Under **General Condition – Conduct of Claim** of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC

Hitachi Capital Asia Pacific Pte Ltd

Attn: Mr Ang

484b Choa Chu Kang Avenue 5

Singapore 682484

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 17/12/2018

WIP No. : 43665

Veh.In/Out:

*Tel.No. : Mobile: 94564904

Reg.No. : SLK8391T

Reg.date : 31/01/2017

Mileage : 0

Chassis No: SAJAB4AN7HCP00318

Closed by : Patricia Kueh Anak S

Svc Consultant :

Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE FRT RH DOOR, 900	0	3600.00	0		3,600.00 S	2250
	REAR RH DOOR, RH ROCKET PANEL, RHF DOOR HANDLE, ETC						
800	TO PUTTY SPRAYPAINT ON 800	0	3200.00	0		3,200.00 S	2400
	FRT RH DOOR, REAR RH DOOR, RH ROCKET PANEL, ETC						
802	TO TRANSFER FRT RH DOOR PART	0	500.00	0		500.00 S	✓
802	TO TRANSFER REAR RH DOOR PART	0	500.00	0		500.00 S	✓
280	TO CHECK WIRING INCLUDE	0	486.00	0		486.00 S	✓
	RESETTING OF ALL ELECTRICAL MODULES						

DOOR PANEL RHF XE	1.0 EA	1492.30	1,492.30 S	bt
SOUND DEADENING PAD	2.0 EA	250.00	500.00 S	re
DOOR PANEL RHR XE	1.0 EA	1824.10	1,824.10 S	bt
JT4N13770LML/MOULDIN	1.0 EA	549.50	549.50 S	re
DOOR FINISHER RH FRT	1.0 EA	316.60	316.60 S	?
DOOR FINISHER RH FRT	1.0 EA	256.50	256.50 S	?

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification: is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tan Jiah 97495749
"WP"

20/12/18 @ 12pm

*Resurvey before paint.

sur@lkkauto.com

6 days

SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC

Hitachi Capital Asia Pacific Pte Ltd

Attn: Mr Ang

484b Choa Chu Kang Avenue 5

Singapore 682484

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 17/12/2018

WIP No. . : 43665

Veh.In/Out:

*Tel.No. . : Mobile: 94564904

Reg.No. . : SLK8391T

Reg.date. : 31/01/2017

Mileage . : 0

Chassis No: SAJAB4AN7HCP00318

Closed by : Patricia Kueh Anak S

Svc Consultant :

Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	FINISHER CHROME C PI	1.0 EA	264.40			264.40	S ?
	DOOR FINISHER RH REA	1.0 EA	263.90			263.90	S ?
	SEAL-DOOR FRT	1.0 EA	232.30			232.30	S ✓
	SEAL-DOOR REAR	1.0 EA	207.10			207.10	S ✓
	HANDLE-DOOR FRT	1.0 EA	397.20			397.20	S ✓
	HANDLE-DOOR REAR	1.0 EA	397.20			397.20	S x m
	LATCH	1.0 EA	620.90			620.90	S ?
	ADHESIVE SEALER FL2	1.0 EA	549.10			549.10	S ?

Gross Total. 16,157.10

Labour Total 8,286.00
 Parts Total 7,871.10
 Package Total 0.00

Net..... 16,157.10
 GST @ 7.0% 1,131.00
 Total..... 17,288.10
 Paid..... 0.00
 Please Pay.. 17,288.10

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

...CLAIM SUBFOLDER...(Pending for Survey Report)






























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Dec 2018		19 Dec 2018 15:05 Edit Adj Rpt	S\$11,338.50 Edit Estimates	S\$11,338.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD								
Vehicle Reg. No.:	SLK8391T	Date of Loss:	14/12/2018 00:00 - :59 [22 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D05850C02	Policy/Cover Note No.:	DMPCSN3098841700						
Vehicle Reg. No. (Insured):	SGU8871G	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Wearnes Automotive Pte Ltd (Leng Kee) 28 Leng Kee Road, 159105 Leng Kee - Tel: 63782680								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 31/12/2018]								
Adj Asg. Remarks:	EST \$17,288.10, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLK8391T (SNM18D05850C02)**
[SGU8871G]

TP
HITACHI CAPITAL ASIA PACIFIC PTE LTD
Dec 14 2018 12:00AM
[-]
Wearnes Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
14	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
15	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
16	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
17	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
18	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
19	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
20	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
21	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
22	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
23	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
24	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
25	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
26	18/01/19 15:37	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/12/18 15:05	REPAIR EST	 Load PDF	
2	19/12/18 15:05	TP GIA	 Load PDF	
3	27/12/18 16:02	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18022772/T1TD3E2

Date: 21/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3098841700

Claimant Vehicle
No: SLK8391TInsured Vehicle
No: SGU8871G

Date of Loss: 14/12/2018

Nature of Claim: TP

Claim
No: SNM18D05850C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK8391T

Make & Model: JAGUAR XE, 2.0 (A)

Engine No: 160518W0100204DTD

Reg. Date: 31/01/2017 (Man. Year: 2016)

Chassis No: SAJAB4AN7HCP00318

Colour: Blue

Odometer: 56764 km

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size: 225/45 R18

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,871.10	5,202.50	2,668.60	33.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,286.00	6,136.00	2,150.00	25.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,157.10	11,338.50	4,818.60	29.82
+ GST 7.00/7.00% (S\$)	1,131.00	793.70	337.30	29.82
Nett Amount (S\$)	17,288.10	12,132.20	5,155.90	29.82

INSPECTION

Date of Assignment: 19/12/2018

Date Inspected: 20/12/2018 Inspected At:

Wearnes Automotive Pte Ltd (Leng Kee)
28 Leng Kee Road
Singapore 159105

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$2,271.40 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Jan 2019)

Parts: 143 JAGUAR XE 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLK8391T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL RHF XE	Bent	1,492.30 FS	*1,492.30 FS
2	2		*SOUND DEADENING PAD	Necessary	500.00 FS	*500.00 FS
3	1		*DOOR PANEL RHR XE	Bent	1,824.10 FS	*1,824.10 FS
4	1		*JT4N13770LML/MOUL DIN	Necessary	549.50 FS	*549.50 FS
5	1		*DOOR FINISHER RH FRT	* Check	316.60 FS	*- FS
6	1		*DOOR FINISHER RH FRT	* Check	256.50 FS	*- FS
7	1		*FINISHER CHROME C PI	* Check	264.40 FS	*- FS
8	1		*DOOR FINISHER RH REA	* Check	263.90 FS	*- FS
9	1		*SEAL-DOOR FRT	Necessary	232.30 FS	*232.30 FS
10	1		*SEAL-DOOR REAR	Necessary	207.10 FS	*207.10 FS
11	1		*HANDLE-DOOR FRT	Distorted	397.20 FS	*397.20 FS
12	1		*HANDLE-DOOR REAR	Not Necessary	397.20 FS	*- FS
13	1		*LATCH	* Check	620.90 FS	*- FS
14	1		*ADHESIVE SEALER FL2	* Check	549.10 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **7,871.10** **5,202.50**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRT RH DOOR, REAR RH DOOR, RH ROCKET PANEL, RHF DOOR HANDLE, ETC	New	3,600.00	2,250.00
2	TO PUTTY SPRAYPAINT ON FRT RH DOOR, REAR RH DOOR, RH ROCKET PANEL, ETC	New	3,200.00	2,400.00
3	TO TRANSFER FRT RH DOOR PART	New	500.00	500.00
4	TO TRANSFER REAR RH DOOR PART	New	500.00	500.00
5	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	486.00	486.00
Gross Labour Cost (\$\$)			8,286.00	6,136.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >