

ASS. REC. BY:

REF: CS/FCI18022774/Kq03ⁿ²

Special Instruction:

Surveyor:

Kennedy

ASSIGNMENT (Office)

CWS

From (Person):

Bisheer

of

FCI

Date/Time: 3:11pm 19/12/18

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJX 5206X

Insured:

SHB 2993R

at Workshop m/s

Jeli Huat (Meng Kee)

Tel:

6453 8110

of

160 Sin Ming Drive # 04-02 / 07-03

Policy No:

Claim No:

D18008869MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/12/2018

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

3:12pm 19/12/18

Person Contacted:

Jenny

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJX 5206X - CCS/AIG18022754/Uja3

DUA: 18/12/2018

SHB 2993R - NA/FCI10007132/r

DUA: 13/01/2019

11/12/18 @ 10.49am revised to Sahara by email.

819

L1 Lm 857501 Cabnet Term (Red 1340.35, 19%.)

ASS. REC. BY:

REF:

PC21

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.:

Yes or No

Lump Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

20/12

File report to Customer

MV: B26K641; LRA: B20201; NV: B5799

RECEIVED 10 APR 2019

Date/Time, File Pass to?

11/04/19

Date/Time, File Return to?

21

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

7

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

TP

5750

Veh No:

PX 5206 X

Yr Regn:

06, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Camry

Hybrid c.c

2362

Colour:

mp. Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

119127

T/Radio: Insured / Std / NI / NA

Eng No:

C/No:

NR053FK400012044

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

d

mm

Rear

R/Bal.

d

mm

L/Bal.

d

mm

D.O.A.

15/12/18

L/Bal.

d

mm

D.O.A.

19/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

L/R

The U/C / Chassis frame / Body Structure affected due to collision.

M. M. M.

9/4/2019

Date/Time, File Pass to?

11/04/19

Date/Time, File Return to?

21

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

7

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

TP

5750

150
50
50+50
46
346



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008869MFSH

Date: 21 December 2018

Our Ref: CS/FCI18022774/Kqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJX 5206X

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/12/2018 at the premises of M/s LAI HUAT MENG KEE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,716.87</u>
Revised Estimate Amount	: S\$ <u>4,896.07</u>
"Check" Items Amount	: S\$ <u>302.15</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the rear & front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	17-12-2018	Our Ref No. D18008869MFSH
Accident Date	15-12-2018	Claim Type. Third Party
Insured Vehicle	SHB2993R	Third Party Vehicle. SJX5206X
Survey Location	160 SIN MING DRIVE #04-01, #04-02 & #07-03 SIN MING AUTOCITY	
Contact Person.	JENNY LIM	
Contact No.	6453 8110/ 0	Fax No. 6459 6267
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LAI HUAT (MENG KEE) MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 21 December 2018 10:49 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008869MFSH/1
Attachments: CSFCI18022774Kqd3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SJX 5206X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 19 December 2018 3:34 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008869MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 19 December 2018 3:11 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008869MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S1470393D**
 Name: **SIEW JIN HUA**
 Birth Date: **02 May 1961**
 Issue Date: **01 Aug 2003**

000689440J

REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. **S1470393D**



NAME

SIEW JIN HUA

RACE

CHINESE

DATE OF BIRTH

02-05-1961

COUNTRY OF BIRTH

SINGAPORE

SEX

F

S1470393D

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 **Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms**

PASS DATE

18 Mar 1986

NP 428A



3793026

NRIC No. **S1470393D**

DATE OF ISSUE

20-10-2005

**72 THOMSON RIDGE
 SINGAPORE 574654**

NRIC No: **S1470393D**

Date: **01/11/2017**

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Club/Association/Organisation
Owner ID:	0073L
Vehicle Details	
Vehicle No.:	SJX5206X
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY HYBRID AUTO
Primary Colour:	Blue
Manufacturing Year:	2010
Engine No.:	2AZH497198
Chassis No.:	MR053FK4000012044
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$42,900.00
Original Registration Date:	22 Jun 2010
First Registration Date:	22 Jun 2010
Transfer Count:	1
Actual ARF Paid:	\$25,740.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jun 2020
PARF Rebate Amount:	\$14,157.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jun 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$43,003.00
COE Rebate Amount:	\$4,800.00
Total Rebate Amount:	\$18,957.00

The information contained herein is correct as at 09 Apr 2019

OK

$PARF = 14157$
 $PARF = 14157 \times (OMV \times 55\%)$
 $COE = QP \times \frac{bal\ mth}{10\ yrs}$
 $= 43003 \times \frac{18}{120}$
 $= 6450.45$
 $UTR = PARF + COE$
 $= 20607.45$
 $UTR = 20607$

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Club/Association/Organisation
Owner ID:	0073L

Vehicle Details

Vehicle No.:	SJX5206X
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY HYBRID AUTO
Primary Colour:	Blue
Manufacturing Year:	2010
Engine No.:	2AZH497198
Chassis No.:	MR053FK4000012044
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$42,900.00
Original Registration Date:	22 Jun 2010
First Registration Date:	22 Jun 2010
Transfer Count:	1
Actual ARF Paid:	\$25,740.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jun 2020
PARF Rebate Amount:	\$14,157.00

Intended COE Rebate Details

COE Expiry Date:	21 Jun 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$43,003.00
COE Rebate Amount:	\$6,044.00
Total Rebate Amount:	\$20,201.00

The information contained herein is correct as at 17 Dec 2018

OK

AUTOPLUS PRIVATE VEHICLE

Policy No. : 2100257414-07
 Period of Insurance : 22 Jun 2018 to 21 Jun 2019

Issued Date : 31 May 2018

ABOUT THE POLICYHOLDER

Name of Policyholder : Singapore Institute of International Affairs
 Address : 60A Orchard Road
 #04-03 The Atrium@Orchard
 SINGAPORE 236890
 Occupation/Nature of Business : Professional, Administrative & Support Services Activities (eg Audit/ Law firm)

ABOUT THE VEHICLE

Registration No. : SJX5206X
 Chassis No. : MR053FK4000012044
 Seating Capacity : 5
 Make/Model : TOYOTA CAMRY HYBRID
 Hire Purchase Company/Employer's Loan : NA
 Engine Capacity/Tonnage : 2,362.00 CC
 Engine No. : 2AZH497198
 Body Type : Sedan
 First Year of Registration : 2010

ABOUT THE COVER

Sum Insured : Market Value
 Driver Restriction : NA
 Off Peak Car : No
 Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive :

Any person who is driving on the Policyholder's order or with their permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Other Key Policy Benefits :

God, Dealer (First 3 years from original registration) + AIG Authorised Workshops, Waiver of Excess, PA to Authorised Driver / Unnamed Passengers- \$10000, PA Insured- \$50000, Key Replacement Cover- \$800, Strike, Riots and Civil Commotions, Loss of Use 1500cc - 1600cc Optional, In-Car Camera Excess Waiver

EXCESS

Section 1
 Fire - \$0 Own Damage - \$1200 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver
 Siow Jin Hua - \$1200 (Own Damage)

PREMIUM

Premium : \$ 1,111.01
 GST (7%) : \$ 77.77

Total : \$ 1,188.78

Your Premium includes the following discount(s):

No Claim Discount - 40%

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SHB2993R	15 Dec 2018 / 16:00:00	Successful	F03	MS FIRST CAPITAL INSURANCE LIMITED

[Previous](#)

[OK](#)



Thank you

Lai Mei Ling Deborah has successfully logged out.

Your last login date and time was 17 Dec 2018, 09:59:01.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No. 	Asset Type	Asset ID	Asset Owner ID	Transa
1	Vehicle	SHB2993R	-	18.3%

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267

GST No: M2-0128609-3

UEN: 199407592C

SUPPLEMENTARY

ESTIMATE

EST. No EST0021021
Singapore Institute of International
Affairs

Page 1 of 1
Your ref. TP-SHB 2993R MS FC
Job No. 70080
Our ref 18.12.27
Payment
Date 26/12/2018

Attn

Vehicle No SJX 5206X
Vehicle Model : Toyota Camry
Accident on ... 15/12/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supplementary item:					
1.00	Pc	Rear boot lid	Bu 863.00	25.00	647.25 CH ✓
1.00	Pc	Rear tail lamp LH	75 cm 455.41	25.00	341.56 CH ✓
1.00	Pc	Front bumper reinforcement	B 421.74	25.00	316.31 CH ✓
1.00	Pc	Front bumper sponge	cm 91.14	25.00	68.36 CH ✓

Sub-Total 1,373.48
GST 7.00% 96.14
Total S\$ 1,469.62

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST No: EST0021021
Singapore Institute of International
Affairs

Page 1 of 2
Your ref: TP-SHB 2993R MS FC
Job No: 70080
Our ref: 18.12.27
Payment
Date: 18/12/2018

Attn:

Vehicle No: SJX 5206X
Vehicle Model: Toyota Camry
Accident on: 15/12/2018

Not Attached
61 Day B?
Assuming After Paint

7 days

Quantity	Unit	Description	Unit price	Disc pct	Amount
Supply of Parts:					
1.00	Pc	Rear bumper	<i>Bu</i> 530.80	25.00	398.10
1.00	Pc	Rear bumper reinforcement	<i>Bu</i> 420.00	25.00	315.00
1.00	Pc	Rear bumper reflector RH	56.90	25.00	42.68
1.00	Pc	Rear bumper side holder LH	55.37	25.00	41.53
2.00	Pcs	Rear bumper lower clips	3.50	25.00	5.25
1.00	Pc	Rear parking sensor RH (centre)	395.50	25.00	296.63
1.00	Pc	Rear end panel	602.00	25.00	451.50
1.00	Pc	Rear end panel top cover	353.84	25.00	265.38
1.00	Pc	Rear end panel support	169.55	25.00	127.16
1.00	Pc	Rear spare tyre top cover	384.85	25.00	288.64
1.00	Pc	Hybrid emblem	68.60	25.00	51.45
1.00	Pc	Logo emblem	70.24	25.00	52.68
1.00	Pc	Hybrid Synergy Drive emblem	38.80	25.00	29.10
1.00	Pc	Camry emblem	49.98	25.00	37.49
1.00	Pc	Front bumper	491.60	25.00	368.70
1.00	Pc	Front bumper lower grille	233.31	25.00	174.98
1.00	Pc	Front radiator grille	580.80	25.00	435.60

2918.25

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

來發 (明記) 摩多有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST No: EST0021021
Singapore Institute of International
Affairs

Page: 2 of 2
Your ref: TP-SHB 2993R MS FC
Job No: 70080
Our ref: 18/12/27
Payment:
Date: 18/12/2018

Attn:

Vehicle No: SJX 5200X
Vehicle Model: Toyota Camry
Accident on: 15/12/2018

Quantity	Unit	Description	Unit price	Disc pct	Amount
		Special nett item:			
1.00	Pc	Front number plate	35.00		35.00 ✓
		Labour & Misc.			
1.00		To dismantle and renew front bumper	200.00		200.00 ✓
1.00		To spray paint (Pearl / front portion)	250.00		250.00 2201
1.00		To straighten rear body including cutting and welding, to knock dents on rear fender LH rear luggage panel rear tail lamp panel LH & RH and renew of parts	850.00		850.00 7501
1.00		To spray paint (Pearl / rear portion)	1,000.00		1,000.00 9001
					2670

Sub Total: 5,716.87
GST 7.00%: 400.18
Total: S\$ 6,117.05

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18022774/Kqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-04-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2993R	Veh. Inspected	SJX 5206X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008869MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	19/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY HYBRID (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	MR053FK4000012044	Colour	METALLIC PEARL BLUE	
Odometer	119127	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	YOKOHAMA	8 mm	
L/H Front Tyre	215/60 R16	YOKOHAMA	8 mm	
R/H Rear Tyre	215/60 R16	YOKOHAMA	8 mm	
L/H Rear Tyre	215/60 R16	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/12/2018	Inspection Date	19/12/2018	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 5206X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED / CRACKED	530.80	530.80
1	REAR BUMPER REINFORCEMENT	BUCKLED	420.00	420.00
1	REAR BUMPER REFLECTOR RH	CRACKED	56.90	56.90
1	REAR BUMPER SIDE HOLDER LH	DISTORTED	55.37	55.37
2	REAR BUMPER LOWER CLIPS @\$3.50	NECESSARY	7.00	7.00
1	REAR PARKING SENSOR RH (CENTRE)	DENTED	395.50	395.50
1	REAR END PANEL	BENT	602.00	602.00
1	REAR END PANEL TOP COVER	DENTED	353.84	353.84
1	REAR END PANEL SUPPORT	BENT	169.55	169.55
1	REAR SPARE TYRE TOP COVER	SERVICEABLE	384.85	-
1	HYBRID EMBLEM	NECESSARY	68.60	68.60
1	LOGO EMBLEM	NECESSARY	70.24	70.24
1	HYBRID SYNERGY DRIVE EMBLEM	NECESSARY	38.80	38.80
1	CAMRY EMBLEM	NECESSARY	49.98	49.98
1	FRONT BUMPER	BUCKLED	491.60	491.60
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	233.31	-
1	FRONT RADIATOR GRILLE	CRACKED	580.80	580.80
1	REAR BOOT LID (ADDITIONAL)	BUCKLED	863.00	863.00
1	REAR TAIL LAMP LH (ADDITIONAL)	MTG CRACKED	455.41	455.41
1	FRONT BUMPER REINFORCEMENT (ADDITIONAL)	BENT	421.74	421.74
1	FRONT BUMPER SPONGE (ADDITIONAL)	CRACKED	91.14	91.14
	LESS 25% DISCOUNT		-1,585.11	-1,430.57
			4,755.32	4,291.70
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	BENT	35.00	35.00
			35.00	35.00
LABOUR				
	TO DISMANTLE AND RENEW FRONT BUMPER.		200.00	200.00
	TO SPRAY PAINT (PEARL/FRONT PORTION).		250.00	220.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO STRAIGHTEN REAR BODY INCLUDING CUTTING AND WELDING. TO KNOCK DENTS ON REAR FENDER LH, REAR LUGGAGE PANEL, REAR TAIL LAMP PANEL LH & RH AND RENEW OF PARTS.		850.00	750.00
	TO SPRAY PAINT (PEARL/REAR PORTION).		1,000.00	900.00
			2,300.00	2,070.00
GRAND TOTAL			7,090.32	6,396.70

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,750.00
--	--	--	--	----------

Report Ref No. CS/FCI18022774/Kqd3n2

MARKET VALUE: \$26,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$20,201.00=NETT VALUE: \$5,799.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.