

# 来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No ..... EST0021021  
Singapore Institute of International  
Affairs

Page ..... 1 of 2  
Your ref. .... TP-SHB 2993R MS FC  
Job No. .... 70080  
Our ref. .... 18.12.27  
Payment .....  
Date ..... 18/12/2018

Attn .....

Vehicle No .... SJX 5206X  
Vehicle Model : Toyota Camry  
Accident on ... 15/12/2018

*Not WhatsApp  
Call 8?  
Recovery After Paint  
7 days*

| Quantity         | Unit | Description                     | Unit price | Disc. pct. | Amount |
|------------------|------|---------------------------------|------------|------------|--------|
| Supply of Parts: |      |                                 |            |            |        |
| 1.00             | Pc   | Rear bumper                     | 530.80     | 25.00      | 398.10 |
| 1.00             | Pc   | Rear bumper reinforcement       | 420.00     | 25.00      | 315.00 |
| 1.00             | Pc   | Rear bumper reflector RH        | 56.90      | 25.00      | 42.68  |
| 1.00             | Pc   | Rear bumper side holder LH      | 55.37      | 25.00      | 41.53  |
| 2.00             | Pcs  | Rear bumper lower clips         | 3.50       | 25.00      | 5.25   |
| 1.00             | Pc   | Rear parking sensor RH (centre) | 395.50     | 25.00      | 296.63 |
| 1.00             | Pc   | Rear end panel                  | 602.00     | 25.00      | 451.50 |
| 1.00             | Pc   | Rear end panel top cover        | 353.84     | 25.00      | 265.38 |
| 1.00             | Pc   | Rear end panel support          | 169.55     | 25.00      | 127.16 |
| 1.00             | Pc   | Rear spare tyre top cover       | 384.85     | 25.00      | 288.64 |
| 1.00             | Pc   | Hybrid emblem                   | 68.60      | 25.00      | 51.45  |
| 1.00             | Pc   | Logo emblem                     | 70.24      | 25.00      | 52.68  |
| 1.00             | Pc   | Hybrid Synergy Drive emblem     | 38.80      | 25.00      | 29.10  |
| 1.00             | Pc   | Camry emblem                    | 49.98      | 25.00      | 37.49  |
| 1.00             | Pc   | Front bumper                    | 491.60     | 25.00      | 368.70 |
| 1.00             | Pc   | Front bumper lower grille       | 233.31     | 25.00      | 174.98 |
| 1.00             | Pc   | Front radiator grille           | 580.80     | 25.00      | 435.60 |

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:  
Date:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。  
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

# 来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No ..... EST0021021  
Singapore Institute of International  
Affairs

Page ..... 2 of 2  
Your ref. .... TP-SHB 2993R MS FC  
Job No. .... 70080  
Our ref. .... 18.12.27  
Payment .....  
Date ..... 18/12/2018

Attn .....

Vehicle No .... SJX 5206X  
Vehicle Model : Toyota Camry  
Accident on ... 15/12/2018

| Quantity           | Unit | Description  | Unit price | Disc. pct. | Amount       |
|--------------------|------|--|------------|------------|--------------|
| Special nett item: |      |  |            |            |              |
| 1.00               | Pc   | Front number plate   | 35.00      |            | 12 35.00 ✓   |
| Labour & Misc:     |      |  |            |            |              |
| 1.00               |      | To dismantle and renew front bumper  | 200.00     |            | 200.00 ✓     |
| 1.00               |      | To spray paint (Pearl / front portion)   | 250.00     |            | 250.00 22d   |
| 1.00               |      | To straighten rear body including cutting and welding, to knock dents on rear fender LH, rear luggage panel, rear tail lamp panel LH & RH and renew of parts | 121 850.00 |            | 850.00 75d   |
| 1.00               |      | To spray paint (Pearl / rear portion)  | 1,000.00   |            | 1,000.00 90d |
| Sub-Total          |      |  |            |            | 5,716.87     |
| GST 7.00%          |      |  |            |            | 400.18       |
| Total              |      |  |            |            | S\$ 6,117.05 |

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

7090.32