



南方摩哆
SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel: 62730369 Fax: 62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 17th December 2018
Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 078120

Dear Sirs

Re: Cost of repair to BMW C640G7 - FZ 888P

1 pc of Mirror LH	SX	250.00 mis
" Mirror bracket LH		140.00 bro
" Front fairing LH		260.00 ut
" Centre fairing LH		480.00 ut
" Lower cowling		640.00 ut
" Side box		380.00 ut
" Givi Windscreen		280.00 ut
" BMW Name plate		65.00 ut
" Footrest plate		380.00 X
		4,045.00
		40% 10
		3,676.50

Less 10%

Net

Labour

250:

350.00

4,026.50

Tanpin 97495749
-WP-

20/12/18 @ 2pm

Receiving after repair.
surellha auto.wm
4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours faithfully,
SOUTHERN MOTOR

Tel 64193000
Fax 64153727