27/05/2000 ASS, REC, BY:	REF: CS AIG18622785	Usda	N2 Special Instruction	
Minus Minus From (Person): Azlan Sya	assignment (		Date/Time:	19/10/168/2·38pm
Estimated Cost:  OD / TP WS / TP RES / OD  To Inspect Vehicle No.	Bill		red: GBA	3777T
			Tel: 6747	77. 35.35
Policy No:	C	aim No:		
Sum Insured:  Make of Veh: (Client's Record)		Excess:		17/12/2018 after 2pm
CA / REV / REP. / REV : Date/Time: 450pm 19	선생 역계에 전에 그렇게 그 .	Mr. Tan	H.O.D. End Vehicle IN I	
Date/Time Action/Instruct	ion ( ) Estimate  45 x - x			
	77- NA/MG17015583	1/24	Dui	1: 1/8/2017.
				ž : ·
			1912	

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

/ehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	8271A
Vehicle Details	
/ehicle No.:	GBF2645X
Vehicle to be Exported:	No
ntended Deregistration Date:	20 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1KD2633872
Chassis No.:	JTFAT35YX0K206739
Maximum Power Output:	4 <b>*</b> )
Open Market Value:	\$24,946.00
Original Registration Date:	15 Aug 2016
First Registration Date:	15 Aug 2016
Transfer Count:	1
Actual ARF Paid:	\$1,248.00
Intended PARF Rebate Details	No
PARF Eligibility:	INO
PARF Eligibility Expiry Date:	±0.00
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	14 Aug 2026
COE Expiry Date:	C - Goods Vehicle & Bus
COE Category:	10
COE Period(Years):	\$9,657.00
PQP Paid:	\$7,388.00
COE Rebate Amount:	37.300.00

The information contained herein is correct as at 20 Dec 2018

ОК

## Pre repair inspection request - GBF2645X VS GBA3777T (OI) DOA 17/12/2018

From: Azlan, Syazairdina

admin-a@lkkauto.com, assignments@lkkauto.com

Fong, Andy-SY, Chin, Lee-Ving, Abu Kassim, Noor Mariesa, Md Ishak, Mond Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Hor, Yinrul, Chan, Yoke Shi, Kaur, Baljit

Sent: 19/12/2018 4:38:10 PM

Attachments: T 81145 (our ltr dd 181218 - Notice of Accident).pdf

Hi,

Please refer to the enclosed request from Cheonghoh Law Corporation.

Claim no

: 8020694651SG003

Case Owner : CHEE HENG LOH

If you have any queries/concerns, please let us know.

Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]

Sent: Wednesday, December 19, 2018 4:30 PM

To: Azlan, Syazairdina

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi;

Kaur, Baljit; Kai Liang Kai Liang

Subject: Re: Our ref: LCH.jp/2KB03-81145.18 Your ref: 8020694651SG003 - Accident involving GBF 2645 X / GBA 3777 T (AIG) on 17/12/18 along slip road of AYE

towards West Coast Way - Pre-repair survey ("PRS") of GBF 2645 X

Dear Sirs

We refer to the above matter and your e-mail of even date below.

We write to confirm our client nominates Marcus Chua from LKK Auto Consultants Pte Ltd to conduct the pre-repair survey of the damages to GBF 2645 X and he be appointed as the Single Joint Expert.

Regards, Jennifer Cheonghoh Law Corporation Blk 53 Chin Swee Road #03-05 Singapore 160053

Tel: 63378700 Fax: 63373700

On 19 Dec 2018, at 16:23, Azlan, Syazairdina <<u>Syazairdina.Azlan@aig.com</u>> wrote:

Hi Jennifer,

Please confirm that you are nominating Marcus Chua from LKK Auto Consultants Pte Ltd named in the list of surveyors to conduct the pre-repair survey and appointed as the "Single Joint Expert".

Thanks and regards.

Syaza Irdina Azlan

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]

Sent: Wednesday, December 19, 2018 4:19 PM

To: Azlan, Syazairdina

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul;

Chan, Yoke Shi; Kaur, Baljit; Kai Liang Kai Liang

Subject: Re: Our ref: LCH.jp/2KB03-81145.18 Your ref: 80206946515G003 - Accident involving GBF 2645 X / GBA 3777 T (AIG) on 17/12/18 along slip road of AYE towards West Coast Way - Pre-repair survey ("PRS") of GBF 2645 X

### URGENT

Dear Sirs

We refer to the above matter and your e-mail of even date below.

Our client hereby nominates Marcus Chua from LKK Auto Consultants Pte Ltd as listed in your aforesaid e-mail to conduct the pre-repair survey ("PRS") of the damages to our client's vehicle no. GBF 2645 X arising out of the above mentioned accident.

Kindly liaise with our client's repair workshop for the PRS of our client's vehicle, the details are as follows :-

Kai Liang Motor Service Autobay @ Kaki Bukit 1 Kaki Bukit Ave 6 #01-101 Singapore 417883

Person to contact: Annie/Mr Tan (contact no. 67474189)

Kindly acknowledge.

Thank you.

Regards. Jennifer Cheonghoh Law Corporation Blk 53 Chin Swee Road #03-05 Singapore 160053 Tel: 63378700 Fax: 63373700

On 19 Dec 2018, at 15:21, Azlan, Syazairdina <<u>Syazairdina.Azlan@aig.com</u>> wrote:

<logo.jpeg>

<lock.gif>

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息,请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิด ไฟส์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려 면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

Click here by 2018-12-26 15:21 +08 to read your message. After that, open the attachment.

Mare Info

Disclaimer. This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights

<SecureMessageAtt.html>

#### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:
The information in this small (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this small in error, please immediately notify me by "Repty" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairdina Azlan@aig.com To: mail@cheonghoh.sg Cc; Andy-SY, Fong@eig.com , Lee-Ying Chin@eig.com , NoorMariesa AbuKassim@eig.com , Imran. Ishak@eig.com , ShengYang , Lim@eig.com , Aashween jeetkaur, Mithoosingh@eig.com , Yinrul, Hor@eig.com , yokeshi.chan @aig.com Baijit.Kaur@aig.com
Subject: RE: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBA3777T AND GBF2645X ON 17/12/2018
Date: Wed, 19 Dec 2018 07:21:51 +0000 Dear Sir/Madam,

Reminder for pre-repair survey.

Kindly response to the email below whether agree to the appointment of any of these motor surveyors below as a single joint expert.

Thanks and regards,

Syaza Irdina Azlan AIG

Express Claims Adjuster II SG Claims Operations | AIG Shared Services

From: Azlan, Syazairdina

Sent: Tuesday, December 18, 2018 4:05 PM

To: mail@cheonghoh.sg

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul; Chan, Yoke Shi; Kaur, Baljit

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBA3777T AND GBF264SX ON 17/12/2018

#### Without Prejudice

Your Reference Our Reference : LCH.jp/2KB03-81145.18 : 8020694651SG003

women with the control

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Lim, Sheng Yang

Sent: Tuesday, December 18, 2018 3:41 PM

To: Azlan, Syazairdina

Subject: FW: Our ref: LCH.jp/2KB03-81145.18 Your ref: GBA 3777 T - Accident involving GBF 2645 X / GBA 3777 T (AIG) on 17/12/18 along slip road of AYE towards West Coast Way - Notice of Accident

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]

Sent: Tuesday, December 18, 2018 3:37 PM

To: Abu Kassim, Noor Mariesa; Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene

Subject: Re: Our ref: LCH.jp/2KB03-81145.18 Your ref: GBA 3777 T - Accident involving GBF 2645 X / GBA 3777 T (AIG) on 17/12/18 along slip road of AYE towards West Coast Way - Notice of Accident

#### URGENT

Dear Sirs

Kindly see attached our letter dated 18 December 2018 - Notice of Accident and enclosing a copy of our client's accident report for your attention.

Regards, Jennifer Cheonghoh Law Corporation Blk 53 Chin Swee Road #03-05 Singapore 160053 Tel: 63378700 Fax: 63373700

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

AND YOUR PROPERTY.	ACCIDENT STATEMENT
Date Of Report	17/12/2018 15:59
Date Of Accident	17/12/2018 11:45
Exact Location Of Accident	SLIP ROAD OF AYE TOWARDS WEST COACH WAY
Country/State of Loss	SINGAPORE

TRANSPORTED TO SERVICE	DETAILS OF OWN VEHICLE	Mark Market St.
Vehicle Registration Number	GBF2645X	
Insured/Policyholder		

CSM DESIGN Name Of Registered Owner 53048271A Co Reg No

KELVIN.CSMDESIGN@GMAIL.COM **Email Address** 

Mobile Phone No OFFICE-69096481 Alternative Phone No

Vehicle Particulars TOYOTA

Manufacturer TOYOTA DYNA 150 MANUAL Model

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy NO

for repair to your vehicle? THIRD PARTY If No, Please state action to be taken

COMMERCIAL VEHICLE Vehicle Category

Insurance Company

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

DMCVSN3047951800 Policy Number

Cover Note Number

Driver

LEE KOK CHAW Name of Driver S1803139F NRIC No 12/04/1967 Date Of Birth OUTDOOR Occupation 18/07/1984 Date Of Driving Pass

34 YEARS AND 4 MONTHS **Driving Experience** 

MALE Gender

+65-90282389 Mobile Number

Fax Number Contact Number

KELVIN.CSMDESIGN@GMAIL.COM **EMail Address** 

Address

BLK 128 PENDING ROAD #10-310

Postcode

670128

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

σ.

## General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

NO

#### Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

4

#### **Details of Police Action**

Was the accident reported to the police?

NO

If Yes. Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

### Circumstances of Accident

I WAS TRAVELLING ALONG AYE TOWARDS WEST COACH WAY, WHEN THE FRONT VEHICLE C:YN8515J BRAKE, I ALSO BRAKE AND STOPPED COMPLETELY, SUDDENLY I FELT AN IMAPCY FROM MY VEHICLE REAR PORTION. THE IMPACT WAS SO STRONG AND PUSHED MY VEHICLE FORWARD AND HAD HIT ONTO THE FRONT VEHICLE, UPON CHECKING, THE REAR VEHICLE B:GBA3777T HAD COLIDED ONTO MY VEHICLE REAR PORTION, NO ONE WAS INJURED.

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

## DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

**GBA3777T** 

Vehicle Make/Model/Colour

TOYOTA

**Details Of Properties** 

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

CHIN VUI KIEN

NRIC/Passport Number

406485773 83459143

Contact Number Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

# DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

YN8515J

ISUZU

COMMERCIAL VEHICLE

MR HUANG

87092655

KAI LIANG MOTOR SERVICE BLK1 KAKI BUKIT AVE 6 #01-101 AUTOBAY SINGAPORE 417883

N.7	4 Alberral
	12500 2
1	5 St 5-1 4/2/

VEHICLE NO:	GBF 264_X			
QTY	PARTICULAR		201001	01.155.10
1 PCS	TAILGATE		rysey	\$1,455.10
1 PCS	TAILGATE LOWER MEMBER		4.	\$878.10
1 PCS	TAILGATE LOCK HINGES O/S		7.6~	\$148.50
1 PCS	TAILAM? O/S		cn	4200.00
1 PCS	FRONT PANEL		/	\$1,219.30 💢
1 PCS	FRONT GRILLE		1	\$671.01 X
1 PCS	FRONT BUMPER	10	1	\$566.10
1 PCS	HEADLAMP N/S	1) (m		\$673.31
1 PCS	FRONT VIEW MIRROR BRACKET N/S	1234	300	\$455.10
				\$6,333.02
	S.NETT			
1 SET	TAILGATE CORPORATE STICKER		nu	\$300.00
1 PCS	TAILGATE 70 KM/H & 6 PAX STICKER		rely	\$20.00
1 PCS	REAR REVERSE SENSOR		Ship	\$250.00 200
	LABOUR CHARGES:			
	TO CHECK WIRING			\$50.00 30
	TO SPRAY RUSF PROOFING			\$80.00
	TO DISMANTLE & REPLACING REVERSE SENSOR			\$80.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS			\$680.00 600
	TO PUTTY & SPRAY PAINTING			\$1,080.00 9000
			TO	\$8,873.02

Account of Said by Penstar

252 252 2-22488 5.N-520.00 (obun-1630.00 4398.88 /ess 202 3519

# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/AIG18022785/USD3N2

Date:

16/01/2019

REFERENCE

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. Policy No:

0999994530

Claimant

**GBF2645X** 

Insured Vehicle No:

**GBA3777T** 

Vehicle No: Date of Loss:

17/12/2018

Nature of Claim:

TP

Claim No: 8020694651SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

**GBF2645X** 

Make & Model:

TOYOTA DYNA 150, 3.0 D (M) 15/08/2016 (Man. Year: 2016)

Engine No: Chassis No: Odometer:

1KD2633872

80200 km

JTFAT35YX0K206739

Reg. Date:

Silver

Colour:

**Engine Capacity:** Market Value/New Car 2982 cc N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side: 195R15

Bridgestone 6 mm

Rear Tyre Size: Rear Left Side:

155R12(D)

Bridgestone 6/6 mm

Front Right Side:

Bridgestone 6 mm

Rear Right Side:

Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 6,903.02 0.00	Adjuster's 2,768.88 0.00	4,134.14 0.00	Diff % 59.89
Labour Paintwork Labour Towing	1,970.00 0.00 0.00	1,630.00 0.00 0.00	340.00 0.00 0.00	17.26
Calculated Gross Total (S\$)  Approved Total (Overridden) (S\$)	8,873.02	4,398.88 3,500.00	4,474.14	50.42
Nett Amount (S\$)	8,873.02	3,500.00	5,373.02	60.55

INSPECTION

Date of Assignment:

19/12/2018

Date Inspected:

20/12/2018 Inspected At:

Kai Liang Motor Service - Kaki Bukit

(HQ)

BLK 1 KAKI BUKIT AVE 6 #01-101

AUTOBAY

Singapore 417883

Estimated Period of Repair:

4.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

1       1       *TAILGATE LOWER MEMBER       Repair       878.10 F         3       1       *TAILGATE LOCK HINGES O/S       Bent       148.50 F       *         4       1       *TAILLAMP O/S       Cracked       266.50 F       *         5       1       *FRONT PANEL       Repair       1,219.30 F         6       1       *FRONT GRILLE       Repair       671.01 F         7       1       *FRONT BUMPER       Repair       566.10 F         8       1       *HEADLAMP N/S       Cracked       673.31 F         9       1       *FRONT VIEW MIRROR BRACKET N/S       Bent       455.10 F         10       1       *SET TAILGATE CORPORATE STICKER       Necessary       300.00 FS         11       1       *TAILGATE 70KM/H & 6 PAX STICKER       Necessary       20.00 FS         12       1       *REAR REVERSE SENSOR       Shorted       250.00 FS         F=Franchise part. S=SpcNett. L=ListItemDisc.         Sub Total (S\$)       6,903.02       3         - List Item Discount on L Items 0.00/25.00% (S\$)       0.00	Amount	Repairer's	Condition	ed Parts Particulars			
TAILGATE LOWER MEMBER   Topin   Tailgate Lower Member   Tailgate Lock Hinges O/S   Bent   148.50 F	1,455.10FL		Dented/Bent	*TAILGATE		1	1
3       1       *TAILGATE LOCK HINGES O/S       Bent       148.50 F         4       1       *TAILLAMP O/S       Cracked       266.50 F       **         5       1       *FRONT PANEL       Repair       1,219.30 F         6       1       *FRONT GRILLE       Repair       671.01 F         7       1       *FRONT BUMPER       Repair       566.10 F         8       1       *HEADLAMP N/S       Cracked       673.31 F       *         9       1       *FRONT VIEW MIRROR BRACKET N/S       Bent       455.10 F       *         10       1       *SET TAILGATE CORPORATE STICKER       Necessary       300.00 FS       *         11       1       *TAILGATE 70KM/H & 6 PAX STICKER       Necessary       20.00 FS       *         12       1       *REAR REVERSE SENSOR       Shorted       250.00 FS       *         F=Franchise part. S=SpcNett. L=ListItemDisc.         Sub Total (S\$)       6,903.02       3         - List Item Discount on L Items 0.00/25.00% (S\$)       0.00	*-FL		Repair	*TAILGATE LOWER MEMBER		1	2
4 1 *TAILLAMP O/S Cracked 266.50 F 5 1 *FRONT PANEL Repair 1,219.30 F 6 1 *FRONT GRILLE Repair 671.01 F 7 1 *FRONT BUMPER Repair 566.10 F 8 1 *HEADLAMP N/S Cracked 673.31 F * 9 1 *FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F * 10 1 *SET TAILGATE CORPORATE STICKER Necessary 300.00 FS * 11 1 *TAILGATE TOKM/H & 6 PAX STICKER Necessary 20.00 FS * 12 1 *REAR REVERSE SENSOR Shorted 250.00 FS * F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) 6,903.02 3, - List Item Discount on L Items 0.00/25.00% (S\$) 0.00	*148.50 FL	148.50 F	Bent			1	
#FRONT PANEL Repair 1,219.30 F for 1 FRONT GRILLE Repair 671.01 F for 1 FRONT BUMPER Repair 566.10 F for 1 FRONT BUMPER Repair 566.10 F for 1 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 1 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 1 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 1 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 1 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 1 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 1 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 1 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 1 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 1 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 1 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 1 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 1 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 1 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 1 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 2 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 3 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 2 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 3 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 3 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 3 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 3 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 3 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 3 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 3 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 3 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 3 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 3 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 3 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 3 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 4 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 4 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 4 FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F for 4 FRONT VIEW MIRROR BRACKET N/S BENT F for 4 FRONT VIEW MIRROR BRACKET N/S BENT F for 4 FRONT VIEW MIRROR BRACKET N/S BENT F for 4 FRONT VIEW MIRROR BRACKET N/S BENT F for 4 FRONT VIEW MIRROR BRACKET N/S BENT F for 4 FRONT VIEW MIRROR BRACKET N/S BENT F fo	*266.50 FL	266.50 F	Cracked			4	4
6 1 *FRONT GRILLE Repair 671.01 F 7 1 *FRONT BUMPER Repair 566.10 F 8 1 *HEADLAMP N/S Cracked 673.31 F * 9 1 *FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F 10 1 *SET TAILGATE CORPORATE STICKER Necessary 300.00 FS 11 1 *TAILGATE TOKM/H & 6 PAX STICKER Necessary 20.00 FS 12 1 *REAR REVERSE SENSOR Shorted 250.00 FS F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) 6,903.02 3.  - List Item Discount on L Items 0.00/25.00% (S\$) 0.00	*-FL	1,219.30 F	Repair				_
9 1 *FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F 10 1 *SET TAILGATE CORPORATE STICKER Necessary 300.00 FS * 11 1 *TAILGATE 70KM/H & 6 PAX STICKER Necessary 20.00 FS 12 1 *REAR REVERSE SENSOR Shorted 250.00 FS * F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) 6,903.02 3,  - List Item Discount on L Items 0.00/25.00% (S\$) 0.00	*-FL	671.01 F	500 500 miles (100)			1	5
9 1 *FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F 10 1 *SET TAILGATE CORPORATE STICKER Necessary 300.00 FS * 11 1 *TAILGATE 70KM/H & 6 PAX STICKER Necessary 20.00 FS 12 1 *REAR REVERSE SENSOR Shorted 250.00 FS * F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) 6,903.02 3,  - List Item Discount on L Items 0.00/25.00% (S\$) 0.00	*- FL	566.10 F	The state of the s			1	6
9 1 *FRONT VIEW MIRROR BRACKET N/S Bent 455.10 F 10 1 *SET TAILGATE CORPORATE STICKER Necessary 300.00 FS * 11 1 *TAILGATE 70KM/H & 6 PAX STICKER Necessary 20.00 FS 12 1 *REAR REVERSE SENSOR Shorted 250.00 FS * F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) 6,903.02 3,  - List Item Discount on L Items 0.00/25.00% (S\$) 0.00	*673.31 FL	673.31 F	F21 0 10			1	/
10 1 *SET TAILGATE CORPORATE STICKER Necessary 300.00 FS * 11 1 *TAILGATE 70KM/H & 6 PAX STICKER Necessary 20.00 FS 250.00 FS	*455.10 FL	455.10 F				1	
10 1 **SET TAILGATE CORPORATE SHOKER* 11 1 **TAILGATE 70KM/H & 6 PAX STICKER* 12 1 **REAR REVERSE SENSOR*  F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) 6,903.02 3,  - List Item Discount on L Items 0.00/25.00% (S\$) 0.00	*300.00 FS	300.00 FS		[1978] [1977] [1977] [1972] [1974] [		1	
11 1 **REAR REVERSE SENSOR Shorted 250.00 FS *  F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) 6,903.02 3,  - List Item Discount on L Items 0.00/25.00% (S\$) 0.00	*20.00 F					1	
F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) 6,903.02 3,  - List Item Discount on L Items 0.00/25.00% (S\$) 0.00	*200.00 F					1	1000
Sub Total (S\$) 6,903.02 3, - List Item Discount on L Items 0.00/25.00% (S\$) 0.00			Ollorica			1	
- List Item Discount on L Items 0.00/25.00% (S\$) 0.00	3,518.51	c 002 02		Nett. L=ListItemDisc.	part. S=SpcN	nchise	F=Fra
- List item discount on a items discussion (44)	749.63	Committee and Co		2007 FM 05500 W NOS200			
Total Parts (S\$) 6,903.02 2	749.03	0.00	ns 0.00/25.00% (S\$)	<ul> <li>List Item Discount on L Iter</li> </ul>			
	2,768.88	6,903.02	Total Parts (S\$)				
Report was unsubmitted during this print-out.			80 <u>2</u>				

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended	Labour
Recommended	Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			20.00
1	TO CHECK WIRING	New	50.00	30.00
2	TO SPRAY RUSF PROOFING	New	80.00	50.00
5	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	680.00	600.00
5	TO PUTTY & SPRAY PAINTING	New	1,080.00	900.00
	Gross Labo	ur Cost (S\$)	1,970.00	1,630.00
	Report was unsubmitted du	ing this print-out.		

< END OF ESTIMATES >