



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2003143
INV Date 14/04/2020
Reference CC4/LPC18022789/Kds3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. YM 4517K
Insured Veh. GBG 4060P
Claim No. 18/18/19/VC05/021238
Policy No. Z18VC05000191
Accident Date 17/12/2018
Inspection Date 18/02/2019

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18022789/Kds3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 14-04-2020		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 4060P	Veh. Inspected	YM 4517K	
Policy No.	Z18VC05000191	Coverage (\$)	0.00	
Claim No.	18/18/19/VC05/021238	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	19/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER	c.c	7545	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	FM657MB10123	Colour	RED	
Odometer	265493	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	10.00 X20X16	DOUBLE COIN	9 mm	
L/H Front Tyre	10.00 X20X16	DOUBLE COIN	9 mm	
R/H Rear Tyre	10.00 X20X16 (D)	CEAT	6/6 mm	
L/H Rear Tyre	10.00 X20X16 (D)	CEAT	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/12/2018	Inspection Date	18/02/2019	
Survey held at	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 4517K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	TAILLAMP ASSY (LH/RH) @\$250.00 (WCP)	O/S CRACKED	500.00	250.00
1	REAR NUMBER PLATE LAMP (WCP)	CRACKED	75.00	75.00
	COST PLUS 15%		86.25	48.75
			661.25	373.75
	<u>SPECIAL NETT ITEMS</u>			
1	TAILGATE (SN)	NOT NECESSARY	2,500.00	-
2	TAILGATE '60KM/H' STICKER @\$25.00 (SN)	NOT NECESSARY	50.00	-
1	TAILGATE '40PAX' STICKER (SN)	NOT NECESSARY	25.00	-
2	TAILGATE RUBBER STOPPER (LH/RH) @\$250.00 (SN)	O/S CRACKED	500.00	250.00
1	REAR NUMBER PLATE (SN)	DENTED	40.00	20.00
1	REAR NUMBER PLATE BRACKET (SN)	TO REPAIR SEE LABOUR	100.00	-
1	REAR REINFORCEMENT (SN)	BENT	1,200.00	1,200.00
1	RIGHT REAR TOOL BOX (LOCAL REPAIR) (SN)	DENTED	1,200.00	250.00
			5,615.00	1,720.00
	<u>LABOUR</u>			
	TO REMOVE,CUT OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF REAR NUMBER PLATE BRACKET.		500.00	350.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		600.00	360.00
	TO FOCUS TAILLAMPS .TO CHECK REAR WIRING AND LIGHTING OPERATION.		50.00	20.00
			1,150.00	730.00
GRAND TOTAL			7,426.25	2,823.75

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,250.00
---	--	--	-----------------

Report Ref No. CC4/LPC18022789/Kds3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.