



CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 30272

Vehicle Insured : GBG 4060 P
Accident Date : 17-Dec-2018

Date : 25-Jan-2019

Our Ref : 180841 (LONPAC) / SHUMAN

PAGE : 1

TOH CHIN LEONG CONSTRUCTION PTE LTD
Singapore

*Not Authorised**Return After 8? 2250*

ESTIMATED COST OF REPAIR FOR MIT FM657MSRDEC 7545cc (2006) YM4517K 3 repair days

2 pcs taillamp assy (LH/RH)	<i>discmt</i> @ S\$250.00	500.00 c	<i>✓</i>
1 pc rear number plate lamp		<i>cm</i> 75.00 c	<i>✓</i>
		575.00	
	Add 15% :	86.25	
		661.25	

1 pc tailgate		NN 2,500.00	sn X
2 pcs tailgate "60km/h" sticker	@ S\$ 25.00	<i>nn</i> 50.00	sn X
1 pc tailgate "40pax" sticker		<i>nn</i> 25.00	sn X
2 pcs tailgate rubber stopper(LH/RH) @ S\$250.00	<i>discmt</i>	500.00	sn <i>✓</i>
1 pc rear number plate		<i>nn</i> 40.00	sn <i>201n</i>
1 pc rear number plate bracket		<i>R</i> 100.00	sn X
1 pc rear reinforcement		<i>R</i> 1,200.00	sn <i>✓</i>
1 pc right rear tool box	<i>L-R</i>	<i>nn</i> 1,200.00	sn <i>2501n</i>

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

500.00 *3501*

To putty and respray on affected
portions.

600.00 *3601*

To focus taillamps. To check rear
wiring and lighting operation.

50.00 *201*

Total : S\$ 7,426.25
=====

Singapore Dollars Seven Thousand Four Hundred
and Twenty Six and Cents Twenty Five Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: