

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 18 DECEMBER 2018

Third Party Insurer: AIG

Vehicle No: SLR8340D

Third Party Veh No: SLF8270K

Model: MERCEDES BENZ C350E

Date of Accident: 18/12/2018

Chassis: WDD2050472F438596 - 207

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR RH	1	<i>At work</i>	\$1,575.00 ✓
2	REAR DOOR RH	1		REPAIR
			SUB TOTAL	\$1,575.00
			LESS 10%	-\$157.50
			PARTS TOTAL	\$1,417.50

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

400
\$700.00

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

500
\$700.00

TO TUFF KOTE / ANTI-RUST

30
\$60.00

TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD

120
\$180.00

TO DISMANTLE & REPLACED FRONT RH DOOR & REAR RH DOOR INNER COMPONENT MECHANISM
TO FACILITATE REPAIR WITH CHECK FOR FUNCTION

80
\$200.00

TO CHECK WIRING WITH WATER LEAKAGE TEST

20
\$80.00

LABOUR TOTAL \$1,920.00

ONG / PEI TING

TOTAL \$3,337.50

Not Authorised
Recovery B4 paint
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: