

**Spare Parts**

Vehicle No. : **SMF6681J**  
 Make & Model : **Hyundai ELANTRA AD 1.6 GLS AT (AMS)**  
 Chassis No. : **KMHD841CMJU763794**

Submit By :  
 Year Manufactur : **2018**  
 Engine No. : **G4FGJU274374**

**Cost / List**

S/No	Part Description	Qty	List		Disposition by Surveyor
1	Rear Bumper	1	\$491.80		
2	Rear Right Fender	1	\$1,768.30		
3	Rear Right Bumper bracket	1	\$49.60		
4	Rear Bumper Clips @ \$5.00	10	\$50.00		
	<b><u>Special Nett</u></b>	1	\$80.00		
1	Rear Right Tyre	1	\$150.00		
2	Windscreen Sealant	1	\$40.00		
	<b><u>LABOUR</u></b>				
1	Labour to remove rear bumper and reverse sensor to facilitate replacement of new bumper		\$180.00		
2	To remove, replace and panel beat rear right fender		\$280.00		
3	To remove upholstery, internal garnish, seats to facilitate replacing of rear right fender		\$400.00		
4	To putty and respray rear bumper, rear right fender.		\$560.00		
5	Tuff Kote		\$50.00		
6	To remove and replace rear windscreen		\$150.00		
7	To remove and replace tyre		\$30.00		
8	Balancing tyre		\$30.00		

9	Wheel alignment		\$80.00		

*Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.*