

ASS. REC. BY

REF

CS/CTI18022822/ Ktd3

Special Instructions

Surveyor

Kenneth

ASSIGNMENT (Office)

Meimien

From (Person)

Elaine Cheong

of

CTI

Date/Time

20/12/18 @ 11:47am

Estimated Cost

Bill to

OD / ☒ TP / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLT3411E

Insured:

SJD 7645D

at Workshop m/s

Esteem Performance

Tel:

8799 0066

of

385 Sin Ming Drive

Policy No.

DMPCSN3020281800

Claim No.

SNM18D05863C02

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A

17/12/2018

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement

Date/Time

11:53am @ 20/12/18

Person Contacted

Carmen

Vehicle IN / ☒ OUT

Date/Time

Action/Instruction (✓) Estimate

SLT3411E-X

SJD7645D-X

21/12/18 -

unit yet

31/12/18 -

Vehicle ref in put

\$5264.66 email 2 carmen (Red)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Dec 2018		20 Dec 2018 11:47 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	GRAB RENTALS PTE LTD		
Vehicle Reg. No.:	SLT3411E	Date of Loss:	17/12/2018 00:00 - :59
Claim Type:	TP / SNM18D05863C02	Policy/Cover Note No.:	DMPCSN3020281800
Vehicle Reg. No. (Insured):	SJD7645D	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Esteem Performance Pte Ltd - Sin Ming (HQ) 385 Sin Ming Drive, 575718 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/01/2019]		
Adj Asg. Remarks:	EST \$9837.63, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

From: Carmen Lim <carmen@esteemperf.com.sg>
Sent: Wednesday, 19 December, 2018 6:14 PM
To: Claims Dept of CTI
Cc: serence ctc
Subject: Re: REQUEST FOR PRI SURVEY SLT3411E

Dear China Taiping,

Our insured vehicle should be **SLT 3411 E**

Thank you



Freundliche Grüße / Best Regards

Carmen Lim

Accident Claim Executive | Operation Division

Esteem Performance Pte Ltd

M: 8799 0066

P: 6484 1221

E: carmen@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com



On Wed, Dec 19, 2018 at 6:11 PM Carmen Lim <carmen@esteemperf.com.sg> wrote:

Dear Sir / Madam,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)

We act for Grab Rentals Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no.SLT 3411 E

Please be informed that the said vehicle can be inspected at :

Name of workshop : Esteem Performance Pte Ltd

Address : 385 Sin Ming Drive (Inside VICOM) S 575718

Tel : 8799 0066

Fax : 6259 3326

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.



Freundliche Grüße / Best Regards

Carmen Lim

Accident Claim Executive | Operation Division

Esteem Performance Pte Ltd

M: 8799 0066

P: 6484 1221

E: carmen@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com



This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/12/2018 19:49
Date Of Accident	17/12/2018 11:40
Exact Location Of Accident	ALONG BAGHDAD STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT3411E
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	

Driver

Name of Driver	SIE KIM BOON
NRIC No	S7104760A
Date Of Birth	20/01/1971
Occupation	OUTDOOR
Date Of Driving Pass	22/08/2003
Driving Experience	15 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94882347
Fax Number	
Contact Number	
Email Address	NOEMAIL

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

OOI WENG KIT

NRIC/Passport Number

G8722606P

Contact Number

93905944

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

ACCIDENT STATEMENT (2000 characters)

ON THE DATE AND TIME MENTIONED, I WAS DRIVING ALONG THE SAID MENTIONED ROAD WHEN VEHICLE B, MOVING OFF FROM STATIONARY POSITION FROM MY LEFT AND HIT AGAINST THE LEFT PORTION OF MY VEHICLE. THIS INCIDENT WAS CAPTURED IN MY IN-CAR VIDEO WHICH I HAD SUBMITTED TO MY WORKSHOP. NOBODY WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

17 December 2018 at 2:22 PM

Date/Time:

17 December 2018 at 2:22 PM



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLT 3411 E

Not Authorized
I.B.I
Returning B&P

Parts	(a) Cost / List Price Items	\$	8,623.50
	Plus/Less 25%	\$	2,155.88
	Total of Cost / List	\$	6,467.63
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	350.00
Total Parts Cost		\$	6,817.63
Labour		\$	3,020.00
Total		\$	9,837.63

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : UKC
Survey conducted on : 7/1/19 at

Remarks By Surveyor

- (a) The repair of this vehicle is ☒ authorized / is not authorized until further notice.
- (b) Recommended Days of Repair : 05 day(s)
- (c) Resurvey : Required / ☒ Not Required
- (d) Excess : \$
- (e) Signature of surveyor : Sc Date: 7/1/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLT 3411 E**
Make & Model : **TOYOTA PRIUS**
Chassis No. : **JTDKB3FU403574775**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front door <i>Red/wag</i>	1	\$1,226.70 ✓		✓
2	LH front door hinge top <i>R</i>	1	\$78.34		X
3	LH front door hinge bottom <i>R</i>	1	\$78.34		X
4	LH front door lock <i>R</i>	1	\$428.40		X
5	LH front door checker <i>Sm</i>	1	\$156.79		X
6	LH front door weatherstrip <i>Sm</i>	1	\$198.49		?X
7	LHF door glass outer moulding <i>Sm</i>	1	\$122.95		X
8	LHF power window motor <i>Sm</i>	1	\$543.25		X
9	LHF power window regulator <i>Sm</i>	1	\$211.78		X
10	LHF door outer handle <i>Sm</i>	1	\$375.60		X
11	LH rear door <i>Red/wag</i>	1	\$1,181.75 ✓		✓
12	LH rear door hinge top <i>R</i>	1	\$78.34		X
13	LH rear door hinge bottom <i>R</i>	1	\$78.34		X
14	LH rear door lock <i>R</i>	1	\$411.70		X
15	LH rear door checker <i>Sm</i>	1	\$156.79		X
16	LH rear door weatherstrip <i>Sm</i>	1	\$178.40		X
17	LHR door glass outer moulding <i>Sm</i>	1	\$111.61		X
18	LHR power window motor <i>Sm</i>	1	\$511.69		X
19	LHR power window regulator <i>Sm</i>	1	\$177.64		X
20	LH side skirt <i>5Xo</i> <i>Bmo/Da</i>	1	\$721.50 ✓		?
21	LH side skirt clip <i>WV</i>	10	\$40.00		?X
22	LH rear rim <i>Red</i>	1	\$1,555.10 ✓		✓
23	LH rear tyre <i>Sm</i>	1	\$350.00	S.N	X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 509536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemport.com.sg

Repair Estimates

SLT 3411 E

Parts	(a) Cost / List Price Items	\$	8,623.50
	Plus/Less 25%	\$	2,155.88
	Total of Cost / List	\$	6,467.63
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	350.00
Total Parts Cost		\$	6,817.63
Labour		\$	3,020.00
Total		\$	9,837.63

The above total will be subjected to 7% G.S.T.

Finalised

Not Authorised
1.B.1
Returning B&B parts

4688.68
1171.76
2513.79

1860

5373.79 *5264.68*

Name of Surveyor

Mennerh

Company

6K6

Survey conducted on

7/1/19

at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : *05* day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor

Le

Date:

7/1/19



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 6033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLT 3411 E**
Make & Model : **TOYOTA PRIUS**
Chassis No. : **JTDKB3FU403574775**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front door <i>Del/way</i>	1	\$1,226.70 ✓		✓
2	LH front door hinge top <i>R</i>	1	\$78.34		X
3	LH front door hinge bottom <i>R</i>	1	\$78.34		X
4	LH front door lock <i>R</i>	1	\$428.40		X
5	LH front door checker <i>Sm</i>	1	\$156.79		X
6	LH front door weatherstrip <i>Sm</i>	1	\$198.49		X
7	LHF door glass outer moulding <i>Sm</i>	1	\$122.95		X
8	LHF power window motor <i>Sm</i>	1	\$543.25		✓
9	LHF power window regulator <i>Sm</i>	1	\$211.78		X
10	LHF door outer handle <i>Sm</i>	1	\$375.60		X
11	LH rear door <i>Del/way</i>	1	\$1,181.75 ✓		✓
12	LH rear door hinge top <i>R</i>	1	\$78.34		X
13	LH rear door hinge bottom <i>R</i>	1	\$78.34		X
14	LH rear door lock <i>R</i>	1	\$411.70		X
15	LH rear door checker <i>Sm</i>	1	\$156.79		X
16	LH rear door weatherstrip <i>Sm</i>	1	\$178.40		X
17	LHR door glass outer moulding <i>Sm</i>	1	\$111.61		X
18	LHR power window motor <i>Sm</i>	1	\$511.69		X
19	LHR power window regulator <i>Sm</i>	1	\$177.64		X
20	LH side skirt <i>576.00</i> <i>Brz / Rd</i>	1	\$721.50 ✓		(2)
21	LH side skirt clip <i>Nr</i>	10	\$40.00		X
22	LH rear rim <i>Rd</i>	1	\$1,555.10 ✓		✓
23	LH rear tyre <i>Sm</i>	1	\$350.00	S.N	X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 6033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

3404.66

5313.79

4688.05



Blok 5033 Ang Mo Kio, Ind Park 2 #01-251/250, 500030.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.estampart.com.sg

Vehicle No. : SLT 3411 E Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Dec 2018		20 Dec 2018 11:47 Edit Adj Rpt	S\$5,264.66 Edit Estimates	S\$5,264.66 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	*, ID: -								
Main Claimant:	GRAB RENTALS PTE LTD								
Vehicle Reg. No.:	SLT3411E	Date of Loss:	17/12/2018 00:00 - :59 [13 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D05863C02	Policy/Cover Note No.:	DMPCSN3020281800						
Vehicle Reg. No. (Insured):	SJD7645D	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Esteem Performance Pte Ltd - Sin Ming (HQ) 385 Sin Ming Drive, 575718 Sin Ming - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 02/01/2019]								
Adj Asg. Remarks:	EST \$9837.63, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT3411E (SNM18D05863C02)
[SJD7645D]
TP
GRAB RENTALS PTE LTD
Dec 17 2018 12:00AM
[-]
Esteem Performance Pte Ltd - Sin Ming

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/19 16:25	General View	Load JPG	☒
2	25/02/19 16:25	General View	Load JPG	☒
3	25/02/19 16:25	General View	Load JPG	☒
4	25/02/19 16:25	General View	Load JPG	☒
5	25/02/19 16:25	General View	Load JPG	☒
6	25/02/19 16:25	General View	Load JPG	☒
7	25/02/19 16:25	General View	Load JPG	☒
8	25/02/19 16:25	General View	Load JPG	☒
9	25/02/19 16:25	General View	Load JPG	☒
10	25/02/19 16:25	General View	Load JPG	☒
11	25/02/19 16:25	General View	Load JPG	☒
12	25/02/19 16:25	General View	Load JPG	☒
13	25/02/19 16:25	General View	Load JPG	☒
14	25/02/19 16:25	General View	Load JPG	☒
15	25/02/19 16:25	General View	Load JPG	☒
16	25/02/19 16:25	General View	Load JPG	☒
17	25/02/19 16:25	General View	Load JPG	☒
18	25/02/19 16:25	General View	Load JPG	☒
19	25/02/19 16:28	Reinspection Photo	Load JPG	☒
20	25/02/19 16:28	Reinspection Photo	Load JPG	☒
21	25/02/19 16:28	Reinspection Photo	Load JPG	☒
22	25/02/19 16:28	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/12/18 11:46	PRS	Load PDF	
2	20/12/18 11:47	REPAIR EST WITH TP GIA	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118022822/KTD3Q2

Date: 27/02/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3020281800
Claimant Vehicle No :	SLT3411E	Insured Vehicle No :	SJD7645D
Date of Loss:	17/12/2018	Nature of Claim:	TP
		Claim No:	SNM18D05863C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT3411E	Engine No:	2ZRS106340
Make & Model:	TOYOTA PRIUS, 1.5 HYBRID (A)	Chassis No:	JTDKB3FU403574775
Reg. Date:	26/10/2017 (Man. Year: 2017)	Odometer:	113106 km
Colour:	Metallic Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,817.62	3,404.66	3,412.96	50.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,020.00	1,860.00	1,160.00	38.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,837.62	5,264.66	4,572.96	46.48
+ GST 7.00/7.00% (S\$)	688.63	368.53	320.10	46.48
Nett Amount (S\$)	10,526.25	5,633.19	4,893.06	46.48

INSPECTION

Date of Assignment:	20/12/2018	
Date Inspected:	07/01/2019 Inspected At:	Esteem Performance Pte Ltd - Sin Ming (HQ) 385 Sin Ming Drive Singapore 575718
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Feb 2019)
Parts: 144	TOYOTA PRIUS 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLT3411E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT DOOR	Dented / Warped	1,226.70 FL	*1,226.70 FL
2	1		*LH FRONT DOOR HINGE TOP	Repair	78.34 FL	*- FL
3	1		*LH FRONT DOOR HINGE BOTTOM	Repair	78.34 FL	*- FL
4	1		*LH FRONT DOOR LOCK	Repair	428.40 FL	*- FL
5	1		*LH FRONT DOOR CHECKER	Serviceable	156.79 FL	*- FL
6	1		*LH FRONT DOOR WEATHERSTRIP	Serviceable	198.49 FL	*- FL
7	1		*LHF DOOR GLASS OUTER MOULDING	Serviceable	122.95 FL	*- FL
8	1		*LHF POWER WINDOW MOTOR	Serviceable	543.25 FL	*- FL
9	1		*LHF POWER WINDOW REGULATOR	Serviceable	211.78 FL	*- FL
10	1		*LHF DOOR OUTER HANDLE	Serviceable	375.60 FL	*- FL
11	1		*LH REAR DOOR	Dented / Warped	1,181.75 FL	*1,181.75 FL
12	1		*LH REAR DOOR HINGE TOP	Repair	78.34 FL	*- FL
13	1		*LH REAR DOOR HINGE BOTTOM	Repair	78.34 FL	*- FL
14	1		*LH REAR DOOR LOCK	Repair	411.70 FL	*- FL
15	1		*LH REAR DOOR CHECKER	Serviceable	156.79 FL	*- FL
16	1		*LH REAR DOOR WEATHERSTRIP	Serviceable	178.40 FL	*- FL
17	1		*LHR DOOR GLASS OUTER MOULDING	Serviceable	111.61 FL	*- FL
18	1		*LHR POWER WINDOW MOTOR	Serviceable	511.69 FL	*- FL
19	1		*LHR POWER WINDOW REGULATOR	Serviceable	177.64 FL	*- FL
20	1		*LH SIDE SKIRT	Buckled / Dented	721.50 FL	*576.00 FL
21	10		*LH SIDE SKIRT CLIP	Not Necessary	40.00 FL	*- FL
22	1		*LH REAR RIM	Dented	1,555.10 FL	*1,555.10 FL
23	1		*LH REAR TYRE	Serviceable	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,973.50	4,539.55
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,155.88	1,134.89
Total Parts (\$\$)	6,817.62	3,404.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (LHF DOOR ,LHR DOOR ,LHR FENDER ,LH SIDE SKIRT)	New	1,200.00	600.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (LHF DOOR,LHR DOOR ,LHR FENDER ,LH SIDE SKIRT)	New	1,200.00	1,000.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO DO WHEEL ALIGNMENT	New	120.00	60.00
5	TO REMOVE & REFIT DOOR TRIM ,DOOR GLASS ,WINDOW REGULATOR,DOOR LOCK TO ASSIST WORK LOAD	New	300.00	120.00
6	TO TUFF COAT	New	150.00	60.00
Gross Labour Cost (S\$)			3,020.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >