



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-150594

Date of Request: 01/10/2018

Your Ref No: SKW 3224A/HK/JP/CA

KSCGP JURIS LLP
10 Hoe Chiang Road #13-03A
Keppel Tower
Singapore 089315

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 21/09/2018

P. of Accident: AYER RAJAH EXPRESSWAY TOWARDS

Client Vehicle No: SKW3224A

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735
TAX INVOICE

Our Ref No: GR-18-150598

Date of Request: 01/10/2018

Your Ref No:

SKW 3224A/HK/JP/CA

 KSCGP JURIS LLP
 10 Hoe Chiang Road #13-03A
 Keppel Tower
 Singapore 089315

Dear Sir/Msadam,

Date of Accident: 21/09/2018

Vehicle No: SKW3224A

Place of Accident: ALONG AYE TWD TUAS AFTER BUONA VISTA EXIT

Involving Vehicle No: SHD3112A

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SHD3112A	ALONG AYE TWD TUAS AFTER BUONA VISTA EXIT	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

E

☒ GIRO ☐ Cash ☐ Cheque

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/09/2018 11:49
Date Of Accident	21/09/2018 18:30
Exact Location Of Accident	AYE TWDS JURONG BEFORE CLEMENTI EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3112A
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	WONG SAY BENG
NRIC No	S1354328C
Address	816 #13-10 JELlicoe ROAD
General Information of the Accident	
Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Other Information	
Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	2
Circumstances of Accident	
SEE ATTACH.	
Attachment(s)	
Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

Vehicle Registration Number


SKW3224A

Vehicle Make/Model/Colour

Name of Driver

Insurance Company Name

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21/9/18 at about 18:30 hrs, I was driving on lane 1 along AYE towards Jurong before Clementi Exit.

Shortly after Veh B in front of my taxi braked to stopped, I immediately applied brake upon noticed it. Unfortunately, I'm not able to stop my taxi in time and gently collided onto the rear portion of Veh B.

01 female passenger on board my taxi. No injury reported in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 PORT TRANSPORTATION PTE LTD
 CC REG. NO. 189303021R

 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

OMFORT TRANSPORTATION PTE LTD
CO REG NO 199503921R


Loke Wei Yiong

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Enquire Vehicle & Owner Information (Vehicle No. SHD3112A As At 21 Sep 2018 / 17:45:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: SKW3224A/HK/JP/CA

Current Owner Details

Owner ID Type: Company

Owner ID: 199303821R

Owner Name: COMFORT TRANSPORTATION PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 383

Registered Street Name: SIN MING DRIVE

Registered Unit No.: -

Registered Building Name: GAS BUILDING

Registered Postal Code: 575717

Current Vehicle Details

Vehicle No.: SHD3112A

Make Description/Model: HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR

Insurance Company Name: INDIA INT'L INS PTE LTD



**PRO
PLUS
AUTOMOBILE
ENGINEER**

221 Balestier Road #10-01 Rocco Balestier Singapore 329928
Tel: (65) 6266 5255 Fax: (65) 6352 6902 Email: ethan08@singnet.com.sg / sthtan88@gmail.com
Mobile: +65 96730595 / +65 9788 9808 / +65 96999248
Company Registration No: 40188600M

*Consultants to Motor Industry, Automobile
Engineers, Claims Investigators, Accident
Reconstruction Specialists, Insurance Loss
Assessors / Adjusters, Valuers And
Licensed Appraisers.*

TO:

M/s Sia Choon Hoo
c/o Block 7 Pioneer Road North
#01-43 Lokyang Light Industrial Park
Singapore 628459

INVOICE NO. 29647

OUR REFERENCE : PP/ET/CT.3224.TP.11-18

YOUR REFERENCE: Third Party

DATE : 29 November 2018

VEHICLE REGISTRATION NO : SKW 3224 A
VEHICLE MAKE /MODEL : Toyota Corolla Altis 1.6

- ☒ TO INSPECTION/APPRAISAL FEES
- ☐ TO AFFIRM AFFIDAVIT ON
- ☐ TO COURT ATTENDANCE ON
- ☐ TO REINSPECTION FEES
- ☒ TO PHOTOGRAPHY
- ☒ TO TRANSPORTATION CHARGES & follow-up reinspection
- ☐ OTHERS (SPECIFY)
- ☐ SINGAPORE DOLLARS: SEVEN HUNDRED & TWENTY FIVE ONLY

S\$ 725.00

E & O. E.



for PRO PLUS AUTOMOBILE ENGINEERS

18-4941-HK

HOE KENG MOTOR SERVICE AND TRADING

Block 7 Pioneer Road North #01-43
Lokyang Light Industrial Park
Singapore 628459
Company Reg No. 38800900U
T 62684111 F 62684112
Info@hoekengmotor.com

29 November 2018

Mr Sia Choon Hoo
c/o Block 7 Pioneer Road North
01-43 Lokyang Light Industrial Park
Singapore 628459

FINAL REPAIR COSTS

SKW 3224 A
Toyota Corolla Altis 1.6

To cost of repair lump sum as recommend by surveyor.....\$4,000.00 NETT

SINGAPORE DOLLARS : FOUR THOUSAND ONLY

HOE KENG
Motor Service & Trading
Blk 7, Pioneer Road North
#01-43 Lokyang Light Ind. Park
Singapore 628459
Tel / 6268 4111 Fax 6268 4112



**PRO
PLUS
AUTOMOBILE
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329628
Tel: +65 6707 8932 Fax: +65 6352 6802
Mobile: +65 9673 0595 / +65 9786 9809
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com
Company Registration No: 40156500M

*Consultants to Motor Industry, Automobile
Engineers, Claims Investigators, Accident
Reconstruction Specialists, Insurance Loss
Assessors / Adjusters, Valuers And
Licensed Appraisers.*

Our Ref : PP/ET/CT.3224.TP.11-18

29 November 2018

Mr Sia Choon Hoo
c/o Block 7 Pioneer Road North
01-43 Lokyang Light Industrial Park
Singapore 628459

WITHOUT PREJUDICE

Dear Sirs,

**Re : Third Party Claim
Vehicle Registration No. SKW 3224 A**

We refer to your instruction to appraise the above-mentioned vehicle on 22 September 2018.

A static inspection was carried out and our report is enclosed for your perusal. The estimated repair costs submitted by Messrs **Hoe Keng Motor Services & Trading** for \$10,847.72 as per our attached schedule has been rechecked thoroughly by us against the actual damages sustained on the vehicle, and we recommend the replacements and rectifications accordingly.

Our revised quotation for the repair is \$4,965.23. In our opinion, we consider it to be excessive. We, therefore, recommend a contract lump sum repair cost. This is more economical than to have the vehicle repaired on a parts by/for parts basis. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair this vehicle for \$4,000.00 NETT which, in our opinion is fair and reasonable.

The repairer has agreed to undertake the repairs to your requirements at the recommended contract lump sum. However, we have not given authorisation and instruction to the repairer to proceed with the repairs.

The entire repair of the damaged vehicle should be completed within a reasonable period of 6 (six) days, excluding weekends and public holidays.

We are reverting the matter to you for a decision, and enclosed is our invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Very truly yours,
PRO PLUS AUTOMOBILE ENGINEERS


Errol Tan
Licensed Appraiser & Automobile Engineer

Encls:

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error please contact us immediately by telephone so that we can arrange for its return.



221 Balestier Road #10-01, Rocca Balestier, Singapore 329928
 Tel: +65 6707 8932 Fax: +65 6352 8802
 Mobile: +65 9673 0595 / +65 9788 9809
 E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com
 Company Registration No: 40156500M

**PRO
PLUS
AUTOMOBILE
ENGINEERS**

*Consultants to Motor Industry, Automobile
Engineers, Claims Investigators, Accident
Reconstruction Specialists, Insurance Loss
Assessors / Adjusters, Valuers And
Licensed Appraisers.*

VEHICLE INSPECTION REPORT

To: Mr Sia Choon Hoo
 c/o Block 7 Pioneer Road North
 #01-43 Lokyang Light Industrial Park
 Singapore 628459

Insured :
 Policy Number :
 Claim Number :
 Our Reference : PP/ET/CT.3224.TP.11-18
 Own Damage/Sum Insured :
 Excess :
 Third Party/Insee Company :
 Date : 29 November 2018

Instructed By : Ms Sabrina Poh
 Date of Assignment : 22 September 2018
 Date of Accident : 21 September 2018
 Date of Inspection : 22 September 2018
 Name of Workshop : Hoe Keng Motor Service &
 Trading
 Place of Inspection : Block 7 Pioneer Road North
 #01-43 Lokyang Light Industrial
 Park
 Singapore 628459

PARTICULARS OF DAMAGED VEHICLE

Registration Number	: SKW 3224 A	Odometer Reading	: 065 197 Km
Make/Model	: Toyota Corolla Alits 1.6	Radio/Cassette/CD	: Fitted
Year of Manuf/Reg	: 2015	Air Conditioner	: Fitted
Engine Number	: 1ZKY 224214	View Mirrors	: Fitted -O/s & n/s
Chassis Frame Number	: MRO53REH104541168	Seat Belts	: Fitted -Front & rear
Class/Type	: Passenger (Saloon)	Other Accessories	:
Colour	: Metallic Blue	(Specify)	:

PRE-ACCIDENT CONDITION OF VEHICLE

General Condition	: Good	Any Apparent Engine	:
Paintwork	: Good	Modification/s	:
Footbrakes	: Serviceable	Market Value	: -
Steering	: Serviceable	Scrap Value (PARF/OMV)	: -
Undercarriage (Front)	: Serviceable		
Undercarriage (Rear)	: Serviceable		

TYRE CONDITIONS ON VEHICLE

		NEAR SIDE	OFF SIDE
Front (Size)	: 205/55R16	75%	75%
MAKE	: Yokohama		
Rear (Size)	: 205/55R16	75%	75%
MAKE	: Yokohama		
SPARE (Size)	: -		
MAKE	: -		
Type of Road Wheels	: Alloy		

NOTE: The above percentages represent the estimated remaining life of the tyre threads
 * Denotes damaged component/s

PRO PLUS AUTOMOBILE ENGINEERS

Continuation Sheet No: 1

APPRAISEMENT SCHEDULE

Registration No: SKW 3224 A

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$ v	Revised Amount \$ g
<u>PARTS REPLACEMENT- LIST ITEMS</u>					
1	1 pc	Bootlid	Dented/bent	754.70	Rejected X nn
2	1 pc	Bootlid 'TOYOTA' motif	Essential	50.12	50.12 X nn
3	1 pc	Bootlid 'COROLLA' emblem	Essential	46.48	46.48 X nn
4	1 pc	Bootlid 'ALITS' emblem	Essential	46.48	46.48 X nn
5	1 pc	Bootlid outer handle [chrome]	No apparent damage	231.30	Rejected X nn
6	2 pcs	Bootlid reflector @\$401.10	Serviceable	802.20	Rejected X nn
7	2 pcs	Bootlid hinge @\$78.60	Bent/misaligned	157.20	Repair X nn
8	1 pc	Bootlid inner lock c/w sensor	Bent/malfunctioned	379.20	379.20 X nn
9	1 pc	Bootlid draught weatherstrip	Essential	266.40	266.40 X nn
10	2 pcs	Taillamp assembly @\$486.60	Displaced/serviceable	973.20	Rejected
11	1 pc	Rear end panel	Thrusted inwards/buckled	581.20	581.20 repair
12	1 pc	Rear end panel inner garnish	Distorted	271.40	271.40 X nn
13	1 pc	Rear bumper	Dented/distorted	639.90	639.90
14	2 pcs	Rear bumper absorber damper bracket @\$123.34	Bent	246.68	246.68 X nn
15	1 pc	Rear bumper beam	Bent/buckled	389.00	389.00
16	2 pcs	Rear bumper bracket @\$104.60	Bent/twisted	209.20	209.20
17	2 pcs	Rear bumper side support @\$69.72	Bent	139.44	139.44
18	2 pcs	Rear bumper side retainer @\$57.40	Cracked	114.80	114.80
19	2 pcs	Rear bumper seal @\$46.69	Essential	93.38	93.38
20	1 pc	Exhaust muffler/tailpipe	Bent	751.44	Refer labour charges XR
21	2 pcs	Exhaust muffler/tailpipe mounting @\$17.00	Serviceable	34.00	Rejected X nn
Less : 25% by Pro Plus Automobile Engineers				1585.72 25% 1189.29	3473.68 868.42
Sub - Total				7177.72	2605.23

APPRAISEMENT SCHEDULE

Registration No: SKW 3224 A

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$ ¢	Revised Amount \$ ¢
			B/F	7177.72	2605.23
		<u>PARTS REPLACEMENT- SPECIAL NETT ITEMS</u>			
1	1 set	Bootlid inner trim clip/fastener	Essential	50.00	30.00 X <i>an</i>
2	1 set	Rear end panel inner garnish clip/fastener	Essential	40.00	20.00 X <i>an</i>
3	1 set	Rear bumper clip/fastener	Essential	50.00	30.00
4	1 set	Rear bumper reverse sensor	Malfunctioned	350.00	250.00 200
5	2 pes	Terostat @\$80.00	Essential	160.00	120.00 X <i>an</i>
					230
Sub - Total				7827.72	3055.23

PRO PLUS AUTOMOBILE ENGINEERS

Continuation Sheet No: 3

APPRAISEMENT SCHEDULE

Registration No: SKW 3224 A

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$ £	Revised Amount \$ £
			B/F	7827.72	3055.23
		<u>LABOUR & MISC. CHARGES</u>			
1		To disconnect rear wire harness of rear bumper reverse sensors to facilitate repairs, reconnect & check functions including to replace/recalibrate rear bumper reverse sensors to specifications.		80.00	50.00 ✓
2		To dismantle/transfer/rebuild bootlid fittings/ancillary accessories etc to new bootlid.		160.00	Rejected X n/n
3		To dismantle/install rear luggage fittings/ancillary attachments, trims, garnishes, spare tyre, tools etc to facilitate repairs.	1189.29 2301.00 790.00	160.00	60.00 40
4		To check diagnostics of vehicle management/control units, reset memories to specification etc.	2209.29	120.00	Rejected X n/n
5		To dismantle/renew the rear accident damaged portion. To heat, cut/weld rear end panel including to heat, knock-out, reshape, straighten, orientate & align bootlid & its inner reinforcement, bootlid hinge o/s & n/s, bootlid striker, rear fender o/s & n/s, rear door lock pillar/dog leg o/s & n/s, rear door inner lock o/s & n/s, o/s & n/s rear door & their inner reinforcement, rear compartment floor/tyre well panel etc to symmetrical dimensions.	209 1767.43 H/s - 1750 3 days	1250.00	1000.00 300
6		To putty/primer application and spray painting including touch-up affected areas with polyurethane paint.)))		
7		To rustproofing & cavities preservation to the replaced and repaired panels.))	1250.00	400 800.00
Grand - Total				10847.72	4965.23

Note: The repairer has agreed to undertake the repairs at a contract lump sum of \$4,000.00 NETT, corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative option for the recommended replacement components to either be repaired or be replaced.

Pro Plus Automobile Engineers

ERROL TAN

B.A.Econ (Hons), UK


Dip. Auto Engr. & Motor Trade Management, UK
Automobile Engineer & Licensed Appraiser

PRO PLUS AUTOMOBILE ENGINEERS

IMPACT OF VEHICLE

Direction of Impact (←→)

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered onto the rear portion of the vehicle.



SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT



Damage Area/s:

Damages sustained were the bootlid & its inner reinforcement- dented/bent, bootlid hinge o/s & n/s- bent/misaligned, bootlid inner lock/striker- bent inwards/shifted/disrupted, rear end panel- thrust inwards/buckled, rear bumper assembly, rear fender o/s & n/s- buckled, rear door lock pillar/dog leg o/s & n/s- buckled/sandwiched with o/s & n/s rear door assemblies resulting in their inner locks- shifted/misaligned, rear compartment floor/tyre well panel- buckled etc.

Note : Follow-up reinspection of damaged components & works-in-progress on 23 October 2018.

Follow-up reinspection of vehicle on 29 October 2018 after spray painting & noted that the listed components as per our recommendations were replaced and repaired accordingly.

ESTIMATE

The estimate submitted by **M/s Hoe Keng Motor Service & Trading** as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. As instructed, we have/have not authorised the repairs.

	Repairer's Estimate	Our Recommendation	
Spare Parts :	7827.72	3055.23	Estimated number of
Labour Charges :	1250.00	1000.00	days for repairs: 6
Paint Work :	1250.00	800.00	
Towing Charges :			Number of photographs
Others :	520.00	110.00	taken at time of
TOTAL	10847.72	4965.23	static inspection: 25

Remarks: The repairer has agreed to undertake the repairs on a contract lump sum of \$4,000.00 NETT corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

NOTE: The revised estimate was made from a visual inspection. Any discrepancies or unseen damage/s should be notified with the company within 7 (seven) days from the date thereof. Otherwise, the revised amount should deem to be valid.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III18017610/R1qbs2-1		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 31-12-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 3112A	Veh. Inspected	SKW 3224A
	Policy No.	MCOM0015	Coverage (\$)	0.00
	Claim No.	MCT18090613	Excess (\$)	0.00
	Assign From	STANLEY LAI	Assign Date	20/12/2018
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA COROLLA ALTIS 1.6	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	MR053REH104541168	Colour	GREY
	Odometer	65197	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55R16	YOKOHAMA	6 mm
	L/H Front Tyre	205/55R16	YOKOHAMA	6 mm
	R/H Rear Tyre	205/55R16	YOKOHAMA	6 mm
	L/H Rear Tyre	205/55R16	YOKOHAMA	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	21/09/2018	Inspection Date	23/10/2018
	Survey held at	HOE KENG MOTOR SERVICE & TRADING BLK 7 PIONEER ROAD NORTH #01-43 SINGAPORE 628459		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 3224A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	NOT NECESSARY	754.70	-
1	BOOTLID 'TOYOTA' MOTIF	NOT NECESSARY	50.12	-
1	BOOTLID 'COROLLA' EMBLEM	NOT NECESSARY	46.48	-
1	BOOTLID 'ALTIS' EMBLEM	NOT NECESSARY	46.48	-
1	BOOTLID OUTER HANDLE (CHROME)	NOT NECESSARY	231.30	-
2	BOOTLID REFLECTOR @ \$401.10	NOT NECESSARY	802.20	-
2	BOOTLID HINGE @ \$78.60	NOT NECESSARY	157.20	-
1	BOOTLID INNER LOCK C/W SENSOR	NOT NECESSARY	379.20	-
1	BOOTLID DRAUGHT WEATHERSTRIP	NOT NECESSARY	266.40	-
2	TAILLAMP ASSEMBLY @ \$486.60	SERVICEABLE	973.20	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	581.20	-
1	REAR END PANEL INNER GARNISH	NOT NECESSARY	271.40	-
1	REAR BUMPER	DENTED / DISTORTED	639.90	639.90
2	REAR BUMPER ABSORBER DAMPER BRACKET @ \$123.34	NOT NECESSARY	246.68	-
1	REAR BUMPER BEAM	BENT / BUCKLED	389.00	389.00
2	REAR BUMPER BRACKET @ \$104.60	BENT / TWISTED	209.20	209.20
2	REAR BUMPER SIDE SUPPORT @ \$69.72	BENT	139.44	139.44
2	REAR BUMPER SIDE RETAINER @ \$57.40	CRACKED	114.80	114.80
2	REAR BUMPER SEAL @ \$46.69	ESSENTIAL	93.38	93.38
1	EXHAUST MUFFLER / TAILPIPE	TO REPAIR SEE LABOUR	751.44	-
2	EXHAUST MUFFLER / TAILPIPE MOUNTING @ \$17.00	NOT NECESSARY	34.00	-
	LESS 25% DISCOUNT		-	-396.43
			7,177.72	1,189.29
SPECIAL NETT ITEMS				
1	SET BOOTLID INNER TRIM CLIP / FASTENER (SN)	NOT NECESSARY	50.00	-
1	SET REAR END PANEL INNER GARNISH / FASTENER (SN)	NOT NECESSARY	40.00	-
1	SET REAR BUMPER CLIP / FASTENER (SN)	ESSENTIAL	50.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	MALFUNCTIONED	350.00	200.00
2	TEROSTAT @ \$80.00 (SN)	NOT NECESSARY	160.00	-
			650.00	230.00

Report Ref No. CS3/III18017610/R1qbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISCONNECT REAR WIRE HARNESS OF REAR BUMPER REVERSE SENSORS TO FACILITATE REPAIRS, RECONNECT & CHECK FUNCTIONS INCLUDING TO REPLACE / RECALIBRATE REAR BUMPER REVERSE SENSORS TO SPECIFICATIONS.		80.00	50.00
	TO DISMANTLE / TRANSFER / REBUILD BOOTLID FITTINGS / ANCILLARY ACCESSORIES ETC TO NEW BOOTLID.	NOT NECESSARY	160.00	-
	TO DISMANTLE / INSTALL REAR LUGGAGE FITTINGS / ANCILLARY ATTACHMENTS, TRIMS, GARNISHES, SPARE TYRE, TOOLS ETC TO FACILITATE REPAIRS.		160.00	40.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	120.00	-
	TO DISMANTLE / RENEW THE REAR ACCIDENT DAMAGED PORTION. TO HEAT, CUT / WELD REAR END PANEL INCLUDING TO HEAT, KNOCK-OUT, RESHAPE, STRAIGHTEN, ORIENTATE & ALIGN BOOTLID & ITS INNER REINFORCEMENT, BOOTLID HINGE O/S & N/S, BOOTLID STRIKER, REAR FENDER O/S & N/S, REAR DOOR LOCK PILLAR / DOG LEG O/S & N/S, REAR DOOR INNER LOCK O/S & N/S, O/S & N/S REAR DOOR & THEIR INNER REINFORCEMENT, REAR COMPARTMENT FLOOR / TYRE WELL PANEL ETC TO SYMMETRICAL DIMENSIONS. INCLUSIVE OF THE REPAIR OF REAR END PANEL }		1,250.00	300.00
	AND EXHAUST MUFFLER / TAILPIPE. }		-	-
	TO PUTTY / PRIMER APPLICATION AND SPRAY PAINTING INCLUDING TOUCH-UP AFFECTED AREAS WITH POLYURETHANE PAINT. }		1,250.00	400.00
	TO RUSTPROOFING & CAVITIES PRESERVATION TO THE REPLACED AND REPAIRED PANELS. }		-	-
			3,020.00	790.00
	GRAND TOTAL		10,847.72	2,209.29
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,750.00

Report Ref No. CS3/III18017610/R1qbs2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.