Menmen . Makus	ASSIGNMENT (Office	
Mulmen Chong Boon Sen	of C11	Date/Time: 20/12/18/ 1.34P
Estimated Cost	Bill to:	
OD (TY) WS/TP RES/OD RES/EV	90 m	914n 7 /s/
	SLJ 4937B	Insured: SJW 74Y
at Workshop m/s Siong	Hei Motor	Tel: 6555 7272
of No-1 Keylei		
Policy No. DMPCSN304943	(80] Claim N	No: 3NM18005849 CO2
Sum Insured:	Exces	88.
Make of Veh:	٠,	D.O.A 15/12/2018 .
(Client's Record)		D.O.R. 15[12] 0016 .
ACHTEROPOLICA AND ACTION ACTION AND ACTION ACTION ACTION AND ACTION ACTIO	м)	
CA / REV / REP. / REV 24 HRS	erson Contacted: Ah hu	H.O.D. Endorsement
CA / REV / REP. / REV 24 HRS	erson Contacted. Ah hu	H.O.D. Endorsement
CA / REV / REP. / REV 24 HRS (Date/Time; 1.5 pm 2012 18 P	erson Contacted. Ah hu	H.O.D. Endorsement
Date/Time: 1.5 pm 2012 18 Por Action/Instruction ( St. J. 44318 - X	erson Contacted. Ah hu	H.O.D. Endorsement  Vehicle (IN)LOUT
Date/Time: 1.5 pm 20112118 Por Date/Time: Action/Instruction ( St. J. 44318 - X	erson Contacted Ah hu  SEStimate	H.O.D. Endorsement  Vehicle (IN)LOUT

(08/11/13) wef  ASS. REC. BY: Marcus  REF:	C71/
ASS, REC. BI. 1990 C.	ASSIGNMENT
From: Date:	Veh No: Start M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD ITP / WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: SLJ 4937	Make: Next 3 c.c 1496
at Workshop m/s Signy her of Insured:	Sp.Reading / 25-36/ T/Radio: Insured / Std / NI / NA Eng/No:
Policy No.  Claims No.  Sum Insured: Excess:	C/No: JM 6 BN 22 A & P 0 1 1 2 S 2  Gen. Cond: Good / Fair / Poor / Burnt  Steering: Inorder / Jammed / Leaked / Burnt or
Sum mourou.	Brake: Inorder / Jammed / Leaked / Burnt or
(Client's Record)  Make of Veh:	Modi: Nil) / S/Rim / STD A/Rim or
	Tyre Size: F: 205/60216
(Policy Condition)	R:  BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Remark: The veh had commenced its repair at the time of inspection.	TOYO LYOKO or
Bal. or Market Value:	Front 6 Rear
IDAC Accident Rport: Consistent? : Yes or No	
GIA LPR Seen: Consistent? : Yes or No	52/12/0
Est. Repairs: days Res.: Yes or N Lum Sum: % 3 Val.: Yes or N	
CA / REV / REP. / 24 HRS LTA SO Vehi	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or cle: IN / OUT
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction  W/// S \$ 5 (00 Cong	Find with AH hurf.
24/2/18 Confined 4/5 \$ 5 (\$5,691.16 Red	5,100/- @ 5 days with Marais.
RE	CEIVED 2 8 DEC 2018
Date/Time, File Pass to? : Prell. Report	Days Of Repair:
1) Typ. 44 : Final Report Date/Time, File Return to?	Resurvey No. of Trip:   Survey Fee: Transportation:
2)	Add Fee: : Site Insp (\$ )S+RSSI
	: Interview (\$ ) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$ 5,100/- L/S)	: Weekend (\$ )
100 5M 50 35/0000000 5000 533/00	TOTAL

# ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Ad) Assigned	Adj Rpt	Ad) Sul	amitted	Ins Auth'ed	Status	
Main	18 Dec 2018		20 Dec 2018 13:34 Assign					New A	ssignment   Case
	Main	Re	ference		Claim Details		Docume	nts	Show All
CLAIM SU	BFOLDER DE	TAILS			APPRILITATION OF THE PARTY.	[Create	ed by insurer]		
Insured:									
Main Claimant:	SUBRAMA	NIYAN KABILAN	1						
Vehicle Reg No.:	SLJ4937	′В			Date of Loss:	ss: 15/12/2018 00:00 - :59			
Claim Type	: TP / SNM	118D05849C02			Policy/Cover Note No.:	DMPCSN3049431801			
Vehicle Reg No. (Insured):	SJW74Y				Policy No. (Claimant):				
					Excess:	5\$0.00			
Repairer:	Siong Hai	Motor & Trading	(HQ) NO 1 KAI	KI BUKIT AV	E 6, #02-03 AU	TOBAY @	KAKI BUKIT, 4178	83 Kaki Bul	kit - Tel:
Handling Insurer:	China Tair	ping Insurance (	Singapore) Pte	. Ltd. (HQ)	- Tel: 6389 611	l1 [Han	dled by Chong Be	oon Sen]	
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Final Rpt	due 02/	01/2019]		
Adj Asg. Remarks:	NO EST, AS	SSIGN MARCUS CH	IUA AS SJE.						
ASSOCIAT	TED MAIL RE	CEIVED						View All	Compose Case M
There are n	no mail for this	case.						3	
ALL ASSO	CIATED TAS	KS⊡				View A	II   Search Tasks	Create N	ew Task   Compl
Due Date	e Priority	Type Task	Group Subj	ect Han	dler Assign	ned By	Completed O		ated On Dor
No results.					10.70	38			

#### Lucas Lee

From:

Ruby Ong <ruby@htapartners.com.sg>

Sent:

Thursday, 20 December, 2018 10:59 AM

To:

Lucas Lee

Cc:

Chong Boon Sen

Subject:

RE: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY -CTI REF: SNM18D05849C02 YR

REF: TCL.GCN.ro.50515.18.shm - ACCIDENT INVOLVING SU4937B & SJW74Y ON

15/12/18

Importance:

High

WITHOUT PREJUDICE

URGENT

Dear Sir

We refer to your email dated 19 December 2018.

Our client is agreeable to appoint Marcus Chua as the single joint expert to carry out the pre-repair survey for <u>SU</u> 4937B.

Please make the necessary arrangements with the contact person. The details are as follows:

Venue

Siong Hai Motor & Trading

1 Kaki Bukit Avenue 6 #02-03 Autobay Singapore 417883

Contact Person:

Mr Ah Huat (H/P: 6555 7272)

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards, Ruby Ong Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road #02-10/12 The Riverwalk

Singapore 058416 Tel: 6533 0212 ext 278

Fax: 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Lucas Lee [mailto:lucas.lee@sg.cntaiping.com]
Sent: Wednesday, December 19, 2018 2:52 PM

To: Anil Kumar <anil@htapartners.com.sg>

Subject: RE: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY -CTI REF: SNM18D05849C02 YR REF:

TCL.GCN.ro.50515.18.shm - ACCIDENT INVOLVING SLJ4937B & SJW74Y ON 15/12/18

#### Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING	3
Kelvin Ang	
SEE CHEW S	ENG
MOHD FADH	ILAH BIN OSMAN
XING QUO Q	IANG
KENNETH KC	NG
SIMON HO	
CHUA WEIJII	
MARCUS CHI	JA
HENRY NG	

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Case Handler: Chong Boon Sen

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181

Fax (65) 6222 7175/6224 7478 Email: lucas.lee@sg.cntaiping.com Website: www.sg.cntaiping.com



Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Anil Kumar [mailto:anil@htapartners.com.sg]

Sent: Monday, 17 December, 2018 4:48 PM

To: Claims Dept of CTI

Cc: Ruby Ong

Subject: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - YOUR REF: SJW74Y & OUR REF: TCL.GCN.ro.50515.18.shm -

ACCIDENT INVOLVING SLI4937B & SJW74Y ON 15/12/18

Dear Sir,

### ACCIDENT INVOLVING SLJ4937B & SJW74Y ALONG / AT HAVELOCK ROAD ON 15/12/18 @ TIME: 16:20 HRS

We are instructed to notify you of the above-mentioned road traffic accident which involves our client's vehicle registration number SLJ4937B and vehicle registration number SJW74Y driven by your insured at the material time.

As a result of the accident, our client's motorcycle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,

Anil (Secretary) M/s Hin Tat Augustine & Partners 20 Upper Circular Road #02-10/12 The Riverwalk Singapore 058416

Tel: 6533 0212 ext.256 Direct Fax: 63383536 Fax: 6533 0313

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

SGCARMART.COM

Login Sign up

New Cars

"Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

ulliu.

EQUINIX

(I)X

Frost & Sullivan highlights opportunities & challenges on digital health in Singapore >

> Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

New 5 Years Coe Renewal Toyota Altis 1.6A



2.88%p.a Lowest Interest@GV Cars Financing \$1800 Downpayment Monthly From **\$558** GV Credit Pte Ltd StarAd

Auto Inn click here to vie our PRISTINE USED CARS at GREAT PRICES

Browse by Category

Post an Ad

Advertiser Login

Ways of Selling

« Back ( 1 2 ) Next =

Sort by Date Posted Advanced Search M ✓ 20 results/page ✓

Submit (

28 vehicles

mazda 3

Model

Price

Depreciation

Reg Date 2016

Mileage Eng Cap

Veh Type

Status

Search Selection

mazda 3

\$8,190 /vr

1.496 cc

Hatchback

Available

PERMINANT.

Available

Mazda 3 HB 1.5A Deluxe

\$64,800

29-Jan-2016

43,000 km

Sporty And Rare Hatch Back! Sedan Is Too Mainstream. Fully Maintained And Serviced By Agent. 2.28% Finance For Promotion Period! Drop By Our AML Showroom For Complimentary 1 Year Service Shield Packag...

Hua Yang Credit Pte Ltd

Posted: 20-Dec-2018 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 HB 1.5A

\$69.300

\$7.890 /vr

12-Dec-2016

1.496 cc

38,000 km

Hatchback

Available

Graded A by

20% Deposit! Under Warranty And Free Servicing With Agent, Superb Condition, Buy With A Peace Of Mind, Easy Loan / Trade In Available.

Posted: 20-Dec-2018 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.5A Sunroof

\$63,800

\$7,750 /yr

20-Jun-2016

1.496 cc

50,000 km

Sedan

Available

Accident Free, Low Down Payment Drive Away Options! Flexible In House Financing And High Trade In Available! Fuel Efficient! Upgraded Infotainment System With Reverse Camera! Call Now For Viewing!

Hua Yang Credit Pte Ltd

Posted: 20-Dec-2018 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.5A

\$56,000

\$6,950 /yr

31-Mar-2016

1,496 cc

24,000 km

Sedan

Available

1 Owner And Low Mileage, Agent Maintained, Warranty Til MAR 2019 And One Free Servicing Left With Agent, Pristine Condition, As Good As New Both Interior And Exterior. Consignment Unit, High Loan Assi...

Posted: 19-Dec-2018 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Customized Car Pedal Cover

Mazdaspeed Customized Car Pedal Cover

More info about this product



Mazda 3 1.5A

\$68,800

\$7,830 /yr

29-Dec-2016

1.496 cc

37.000 km

Available

Just Arrived! Well Maintained And Very Good Condition, High Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today.

Posted: 19-Dec-2018 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.5A

\$63,000

16-Feb-2016

1,496 cc

62,000 km

Sedan

Available

DIRECT OWNER

Not Driving Much As Been Posted To USA For Work Recently And Decide To Sell Off. Brand New Condition. Accident Free, Just Upgraded New Rims And Tyres.

Posted: 18-Dec-2018 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda

Mazda 3 1.5A Sunroof Compare

\$65,800

\$8,300 /yr

30-Mar-2016

1,496 cc

58,000 km

Sedan

Available WATER TO STREET

https://www.sgcarmart.com/used\_cars/listing.php?MOD=mazda+3&PRC=0&DEP=0&RGD=2016&VE...

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5825Z
Vehicle Details	
Vehicle No.:	SLJ4937B
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	P520394861
Chassis No.:	JM6BN22A8H0111232
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$17,330.00
Original Registration Date:	13 Dec 2016
First Registration Date:	13 Dec 2016
Transfer Count:	2
Actual ARF Paid: Intended PARF Rebate Details	\$12,330.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Dec 2026
PARF Rebate Amount:	\$9,247.00
Intended COE Rebate Details	
COE Expiry Date:	12 Dec 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$54,200.00
COE Rebate Amount:	\$41,085.00
Total Rebate Amount:	\$50,332.00

The information contained herein is correct as at 20 Dec 2018

ОК

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available. aforesaid.

	ACCIDENT STATEMENT	
Date Of Report	17/12/2018 19:10	
Date Of Accident	15/12/2018 16:20	
Exact Location Of Accident	HAVERLOCK ROAD	
Country/State of Loss	SINGAPORE	

Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLJ4937B
Insured/Policyholder	14.45 475 美元战争的 14.75 年后是全部战争的战争的争争。
Name Of Registered Owner	AMV PTE. LTD.
Co Reg No	201505825Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98583956
Vehicle Particulars	

Vehicle Particulars	
Manufacturer	MAZDA
Model	3-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	

Are you claiming under your own insurance policy for repair to your vehicle?

If No. Please state action to be taken THIRD PARTY PRIVATE CAR

Vehicle Category Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD Name of Insurance Company COMPREHENSIVE Type Of Coverage

Fleet Policy NO

Policy Number 5095333202-01

Cover Note Number

Driver SUBRAMANIYAN KABILAN Name of Driver G2392472U Passport No/FIN Date Of Birth 24/01/1993 OUTDOOR Occupation 17/07/2017 Date Of Driving Pass 1 YEAR AND 4 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-91396944 Mobile Number

Fax Number Contact Number

NOEMAIL EMail Address

Address

47 BENDEMEER ROAD #04-1473

Postcode

330047

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

NO 2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance? Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

SJW74Y

Vehicle Make/Model/Colour

AUDI

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan Pg. 1

JILLINIII WIII

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

understand, admowledge, agree and consent that

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
  - (Iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
  - my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - ()) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud. regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders.

ignature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT(VAC)


23 KAKI BUKIT AVE 4
Reporting Sength Ber 917993 Signature

Tel: 67416697 Namer NRIC/FIN NG-BX: 67492305

Email: vackb@singnet.com.sg

GIAPMS SHARE FRANKSHIP VS

#### Sketch Plan #2 Pg. 1



#### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 15/12/18 at around 16:20, I was driving along Kim Seng Road on have 3 and Usartina to take the exit to Haudock Road. There was a white dotted line on the road
and roughly I was about 80m behind the white line As the vehicle infront of me had
brake and stopped, I too Followed behind and brake to wait. And roughly about 8 to 10 seconds later John of number 57 w 744 which was behind my vehicle came hitting the back
rear of my volide.

DECLARATION enectare the foresting particulars are true in every respect, 2015058252

Policyholder's Signature Date & Time:

Oriver's Signature (If driver is not the policyholder) Date & Time:

GIARMC TheidsPlanForm\_V3

### SIONG HAI MOTOR AND TRADING

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 65557272

Fax: 67411019

H/P: 93365311 (Ah Huat)

Vehicle NoSLJ4937B

Model:MAZDA 3

1 Not Alloans - Work - 1/5 # 5100 - 20/11/18

QTY	<u>List Items</u>	Price \$
1	Rear bootlid	57/Serf 1078.60
1	Rear bootlid logo	Nec 65.80
1	Rear boot EMBLEM "Mazda"	NUC 58.20/
1	Rear boot EMBLEM "3"	Nec 34.40
1	Rear boot EMBLEM "SKYACTIV"	68.60
2	Rear boot lid lamp L/R (1) 48.6	11 682.40 ×
1	Rear boot lid inner lock	4 ~45hM 250.30
1	Rear boot lid lock striker	1/1 65.50,X
1	Rear boot lid inner trim	11 224.10×
2	Rear boot lid L/R hinges (1) 115	イフ 230.00 火
1	Rear boot lid weatherstrip	Nec 124.60/
2	Rear L/R boot lid licence lamp (1) 48.6	A 1 97.20 €
2	Rear bumper L/R tow hook covers (1) 42.5	17 85.00 <
2	Rear L/R bumper reflectors (1) 89.5	179.00 ×
1	Rear bumper reinforcement	D/But 541.70
2	Rear L/R bumper side retainers (1) 42.5	85.20
2	Rear bumper top clips (1) 12.6	25.20
2	Rear bumper top clips holders (1) 14.2	17 28.40 X
1	Rear end panel	77 447.60
1	Rear end panel inner trim	LNI 241.20
1	Rear floor board	1 1 361.20 €
2	Rear L/R floor sponge trays (1) 110.2	11 220.40
2	Rear L/R fender inner shields (1) 68.6	11 1783.80×
2	Rear L/R taillamps (1) 849.6	CNL 1699.20
2	Rear L/R taillamps panels (1) 155.6	2.07 R 311.20 K
1	Rear smart keyless antenna	17 241.20 X
1	Rear bumper	2º/0e 1074.80
	Leader-Control Service (COLD TO COLD COLD COLD COLD COLD COLD COLD COL	10304,80

Total Less 20% 8658.20 1731.64

\$6,926.56

Special	Nett	Items
Special	Merr	ILCIIIS

10	Rear boot inner trim clips (1) 4.5	17	45.00 €
6	Rear bumper clips (1) 4.5	w	27.00
10	Rear fender inner trim clips (1) 5.5	11	55.00 ≪
2	Rear exhaust mountings (!) 42.6	11	85.20×
4	Rear taillamp side clips (1) 10.6	17	42.40 /
1set	Rear number plate with casing	na,	120.00 /
1set	Rear bumper PDC sensors	slud	320.00 I 00
1	Rear reverse camera	NA	500.00 ⊁

\$ 1,194.60

#### **Labour Charges**

Towing charges	11	100.00
To remove and refix rear reverse sensors		120.00 50
To respray undercoating		220.00 60
To remove and refix interior trims to assist repair		150.00 80
To check electrical wiring		80.00 20
To respray painting and ETC		1000.00 800
Panel beating,cut,weld,panel,remove and		1000.00 600
replacing above parts		

\$2,670.00

**ESTIMATE AND LABOUR GRAND TOTAL** 

12108 44 \$10,791.16



6473.72

#### LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI18022832/USD3N2

Date:

02/01/2019

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMPCSN3049431801

Claimant Vehicle No:

SLJ4937B

Insured Vehicle SJW74Y No:

TP

Date of Loss:

15/12/2018

Nature of

Claim:

Claim No:

SNM18D05849C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLJ4937B

Make & Model:

MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)

Engine No:

P520394861

Reg. Date:

13/12/2016 (Man. Year: 2016)

Chassis No: Odometer:

JM6BN22A8H0111232 125361 km

Colour:

Red

**Engine Capacity:** Market Value/New Car 1496 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

205/60R16

Rear Tyre Size:

205/60R16

Front Tyre Size: Front Left Side: Front Right Side:

Campeon 6 mm Campeon 6 mm Rear Left Side: Rear Right Side: Campeon 6 mm Campeon 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts	Repairer's 9,438.44	Adjuster's 4,863.32	Difference 4,575.12	Diff % 48.47
Miscellaneous Items	0.00	0.00	0.00	7400-7500
Labour Paintwork Labour	2,670.00	1,610.00 0.00	1,060.00 0.00	39.70
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,108.44	6,473.32	5,635.12	46.54
Approved Total (Overridden) (S\$)		5,100.00	11 1147	
Nett Amount (S\$)	12,108.44	5,100.00	7,008.44	57.88

INSPECTION

Date of Assignment:

20/12/2018

Date Inspected:

20/12/2018 Inspected At:

Siong Hai Motor & Trading (HQ) NO 1 KAKI BUKIT AVE 6, #02-03

AUTOBAY @ KAKI BUKIT

Singapore 417883

Estimated Period of Repair:

5.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

#### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Jan 2019)

MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0) 143 Parts:

Labour: (Price-denominated Standard List) Repairer's

Print Code: (Unsubmitted, no print-code for SLJ4937B) These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*

Recom	mended	Parts
1100011	IIIOIIGO	4 1 4110

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	1,078.60 FL	*1,078.60 FL
2	1		*REAR BOOTLID LOGO	Necessary	65.80 FL	*65.80 FL
3	1		*REAR BOOT EMBLEM MAZDA	Necessary	58.20 FL	*58.20 FL
4	1		*REAR BOOT EMBLEM 3	Necessary	34.40 FL	*34.40 FL
5	1		*REAR BOOT EMBLEM SKYACTIV	Necessary	68.60 FL	*68.60 FL
6	2		*REAR BOOT LID LAMP L/R	Not Necessary	682.40 FL	*-FL
7	1		*REAR BOOT LID INNER LOCK	Twisted/Shorted	250.30 FL	*250.30 FL
8	1		*REAR BOOT LID LOCK STRIKER	Not Necessary	65.50 FL	*-FL
9	1		*REAR BOOT LID INNER TRIM	Not Necessary	224.10 FL	*-FL
10	2		*REAR BOOT LID L/R HINGES	Not Necessary	230.00 FL	*-FL
11	1		*REAR BOOT LID WEATHERSTRIP	Necessary	124.60 FL	*124.60 FL
12	2		*REAR L/R BOOT LID LICENCE LAMP	Not Necessary	97.20 FL	*-FL
13	2		*REAR BUMPER L/R TOW HOOK COVERS	Not Necessary	85.00 FL	*-FL
14	2		*REAR L/R BUMPER REFLECTORS	Not Necessary	179.00 FL	*-FL
15	1		*REAR BUMPER REINFORCEMENT	Dented/Bent	541.70 FL	
16	2		*REAR L/R BUMPER SIDE RETAINERS	Bent	85.20 FL	*85.20 FL
17	2		*REAR BUMPER TOP CLIPS	Necessary	25.20 FL	
18	2		*REAR BUMPER TOP CLIPS HOLDERS	Not Necessary	28.40 FL	*-FL
19	1		*REAR END PANEL	Dented	447.60 FL	*447.60 FL
20	1		*REAR END PANEL INNER TRIM	Twisted	241.20 FL	*241.20 FL
21	1		*REAR FLOOR BOARD	Not Necessary	361.20 FL	
22	2		*REAR L/R FLOOR SPONGE TRAYS	Not Necessary	220.40 FL	*-FL
23	2		*REAR L/R FENDER INNER SHIELDS	Not Necessary	1,783.80 FL	*-FL
24	2		*REAR L/R TAILLAMPS	Cracked	1,699.20 FL	*1,699.20 FL
25	2		*REAR L/R TAILLAMP PANELS	Repair	311.20 FL	*-FL
26	1		*REAR SMART KEYLESS ANTENNA	Not Necessary	241.20 FL	*-FL
27	1		*REAR BUMPER	Dented/Deformed	1,074.80 FL	*1,074.80 FL
28	10		*REAR BOOT INNER TRIM CLIPS	Not Necessary	45.00 FS	
29	6		*REAR BUMPER CLIPS	Necessary	27.00 FS	*27.00 FS
30	10		*REAR FENDER INNER TRIM CLIPS	Not Necessary	55.00 FS	*-FS
31	2		*REAR EXHAUST MOUNTINGS	Not Necessary	85.20 FS	
32	4		*REAR TAILLAMP SIDE CLIPS	Not Necessary	42.40 FS	*-FS
33	1		*SET REAR NUMBER PLATE WITH CASING	Not Necessary	120.00 FS	
34	1		*SET REAR BUMPER PDC SENSORS	Shorted	320.00 FS	*200.00 FS
35	1		*REAR REVERSE CAMERA	Not Necessary	500.00 FS	*-FS
F=Fr	anchise	part. S=Spc	Nett. L=ListItemDisc.	<i>40</i>		
				Sub Total (S\$)	11 499 40	6 022 40

Sub Total (S\$) 11,499.40 6,022.40 - List Item Discount on L Items 20.00/20.00% (S\$) 1,159.08 2,060.96

> Total Parts (S\$) 9,438.44 4,863.32

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items There are no new miscellaneous items selected.

#### Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
r Items			
TOWING CHARGES	New	100.00	
TO REMOVE AND REFIX REAR REVERSE SENSORS	New	120.00	50.00
TO RESPRAY UNDERCOATING	New	220.00	60.00
TO REMOVE AND REFIX INTERIOR TRIMS TO ASSIST REPAIR	New	150.00	80.00
TO CHECK ELECTRICAL WIRING	New	80.00	20.00
TO RESPRAY PAINTING AND ETC	New	1,000.00	800.00
PANEL BEATING,CUT,WELD,PANEL,REMOVE AND REPLACING ABOVE PARTS	New	1,000.00	600.00
Gross Labour Cost (S		2,670.00	1,610.00
	TITLEMS TOWING CHARGES TO REMOVE AND REFIX REAR REVERSE SENSORS TO RESPRAY UNDERCOATING TO REMOVE AND REFIX INTERIOR TRIMS TO ASSIST REPAIR TO CHECK ELECTRICAL WIRING TO RESPRAY PAINTING AND ETC PANEL BEATING, CUT, WELD, PANEL, REMOVE AND REPLACING ABOVE PARTS	TITEMS TOWING CHARGES TO REMOVE AND REFIX REAR REVERSE SENSORS TO RESPRAY UNDERCOATING TO REMOVE AND REFIX INTERIOR TRIMS TO ASSIST REPAIR TO CHECK ELECTRICAL WIRING TO RESPRAY PAINTING AND ETC PANEL BEATING, CUT, WELD, PANEL, REMOVE AND New	TOWING CHARGES TOWING CHARGES TO REMOVE AND REFIX REAR REVERSE SENSORS TO RESPRAY UNDERCOATING TO REMOVE AND REFIX INTERIOR TRIMS TO ASSIST REPAIR TO CHECK ELECTRICAL WIRING TO RESPRAY PAINTING AND ETC PANEL BEATING, CUT, WELD, PANEL, REMOVE AND REPLACING ABOVE PARTS  New 100.00 10

< END OF ESTIMATES >