

10/03/98

ASS. REC. BY:

REF:

CIT/PIR032837/D

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

of Churni Mohr

Date/Time:

17/12/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 40298

Insured:

At Workshop m/s

Tel:

of

Policy No:

Claim No:

SHA 40298

Sum Insured:

Excess:

Make of Veh:

D.O.A.

9/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SHA 40298-X

\$380

MCD818159630 / ComfortDelGro Engineering Pte Ltd - Laying
 ENTRY DATE & TIME: 11/12/2018 07:21
 SUBMITTED BY: Catherine Poh May Jian

Your NCD will be affected due to late reporting
 Actual e-Filing Submission Date & Time: 11/12/2018 07:28

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 11/12/2018 07:21
 Date Of Accident 09/12/2018 18:45
 Exact Location Of Accident SENTOSA GATEWAY (IN FRONT VIVOCITY BUILDING)
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHA4029S
 Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
 Vehicle Particulars
 Manufacturer HYUNDAI
 Model IONIQ HYBRID
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
 Insurance Company
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number D-18088936MFSH
 Cover Note Number
 Driver
 Name of Driver CHUA POH GEK
 NRIC No S6820084I
 Date Of Birth 28/05/1968
 Occupation OUTDOOR
 Date Of Driving Pass 08/09/1987
 Driving Experience 31 YEARS AND 3 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-93887814
 Fax Number
 Contact Number
 EMail Address ERICHUAPG@HOTMAIL.COM

Address 209 06-1602 ANG MO KIO AVENUE 3
Postcode 560209
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions RAINING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (including Driver) 4

Passenger 1
NAME: : -
GENDER: : MALE

Passenger 2
NAME: : -
GENDER: : FEMALE

Passenger 3
NAME: : -
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJH93X
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver ZHU QICHAO
NRIC/Passport Number S7982832G

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRY RHT

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

CHUA POH GEK

Approximate Age

50

Injuries Sustain

NECK

Injured person in which vehicle?

SHA4029S

Were seat belts worn?

YES


Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SHA 4029S
SJH 93X



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Veh B (SJH 93X) Mr Zhu Qichao S7982832G

REG. NO. 199303821R

Driver's Signature

Date & Time: 10.12.18@0840HRS

Name: _____

NRIC/FIN No.: June Tan

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 4029S

DATE : 10.12.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet			\$ 2,253.80
	Bonnet Hinge (LH/RH)	\$	118.70	\$ 237.40
	Bonnet Lock			\$ 127.30
	Radiator Grille			\$ 1,227.50
	Front Bumper Cover			\$ 418.30
	Front Bumper Sponge			\$ 86.90
	Front Bumper Reinforcement			\$ 1,075.10
	Speaker Assy- VESS			\$ 154.40
	Radar Sensor			\$ 2,910.90
	Front Bumper Moulding Centre Upper (LH/RH)	\$	108.50	\$ 217.00
	Front Bumper Moulding (LH/RH)	\$	93.60	\$ 187.20
	Front Bumper Lower Stiffner			\$ 85.10
	Front Bumper Lip			\$ 35.10
	Front Bumper Bracket Top (LH/RH)	\$	35.00	\$ 70.00
	Front Bumper Bracket (LH/RH)	\$	28.00	\$ 56.00
	Front Bumper Side Bracket Support	\$	12.00	\$ 24.00
	Front Bumper Clips 10 pcs			\$ 22.00
	Headlamp Support Panel Assy			\$ 949.30
	Headlamp (LH/RH)	\$	1,198.80	\$ 2,397.60
	Day Light, LH			\$ 642.50
	Day Light, RH			\$ 642.50
	Day Light Wiring ,LH/RH	\$	585.50	\$ 1,171.00
	Radiator			\$ 884.80
	Radiator Blower Motor			\$ 378.00
	Radiator Fan			\$ 375.10
	Radiator Shroud			\$ 275.50
	Radiator Hose Upper			\$ 66.20
	Radiator Hose Lower			\$ 66.20
	Emblem-Blue Drive	\$	26.60	\$ 53.20
	Front Fender Shield (LH/RH)	\$	114.70	\$ 229.40
	Air Cleaner Assy			\$ 282.70
	Air Duct			\$ 96.80
	Aircon Condenser			\$ 663.60
	Aircon Suction & Liquid Hose			\$ 679.60
	Aircon Discharge Hose			\$ 148.50
	Wiper Panel Top Garnish			\$ 97.00
	Wiper Container			\$ 68.00
	Wiper Container Motor			\$ 78.00
	Front Wheel Hub Cap (RH)			\$ 175.10
	Front Chasis Member			\$ 1,314.80
	Engine Under Cover			\$ 469.40
	Engine Crossmember			\$ 1,803.90
	Engine Mounting, RH			\$ 580.90
	Wiring-Front			\$ 3,802.10
	Wiring-Engine			\$ 3,474.00

SHA 4029S

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Motor Assy, Hybrid Vehicle			\$ 4,833.00	
	Generator Assy, Hybrid Vehicle			\$ 3,358.10	
	Inverter Assy, w/Convertor			\$ 5,390.20	
	Hybrid Spare Tank			\$ 371.30	
	Hybrid Cooling Pipe Motor			\$ 432.20	
	Hybrid Inverter Bypass Hose-inlet			\$ 42.60	
	Hybrid Inverter Bypass Hose-Outlet			\$ 29.30	
	SUB TOTAL			\$ 45,510.40	
	LESS 20%			\$ 9,102.08	
	DISCOUNTED TOTAL			\$ 36,408.32	
	Front Number Plate			\$ 25.00	Nett
	Front No Plate Trim Cover			\$ 30.00	Nett
	Emblem-Blue Drive			\$ 26.60	Nett
				\$ 81.60	
	Labour Charge				
	Panel Beating			\$ 1,500.00	
	Spray Painting Charge			\$ 1,000.00	
	Wiring Charge			\$ 50.00	
	Tuff Kote			\$ 100.00	
	Towing Charge			\$ 50.00	
	Front Chassis Alignment Charge			\$ 400.00	
	FRT Wheel Alignment			\$ 120.00	
	Remove/Refix Aircon & Refill Gas			\$ 150.00	
	Remove/Refix Engine			\$ 650.00	
	Remove/Refix Dashboard			\$ 450.00	
	Remove/Refix Fuse Box			\$ 180.00	
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	
	TOTAL LABOUR			\$ 5,130.00	
	ESTIMATE TOTAL			\$ 41,619.92	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					