

Trans-cab Auto Services Pte Ltd**AAD1812-129**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5599X*Not Authored*
11 Sep @ 4800

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5599X

VF1ABL15AUC279400

RENAULT

LATITUDE

16.12.2018

AIG

PART		LIST	
1	FENDER PANEL FRT LH	\$	<i>B</i> 783.83 ✓
1	WHEELARCH FRT LH	\$	<i>S</i> 278.84 X
1	FENDER BRACKET LOWER LH	\$	<i>S</i> 15.79 X
1	FENDER INSULATOR LH	\$	<i>S</i> 130.84 X
1	DOOR PANEL FRT LH	\$	<i>M</i> 2,844.66 ✓
1	DOOR HINGE UPPER LH	\$	<i>H</i> 261.28
1	DOOR HINGE LOWER LH	\$	<i>H</i> 300.55
1	DOOR CHECK FRT LH	\$	<i>S</i> 194.77
1	DOOR LOCK FRT LH	\$	<i>H</i> 908.75
1	DOOR CATCH FRT LH	\$	<i>S</i> 131.23
1	DOOR HANDLE OUTER FRT LH	\$	<i>S</i> 477.76
1	DOOR HANDLE COVER FRT LH	\$	<i>S</i> 13.22
1	DOOR HANDLE MODULE FRT LH	\$	<i>S</i> 133.60
1	DOOR REGULATOR FRT LH	\$	<i>S</i> 505.19
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>S</i> 796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>S</i> 120.97
1	DOOR MIRROR ASSY LH	\$	<i>CM</i> 1,483.40 ✓
1	DRIVESHAFT LH	\$	<i>H</i> 1,914.79
1	STABILIZER BAR FRT L70Y	\$	<i>S</i> 604.65
2	STABILIZER LINK FRT L70Y	\$	<i>S</i> 117.22
1	STEERING PINION RACK L70Y	\$	<i>S</i> 4,413.11
1	AIR CLEANER BOX	\$	<i>S</i> 464.20
1	AIR CLEANER HOSE	\$	<i>S</i> 175.85
1	LOWER ARM LH L70Y	\$	<i>S</i> 685.76
1	KUNCKLE ARM LH L70Y	\$	<i>S</i> 846.98
1	ABSORBER FRT LH L70Y	\$	<i>S</i> 360.54
1	HEADLAMP LH	\$	<i>S</i> 1,184.43

Trans-cab Auto Services Pte Ltd

AAD1812-129

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5599X

	\$	20,148.69
10%	\$	2,014.87
	\$	18,133.82

Special Nett

1	FRONT DOOR STICKER 'Trans-cab'	\$	na	80.00	605a
1	FRONT DOOR STICKER 'Chassis'	\$	na	50.00	155a
1	REAR DOOR STICKER '6555 3333'	\$	na	80.00	X
1	DOOR CHECK BOLT	\$	na	22.69	} X
1	DOOR GUIDE SCREW	\$	na	10.85	
1	DOOR HINGE BOLT	\$	na	10.85	
1	DOOR HINGE NUT RH	\$	na	14.60	
1	DOOR CHECK BOLT	\$	na	22.69	
1	DOOR CHECK NUT	\$	na	3.75	
1	DOOR LOCK SCREW L70Y	\$	na	6.12	
1	DOOR CATCH SCREW L70Y	\$	na	10.06	} X
1	FRONT LEFT TYRE	\$	na	330.00	
1	FRONT LEFT TYRE RIM	\$	na	380.00	

TOTAL \$ 1,021.63**TOTAL PARTS \$ 19,155.45****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	400a
Putty and spray painting of the affected portion.	\$	3,000.00	72a
To rust-proofing of the affected areas.	\$	170.00	60a
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X

Trans-cab Auto Services Pte Ltd**AAD1812-129**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5599X

To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	na 380.00	X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	na 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	na 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	na 380.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	601
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	na 380.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	na 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00	X

TOTAL \$ 9,770.00**Over All Total \$ 28,925.45**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15 DAYS

3 days