PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D Tanfing 74 95749

7/1/182350pm

02days

Enun yunepair.

20-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6292 Z

1 pc	Rear bumper		\$ 696.00 de
1 pc	Rear bumper lower cover		\$ 206.00 all X
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00		\$ 58.00×
1 pc	Rear bumper inner sponge		\$ 114.00 🗷
1 pc	Rear bumper reinforcement		\$ 607.00 ₹
2 pcs	Rear bumper stay o/s & n/s @ \$53.00		\$ 106.00 ⋉
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00		\$ 36.00 ⊁
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00		\$ 36.00 ≮
1 pc	Rear bumper n/s reflector	LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting	\$ 46.00 X
			\$ 1,905.00
		 To display damaged part(s) during resurvey Less 10% 	\$ 190.50
S/NETT		Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed	\$ 1,714.50
	Rear bumper clips	Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	\$ 48.00 20 neg
1 set	Reverse sensor	Acknowledged by Repairer	\$ 280.00 200
1 pc	Rear bumper top protector	Signature: Date:	\$ 80.00
	Sundry		\$ 50.00 20 ner
	To dismantle / replace reverse sensor to new bumper and reset to the same		\$ 120.00 30.
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 180.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc		\$ 650.00 200
	To putty and spray painting on rear bumper, end panel		\$ 500.00 200
	To apply rustproofing on the repaired and replaced panels.		\$ 150.00 ×
			\$ 3,772.50

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.