



AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/122018/3721
Accident date : 15/12/2018
Your Ref : SLZ6110Y


Invoice No.:

Date : 19/12/2018

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way #07-16
Singapore 079120

ESTIMATE COST OF REPAIRS TO BMW 318I SKP3071K

1	pc	Front bonnet / RT	\$	1,166.55	✓
2	pcs	Front bonnet hinge @ \$81.85 x 2 NN	\$	163.70	✓
1	pc	Front bonnet absorber x	\$	109.45	✓
2	pcs	Front headlamp @ \$980.25 - CAA	\$	1,960.50	✓
2	pcs	Front grille @ \$109.90 1pc - mis sch	\$	219.80	(09.9)
1	pc	Front bumper - CAA	\$	1,105.15	✓
1	pc	Front bumper towing cover - mis.	\$	45.60	✓
1	pc	Front bumper centre grille x / BR	\$	85.70	?
2	pcs	Front bumper fog lamp @\$258.15 x - BR	\$	516.30	?
2	pcs	Front bumper fog lamp cover @\$61.10 x - BR	\$	122.20	?
2	pcs	Front bumper retainer @\$15.45 - ee.	\$	30.90	✓
1	pc	Front bumper reinforcement x - BT	\$	550.30	?
2	pcs	Front bumper bracket @\$35.15 x NN	\$	70.30	?
1	pc	Front LH fender - BT	\$	648.35	✓
2	pcs	Front LH fender bracket @\$25.50 x NN	\$	51.00	?
4	pcs	Front LH fender inner fibric @ 112.10 x / CAA	\$	448.40	?
1	pc	Front support panel x - CAA	\$	593.50	?
1	pcs	Front air cond condensor x - BT	\$	979.45	?
B/F			\$	8,867.15	



Vin's

AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722

T 6453 2121 (4 lines) / 6458 1111 (24 hrs)

F 6459 9795 / 6459 0433

E admin@vinsautogroup.com.sg

W www.vinsautogroup.com.sg

Our Ref TP/122018/3721

Date : 19/12/2018

C/F

\$ 8,867.15

1	pcs	Front air cond pipe No 1	x	LNN	\$	247.00	X
1	pcs	Front air cond pipe No 2	x	LNN	\$	283.30	X
1	pcs	Front radiator	R/	BT	\$	670.80	?
1	pcs	Front radiator fan assy	X/	CRAS	\$	1,083.75	X
1	pcs	Front radiator air duct	R/	CRA	\$	157.20	?
2	pcs	Front safety belt @ \$389.05	LH -	Act. RHD NN	\$	778.10	389.05
1	pc	Front air bag ECU	X	NN	\$	927.15	?
1	pc	Front battery cable	-	Act	\$	293.05	/
					\$	13,307.50	5749.05
Less 5%					\$	(665.38)	
					\$	12,642.13	5461.6

To towing	\$	120.00	?
To refill air cond gas	\$	150.00	R 120
To reset air bag system	\$	250.00	200
To repair front damage	\$	980.00	800
To spray painting	\$	980.00	800
		\$	15,122.13

VIN'S MOTOR PTE LTD

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

6 Days.
Lumpsum Repair.
After repair photos.
Gmo Qianp.
20/12/18.



AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/122018/3721
Accident date: 15/12/2018
Your Ref : SLZ6110Y

Tax Invoice :

Date : 21/12/2018

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way #07-16
Singapore 079120

SUPPLEMENTARY COST OF REPAIRS TO BMW 318I SKP3071K

1	pc	Front bumper under cover	✓	CRA	\$	412.50
2	pcs	Front support air duct @ \$68.75	✓	CRA	\$	137.50
2	pcs	Front headlamp lower bracket @ \$71.95	✓	CRA	\$	143.90
					\$	693.90
		Less 5 %			\$	(34.70)
					\$	<u>659.21</u>

VIN'S MOTOR PTE LTD

Guo Qil
21/12/18