

Cheng Hoe Motor Pte Ltd

GBA 7625Y

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 18/12/2018

TP Veh Reg No: SKG628Y

Estimate No: ES1891433/YISHUN

Date: 19 Dec 2018

Policy No: D18MTPCVE004114

Veh Reg No: GBA7625Y

Make/Model: TOYOTA HIACE (M)

Chassis No: JTFHT02P900006990

Engine No: 1KD1711682

Reg. Date: 17/12/2007

Not Notified

1/1 Reg & ?

Resurvey After Paint 7-10 days

Estimate Repair Cost to Vehicle No :GBA7625Y

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 FRONT BUMPER	448.20	1 PC	<i>CM</i> 448.20	<i>✓</i>
2 FRONT BUMPER REINFORCEMENT	304.20	1 PC	304.20	<i>✓</i>
3 FRONT BUMPER RH FOG LAMP	168.92	1 PC	<i>RH</i> 168.92	<i>✓</i>
4 FRONT BUMPER RH FOG LAMP GARNISH	43.30	1 PC	<i>DIT</i> 43.30	<i>✓</i>
5 FRONT BUMPER TOW COVER	25.10	1 PC	<i>DO</i> 25.10	<i>✓</i>
6 FRONT BUMPER RH SIDE RETAINER	168.82	1 PC	<i>CM</i> 168.82	<i>✓</i>
7 FRONT BUMPER CLIPS	3.50	6 PCS	<i>MR</i> 21.00	<i>✓</i>
8 RH HEADLAMP	626.60	1 PC	<i>BR</i> 626.60	<i>✓</i>
9 FRONT RH CORNAL PANEL	233.90	1 PC	<i>RH</i> 233.90	<i>✓</i>
10 FRONT PANEL	844.30	1 PC	<i>RH</i> 844.30	<i>✓</i>
11 FRONT PANEL LOGO	70.20	1 PC	<i>MR</i> 70.20	<i>✓</i>
12 FRONT PANEL RH HINGE	59.10	1 PC	<i>DIT</i> 59.10	<i>✓</i>
13 FRONT GRILLE	530.10	1 PC	530.10	<i>✓</i>
14 AIR FILTER HOUSING	873.30	1 PC	<i>BR</i> 873.30	<i>✓</i>
15 FRONT RH STEP GARNISH	152.70	1 PC	<i>DIT/MR</i> 152.70	<i>✓</i>
16 FRONT RH DOOR	1,794.10	1 PC	<i>RH</i> 1,794.10	<i>✓</i>
17 FRONT RH DOOR INNER LOCK	549.17	1 PC	549.17	<i>✓</i>
18 FRONT RH DOOR INNER BOARD	751.10	1 PC	751.10	<i>✓</i>
19 FRONT RH DOOR INNER RUBBER	185.76	1 PC	185.76	<i>✓</i>
20 FRONT RH DOOR TOP HINGE	78.18	1 PC	<i>RH</i> 78.18	<i>✓</i>
21 FRONT RH DOOR BOTTOM HINGE	78.18	1 PC	<i>RH</i> 78.18	<i>✓</i>
22 FRONT RH DOOR SIDE MIRROR	299.30	1 PC	<i>Ad/LW</i> 299.30	<i>✓</i>
23 FRONT WINDSCREEN GLASS RUBBER	229.80	1 PC	<i>MR</i> 229.80	<i>50% in</i>
24 FRONT RH WINDSCREEN PILLAR OUTER	377.18	1 PC	377.18	<i>✓</i>
25 BRAKE BOOSTER	1,256.79	1 PC	1,256.79	<i>✓</i>
26 BRAKE MUSTER PUMP	455.97	1 PC	455.97	<i>✓</i>
			10,625.27	
	Less 25%		2,656.32	7,968.95

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 18/12/2018

TP Veh Reg No: SKG628Y

Estimate No: ES1891433/YISHUN

Date: 19 Dec 2018

Policy No: D18MTPCVE004114

Veh Reg No: GBA7625Y

Make/Model: TOYOTA HIACE (M)

Chassis No: JTFHT02P900006990

Engine No: 1KD1711682

Reg. Date: 17/12/2007

Estimate Repair Cost to Vehicle No :GBA7625Y

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
Labour				
27 TOWING (4 WHEEL TOW)	100.00	1 LA	100.00	✓
28 REMOVE AND REFIX FRONT WINDSCREEN GLASS	60.00	1 LA	60.00	✓
29 REMOVE & REFIX DASHBOARD,METER ASSY & CHECK WIRING	250.00	1 LA	250.00	✓
30 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
31 PANEL BEATING	1,400.00	1 LA	1,400.00	800-1100!
32 REMOVE & REFIX SEAT,CARPET,GARNISH, TOP ROOF LINING,ETC	100.00	1 LA	100.00	80
33 REMOVE & REFIX FRT RH DOOR GLASS & CHECK CENTRAL LOCK & POWER MIRROR	60.00	1 LA	60.00	✓
34 PUTTY & RESPRAY ON FRT AFFECTED AREAS	1,200.00	1 LA	1,200.00	1100!
35 TO CHECK FRT UNDER CARRIAGE & CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 LA	60.00	✓
36 RUSTPROOFING	90.00	1 LA	90.00	✓
			3,420.00	3,420.00
Total			S\$ 11,388.95	
Add GST @ 7%			797.23	
Total Amount Payable			S\$ 12,186.18	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE