

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5330D**AAD1812-139**

Not Authored
11 Rm & 7 Tless
Book Value ??

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5330D

VF1ABL15AUC279361

RENAULT

LATITUDE

10.12.2018

AIG**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Mr</i>	1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	<i>Mr</i>	181.75	✓
3	1	BUMPER ABSORBER FRT	\$	<i>Bn</i>	394.68	✓
4	1	BUMPER RETAINER FRT LH	\$	<i>CM</i>	151.41	✓
5	1	BUMPER SUPPORT FRT	\$	<i>Mr</i>	123.88	✓
6	1	BUMPER RETAINER FRT RH	\$	<i>CM</i>	150.77	✓
7	1	BUMPER SUPPORT FRT	\$	<i>Mr</i>	123.88	✓
8	1	BUMPER UNDERTRAY FRT	\$	<i>CM</i>	472.83	✓
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Mr</i>	266.80	✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Mr</i>	207.21	✓
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Mr</i>	207.21	✓
12	1	BUMPER BEAM FRT	\$	<i>Bn</i>	914.08	✓
13	1	TOW COVER FRT	\$	<i>Mr</i>	28.61	✓
14	1	RADIATOR GRILLE	\$	<i>Mr</i>	1,707.78	✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Mr</i>	225.36	✓
16	1	RADIATOR GRILLE FRAME	\$	<i>CM</i>	1,353.75	✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i>	615.90	✓
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>Bn</i>	89.79	✓
19	1	FRONT BRACE PANEL	\$	<i>Bn</i>	177.22	✓
20	1	HORN	\$	<i>CM</i>	314.17	✓
21	1	HORN BRACKET	\$	<i>R</i>	40.45	X
22	1	HEADLAMP LH	\$	<i>Mr</i>	1,184.43	✓
22	1	HEADLAMP HARNESS	\$	<i>Sn</i>	928.29	X
22	1	HEADLAMP RH	\$	<i>Bn</i>	1,184.43	✓
22	1	HEADLAMP HARNESS	\$	<i>Sn</i>	928.29	X
22	1	HEADLAMP PANEL FRT LH	\$	<i>Bn</i>	152.15	✓
25	1	HEADLAMP PANEL FRT RH	\$	<i>Bn</i>	152.15	✓
26	1	BONNET	\$	<i>Bn</i>	1,941.63	✓

Trans-cab Auto Services Pte Ltd**AAD1812-139**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5330D

27	1	BONNET INSULATOR	\$	De form	405.73	✓
28	1	BONNET STRUT LH	\$	Per	88.61	—
29	1	BONNET STRUT RH	\$	Per	88.61	—
30	1	BONNET HINGE LH	\$	Dis	348.31	—
31	1	BONNET HINGE RH	\$	Dis	348.31	✓
32	1	BONNET LOCK	\$	Bj	305.48	✓
33	1	BONNET CABLE	\$	Sn	119.19	X
34	1	BONNET CABLE COVER	\$	Sn	161.03	X
35	1	BONNET SEAL OUTER	\$	Se	92.36	X
36	1	BONNET SEAL INNER	\$	Sn	157.28	X
37	1	FENDER PANEL FRT LH	\$	Bu	783.83	✓
38	1	WHEELARCH FRT LH	\$	CM	278.84	✓
39	1	FENDER BRACKET LOWER LH	\$	R	15.79	X
40	1	FENDER INSULATOR LH	\$	Sn	130.84	X
41	1	FENDER PANEL INNER FRT RH L70Y	\$	R	1,654.50	X
42	1	FENDER PANEL SUPPORT FRT RH L70Y	\$	R	1,095.24	X
43	1	FENDER PANEL BRACKET FRT RH L70Y	\$	R	209.97	X
44	1	FENDER PANEL BRACKET FRT RH L70Y	\$	Se	143.27	X
45	1	WHEEL HOUSING PANEL FRT RH L70Y	\$	R	4,682.09	X
46	1	WIPER RESERVOIR	\$	Per	348.25	—
47	1	WIPER RESERVOIR NECK	\$	Per	136.11	✓
48	1	WIPER RESERVOIR MOTOR	\$	Sn	270.06	X
49	1	AIR CLEANER LOWER	\$	Sn	271.26	X
50	1	AIR CLEANER HOSE	\$	Sn	76.14	X
51	1	AIR CLEANER BOX	\$	Sn	464.20	X
52	1	TURBO DUCT	\$	Sn	1,027.80	X
53	1	A/C HEATER VALVE	\$	Sn	484.50	X
54	1	SUBFRAME OUTER FRT	\$	Bj	2,652.45	✓
55	1	SUBFRAME BRACKET OUTER LH	\$		92.36	?
56	1	SUBFRAME BRACKET OUTER RH	\$	Dis	92.36	✓
57	1	ENGINE UNDERTRAY	\$		564.98	?
58	1	A/C CONDENSER	\$	Bj	2,020.37	✓
59	1	A/C CONDENSER GARNISH LH UPPER	\$	Sn	39.67	X
60	1	A/C CONDENSER GARNISH RH UPPER	\$	Sn	39.67	X
61	1	A/C CONDENSER GARNISH LH	\$	Sn	58.81	X
62	1	A/C CONDENSER GARNISH RH	\$	Sn	59.60	X
63	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Sn	208.39	X
64	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Sn	658.72	X

Trans-cab Auto Services Pte Ltd**AAD1812-139**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5330D

74	1	A/C PIPE COMPRESSOR	\$	334.29	?
75	1	A/C PIPE	\$	658.72	?
76	1	A/C COMPRESSOR	\$	<i>S₂</i> 2,684.61	X
77	1	AIR COOLER	\$	<i>R₁</i> 792.60	✓
78	1	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13	?
79	1	AIR INTERCOOLER HOSE (Short)	\$	375.14	?
80	1	TRANSMISSION COOLER	\$	1,219.30	?
81	1	TRANSMISSION COOLER PAD	\$	17.96	?
82	1	RADIATOR	\$	<i>R₁</i> 1,202.20	✓
83	2	RADIATOR STUD UPPER	\$	<i>R</i> 14.41	X
84	2	RADIATOR BUSH UPPER	\$	<i>R</i> 50.12	X
85	2	RADIATOR MTG LOWER	\$	<i>R</i> 55.85	X
86	1	RADIATOR FAN COWLING	\$	<i>C M</i> 820.54	✓
87	1	RADIATOR FAN MOTOR LH	\$	967.36	?
88	1	RADIATOR FAN MOTOR RH	\$	1,479.46	?
89	1	RADIATOR TANK	\$	324.62	?
90	1	RADIATOR HOSE UPPER	\$	240.56	?
91	1	RADIATOR HOSE LOWER	\$	491.18	?
92	1	RADIATOR TANK HOSE	\$	61.18	?
93	1	AUTO COMPUTER	\$	<i>S₂</i> 5,032.17	X
94	1	INJECTION COMPUTER	\$	<i>S₂</i> 4,706.30	X
95	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	5,154.52	?
96	1	STEERING PUMP ELECTRIC	\$	<i>S₂</i> 2,306.90	X
97	1	STEERING PINION RACK	\$	4,413.11	?
98	1	SEATBELT LH L70Y	\$	<i>T₁</i> 2,937.80	✓
99	1	SEATBELT RH L70Y	\$	<i>T₂</i> 2,925.37	✓
100	1	SEATBELT BUCKLE LH L70Y	\$	984.13	?
101	1	SEATBELT BUCKLE RH L70Y	\$	949.80	?
102	1	PASSENGER AIRBAG L70Y	\$	<i>Burn</i> 3,412.40	✓
103	1	STEERING AIRBAG L70Y	\$	<i>✓</i> 2,525.75	✓
104	1	AIRBAG COMPUTER L70Y	\$	<i>Ne</i> 1,259.82	✓
105	1	AIRBAG SENSOR L70Y	\$	<i>Ne</i> 724.63	✓
106	1	AIRBAG SENSOR L70Y	\$	<i>Ne</i> 289.30	✓
107	1	DASHBOARD L70Y	\$	<i>T₁</i> 4,900.54	✓
108	1	WINDSCREEN FRT L70Y	\$	<i>C M</i> 1,364.06	✓
109	1	AIRBAG COMPUTER L70Y	\$	<i>Amcan</i> 1,259.82	X
110	1	AIRBAG SENSOR L70Y	\$	<i>✓</i> 724.63	X
111	1	AIRBAG SENSOR L70Y	\$	<i>✓</i> 289.30	X

Trans-cab Auto Services Pte Ltd**AAD1812-139**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5330D

112	1	LOWER ARM LH L70Y	\$	Bj	685.76	✓
113	1	KUNCKLE ARM LH L70Y	\$	Bj	846.98	✓
114	1	ABSORBER FRT LH L70Y	\$		360.54	?

TOTAL	\$	97,011.15
10%	\$	9,701.12
	\$	87,310.04

Specical Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00	✓
2	1SET	BUMPER CLIP FRT	\$	na	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	} X
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
7	1	TOW COVER FRT	\$	na	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	na	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	} X
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
21	1	Windscreen moulding	\$	na	100.00	✓
22	1SET	Front licence plate with holder	\$	mir	80.00	45sa
23	1	DOOR CHECK BOLT	\$	sn	22.69	} X
24	1	DOOR GUIDE SCREW	\$	sn	10.85	
25	1	DOOR HINGE BOLT	\$	sn	10.85	
26	1	DOOR HINGE NUT RH	\$	sn	14.60	
27	1	DOOR CHECK BOLT	\$	sn	22.69	
28	1	DOOR CHECK NUT	\$	sn	3.75	} X
29	1	DOOR LOCK SCREW L70Y	\$	sn	6.12	
30	1	DOOR CATCH SCREW L70Y	\$	sn	10.06	
31	1	WINDSCREEN SEALANT	\$	na	253.80	40sa
32	1	FRONT LEFT TYRE	\$	Per	300.00	70sa
33	1	FRONT LEFT TYRE RIM	\$	i	380.00	?

Trans-cab Auto Services Pte Ltd

AAD1812-139

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5330D

TOTAL \$ 1,597.93**TOTAL PARTS \$ 88,907.97**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	2200
Towing Fees.	\$	120.00	500
To apply paint protection system (PPS) maintain and enhancement	\$	380.00	~ ~ X
Putty and spray painting of the affected portion.	\$	6,000.00	18800
To rust-proofing of the affected areas.	\$	170.00	1500
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	1000
To check steering geometry and computer wheel alignment	\$	220.00	600
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	} 2500
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	
To lift-up engine with gear box and refit.	\$	440.00	?
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00	?
To remove and refit air bag system and reset.	\$	480.00	2500

Trans-cab Auto Services Pte Ltd**AAD1812-139**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5330D

To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 100l
To replace, refix and top up coolant for radiator	\$	170.00 50l
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 50l
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X
To Transfer Of Door Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 120l
To remove and renew engine and gear box mounting.	\$	380.00 ?
To dismantle and refit engine cross-member and engine mounting.	\$	380.00 ?
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00 X
To check ABS brake efficiency, final checking and testing.	\$	nn 380.00 X
To remove and refit ABS pump relay to enable repair.	\$	nn 380.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00 20l

Trans-cab Auto Services Pte Ltd

AAD1812-139

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5330D

TOTAL	\$	19,130.00
--------------	-----------	------------------

Over All Total	\$	108,037.97
-----------------------	-----------	-------------------

Repair Days (Lump Sum)~~30 DAYS~~

16 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: